

Nº:

1079

Técnico:

Márcio Vieira

Data:

quarta-feira, 10-09-2025

Detalhes:

Verificar escorregas, reparar falha no top coat do whizzer, à entrada na parte de baixo.

A handwritten signature in black ink is written over the signature line. The signature is stylized and appears to be 'MV' or similar initials.