

Nº:

1081

Técnico:

Márcio Vieira

Data:

sexta-feira, 12-09-2025

Detalhes:

Verificar ativa, reparar rachadura na aba de cima à entrada do torpedo.
Reparar falha no top coat na "flor" do disco river.

A handwritten signature in black ink is written over the signature line. The signature is stylized and appears to be 'MV' or similar initials.