

AKOLISA CRANE LIMITED

ENGINEERING, SERVICES & CERTIFICATION OF LIFTING EQUIPMENTS

HEAD OFFICE: No. 49 Okwuro water-site off Standard rd, Elenwo. ph

EMAIL: akolisaventures@yahoo.com

WEBSITE: www.akolisacrane.com

TEL NO: 084-757807, 084-777926

Mobile No: 08064347013



24th February, 2022.

ATTN:
MANAGING DIRECTOR,
ELSHCON NIGERIA LTD,
SLAUGHTER BASE,
PORT-HARCOURT, RIVERS STATE NIGERIA.

CRANE INSPECTION REPORT

. 1

MAKE:	TEREX
MODEL:	RT335
CRANE S/NO.:	11560
LMI Make:	GREER COMPANY
LMI Model:	RCI510
CRANE LOCATION:	PHC

OBSERVATIONS

1. The Maestro system is not coming on.

Errors are

A003

B0

C00

D03

A003: means TDX1 rod pressure transducer faulty

D03: means wrong boom length and chart not found

RECOMMENDATIONS

- (a). Replacement of pressure transducers
- (b). Replace length potentiometer and do system setup

Signed:

NDUBUISI Emmanuel



BRANCHES

NO. 4 OMERELU STREET, BEHIND HOTEL PRESIDENTIAL, G.R.A. PHASE 1, PORT HARCOURT, RIVERS STATE.

AKOLISA CRANE LIMITED

ENGINEERING, SERVICES & CERTIFICATION OF LIFTING EQUIPMENTS

HEAD OFFICE: No. 49 Okwuro water-site off Standard rd, Elenwo. ph

EMAIL: akolisaventures@yahoo.com

WEBSITE: www.akolisacrane.com

TEL NO: 084-757807, 084-777926

Mobile No: 08064347013



24th February, 2022.

ATTN:
MANAGING DIRECTOR,
ELSHCON NIGERIA LTD,
SLAUGHTER BASE,
PORT-HARCOURT, RIVERS STATE NIGERIA.

CRANE INSPECTION REPORT

NO. 2

MAKE: BADGER CRANE
MODEL: 4450
CRANE S/NO.: 14844
SWI:
LMI MODEL: W2245
CRANE LOCATION: PHC

OBSERVATIONS

1. Load reading is not correct

RECOMMENDATIONS

1. Outright calibration of the load and other sensors

Signed:

NDUBUISI Emmanuel



BRANCHES

NO. 4 OMERELU STREET, BEHIND HOTEL PRESIDENTIAL, G.R.A. PHASE 1, PORT HARCOURT, RIVERS STATE.