




No. 28 Ojike Street,
Mile 1 Diobu, Port Harcourt.

EUGENE OGWO

MECHANICAL RESOURCES

Auto Dealer / Mechanics, Transportation, Supplies & General Contractors.



Phone: 08038833164

11/9/2019

THE WORKSHOP MANAGER,
ELSHCON L.T.D,
PORT HARCOURT.

SIR.

QUOTATION FOR WORKING ON 35 TON GROVE CRANE MODEL AT 8168-3

I have inspected the 35 tons crane for repair.

1. Three outrigger ram seal bad, cost of new seals ₦55, 000 each X 3 = ₦ 165,000. *= 150,000*
 2. Two inner shifting outrigger ram seal 25,000 each x 2= ₦ 50,000.
 3. Teliscop faiber adjustment balance two pcs cost ₦ 65,000.
- Electrical Work. (1) Light, Alternator for repair. ₦ 55,000,
Air system valve servicing and parts ₦ 55,000.
Labour for mechanical work ₦ 200,000 *- 170,000*
Total ₦ 590,000.00

There will be mobilization fee at half of money charge pay for spare parts money.
Kindly refer your payment (s) other then cash to the account below

F.C.M.B

Account Number: 2805297013

Account Name: Ogwo Chinedu Dick

Thank in esteem regards

Yours faithfully

Ogwo Chinedu Dick

*Grand Total for the
fixing of the 35ton Grove Crane
₦ 545,500*

*Chinedu
Timber
25/9/19*