

10:49

VoLTE 4G LTE1 97%



Engr Ralph Project...

last seen today at 10:33



response.

10:04



Site Picture.pdf

35 pages • 2.6 MB • PDF



10:05

Dear Rufai,

The person that assisted us to attend the site visit yesterday need to be settled. Please apply for that as discussed with MD even though the amount wasnt fixed but it is cheaper than sending someone from here

Kindly please process the payment of N50k as negotiated with the site inspector for his transport, feeding and fee.

See attached the sintered report from him as is needed for our bid response.

10:06

Engr Ralph Project Consultant Elshcon

Dear Rufai,

The person that assisted us to attend the sit...

OK.


10:10 ✓✓

Good morning 10:10 ✓✓



Message






Above was the pictorial measurement instruction given to the free lance site inspector

Below were the instruction given to him:

1. Find a tape you will go with, you need to go there with a measuring tape and a rope too.
2. You need to snap pictures of all the angles too of this material. I don't mind snapping up to 20 different pictures of different sides of this elbow pipe.
3. Count the bolt holes, measure the diameter of the pipe too (this is the hollow pipe section)

Report

Free hand sketch of the measurements taken:



Pup piece distance is the actual distance that we required to know, the curved elbow arc length measurement was taken to confirm the type of elbow under consideration here.

Other pictures taken are as below:



Pictorial measurement of pup piece end welded to the Flange and elbow = **9 inches** (Approx. 23cm)