

# OCEANLINK LOGISTICS

## INCIDENT REPORT

Confidential Internal Use Only

Incident ID	IR-1015	Vessel ID	VSL-102
Date	26/10/2025	Port	Makassar
Reported By	Ops Officer L. Santoso	Weather	Storm

**Summary**

Vessel altered route 10 nautical miles east to avoid the storm corridor. Navigation system rebooted mid-voyage due to electrical fault. Incident occurred during Storm conditions en route to Makassar.

**Impact**

Navigation system rebooted mid-voyage due to electrical fault.

**Action Taken**

Vessel altered route 10 nautical miles east to avoid the storm corridor.

**Recommendation**

Install advanced radar calibration system to mitigate heavy weather distortion.

*Report generated by OceanLink Logistics Internal Safety Department*