

## **DX FT8 Project Firmware Version 1.9.6 Release Notes: 30 June 2025**

Further on air testing has revealed a flaw with the changes made to allow for repeat RR73 messages in V1.9.5.

In the case of being in the Beacon Mode and a Repeat RR73 message is sent, the RSL from the Target Station is logged as zero instead of the value sent from the Target Station.

Now, in version V1.9.5 the RSL from the Target Station is logged properly.