

## WORK ORDER/SERVICE REQUISITION FORM

Ship Name : Atlantis

WO/SR No : 0340524

Performed By : SR/Contractor

Title : Replace/Repair poured deck in lower forward berthing

### SCHEDULING DATA

Scheduled : 07/06/2020

Event : Mid-life Refit

Completed :

Canceled :

Next Due Date :

Interval :

### ADMINISTRATIVE DATA

Created By: HICKEY, JENNIFER

On : 09/28/2019

Auth. By: HICKEY, JENNIFER

On : 09/28/2019

Apprvd. By:

On :

Account No:

Project No:

Priority : D

Job Catg:

Class Job No :

Sugg Vend:

Dept.:

### EQUIPMENT PARTICULARS

### SPACE PARTICULARS

Name: 2-22-1 Passageway  
Space Index Passageway  
Area(in m2) 0.0  
Remarks

Class Name : Class Code:

Treatment 0.0

Name: 2-33-1 Locker  
Space Index Locker  
Area(in m2) 0.0  
Remarks

Class Name : Class Code:

Treatment 0.0

### RESOURCES & COST DATA

Estimated Cost : 0.00

Estimated Man-Hrs : 0

Std. Job Cost :

Actual. Man-Hrs : 0

Resource :

### WO DESCRIPTION

Replace or repair the damaged poured deck in lower forward berthing (1st platform deck berthing area forward of frame 40). In at least 3 places, the poured deck is cracked, most likely with corrosion underneath. Poured deck needs to be removed and steel deck below treated appropriately to remove rust and allow new poured deck to adhere. See attached pictures. Damage noted at bottom of ladder on either side of man door just forward of frame 40, as well as forward of cleaning gear locker. Consideration should be given to adding a poured deck to the cleaning gear locker.

### WO FINDINGS

Perform By:

Tested By:

Signature:

Designation:

---

## IMAGES

snake pit deck 1.JPG11



## IMAGES

snake pit deck 2.JPG21





## IMAGES

snake pit deck 3.JPG31



---

## JOB SAFETY ANALYSIS

JSA Required : NO

Use Template :