

2:06



124



## Card



..... 9774

Devon Barber

VISA

CVV ... EXP ..../..



Lock



Copy .. 9774



Explore offers

Instant discounts



## Spending



Insights & activity

\$13 in Nov





2:06



## Midas 20 Egg Har Hin

May 20 at 12:34 PM

# \$1,101.36

### Transaction details



**Complete**

Purchase from Midas 20 Egg Har Hin



**Payment method**

Black Metal Card 9774



**On statement as**

MIDAS 20 EGG HAR 3109 HIN

### What you can do




**View Round Up receipt**







Midas Egg Harbor  
3109 Hingston Ave  
Egg Harbor, NJ 08234  
Trust The Midas Touch  
**609.900.6475** 📞  
[midaswestberlin@gmail.c](mailto:midaswestberlin@gmail.com)  
[om](mailto:om) ✉



RO# 0002663 5/20/2025  
DEVON BARBAR  
2019 VOLKSWAGEN  
PASSAT  
VIN:  
1VWLA7A36KC002247  
License: F35VLP  
Mileage: 95789

Service Advisor  
PERRY HERMAN

Filter





## Midas Closer Look Vehicle Check

### Exterior

☒ Body & Glass: Visual Inspection OK

Images:



☒ Exterior Lights: Visual Inspection OK

Technician  
KURTIS WASYLKOWSKI

✓ Exterior Lights: Visual Inspection OK

✓ Wipers: Visual Inspection OK

### Interior

⚠ Dash Indicator Lights: TPMS Light On "Solid"  
- Evaluation Required

Images:




### Under Hood

✓ Horn: Operating


✓ Engine Air Filter: Visual Inspection OK

Images:



◆ Cabin Air Filter: Beyond Service Interval -  
Replacement Suggested

Images:



---

✅ Battery / Cables: Visual Inspection OK

Images:




---

✅ Hoses: Visual Inspection OK

---

✅ Belts (except timing belt): Visual Inspection OK

Images:



---

✅ Windshield Washer Fluid: Reservoir Full

---

✅ Engine Oil: Dipstick Within Specifications

---

✅ Power Steering Fluid: Dipstick Within Specifications

---


✅ Transmission / Transaxle Fluid: Dipstick Within Specifications

---

⚠️ Coolant: Beyond Service Interval - Fluid Exchange Suggested

Images:





---

### Under Vehicle


✅ Exhaust System: Visual Inspection OK

✅ Differential / Transfer Case: Visual Inspection OK

✅ Steering System: Visual Inspection OK


✅ Shocks / Struts Front: Visual Inspection OK

Images:



⚠️ Shocks / Struts Rear: Degraded Ride/Control - Replacement Suggested

Images:



✅ Driveline (CV / Drive Shaft): Visual Inspection OK

---


### Brakes

⚠️ Brake Fluid: Beyond Service Interval - Fluid Exchange Suggested

Images:



Images:




---

☒ Brake Symptom Observed: None at this time

---

☒ Brake Visual Inspection Front: Visual Inspection OK

Images:



---

☒ Brake Visual Inspection Rear: Visual Inspection OK

Images:



---

### Tire Condition

☒ Tire Size Actual - See Picture: Matches Placard Specifications

Images:





---

◆ LF - Tread Depth: 4/32" - Close To The End Of Useful Life


Images:



---

◆ RF - Tread Depth: 3/32" - Close To The End Of Useful Life


Images:



---

✅ RR - Tread Depth: 6/32" - Tread Depth Within Guidelines


Images:




---

◆ LR - Tread Depth: 4/32" - Close To The End Of Useful Life


Images:








### Tire Inspection Suggestions: Irregular Tread Wear - Evaluation Required

#### Tire Pressure

 LF - Tire Pressure: Matches Placard Specifications

 RF - Tire Pressure: Matches Placard Specifications

 RR - Tire Pressure: Matches Placard Specifications

 LR - Tire Pressure: Matches Placard Specifications

#### Technician Note

☒ Technician Notes: See Notes Below

Comments:

rec 4 tires and alignment by  
edgewear and tread depth  
rec cabin filter by mileage rec  
coolant and brake flush by  
mileage rec rear shocks by  
mileage rec tune up by  
mileage rec fuel service by  
mileage front and rear end  
tight, caster out 1 degree not  
adjustable

Images:



