



1. Unmachined surfaces must be dry and coated with anti-rust paint.
2. Unspecified fillets: R3 to R5.
3. Conduct hydraulic pressure test; no leakage within 5 minutes.



	Name	Zhiqiang Zhou
	Scale	1:1.25
		No.1 A4