



| Overview | | | | Site |
|-------------|-------------|-------|------------|---|
| Inspect No: | 1139 | Page: | 1/1 | <div>AECOM - MIDLANDS HUB</div> <div>Drift Drive Crick Northamptonshire NN6 7GZ</div> |
| Job No: | 10012 | | | |
| Customer: | AECOM | | | |
| Contact: | Rob Bewick | Date | 22/03/2023 | |
| Tel: | 7553 226429 | | | |

Fail

| Client-ID | Make / Model | Serial No | ISI Equipment No |
|--------------------|---------------------------|--------------------|------------------|
| Roof Access Ladder | Ladders & Scaffolding All | Roof Access Ladder | 2001388 |

| Asset Photograph | |
|--|--|
| Capture photograph of Asset, including asset number | See Photo 1 |
| Hazard Priority and Findings | |
| Intolerable - Defects requiring immediate action | Missing horizontal rungs at first rest platform. Installation is not compliant with BS4211 |
| Substantial - Defects requiring attention within a time period | None |
| Moderate - Other defects requiring attention | None |
| Tolerable - Observations | None |



| General Comments |
|------------------|
| None |

Engineer

Graham Willars