

# CLASSIC PLY AND BOARDS

VIII/421 B, KOTTACHIRA, ODAKKALY,  
METHALA P.O. PERUMBAVOOR,  
ERNAKULAM DIST - 683 545  
classicplyboard@gmail.com  
+91 9847097259  
+91 9947772170

Mfs : PLYWOOD (COMMERCIAL, MARINE, GURJAN, PF), DENCIFIED SHUTTERING & CHECKED PLYWOOD etc.

Ref: Classic/03/2023

20.03.2023

To  
The Inspector of Factories and Boilers,  
Perumbavoor.

Sir,

Sub: Repair of Boiler No. KTK-3736

We are decided to replace 3 Nos. smoke tubes in the above said boiler.  
We would kindly request you to inspect the same and take necessary  
steps to replace 3 Nos. smoke tube as early as possible.

Position of Tube :-

*From the front view 2<sup>nd</sup> pass LHS bottom to top 4<sup>th</sup> Raw 1<sup>st</sup> tube.*

*From the front view 2<sup>nd</sup> pass LHS bottom to top 6<sup>th</sup> Raw 2<sup>nd</sup> tube.*

*From the front view 2<sup>nd</sup> pass LHS bottom to top 10<sup>th</sup> Raw 3<sup>rd</sup>  
tube.*

Size of tubes:-

**3.66mm Thick, 63.5mm OD and 2.610m length**

Thanking and awaiting your valuable action in this regard.

Yours truly

for class  
manager



*[Handwritten signature]*