



Readme CBD1700369 D04

Note / Integration hints

BAC modules

In our integration we used the latest BMW BAC modules which were available (BAC4.3 Version 3.5.0). However, we faced some issues with the BAC modules which forced us to modify the code of the BAC modules to be able to do a complete flash process successfully. Both issues were submitted to BMW and we suppose they get fixed in one of the next BAC4.3 releases.

We added the modified you your SIP in the folder "IntegrationFiles":

 _patchedByVector_Dlog_SweStatus.c
 _patchedByVector_Prog_GenericRequestTransferExit.c

The patches are marked in the files with @@@patchedByVector. You can replace the original files with these ones as long as these issues exist.

At BMW the issue are registered as BAC-6612 and BAC-6828.

DiagSystemTest

One testcase (3.1.4) of the DiagSystemTest could not be performed successfully since the test suite just stops the CANoe measurement when running this testcase. Please contact BMW in case you're facing the same issue.