

Filters


Years in day\_dateThis Year | event\_typenew\_status, user\_set\_status

4 more...

# Augury | Roseburg Engagement Summary

- This report is built to help understand the status of the facilities' engagement with the Augury program, on an organization, business unit, and facility-specific levels, and compared to the Augury benchmark.
- The two main KPIs that are presented throughout this report are **Alert Response Rate** - the % of alerts that the facility responded to out of the alerts that were sent, and **Time to Response** - # of days from alert to the first response by facility.
- Both KPIs are based on **Alarm and Danger** alerts only, and not Monitor. The reason is that Alarm and Danger alerts require a prompt response, while Monitor alerts are less urgent in the majority of cases and require a different response depending on the facility.
- Both KPIs refer to any kind of response available in the platform: repair, observation on an alert

## Company Overview



Filters

Years in day\_date

This Year

event\_type

new\_status, user\_set\_status

[4 more...](#)


Average days from alert to 1st response -...

Roseburg

4.01

Augury Benchmark 5.08

Average time from alert to 1st response



## Region Comparison

Filters

Years in day\_date


This Year

event\_type


new\_status, user\_set\_status

[4 more...](#)

Alert Response Rate



Average time from alert to 1st response




Filters

Years in day\_dateThis Year | event\_typenew\_status, user\_set\_status


4 more...

# Facility Comparison

Alert Response Rate Per Facility - last 3 months ave...



Average days from alert to 1st response per facility ...



## East Region: Facilities Over Time

Filters

Years in day\_date

This Year


|

event\_type

new\_status, user\_set\_status

[4 more...](#)

Simsboro Composites



Filters

Years in day\_date

This Year

|


event\_type

new\_status, user\_set\_status

[4 more...](#)

Taylorsville Composites

# No Results



Filters

Years in day\_date

This Year


|

event\_type

new\_status, user\_set\_status

[4 more...](#)

Pembroke MDF



Filters

Years in day\_date


This Year

event\_type

new\_status, user\_set\_status

[4 more...](#)

El Dorado MDF





Filters

Years in day\_date


This Year

event\_type

new\_status, user\_set\_status

[4 more...](#)

Chester Engineered Wood



# West Region: Facilities Over Time

Filters

Years in day\_date

This Year


|

event\_type

new\_status, user\_set\_status

[4 more...](#)


Weed



Filters	<b>Years in day_date</b> This Year   <b>event_type</b> new_status, user_set_status	<a href="#">4 more...</a>
---------	--	---------------------------

Missoula Composites

No Results



Filters

Years in day\_date

This Year


|

event\_type

new\_status, user\_set\_status

[4 more...](#)

Coquille Plywood



Filters

Years in day\_date

This Year


|

event\_type

new\_status, user\_set\_status

[4 more...](#)

Riddle Plywood



Filters

Years in day\_date


This Year

event\_type

new\_status, user\_set\_status

[4 more...](#)

Riddle Engineered Wood



Filters

Years in day\_date

This Year


|

event\_type

new\_status, user\_set\_status

[4 more...](#)

Dillard Lumber



Filters

Years in day\_date

This Year

|

event\_type

new\_status, user\_set\_status

4 more...

Dillard Plywood

# No Results



## Alerts - Raw Data

Roseburg Resolved Cycles - Resolved Last 7 days

Asset Name	Asset ID	Facility\Branch	Building
HEATER # 3 SANDER DUST BURNE...	5defb69241eb7e000173c...	Pembroke MDF	Pembroke Ha



Filters

Years in day\_dateThis Year | event\_typenew\_status, user\_set\_status

4 more...

Alerts Time to Response per Facility - last 7 days		Alerts Time to Response per Facility - last 7 days		
Plant Name	Alert ID	Plant Name	Alert ID	Alert Date
Pembrok...	67a4f3b5295e0eabf9084709			
Chester ...	67a32455f67b6a46d5e47dd1	Chester Engineered W...	67a4f64e893cc1a50bb35...	02/02/2025
Coquille ...	67a27f75f67b6a46d5e47bb6	Pembroke MDF	67a4f3b5295e0eabf9084...	02/02/2025
Medford ...	679bd1df3588e69feda0deb6	Weed	67a3a53f893cc1a50bb35...	02/02/2025
Weed	67a3a53f893cc1a50bb35841	Weed	67a3ac80893cc1a50bb3...	02/02/2025
Weed	67a3ac80893cc1a50bb3584f	Chester Engineered W...	67a32455f67b6a46d5e4...	02/02/2025
		Coquille Plywood	67a27f75f67b6a46d5e47...	02/02/2025
		Pembroke MDF	67a0a2df893cc1a50bb34...	02/02/2025
		El Dorado MDF	679cf90a3588e69feda0e...	01/02/2025
		Riddle Engineered Wood	679d06e13588e69feda0...	01/02/2025
		Medford MDF	679bd1df3588e69feda0d...	01/02/2025
		El Dorado MDF	679bd9f03588e69feda0d...	01/02/2025
		Weed	679a56c7d58fb98d9d880...	01/02/2025
		Coquille Plywood	679a4b7cd58fb98d9d880...	01/02/2025
		Chester Engineered W...	679a4dadd58fb98d9d88...	01/02/2025
		Riddle Plywood	679a84e7d58fb98d9d88...	01/02/2025
		Pembroke MDF	6798cb8ea0edcc4d4a13...	01/02/2025
		Coquille Plywood	6798f965a0edcc4d4a13a...	01/02/2025
		El Dorado MDF	6796e715b8929dd547ec...	01/02/2025
		Riddle Engineered Wood	6797965fb8929dd547ec8...	01/02/2025
		Weed	6793c7e1b8929dd547ec...	01/02/2025
		Chester Engineered W...	6790a57aad23889ef4dfe...	01/02/2025
		El Dorado MDF	67915ee96a0f0aa2d370...	01/02/2025
		Pembroke MDF	678f7a42cbdc8565ee1c7...	01/02/2025
		Riddle Engineered Wood	678ed6590c602086ce05...	01/02/2025
		Riddle Engineered Wood	678ecaade2b010d2e0a7...	01/02/2025

Filters

Years in day\_date

This Year

|

event\_type

new\_status, user\_set\_status

[4 more...](#)

Machines in alarm or danger per site

site_name	# of machines		# machines in alarm	# machines in danger	#
Pembroke MDF	66		6	4	
Riddle Plywood	55		16	3	
El Dorado MDF	44		12		
Riddle Engineered Wood	44		4		
Chester Engineered Wood	42		8		
Weed	35		6	1	
Medford MDF	28		8	2	
Dillard Lumber	18		6		
Coquille Plywood	15		3	2	
Dillard Powerhouse	12		2		

Filters

Years in day\_dateThis Year | event\_type new\_status, user\_set\_status

4 more...

Machines in Alarm or Danger

site_name	machine_name	Last Health Status	days_sin
Chester Engineered Wood	Diesel Pump	2-Alarm	16
	Double Arbor Rip Gang Hogging Head	2-Alarm	33
	Double Arbor Rip Gang Top Arbor	2-Alarm	221
	ID Fan #2 (USNR - Baghouse)	2-Alarm	4
	L1 HPU Main Pump (1140)	2-Alarm	20
	L2 HPU Main Pump (1140)	2-Alarm	107
	L2 Replacement Feeder Fan	2-Alarm	4
	Stackers #2 Vacuum Fan	2-Alarm	43
Coquille Plywood	BOILER FD FAN (FORCED DRAFT)	3-Danger	6
	BOILER ID FAN (INDUCED DRAFT)	2-Alarm	12
	DRY CHIP BIN BAGHOUSE FAN	2-Alarm	278
	DRY END AIR COMPRESSOR #3 - QUINCY 751	2-Alarm	14
	RCO ID FAN	3-Danger	124
Dillard Lumber	14' Top Head Outside (#2)	2-Alarm	32
	Carmanah Chipper	2-Alarm	31
	Stud Planer Blower	2-Alarm	631
	Stud Planer Side Head Outside	2-Alarm	201
	Stud Planer Top Head Inside	2-Alarm	86
	Stud-Planer Top Head Outside	2-Alarm	78
Dillard Powerhouse	2 Boiler Re-injection Fan	2-Alarm	65
	5 Air Compressor	2-Alarm	92
El Dorado MDF	Boiler Feed Water Pump N	2-Alarm	11
	Core Infeed Booster Fan	2-Alarm	170
	Core Plug Screw	2-Alarm	23
	Core Refiner Feed Screw	2-Alarm	103