


Inserted into air diffuser in chamber ceiling make sure isolated soldered tip does not touch other surfaces and measures only free air.

Adhered to the center of the upper coil face on pipe between fins with JB weld or similar for permanent adhesion. Strain relief wire before adhesion.

Adhered to the center of the lower coil face on pipe between fins with JB weld or similar for permanent adhesion. Strain relief wire before adhesion.

PROPRIETARY NOTICE:
This document and the technical data hereon disclosed are proprietary to Hooks & Associates, Inc. and shall not, without express written permission of Hooks and Associates, Inc. be used in part, or used to solicit quotations from a competitive source or used for manufacture by anyone other than Hooks & Associates, Inc. The information hereon has been developed of private expence and may only be used for purposes of engineering evaluation and for incorporation into technical specifications and other documents which specify procurement of products from Hooks & Associates, Inc.

REV	BY	DESCRIPTION	DATE
			HAIER EVANSVILLE, IN
THERMODYNAMIC LAB POWER SUPPLY UNIT TC SLOT 21-22			
SCALE	NONE	PROJECT HE1	
DESIGNED	T. CUTSINGER	DRAWING	
DRAWN	T. CUTSINGER	E012_10	
SHEET	X	OF	X