

**Haynes**
shows you how

BMW 3-Series 320i & 320xi (12-14), 325i, 325xi, 330i & 330xi (06) & 328i & 328xi (07-14) Haynes Online Manual

6 Front arm balljoint - replacement

The balljoints on both the tension strut and control arm are integral, and cannot be replaced separately. If defective, the complete arm or tension strut must be replaced (see [Section 5](#)).

© 2024 Haynes Manuals, Inc. Contact us