

# WHARTON SMITH 911 PROJECT – RAW DATA EXPORT

=====

Format: DATE | LOCATION | TRADE | STATUS

-----

2025/04/11	ADMIN ASSISTANT 125	In Wall Insulation	in progress
2025/04/11	ADMIN ASSISTANT 125	Overhead Duct Insulation	in progress
2025/04/11	ADMIN ASSISTANT 125	Overhead Duct Rough In	in progress
2025/04/11	ADMIN ASSISTANT 125	Overhead Plumbing	not started
2025/04/11	ADMIN ASSISTANT 125	Wall Drywall	in progress
2025/04/11	ADMIN ASSISTANT 125	Wall Drywall Finish	in progress
2025/04/11	ADMIN ASSISTANT 125	Wall Prime Paint	not started
2025/04/11	AV ROOM 103	In Wall Insulation	complete
2025/04/11	AV ROOM 103	Overhead Duct Insulation	in progress
2025/04/11	AV ROOM 103	Overhead Duct Rough In	in progress
2025/04/11	AV ROOM 103	Overhead Plumbing	not started
2025/04/11	AV ROOM 103	Wall Drywall	in progress
2025/04/11	AV ROOM 103	Wall Drywall Finish	in progress
2025/04/11	AV ROOM 103	Wall Prime Paint	not started
2025/04/11	BREAK ROOM CONFERENCE 182	In Wall Insulation	in progress
2025/04/11	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	in progress
2025/04/11	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	in progress
2025/04/11	BREAK ROOM CONFERENCE 182	Overhead Plumbing	in progress
2025/04/11	BREAK ROOM CONFERENCE 182	Wall Drywall	in progress
2025/04/11	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	not started
2025/04/11	BREAK ROOM CONFERENCE 182	Wall Prime Paint	not started
2025/04/11	Background-159	In Wall Insulation	no data
2025/04/11	Background-159	Overhead Duct Insulation	no data
2025/04/11	Background-159	Overhead Duct Rough In	no data
2025/04/11	Background-159	Overhead Plumbing	no data
2025/04/11	Background-159	Wall Drywall	no data
2025/04/11	Background-159	Wall Drywall Finish	no data
2025/04/11	Background-159	Wall Prime Paint	no data
2025/04/11	CENTRAL BREAKROOM 145	In Wall Insulation	no data
2025/04/11	CENTRAL BREAKROOM 145	Overhead Duct Insulation	no data
2025/04/11	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/04/11	CENTRAL BREAKROOM 145	Overhead Plumbing	no data
2025/04/11	CENTRAL BREAKROOM 145	Wall Drywall	no data
2025/04/11	CENTRAL BREAKROOM 145	Wall Drywall Finish	no data
2025/04/11	CENTRAL BREAKROOM 145	Wall Prime Paint	no data
2025/04/11	COLD CASE 175	In Wall Insulation	complete
2025/04/11	COLD CASE 175	Overhead Duct Insulation	in progress
2025/04/11	COLD CASE 175	Overhead Duct Rough In	in progress

2025/04/11	COLD CASE 175	Overhead Plumbing	in progress
2025/04/11	COLD CASE 175	Wall Drywall	complete
2025/04/11	COLD CASE 175	Wall Drywall Finish	complete
2025/04/11	COLD CASE 175	Wall Prime Paint	in progress
2025/04/11	COMMUNITY AFFAIRS 124	In Wall Insulation	complete
2025/04/11	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	in progress
2025/04/11	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	in progress
2025/04/11	COMMUNITY AFFAIRS 124	Overhead Plumbing	not started
2025/04/11	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/04/11	COMMUNITY AFFAIRS 124	Wall Drywall Finish	in progress
2025/04/11	COMMUNITY AFFAIRS 124	Wall Prime Paint	not started
2025/04/11	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	in progress
2025/04/11	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	in progress
2025/04/11	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	in progress
2025/04/11	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	not started
2025/04/11	COMMUNITY ROOM 247 PPL 102	Wall Drywall	in progress
2025/04/11	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	not started
2025/04/11	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	not started
2025/04/11	CONFERENCE ROOM 153	In Wall Insulation	no data
2025/04/11	CONFERENCE ROOM 153	Overhead Duct Insulation	no data
2025/04/11	CONFERENCE ROOM 153	Overhead Duct Rough In	no data
2025/04/11	CONFERENCE ROOM 153	Overhead Plumbing	no data
2025/04/11	CONFERENCE ROOM 153	Wall Drywall	no data
2025/04/11	CONFERENCE ROOM 153	Wall Drywall Finish	no data
2025/04/11	CONFERENCE ROOM 153	Wall Prime Paint	no data
2025/04/11	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/04/11	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	no data
2025/04/11	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	no data
2025/04/11	CONFERENCE/WAR ROOM 163	Overhead Plumbing	no data
2025/04/11	CONFERENCE/WAR ROOM 163	Wall Drywall	no data
2025/04/11	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	no data
2025/04/11	CONFERENCE/WAR ROOM 163	Wall Prime Paint	no data
2025/04/11	COPY 176	In Wall Insulation	complete
2025/04/11	COPY 176	Overhead Duct Insulation	in progress
2025/04/11	COPY 176	Overhead Duct Rough In	in progress
2025/04/11	COPY 176	Overhead Plumbing	not started
2025/04/11	COPY 176	Wall Drywall	complete
2025/04/11	COPY 176	Wall Drywall Finish	complete
2025/04/11	COPY 176	Wall Prime Paint	complete
2025/04/11	COPY/MAIL ROOM 114	In Wall Insulation	complete
2025/04/11	COPY/MAIL ROOM 114	Overhead Duct Insulation	not started

2025/04/11	COPY/MAIL ROOM 114	Overhead Duct Rough In	in progress
2025/04/11	COPY/MAIL ROOM 114	Overhead Plumbing	in progress
2025/04/11	COPY/MAIL ROOM 114	Wall Drywall	complete
2025/04/11	COPY/MAIL ROOM 114	Wall Drywall Finish	complete
2025/04/11	COPY/MAIL ROOM 114	Wall Prime Paint	not started
2025/04/11	CORRIDOR 107	In Wall Insulation	complete
2025/04/11	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/04/11	CORRIDOR 107	Overhead Duct Rough In	in progress
2025/04/11	CORRIDOR 107	Overhead Plumbing	not started
2025/04/11	CORRIDOR 107	Wall Drywall	complete
2025/04/11	CORRIDOR 107	Wall Drywall Finish	in progress
2025/04/11	CORRIDOR 107	Wall Prime Paint	not started
2025/04/11	CORRIDOR 108	In Wall Insulation	complete
2025/04/11	CORRIDOR 108	In Wall Insulation	in progress
2025/04/11	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/04/11	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/04/11	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/04/11	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/04/11	CORRIDOR 108	Overhead Plumbing	in progress
2025/04/11	CORRIDOR 108	Overhead Plumbing	not started
2025/04/11	CORRIDOR 108	Wall Drywall	complete
2025/04/11	CORRIDOR 108	Wall Drywall	in progress
2025/04/11	CORRIDOR 108	Wall Drywall Finish	in progress
2025/04/11	CORRIDOR 108	Wall Drywall Finish	in progress
2025/04/11	CORRIDOR 108	Wall Prime Paint	not started
2025/04/11	CORRIDOR 108	Wall Prime Paint	not started
2025/04/11	CORRIDOR 109	In Wall Insulation	in progress
2025/04/11	CORRIDOR 109	Overhead Duct Insulation	in progress
2025/04/11	CORRIDOR 109	Overhead Duct Rough In	in progress
2025/04/11	CORRIDOR 109	Overhead Plumbing	in progress
2025/04/11	CORRIDOR 109	Wall Drywall	in progress
2025/04/11	CORRIDOR 109	Wall Drywall Finish	in progress
2025/04/11	CORRIDOR 109	Wall Prime Paint	not started
2025/04/11	CORRIDOR 110	In Wall Insulation	complete
2025/04/11	CORRIDOR 110	In Wall Insulation	complete
2025/04/11	CORRIDOR 110	Overhead Duct Insulation	in progress
2025/04/11	CORRIDOR 110	Overhead Duct Insulation	in progress
2025/04/11	CORRIDOR 110	Overhead Duct Rough In	in progress
2025/04/11	CORRIDOR 110	Overhead Duct Rough In	in progress
2025/04/11	CORRIDOR 110	Overhead Plumbing	in progress
2025/04/11	CORRIDOR 110	Overhead Plumbing	in progress
2025/04/11	CORRIDOR 110	Wall Drywall	complete
2025/04/11	CORRIDOR 110	Wall Drywall	complete
2025/04/11	CORRIDOR 110	Wall Drywall Finish	in progress
2025/04/11	CORRIDOR 110	Wall Drywall Finish	in progress
2025/04/11	CORRIDOR 110	Wall Prime Paint	not started
2025/04/11	CORRIDOR 110	Wall Prime Paint	not started
2025/04/11	CORRIDOR 181	In Wall Insulation	in progress
2025/04/11	CORRIDOR 181	Overhead Duct Insulation	not started
2025/04/11	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/04/11	CORRIDOR 181	Overhead Plumbing	in progress
2025/04/11	CORRIDOR 181	Wall Drywall	in progress
2025/04/11	CORRIDOR 181	Wall Drywall Finish	not started

2025/04/11	CORRIDOR 181	Wall Prime Paint	not started
2025/04/11	CORRIDOR144	In Wall Insulation	in progress
2025/04/11	CORRIDOR144	Overhead Duct Insulation	in progress
2025/04/11	CORRIDOR144	Overhead Duct Rough In	in progress
2025/04/11	CORRIDOR144	Overhead Plumbing	in progress
2025/04/11	CORRIDOR144	Wall Drywall	in progress
2025/04/11	CORRIDOR144	Wall Drywall Finish	in progress
2025/04/11	CORRIDOR144	Wall Prime Paint	in progress
2025/04/11	CPL 173	In Wall Insulation	complete
2025/04/11	CPL 173	Overhead Duct Insulation	in progress
2025/04/11	CPL 173	Overhead Duct Rough In	in progress
2025/04/11	CPL 173	Overhead Plumbing	in progress
2025/04/11	CPL 173	Wall Drywall	in progress
2025/04/11	CPL 173	Wall Drywall Finish	in progress
2025/04/11	CPL 173	Wall Prime Paint	in progress
2025/04/11	CPL 174	In Wall Insulation	complete
2025/04/11	CPL 174	Overhead Duct Insulation	in progress
2025/04/11	CPL 174	Overhead Duct Rough In	in progress
2025/04/11	CPL 174	Overhead Plumbing	not started
2025/04/11	CPL 174	Wall Drywall	complete
2025/04/11	CPL 174	Wall Drywall Finish	complete
2025/04/11	CPL 174	Wall Prime Paint	in progress
2025/04/11	DRY STORAGE 146	In Wall Insulation	no data
2025/04/11	DRY STORAGE 146	Overhead Duct Insulation	no data
2025/04/11	DRY STORAGE 146	Overhead Duct Rough In	no data
2025/04/11	DRY STORAGE 146	Overhead Plumbing	no data
2025/04/11	DRY STORAGE 146	Wall Drywall	no data
2025/04/11	DRY STORAGE 146	Wall Drywall Finish	no data
2025/04/11	DRY STORAGE 146	Wall Prime Paint	no data
2025/04/11	FIRE RISER 178	In Wall Insulation	no data
2025/04/11	FIRE RISER 178	Overhead Duct Insulation	no data
2025/04/11	FIRE RISER 178	Overhead Duct Rough In	no data
2025/04/11	FIRE RISER 178	Overhead Plumbing	no data
2025/04/11	FIRE RISER 178	Wall Drywall	no data
2025/04/11	FIRE RISER 178	Wall Drywall Finish	no data
2025/04/11	FIRE RISER 178	Wall Prime Paint	no data
2025/04/11	GREETING ROOM 106	In Wall Insulation	complete
2025/04/11	GREETING ROOM 106	Overhead Duct Insulation	in progress
2025/04/11	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/04/11	GREETING ROOM 106	Overhead Plumbing	not started
2025/04/11	GREETING ROOM 106	Wall Drywall	complete
2025/04/11	GREETING ROOM 106	Wall Drywall Finish	in progress
2025/04/11	GREETING ROOM 106	Wall Prime Paint	not started
2025/04/11	HR 149	In Wall Insulation	no data
2025/04/11	HR 149	Overhead Duct Insulation	no data
2025/04/11	HR 149	Overhead Duct Rough In	no data
2025/04/11	HR 149	Overhead Plumbing	no data
2025/04/11	HR 149	Wall Drywall	no data
2025/04/11	HR 149	Wall Drywall Finish	no data
2025/04/11	HR 149	Wall Prime Paint	no data
2025/04/11	HR 150	In Wall Insulation	no data
2025/04/11	HR 150	Overhead Duct Insulation	no data

2025/04/11	HR 150	Overhead Duct Rough In	no data
2025/04/11	HR 150	Overhead Plumbing	no data
2025/04/11	HR 150	Wall Drywall	no data
2025/04/11	HR 150	Wall Drywall Finish	no data
2025/04/11	HR 150	Wall Prime Paint	no data
2025/04/11	HR 151	In Wall Insulation	no data
2025/04/11	HR 151	Overhead Duct Insulation	no data
2025/04/11	HR 151	Overhead Duct Rough In	no data
2025/04/11	HR 151	Overhead Plumbing	no data
2025/04/11	HR 151	Wall Drywall	no data
2025/04/11	HR 151	Wall Drywall Finish	no data
2025/04/11	HR 151	Wall Prime Paint	no data
2025/04/11	HR 154	In Wall Insulation	no data
2025/04/11	HR 154	Overhead Duct Insulation	no data
2025/04/11	HR 154	Overhead Duct Rough In	no data
2025/04/11	HR 154	Overhead Plumbing	no data
2025/04/11	HR 154	Wall Drywall	no data
2025/04/11	HR 154	Wall Drywall Finish	no data
2025/04/11	HR 154	Wall Prime Paint	no data
2025/04/11	HR 155	In Wall Insulation	no data
2025/04/11	HR 155	Overhead Duct Insulation	no data
2025/04/11	HR 155	Overhead Duct Rough In	no data
2025/04/11	HR 155	Overhead Plumbing	no data
2025/04/11	HR 155	Wall Drywall	no data
2025/04/11	HR 155	Wall Drywall Finish	no data
2025/04/11	HR 155	Wall Prime Paint	no data
2025/04/11	HR 156	In Wall Insulation	no data
2025/04/11	HR 156	Overhead Duct Insulation	no data
2025/04/11	HR 156	Overhead Duct Rough In	no data
2025/04/11	HR 156	Overhead Plumbing	no data
2025/04/11	HR 156	Wall Drywall	no data
2025/04/11	HR 156	Wall Drywall Finish	no data
2025/04/11	HR 156	Wall Prime Paint	no data
2025/04/11	HR 157	In Wall Insulation	not started
2025/04/11	HR 157	Overhead Duct Insulation	not started
2025/04/11	HR 157	Overhead Duct Rough In	in progress
2025/04/11	HR 157	Overhead Plumbing	in progress
2025/04/11	HR 157	Wall Drywall	not started
2025/04/11	HR 157	Wall Drywall Finish	not started
2025/04/11	HR 157	Wall Prime Paint	not started
2025/04/11	HUMAN RESOURCES 148	In Wall Insulation	not started
2025/04/11	HUMAN RESOURCES 148	Overhead Duct Insulation	not started
2025/04/11	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/04/11	HUMAN RESOURCES 148	Overhead Plumbing	not started
2025/04/11	HUMAN RESOURCES 148	Wall Drywall	not started
2025/04/11	HUMAN RESOURCES 148	Wall Drywall Finish	not started
2025/04/11	HUMAN RESOURCES 148	Wall Prime Paint	not started
2025/04/11	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/04/11	INTERNAL AFFAIRS 119	Overhead Duct Insulation	not started
2025/04/11	INTERNAL AFFAIRS 119	Overhead Duct Rough In	in progress

2025/04/11	INTERNAL AFFAIRS 119	Overhead Plumbing	no data
2025/04/11	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/04/11	INTERNAL AFFAIRS 119	Wall Drywall Finish	in progress
2025/04/11	INTERNAL AFFAIRS 119	Wall Prime Paint	not started
2025/04/11	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/04/11	INTERNAL AFFAIRS 120	Overhead Duct Insulation	in progress
2025/04/11	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/04/11	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/04/11	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/04/11	INTERNAL AFFAIRS 120	Wall Drywall Finish	in progress
2025/04/11	INTERNAL AFFAIRS 120	Wall Prime Paint	not started
2025/04/11	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	complete
2025/04/11	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	in progress
2025/04/11	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	in progress
2025/04/11	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	not started
2025/04/11	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/04/11	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	in progress
2025/04/11	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	not started
2025/04/11	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	complete
2025/04/11	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	in progress
2025/04/11	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	in progress
2025/04/11	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	in progress
2025/04/11	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/04/11	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	in progress
2025/04/11	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	not started
2025/04/11	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	complete
2025/04/11	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	in progress
2025/04/11	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	in progress
2025/04/11	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	in progress
2025/04/11	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/04/11	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/04/11	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	

complete

2025/04/11		IT 115		In Wall Insulation		in progress
2025/04/11		IT 115		Overhead Duct Insulation		not started
2025/04/11		IT 115		Overhead Duct Rough In		not started
2025/04/11		IT 115		Overhead Plumbing		in progress
2025/04/11		IT 115		Wall Drywall		in progress
2025/04/11		IT 115		Wall Drywall Finish		in progress
2025/04/11		IT 115		Wall Prime Paint		not started
2025/04/11		IT 135		In Wall Insulation		complete
2025/04/11		IT 135		Overhead Duct Insulation		in progress
2025/04/11		IT 135		Overhead Duct Rough In		in progress
2025/04/11		IT 135		Overhead Plumbing		in progress
2025/04/11		IT 135		Wall Drywall		complete
2025/04/11		IT 135		Wall Drywall Finish		in progress
2025/04/11		IT 135		Wall Prime Paint		not started
2025/04/11		IT MANAGER 136		In Wall Insulation		no data
2025/04/11		IT MANAGER 136		Overhead Duct Insulation		no data
2025/04/11		IT MANAGER 136		Overhead Duct Rough In		no data
2025/04/11		IT MANAGER 136		Overhead Plumbing		no data
2025/04/11		IT MANAGER 136		Wall Drywall		no data
2025/04/11		IT MANAGER 136		Wall Drywall Finish		no data
2025/04/11		IT MANAGER 136		Wall Prime Paint		no data
2025/04/11		IT MANAGER 137		In Wall Insulation		complete
2025/04/11		IT MANAGER 137		Overhead Duct Insulation		in progress
2025/04/11		IT MANAGER 137		Overhead Duct Rough In		in progress
2025/04/11		IT MANAGER 137		Overhead Plumbing		in progress
2025/04/11		IT MANAGER 137		Wall Drywall		complete
2025/04/11		IT MANAGER 137		Wall Drywall Finish		in progress
2025/04/11		IT MANAGER 137		Wall Prime Paint		not started
2025/04/11		JUVENILE INTERVIEW 165		In Wall Insulation		complete
2025/04/11		JUVENILE INTERVIEW 165		Overhead Duct Insulation		in progress
2025/04/11		JUVENILE INTERVIEW 165		Overhead Duct Rough In		in progress
2025/04/11		JUVENILE INTERVIEW 165		Overhead Plumbing		complete
2025/04/11		JUVENILE INTERVIEW 165		Wall Drywall		complete
2025/04/11		JUVENILE INTERVIEW 165		Wall Drywall Finish		complete
2025/04/11		JUVENILE INTERVIEW 165		Wall Prime Paint		complete
2025/04/11		JUVENILE INTERVIEWERS 166		In Wall Insulation		complete
2025/04/11		JUVENILE INTERVIEWERS 166		Overhead Duct Insulation		in progress
2025/04/11		JUVENILE INTERVIEWERS 166		Overhead Duct Rough In		in progress
2025/04/11		JUVENILE INTERVIEWERS 166		Overhead Plumbing		no data
2025/04/11		JUVENILE INTERVIEWERS 166		Wall Drywall		complete
2025/04/11		JUVENILE INTERVIEWERS 166		Wall Drywall Finish		complete
2025/04/11		JUVENILE INTERVIEWERS 166		Wall Prime Paint		in progress
2025/04/11		KEY ROOM 185		In Wall Insulation		in progress
2025/04/11		KEY ROOM 185		Overhead Duct Insulation		not started
2025/04/11		KEY ROOM 185		Overhead Duct Rough In		in progress

2025/04/11	KEY ROOM 185	Overhead Plumbing	no data
2025/04/11	KEY ROOM 185	Wall Drywall	in progress
2025/04/11	KEY ROOM 185	Wall Drywall Finish	not started
2025/04/11	KEY ROOM 185	Wall Prime Paint	not started
2025/04/11	LT 170	In Wall Insulation	complete
2025/04/11	LT 170	Overhead Duct Insulation	in progress
2025/04/11	LT 170	Overhead Duct Rough In	in progress
2025/04/11	LT 170	Overhead Plumbing	not started
2025/04/11	LT 170	Wall Drywall	complete
2025/04/11	LT 170	Wall Drywall Finish	complete
2025/04/11	LT 170	Wall Prime Paint	complete
2025/04/11	MACHINE ROOM 191	In Wall Insulation	complete
2025/04/11	MACHINE ROOM 191	Overhead Duct Insulation	not started
2025/04/11	MACHINE ROOM 191	Overhead Duct Rough In	in progress
2025/04/11	MACHINE ROOM 191	Overhead Plumbing	not started
2025/04/11	MACHINE ROOM 191	Wall Drywall	complete
2025/04/11	MACHINE ROOM 191	Wall Drywall Finish	in progress
2025/04/11	MACHINE ROOM 191	Wall Prime Paint	not started
2025/04/11	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/04/11	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/04/11	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/04/11	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/04/11	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/04/11	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/04/11	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/04/11	MAIN JANITORIAL111	In Wall Insulation	complete
2025/04/11	MAIN JANITORIAL111	Overhead Duct Insulation	in progress
2025/04/11	MAIN JANITORIAL111	Overhead Duct Rough In	in progress
2025/04/11	MAIN JANITORIAL111	Overhead Plumbing	in progress
2025/04/11	MAIN JANITORIAL111	Wall Drywall	complete
2025/04/11	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/04/11	MAIN JANITORIAL111	Wall Prime Paint	in progress
2025/04/11	MARINE SERGEANT 142	In Wall Insulation	complete
2025/04/11	MARINE SERGEANT 142	Overhead Duct Insulation	in progress
2025/04/11	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/04/11	MARINE SERGEANT 142	Overhead Plumbing	in progress
2025/04/11	MARINE SERGEANT 142	Wall Drywall	complete
2025/04/11	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/04/11	MARINE SERGEANT 142	Wall Prime Paint	not started
2025/04/11	MECHANICAL 192	In Wall Insulation	no data
2025/04/11	MECHANICAL 192	Overhead Duct Insulation	no data
2025/04/11	MECHANICAL 192	Overhead Duct Rough In	no data
2025/04/11	MECHANICAL 192	Overhead Plumbing	no data
2025/04/11	MECHANICAL 192	Wall Drywall	no data
2025/04/11	MECHANICAL 192	Wall Drywall Finish	no data
2025/04/11	MECHANICAL 192	Wall Prime Paint	no data



2025/04/11	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/04/11	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
2025/04/11	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/04/11	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/04/11	MECHANICAL ROOM 122	Wall Drywall	no data
2025/04/11	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/04/11	MECHANICAL ROOM 122	Wall Prime Paint	no data
2025/04/11	MENS RESTROOM 112	In Wall Insulation	in progress
2025/04/11	MENS RESTROOM 112	Overhead Duct Insulation	in progress
2025/04/11	MENS RESTROOM 112	Overhead Duct Rough In	in progress
2025/04/11	MENS RESTROOM 112	Overhead Plumbing	in progress
2025/04/11	MENS RESTROOM 112	Wall Drywall	not started
2025/04/11	MENS RESTROOM 112	Wall Drywall Finish	not started
2025/04/11	MENS RESTROOM 112	Wall Prime Paint	not started
2025/04/11	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
2025/04/11	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	no data
2025/04/11	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	no data
2025/04/11	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	no data
2025/04/11	MIS EQUIPMENT STORAGE 138	Wall Drywall	no data
2025/04/11	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	no data
2025/04/11	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	no data
2025/04/11	MIS SHREDDING 117	In Wall Insulation	in progress
2025/04/11	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/04/11	MIS SHREDDING 117	Overhead Duct Rough In	not started
2025/04/11	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/04/11	MIS SHREDDING 117	Wall Drywall	in progress
2025/04/11	MIS SHREDDING 117	Wall Drywall Finish	not started
2025/04/11	MIS SHREDDING 117	Wall Prime Paint	not started
2025/04/11	OFFICE 128	In Wall Insulation	complete
2025/04/11	OFFICE 128	Overhead Duct Insulation	in progress
2025/04/11	OFFICE 128	Overhead Duct Rough In	in progress
2025/04/11	OFFICE 128	Overhead Plumbing	not started
2025/04/11	OFFICE 128	Wall Drywall	complete
2025/04/11	OFFICE 128	Wall Drywall Finish	complete
2025/04/11	OFFICE 128	Wall Prime Paint	not started
2025/04/11	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	complete
2025/04/11	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	in progress
2025/04/11	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	in progress
2025/04/11	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	not started
2025/04/11	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete

2025/04/11	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	in progress
2025/04/11	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	not started
2025/04/11	PARTS STORAGE 189	In Wall Insulation	not started
2025/04/11	PARTS STORAGE 189	Overhead Duct Insulation	not started
2025/04/11	PARTS STORAGE 189	Overhead Duct Rough In	in progress
2025/04/11	PARTS STORAGE 189	Overhead Plumbing	not started
2025/04/11	PARTS STORAGE 189	Wall Drywall	in progress
2025/04/11	PARTS STORAGE 189	Wall Drywall Finish	in progress
2025/04/11	PARTS STORAGE 189	Wall Prime Paint	not started
2025/04/11	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/04/11	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/04/11	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/04/11	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/04/11	PUBLIC RESTROOM 106	Wall Drywall	no data
2025/04/11	PUBLIC RESTROOM 106	Wall Drywall Finish	no data
2025/04/11	PUBLIC RESTROOM 106	Wall Prime Paint	no data
2025/04/11	Polygraph 152	In Wall Insulation	no data
2025/04/11	Polygraph 152	Overhead Duct Insulation	no data
2025/04/11	Polygraph 152	Overhead Duct Rough In	no data
2025/04/11	Polygraph 152	Overhead Plumbing	no data
2025/04/11	Polygraph 152	Wall Drywall	no data
2025/04/11	Polygraph 152	Wall Drywall Finish	no data
2025/04/11	Polygraph 152	Wall Prime Paint	no data
2025/04/11	RECEPTION 101	In Wall Insulation	not started
2025/04/11	RECEPTION 101	Overhead Duct Insulation	not started
2025/04/11	RECEPTION 101	Overhead Duct Rough In	not started
2025/04/11	RECEPTION 101	Overhead Plumbing	not started
2025/04/11	RECEPTION 101	Wall Drywall	not started
2025/04/11	RECEPTION 101	Wall Drywall Finish	not started
2025/04/11	RECEPTION 101	Wall Prime Paint	not started
2025/04/11	RECEPTION 147	In Wall Insulation	in progress
2025/04/11	RECEPTION 147	Overhead Duct Insulation	in progress
2025/04/11	RECEPTION 147	Overhead Duct Rough In	in progress
2025/04/11	RECEPTION 147	Overhead Plumbing	in progress
2025/04/11	RECEPTION 147	Wall Drywall	in progress
2025/04/11	RECEPTION 147	Wall Drywall Finish	not started
2025/04/11	RECEPTION 147	Wall Prime Paint	no data
2025/04/11	RECEPTION 179	In Wall Insulation	in progress
2025/04/11	RECEPTION 179	Overhead Duct Insulation	not started
2025/04/11	RECEPTION 179	Overhead Duct Rough In	in progress
2025/04/11	RECEPTION 179	Overhead Plumbing	not started
2025/04/11	RECEPTION 179	Wall Drywall	in progress
2025/04/11	RECEPTION 179	Wall Drywall Finish	not started
2025/04/11	RECEPTION 179	Wall Prime Paint	not started
2025/04/11	RECORDS 130	In Wall Insulation	complete
2025/04/11	RECORDS 130	Overhead Duct Insulation	in progress
2025/04/11	RECORDS 130	Overhead Duct Rough In	in progress
2025/04/11	RECORDS 130	Overhead Plumbing	no data
2025/04/11	RECORDS 130	Wall Drywall	complete

2025/04/11	RECORDS 130	Wall Drywall Finish	in progress
2025/04/11	RECORDS 130	Wall Prime Paint	not started
2025/04/11	RECORDS STORAGE 133	In Wall Insulation	complete
2025/04/11	RECORDS STORAGE 133	Overhead Duct Insulation	in progress
2025/04/11	RECORDS STORAGE 133	Overhead Duct Rough In	in progress
2025/04/11	RECORDS STORAGE 133	Overhead Plumbing	not started
2025/04/11	RECORDS STORAGE 133	Wall Drywall	complete
2025/04/11	RECORDS STORAGE 133	Wall Drywall Finish	in progress
2025/04/11	RECORDS STORAGE 133	Wall Prime Paint	not started
2025/04/11	RECORDS SUPERVISOR 131	In Wall Insulation	complete
2025/04/11	RECORDS SUPERVISOR 131	Overhead Duct Insulation	in progress
2025/04/11	RECORDS SUPERVISOR 131	Overhead Duct Rough In	in progress
2025/04/11	RECORDS SUPERVISOR 131	Overhead Plumbing	not started
2025/04/11	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/04/11	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/04/11	RECORDS SUPERVISOR 131	Wall Prime Paint	not started
2025/04/11	RECORDS SUPERVISOR 132	In Wall Insulation	complete
2025/04/11	RECORDS SUPERVISOR 132	Overhead Duct Insulation	in progress
2025/04/11	RECORDS SUPERVISOR 132	Overhead Duct Rough In	in progress
2025/04/11	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/04/11	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/04/11	RECORDS SUPERVISOR 132	Wall Drywall Finish	in progress
2025/04/11	RECORDS SUPERVISOR 132	Wall Prime Paint	not started
2025/04/11	RESTROOM 183	In Wall Insulation	in progress
2025/04/11	RESTROOM 183	Overhead Duct Insulation	in progress
2025/04/11	RESTROOM 183	Overhead Duct Rough In	in progress
2025/04/11	RESTROOM 183	Overhead Plumbing	in progress
2025/04/11	RESTROOM 183	Wall Drywall	not started
2025/04/11	RESTROOM 183	Wall Drywall Finish	not started
2025/04/11	RESTROOM 183	Wall Prime Paint	not started
2025/04/11	Risk Management - 158	In Wall Insulation	no data
2025/04/11	Risk Management - 158	Overhead Duct Insulation	no data
2025/04/11	Risk Management - 158	Overhead Duct Rough In	no data
2025/04/11	Risk Management - 158	Overhead Plumbing	no data
2025/04/11	Risk Management - 158	Wall Drywall	no data
2025/04/11	Risk Management - 158	Wall Drywall Finish	no data
2025/04/11	Risk Management - 158	Wall Prime Paint	no data
2025/04/11	SALLY PORT 105	In Wall Insulation	not started
2025/04/11	SALLY PORT 105	Overhead Duct Insulation	not started
2025/04/11	SALLY PORT 105	Overhead Duct Rough In	not started
2025/04/11	SALLY PORT 105	Overhead Plumbing	not started
2025/04/11	SALLY PORT 105	Wall Drywall	not started
2025/04/11	SALLY PORT 105	Wall Drywall Finish	not started
2025/04/11	SALLY PORT 105	Wall Prime Paint	not started

2025/04/11	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/04/11	SANE EXAM ROOM 168	Overhead Duct Insulation	in progress
2025/04/11	SANE EXAM ROOM 168	Overhead Duct Rough In	in progress
2025/04/11	SANE EXAM ROOM 168	Overhead Plumbing	complete
2025/04/11	SANE EXAM ROOM 168	Wall Drywall	complete
2025/04/11	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/04/11	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/04/11	SGT 171	In Wall Insulation	complete
2025/04/11	SGT 171	Overhead Duct Insulation	in progress
2025/04/11	SGT 171	Overhead Duct Rough In	in progress
2025/04/11	SGT 171	Overhead Plumbing	in progress
2025/04/11	SGT 171	Wall Drywall	complete
2025/04/11	SGT 171	Wall Drywall Finish	complete
2025/04/11	SGT 171	Wall Prime Paint	complete
2025/04/11	SGT 172	In Wall Insulation	complete
2025/04/11	SGT 172	Overhead Duct Insulation	in progress
2025/04/11	SGT 172	Overhead Duct Rough In	in progress
2025/04/11	SGT 172	Overhead Plumbing	in progress
2025/04/11	SGT 172	Wall Drywall	complete
2025/04/11	SGT 172	Wall Drywall Finish	complete
2025/04/11	SGT 172	Wall Prime Paint	complete
2025/04/11	SHIPPING STORAGE 190	In Wall Insulation	no data
2025/04/11	SHIPPING STORAGE 190	Overhead Duct Insulation	no data
2025/04/11	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/04/11	SHIPPING STORAGE 190	Overhead Plumbing	no data
2025/04/11	SHIPPING STORAGE 190	Wall Drywall	no data
2025/04/11	SHIPPING STORAGE 190	Wall Drywall Finish	no data
2025/04/11	SHIPPING STORAGE 190	Wall Prime Paint	no data
2025/04/11	SHOP FORMAN 184	In Wall Insulation	in progress
2025/04/11	SHOP FORMAN 184	Overhead Duct Insulation	not started
2025/04/11	SHOP FORMAN 184	Overhead Duct Rough In	in progress
2025/04/11	SHOP FORMAN 184	Overhead Plumbing	not started
2025/04/11	SHOP FORMAN 184	Wall Drywall	in progress
2025/04/11	SHOP FORMAN 184	Wall Drywall Finish	not started
2025/04/11	SHOP FORMAN 184	Wall Prime Paint	not started
2025/04/11	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/04/11	SOFT INTERVIEW 161	Overhead Duct Insulation	in progress
2025/04/11	SOFT INTERVIEW 161	Overhead Duct Rough In	in progress
2025/04/11	SOFT INTERVIEW 161	Overhead Plumbing	no data
2025/04/11	SOFT INTERVIEW 161	Wall Drywall	complete
2025/04/11	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/04/11	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/04/11	SOFT INTERVIEW 162	In Wall Insulation	complete
2025/04/11	SOFT INTERVIEW 162	Overhead Duct Insulation	in progress
2025/04/11	SOFT INTERVIEW 162	Overhead Duct Rough In	in progress
2025/04/11	SOFT INTERVIEW 162	Overhead Plumbing	not started

2025/04/11		SOFT INTERVIEW 162		Wall Drywall		complete
2025/04/11		SOFT INTERVIEW 162		Wall Drywall Finish		complete
2025/04/11		SOFT INTERVIEW 162		Wall Prime Paint		complete
2025/04/11		SPECIAL OPERATION LT 143		In Wall Insulation		complete
2025/04/11		SPECIAL OPERATION LT 143		Overhead Duct Insulation		in progress
2025/04/11		SPECIAL OPERATION LT 143		Overhead Duct Rough In		in progress
2025/04/11		SPECIAL OPERATION LT 143		Overhead Plumbing		no data
2025/04/11		SPECIAL OPERATION LT 143		Wall Drywall		complete
2025/04/11		SPECIAL OPERATION LT 143		Wall Drywall Finish		complete
2025/04/11		SPECIAL OPERATION LT 143		Wall Prime Paint		not started
2025/04/11		STAIR A		In Wall Insulation		no data
2025/04/11		STAIR A		Overhead Duct Insulation		no data
2025/04/11		STAIR A		Overhead Duct Rough In		no data
2025/04/11		STAIR A		Overhead Plumbing		no data
2025/04/11		STAIR A		Wall Drywall		no data
2025/04/11		STAIR A		Wall Drywall Finish		no data
2025/04/11		STAIR A		Wall Prime Paint		no data
2025/04/11		STORAGE 104		In Wall Insulation		in progress
2025/04/11		STORAGE 104		Overhead Duct Insulation		in progress
2025/04/11		STORAGE 104		Overhead Duct Rough In		in progress
2025/04/11		STORAGE 104		Overhead Plumbing		not started
2025/04/11		STORAGE 104		Wall Drywall		in progress
2025/04/11		STORAGE 104		Wall Drywall Finish		in progress
2025/04/11		STORAGE 104		Wall Prime Paint		not started
2025/04/11		STORAGE 127		In Wall Insulation		complete
2025/04/11		STORAGE 127		Overhead Duct Insulation		in progress
2025/04/11		STORAGE 127		Overhead Duct Rough In		in progress
2025/04/11		STORAGE 127		Overhead Plumbing		no data
2025/04/11		STORAGE 127		Wall Drywall		complete
2025/04/11		STORAGE 127		Wall Drywall Finish		in progress
2025/04/11		STORAGE 127		Wall Prime Paint		not started
2025/04/11		STUDIO 126		In Wall Insulation		complete
2025/04/11		STUDIO 126		Overhead Duct Insulation		in progress
2025/04/11		STUDIO 126		Overhead Duct Rough In		in progress
2025/04/11		STUDIO 126		Overhead Plumbing		no data
2025/04/11		STUDIO 126		Wall Drywall		complete
2025/04/11		STUDIO 126		Wall Drywall Finish		in progress
2025/04/11		STUDIO 126		Wall Prime Paint		not started
2025/04/11		SUPERVISOR 129		In Wall Insulation		complete
2025/04/11		SUPERVISOR 129		Overhead Duct Insulation		in progress
2025/04/11		SUPERVISOR 129		Overhead Duct Rough In		in progress
2025/04/11		SUPERVISOR 129		Overhead Plumbing		not started
2025/04/11		SUPERVISOR 129		Wall Drywall		complete
2025/04/11		SUPERVISOR 129		Wall Drywall Finish		in progress
2025/04/11		SUPERVISOR 129		Wall Prime Paint		not started
2025/04/11		Storage 164		In Wall Insulation		no data
2025/04/11		Storage 164		Overhead Duct Insulation		no data
2025/04/11		Storage 164		Overhead Duct Rough In		no data
2025/04/11		Storage 164		Overhead Plumbing		no data

2025/04/11	Storage 164	Wall Drywall	no data
2025/04/11	Storage 164	Wall Drywall Finish	no data
2025/04/11	Storage 164	Wall Prime Paint	no data
2025/04/11	Storage 177	In Wall Insulation	complete
2025/04/11	Storage 177	Overhead Duct Insulation	in progress
2025/04/11	Storage 177	Overhead Duct Rough In	in progress
2025/04/11	Storage 177	Overhead Plumbing	not started
2025/04/11	Storage 177	Wall Drywall	complete
2025/04/11	Storage 177	Wall Drywall Finish	complete
2025/04/11	Storage 177	Wall Prime Paint	complete
2025/04/11	TECHNICAL SURVEILLANCE 188	In Wall Insulation	in progress
2025/04/11	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	not started
2025/04/11	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	in progress
2025/04/11	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	not started
2025/04/11	TECHNICAL SURVEILLANCE 188	Wall Drywall	in progress
2025/04/11	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	not started
2025/04/11	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	not started
2025/04/11	TRAFFIC SERGEANT 141	In Wall Insulation	complete
2025/04/11	TRAFFIC SERGEANT 141	Overhead Duct Insulation	in progress
2025/04/11	TRAFFIC SERGEANT 141	Overhead Duct Rough In	in progress
2025/04/11	TRAFFIC SERGEANT 141	Overhead Plumbing	in progress
2025/04/11	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/04/11	TRAFFIC SERGEANT 141	Wall Drywall Finish	in progress
2025/04/11	TRAFFIC SERGEANT 141	Wall Prime Paint	not started
2025/04/11	TRIAGE/RECEPTION 134	In Wall Insulation	complete
2025/04/11	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/04/11	TRIAGE/RECEPTION 134	Overhead Duct Rough In	in progress
2025/04/11	TRIAGE/RECEPTION 134	Overhead Plumbing	no data
2025/04/11	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/04/11	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/04/11	TRIAGE/RECEPTION 134	Wall Prime Paint	not started
2025/04/11	TST WORKSHOP 187	In Wall Insulation	in progress
2025/04/11	TST WORKSHOP 187	Overhead Duct Insulation	not started
2025/04/11	TST WORKSHOP 187	Overhead Duct Rough In	in progress
2025/04/11	TST WORKSHOP 187	Overhead Plumbing	not started
2025/04/11	TST WORKSHOP 187	Wall Drywall	in progress
2025/04/11	TST WORKSHOP 187	Wall Drywall Finish	not started
2025/04/11	TST WORKSHOP 187	Wall Prime Paint	not started
2025/04/11	UNISEX RESTROOM 169	In Wall Insulation	in progress
2025/04/11	UNISEX RESTROOM 169	Overhead Duct Insulation	in progress
2025/04/11	UNISEX RESTROOM 169	Overhead Duct Rough In	in progress

progress

2025/04/11		UNISEX RESTROOM 169		Overhead Plumbing		in progress
2025/04/11		UNISEX RESTROOM 169		Wall Drywall		in progress
2025/04/11		UNISEX RESTROOM 169		Wall Drywall Finish		not started
2025/04/11		UNISEX RESTROOM 169		Wall Prime Paint		not started
2025/04/11		VEHICLE MAINTENANCE BAYS 186		In Wall Insulation		in progress
2025/04/11		VEHICLE MAINTENANCE BAYS 186		Overhead Duct Insulation		not started
2025/04/11		VEHICLE MAINTENANCE BAYS 186		Overhead Duct Rough In		not started
2025/04/11		VEHICLE MAINTENANCE BAYS 186		Overhead Plumbing		complete
2025/04/11		VEHICLE MAINTENANCE BAYS 186		Wall Drywall		in progress
2025/04/11		VEHICLE MAINTENANCE BAYS 186		Wall Drywall Finish		in progress
2025/04/11		VEHICLE MAINTENANCE BAYS 186		Wall Prime Paint		not started
2025/04/11		VOLUNTEER/LIGHT DUTY 140		In Wall Insulation		complete
2025/04/11		VOLUNTEER/LIGHT DUTY 140		Overhead Duct Insulation		in progress
2025/04/11		VOLUNTEER/LIGHT DUTY 140		Overhead Duct Rough In		in progress
2025/04/11		VOLUNTEER/LIGHT DUTY 140		Overhead Plumbing		in progress
2025/04/11		VOLUNTEER/LIGHT DUTY 140		Wall Drywall		complete
2025/04/11		VOLUNTEER/LIGHT DUTY 140		Wall Drywall Finish		in progress
2025/04/11		VOLUNTEER/LIGHT DUTY 140		Wall Prime Paint		not started
2025/04/11		WAITING/LOBBY 100		In Wall Insulation		no data
2025/04/11		WAITING/LOBBY 100		Overhead Duct Insulation		no data
2025/04/11		WAITING/LOBBY 100		Overhead Duct Rough In		no data
2025/04/11		WAITING/LOBBY 100		Overhead Plumbing		no data
2025/04/11		WAITING/LOBBY 100		Wall Drywall		no data
2025/04/11		WAITING/LOBBY 100		Wall Drywall Finish		no data
2025/04/11		WAITING/LOBBY 100		Wall Prime Paint		no data
2025/04/11		WOMENS RESTROOM 113		In Wall Insulation		in progress
2025/04/11		WOMENS RESTROOM 113		Overhead Duct Insulation		in progress
2025/04/11		WOMENS RESTROOM 113		Overhead Duct Rough In		in progress
2025/04/11		WOMENS RESTROOM 113		Overhead Plumbing		in progress
2025/04/11		WOMENS RESTROOM 113		Wall Drywall		not started
2025/04/11		WOMENS RESTROOM 113		Wall Drywall Finish		not started
2025/04/11		WOMENS RESTROOM 113		Wall Prime Paint		not started
2025/04/25		ADMIN ASSISTANT 125		In Wall Insulation		no data
2025/04/25		ADMIN ASSISTANT 125		Overhead Duct Insulation		no data
2025/04/25		ADMIN ASSISTANT 125		Overhead Duct Rough In		no data
2025/04/25		ADMIN ASSISTANT 125		Overhead Plumbing		not started
2025/04/25		ADMIN ASSISTANT 125		Wall Drywall		no data

2025/04/25	ADMIN ASSISTANT 125	Wall Drywall Finish	no data
2025/04/25	ADMIN ASSISTANT 125	Wall Prime Paint	no data
2025/04/25	AV ROOM 103	In Wall Insulation	complete
2025/04/25	AV ROOM 103	Overhead Duct Insulation	in progress
2025/04/25	AV ROOM 103	Overhead Duct Rough In	in progress
2025/04/25	AV ROOM 103	Overhead Plumbing	not started
2025/04/25	AV ROOM 103	Wall Drywall	in progress
2025/04/25	AV ROOM 103	Wall Drywall Finish	in progress
2025/04/25	AV ROOM 103	Wall Prime Paint	not started
2025/04/25	BREAK ROOM CONFERENCE 182	In Wall Insulation	in progress
2025/04/25	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	in progress
2025/04/25	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	in progress
2025/04/25	BREAK ROOM CONFERENCE 182	Overhead Plumbing	in progress
2025/04/25	BREAK ROOM CONFERENCE 182	Wall Drywall	in progress
2025/04/25	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	not started
2025/04/25	BREAK ROOM CONFERENCE 182	Wall Prime Paint	not started
2025/04/25	Background-159	In Wall Insulation	no data
2025/04/25	Background-159	Overhead Duct Insulation	no data
2025/04/25	Background-159	Overhead Duct Rough In	no data
2025/04/25	Background-159	Overhead Plumbing	no data
2025/04/25	Background-159	Wall Drywall	no data
2025/04/25	Background-159	Wall Drywall Finish	no data
2025/04/25	Background-159	Wall Prime Paint	no data
2025/04/25	CENTRAL BREAKROOM 145	In Wall Insulation	not started
2025/04/25	CENTRAL BREAKROOM 145	Overhead Duct Insulation	not started
2025/04/25	CENTRAL BREAKROOM 145	Overhead Duct Rough In	in progress
2025/04/25	CENTRAL BREAKROOM 145	Overhead Plumbing	not started
2025/04/25	CENTRAL BREAKROOM 145	Wall Drywall	not started
2025/04/25	CENTRAL BREAKROOM 145	Wall Drywall Finish	not started
2025/04/25	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/04/25	COLD CASE 175	In Wall Insulation	complete
2025/04/25	COLD CASE 175	Overhead Duct Insulation	in progress
2025/04/25	COLD CASE 175	Overhead Duct Rough In	in progress
2025/04/25	COLD CASE 175	Overhead Plumbing	in progress
2025/04/25	COLD CASE 175	Wall Drywall	complete
2025/04/25	COLD CASE 175	Wall Drywall Finish	complete
2025/04/25	COLD CASE 175	Wall Prime Paint	in progress
2025/04/25	COMMUNITY AFFAIRS 124	In Wall Insulation	complete
2025/04/25	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	in progress
2025/04/25	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	in progress
2025/04/25	COMMUNITY AFFAIRS 124	Overhead Plumbing	not started
2025/04/25	COMMUNITY AFFAIRS 124	Wall Drywall	complete



2025/04/25	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/04/25	COMMUNITY AFFAIRS 124	Wall Prime Paint	not started
2025/04/25	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	in progress
2025/04/25	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	in progress
2025/04/25	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	in progress
2025/04/25	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	not started
2025/04/25	COMMUNITY ROOM 247 PPL 102	Wall Drywall	in progress
2025/04/25	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	not started
2025/04/25	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	not started
2025/04/25	CONFERENCE ROOM 153	In Wall Insulation	in progress
2025/04/25	CONFERENCE ROOM 153	Overhead Duct Insulation	not started
2025/04/25	CONFERENCE ROOM 153	Overhead Duct Rough In	in progress
2025/04/25	CONFERENCE ROOM 153	Overhead Plumbing	not started
2025/04/25	CONFERENCE ROOM 153	Wall Drywall	in progress
2025/04/25	CONFERENCE ROOM 153	Wall Drywall Finish	not started
2025/04/25	CONFERENCE ROOM 153	Wall Prime Paint	not started
2025/04/25	CONFERENCE/WAR ROOM 163	In Wall Insulation	complete
2025/04/25	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	in progress
2025/04/25	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	in progress
2025/04/25	CONFERENCE/WAR ROOM 163	Overhead Plumbing	not started
2025/04/25	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/04/25	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete
2025/04/25	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/04/25	COPY 176	In Wall Insulation	complete
2025/04/25	COPY 176	Overhead Duct Insulation	in progress
2025/04/25	COPY 176	Overhead Duct Rough In	in progress
2025/04/25	COPY 176	Overhead Plumbing	not started
2025/04/25	COPY 176	Wall Drywall	complete
2025/04/25	COPY 176	Wall Drywall Finish	complete
2025/04/25	COPY 176	Wall Prime Paint	complete
2025/04/25	COPY/MAIL ROOM 114	In Wall Insulation	complete
2025/04/25	COPY/MAIL ROOM 114	Overhead Duct Insulation	not started
2025/04/25	COPY/MAIL ROOM 114	Overhead Duct Rough In	in progress
2025/04/25	COPY/MAIL ROOM 114	Overhead Plumbing	in progress
2025/04/25	COPY/MAIL ROOM 114	Wall Drywall	complete
2025/04/25	COPY/MAIL ROOM 114	Wall Drywall Finish	complete
2025/04/25	COPY/MAIL ROOM 114	Wall Prime Paint	complete
2025/04/25	CORRIDOR 107	In Wall Insulation	complete
2025/04/25	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/04/25	CORRIDOR 107	Overhead Duct Rough In	in progress

2025/04/25	CORRIDOR 107	Overhead Plumbing   not started
2025/04/25	CORRIDOR 107	Wall Drywall   complete
2025/04/25	CORRIDOR 107	Wall Drywall Finish   complete
2025/04/25	CORRIDOR 107	Wall Prime Paint   in progress
2025/04/25	CORRIDOR 108	In Wall Insulation   complete
2025/04/25	CORRIDOR 108	In Wall Insulation   complete
2025/04/25	CORRIDOR 108	Overhead Duct Insulation   in progress
2025/04/25	CORRIDOR 108	Overhead Duct Insulation   in progress
2025/04/25	CORRIDOR 108	Overhead Duct Rough In   in progress
2025/04/25	CORRIDOR 108	Overhead Duct Rough In   in progress
2025/04/25	CORRIDOR 108	Overhead Plumbing   in progress
2025/04/25	CORRIDOR 108	Overhead Plumbing   not started
2025/04/25	CORRIDOR 108	Wall Drywall   complete
2025/04/25	CORRIDOR 108	Wall Drywall   complete
2025/04/25	CORRIDOR 108	Wall Drywall Finish   in progress
2025/04/25	CORRIDOR 108	Wall Drywall Finish   in progress
2025/04/25	CORRIDOR 108	Wall Prime Paint   in progress
2025/04/25	CORRIDOR 108	Wall Prime Paint   in progress
2025/04/25	CORRIDOR 109	In Wall Insulation   in progress
2025/04/25	CORRIDOR 109	Overhead Duct Insulation   in progress
2025/04/25	CORRIDOR 109	Overhead Duct Rough In   in progress
2025/04/25	CORRIDOR 109	Overhead Plumbing   in progress
2025/04/25	CORRIDOR 109	Wall Drywall   in progress
2025/04/25	CORRIDOR 109	Wall Drywall Finish   in progress
2025/04/25	CORRIDOR 109	Wall Prime Paint   in progress
2025/04/25	CORRIDOR 110	In Wall Insulation   complete
2025/04/25	CORRIDOR 110	In Wall Insulation   complete
2025/04/25	CORRIDOR 110	Overhead Duct Insulation   in progress
2025/04/25	CORRIDOR 110	Overhead Duct Insulation   in progress
2025/04/25	CORRIDOR 110	Overhead Duct Rough In   in progress
2025/04/25	CORRIDOR 110	Overhead Duct Rough In   in progress
2025/04/25	CORRIDOR 110	Overhead Plumbing   in progress
2025/04/25	CORRIDOR 110	Overhead Plumbing   in progress
2025/04/25	CORRIDOR 110	Wall Drywall   complete
2025/04/25	CORRIDOR 110	Wall Drywall   complete
2025/04/25	CORRIDOR 110	Wall Drywall Finish   in progress
2025/04/25	CORRIDOR 110	Wall Drywall Finish   in progress
2025/04/25	CORRIDOR 110	Wall Prime Paint   in progress
2025/04/25	CORRIDOR 110	Wall Prime Paint   in progress
2025/04/25	CORRIDOR 181	In Wall Insulation   in progress
2025/04/25	CORRIDOR 181	Overhead Duct Insulation   not started
2025/04/25	CORRIDOR 181	Overhead Duct Rough In   in progress
2025/04/25	CORRIDOR 181	Overhead Plumbing   in progress
2025/04/25	CORRIDOR 181	Wall Drywall   in progress
2025/04/25	CORRIDOR 181	Wall Drywall Finish   not started
2025/04/25	CORRIDOR 181	Wall Prime Paint   not started
2025/04/25	CORRIDOR144	In Wall Insulation   in progress
2025/04/25	CORRIDOR144	Overhead Duct Insulation   in progress
2025/04/25	CORRIDOR144	Overhead Duct Rough In   in progress
2025/04/25	CORRIDOR144	Overhead Plumbing   in progress
2025/04/25	CORRIDOR144	Wall Drywall   in progress
2025/04/25	CORRIDOR144	Wall Drywall Finish   in progress
2025/04/25	CORRIDOR144	Wall Prime Paint   in progress
2025/04/25	CPL 173	In Wall Insulation   complete

2025/04/25	CPL 173	Overhead Duct Insulation	in progress
2025/04/25	CPL 173	Overhead Duct Rough In	in progress
2025/04/25	CPL 173	Overhead Plumbing	in progress
2025/04/25	CPL 173	Wall Drywall	in progress
2025/04/25	CPL 173	Wall Drywall Finish	in progress
2025/04/25	CPL 173	Wall Prime Paint	in progress
2025/04/25	CPL 174	In Wall Insulation	complete
2025/04/25	CPL 174	Overhead Duct Insulation	in progress
2025/04/25	CPL 174	Overhead Duct Rough In	in progress
2025/04/25	CPL 174	Overhead Plumbing	not started
2025/04/25	CPL 174	Wall Drywall	complete
2025/04/25	CPL 174	Wall Drywall Finish	complete
2025/04/25	CPL 174	Wall Prime Paint	in progress
2025/04/25	DRY STORAGE 146	In Wall Insulation	no data
2025/04/25	DRY STORAGE 146	Overhead Duct Insulation	no data
2025/04/25	DRY STORAGE 146	Overhead Duct Rough In	no data
2025/04/25	DRY STORAGE 146	Overhead Plumbing	no data
2025/04/25	DRY STORAGE 146	Wall Drywall	no data
2025/04/25	DRY STORAGE 146	Wall Drywall Finish	no data
2025/04/25	DRY STORAGE 146	Wall Prime Paint	no data
2025/04/25	FIRE RISER 178	In Wall Insulation	no data
2025/04/25	FIRE RISER 178	Overhead Duct Insulation	no data
2025/04/25	FIRE RISER 178	Overhead Duct Rough In	no data
2025/04/25	FIRE RISER 178	Overhead Plumbing	no data
2025/04/25	FIRE RISER 178	Wall Drywall	no data
2025/04/25	FIRE RISER 178	Wall Drywall Finish	no data
2025/04/25	FIRE RISER 178	Wall Prime Paint	no data
2025/04/25	GREETING ROOM 106	In Wall Insulation	complete
2025/04/25	GREETING ROOM 106	Overhead Duct Insulation	in progress
2025/04/25	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/04/25	GREETING ROOM 106	Overhead Plumbing	not started
2025/04/25	GREETING ROOM 106	Wall Drywall	complete
2025/04/25	GREETING ROOM 106	Wall Drywall Finish	complete
2025/04/25	GREETING ROOM 106	Wall Prime Paint	complete
2025/04/25	HR 149	In Wall Insulation	not started
2025/04/25	HR 149	Overhead Duct Insulation	not started
2025/04/25	HR 149	Overhead Duct Rough In	in progress
2025/04/25	HR 149	Overhead Plumbing	not started
2025/04/25	HR 149	Wall Drywall	not started
2025/04/25	HR 149	Wall Drywall Finish	not started
2025/04/25	HR 149	Wall Prime Paint	not started
2025/04/25	HR 150	In Wall Insulation	not started
2025/04/25	HR 150	Overhead Duct Insulation	not started
2025/04/25	HR 150	Overhead Duct Rough In	in progress
2025/04/25	HR 150	Overhead Plumbing	not started
2025/04/25	HR 150	Wall Drywall	not started
2025/04/25	HR 150	Wall Drywall Finish	not started
2025/04/25	HR 150	Wall Prime Paint	not started
2025/04/25	HR 151	In Wall Insulation	not started
2025/04/25	HR 151	Overhead Duct Insulation	not started
2025/04/25	HR 151	Overhead Duct Rough In	in progress
2025/04/25	HR 151	Overhead Plumbing	in progress

2025/04/25	HR 151	Wall Drywall	not started
2025/04/25	HR 151	Wall Drywall Finish	not started
2025/04/25	HR 151	Wall Prime Paint	not started
2025/04/25	HR 154	In Wall Insulation	no data
2025/04/25	HR 154	Overhead Duct Insulation	no data
2025/04/25	HR 154	Overhead Duct Rough In	no data
2025/04/25	HR 154	Overhead Plumbing	no data
2025/04/25	HR 154	Wall Drywall	no data
2025/04/25	HR 154	Wall Drywall Finish	no data
2025/04/25	HR 154	Wall Prime Paint	no data
2025/04/25	HR 155	In Wall Insulation	not started
2025/04/25	HR 155	Overhead Duct Insulation	in progress
2025/04/25	HR 155	Overhead Duct Rough In	in progress
2025/04/25	HR 155	Overhead Plumbing	not started
2025/04/25	HR 155	Wall Drywall	not started
2025/04/25	HR 155	Wall Drywall Finish	not started
2025/04/25	HR 155	Wall Prime Paint	not started
2025/04/25	HR 156	In Wall Insulation	not started
2025/04/25	HR 156	Overhead Duct Insulation	not started
2025/04/25	HR 156	Overhead Duct Rough In	in progress
2025/04/25	HR 156	Overhead Plumbing	not started
2025/04/25	HR 156	Wall Drywall	not started
2025/04/25	HR 156	Wall Drywall Finish	not started
2025/04/25	HR 156	Wall Prime Paint	not started
2025/04/25	HR 157	In Wall Insulation	not started
2025/04/25	HR 157	Overhead Duct Insulation	not started
2025/04/25	HR 157	Overhead Duct Rough In	in progress
2025/04/25	HR 157	Overhead Plumbing	in progress
2025/04/25	HR 157	Wall Drywall	not started
2025/04/25	HR 157	Wall Drywall Finish	not started
2025/04/25	HR 157	Wall Prime Paint	not started
2025/04/25	HUMAN RESOURCES 148	In Wall Insulation	not started
2025/04/25	HUMAN RESOURCES 148	Overhead Duct Insulation	not started
2025/04/25	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/04/25	HUMAN RESOURCES 148	Overhead Plumbing	not started
2025/04/25	HUMAN RESOURCES 148	Wall Drywall	not started
2025/04/25	HUMAN RESOURCES 148	Wall Drywall Finish	not started
2025/04/25	HUMAN RESOURCES 148	Wall Prime Paint	not started
2025/04/25	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/04/25	INTERNAL AFFAIRS 119	Overhead Duct Insulation	not started
2025/04/25	INTERNAL AFFAIRS 119	Overhead Duct Rough In	in progress
2025/04/25	INTERNAL AFFAIRS 119	Overhead Plumbing	in progress
2025/04/25	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/04/25	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/04/25	INTERNAL AFFAIRS 119	Wall Prime Paint	in progress
2025/04/25	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/04/25	INTERNAL AFFAIRS 120	Overhead Duct Insulation	in progress
2025/04/25	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress

2025/04/25	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/04/25	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/04/25	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/04/25	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/04/25	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	complete
2025/04/25	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	in progress
2025/04/25	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	in progress
2025/04/25	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	not started
2025/04/25	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/04/25	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/04/25	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/04/25	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	complete
2025/04/25	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	in progress
2025/04/25	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	in progress
2025/04/25	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	in progress
2025/04/25	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/04/25	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	complete
2025/04/25	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	complete
2025/04/25	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	complete
2025/04/25	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	in progress
2025/04/25	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	in progress
2025/04/25	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	in progress
2025/04/25	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/04/25	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/04/25	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	complete
2025/04/25	IT 115	In Wall Insulation	complete
2025/04/25	IT 115	Overhead Duct Insulation	not started
2025/04/25	IT 115	Overhead Duct Rough In	not started
2025/04/25	IT 115	Overhead Plumbing	in progress
2025/04/25	IT 115	Wall Drywall	complete
2025/04/25	IT 115	Wall Drywall Finish	in progress
2025/04/25	IT 115	Wall Prime Paint	in progress
2025/04/25	IT 135	In Wall Insulation	complete
2025/04/25	IT 135	Overhead Duct Insulation	in progress
2025/04/25	IT 135	Overhead Duct Rough In	in progress

2025/04/25	IT 135	Overhead Plumbing	in progress
2025/04/25	IT 135	Wall Drywall	complete
2025/04/25	IT 135	Wall Drywall Finish	complete
2025/04/25	IT 135	Wall Prime Paint	complete
2025/04/25	IT MANAGER 136	In Wall Insulation	no data
2025/04/25	IT MANAGER 136	Overhead Duct Insulation	no data
2025/04/25	IT MANAGER 136	Overhead Duct Rough In	no data
2025/04/25	IT MANAGER 136	Overhead Plumbing	no data
2025/04/25	IT MANAGER 136	Wall Drywall	no data
2025/04/25	IT MANAGER 136	Wall Drywall Finish	no data
2025/04/25	IT MANAGER 136	Wall Prime Paint	no data
2025/04/25	IT MANAGER 137	In Wall Insulation	complete
2025/04/25	IT MANAGER 137	Overhead Duct Insulation	in progress
2025/04/25	IT MANAGER 137	Overhead Duct Rough In	in progress
2025/04/25	IT MANAGER 137	Overhead Plumbing	in progress
2025/04/25	IT MANAGER 137	Wall Drywall	complete
2025/04/25	IT MANAGER 137	Wall Drywall Finish	complete
2025/04/25	IT MANAGER 137	Wall Prime Paint	complete
2025/04/25	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/04/25	JUVENILE INTERVIEW 165	Overhead Duct Insulation	in progress
2025/04/25	JUVENILE INTERVIEW 165	Overhead Duct Rough In	in progress
2025/04/25	JUVENILE INTERVIEW 165	Overhead Plumbing	complete
2025/04/25	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/04/25	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/04/25	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/04/25	JUVENILLE INTERVIEWERS 166	In Wall Insulation	complete
2025/04/25	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/04/25	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/04/25	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	not started
2025/04/25	JUVENILLE INTERVIEWERS 166	Wall Drywall	complete
2025/04/25	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/04/25	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/04/25	KEY ROOM 185	In Wall Insulation	in progress
2025/04/25	KEY ROOM 185	Overhead Duct Insulation	not started
2025/04/25	KEY ROOM 185	Overhead Duct Rough In	in progress
2025/04/25	KEY ROOM 185	Overhead Plumbing	not started
2025/04/25	KEY ROOM 185	Wall Drywall	in progress
2025/04/25	KEY ROOM 185	Wall Drywall Finish	not started
2025/04/25	KEY ROOM 185	Wall Prime Paint	not started
2025/04/25	LT 170	In Wall Insulation	complete
2025/04/25	LT 170	Overhead Duct Insulation	in progress
2025/04/25	LT 170	Overhead Duct Rough In	in progress
2025/04/25	LT 170	Overhead Plumbing	not started
2025/04/25	LT 170	Wall Drywall	complete
2025/04/25	LT 170	Wall Drywall Finish	complete
2025/04/25	LT 170	Wall Prime Paint	complete

2025/04/25	MACHINE ROOM 191	In Wall Insulation	complete
2025/04/25	MACHINE ROOM 191	Overhead Duct Insulation	not started
2025/04/25	MACHINE ROOM 191	Overhead Duct Rough In	in progress
2025/04/25	MACHINE ROOM 191	Overhead Plumbing	not started
2025/04/25	MACHINE ROOM 191	Wall Drywall	complete
2025/04/25	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/04/25	MACHINE ROOM 191	Wall Prime Paint	complete
2025/04/25	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/04/25	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/04/25	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/04/25	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/04/25	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/04/25	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/04/25	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/04/25	MAIN JANITORIAL111	In Wall Insulation	complete
2025/04/25	MAIN JANITORIAL111	Overhead Duct Insulation	in progress
2025/04/25	MAIN JANITORIAL111	Overhead Duct Rough In	in progress
2025/04/25	MAIN JANITORIAL111	Overhead Plumbing	in progress
2025/04/25	MAIN JANITORIAL111	Wall Drywall	complete
2025/04/25	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/04/25	MAIN JANITORIAL111	Wall Prime Paint	in progress
2025/04/25	MARINE SERGEANT 142	In Wall Insulation	complete
2025/04/25	MARINE SERGEANT 142	Overhead Duct Insulation	in progress
2025/04/25	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/04/25	MARINE SERGEANT 142	Overhead Plumbing	in progress
2025/04/25	MARINE SERGEANT 142	Wall Drywall	complete
2025/04/25	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/04/25	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/04/25	MECHANICAL 192	In Wall Insulation	complete
2025/04/25	MECHANICAL 192	Overhead Duct Insulation	not started
2025/04/25	MECHANICAL 192	Overhead Duct Rough In	in progress
2025/04/25	MECHANICAL 192	Overhead Plumbing	not started
2025/04/25	MECHANICAL 192	Wall Drywall	in progress
2025/04/25	MECHANICAL 192	Wall Drywall Finish	in progress
2025/04/25	MECHANICAL 192	Wall Prime Paint	in progress
2025/04/25	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/04/25	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
2025/04/25	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/04/25	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/04/25	MECHANICAL ROOM 122	Wall Drywall	no data
2025/04/25	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/04/25	MECHANICAL ROOM 122	Wall Prime Paint	no data
2025/04/25	MENS RESTROOM 112	In Wall Insulation	in progress
2025/04/25	MENS RESTROOM 112	Overhead Duct Insulation	in progress

2025/04/25	MENS RESTROOM 112	Overhead Duct Rough In	in progress
2025/04/25	MENS RESTROOM 112	Overhead Plumbing	in progress
2025/04/25	MENS RESTROOM 112	Wall Drywall	not started
2025/04/25	MENS RESTROOM 112	Wall Drywall Finish	not started
2025/04/25	MENS RESTROOM 112	Wall Prime Paint	not started
2025/04/25	MIS EQUIPMENT STORAGE 138	In Wall Insulation	complete
2025/04/25	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/04/25	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	in progress
2025/04/25	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	in progress
2025/04/25	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/04/25	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/04/25	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/04/25	MIS SHREDDING 117	In Wall Insulation	complete
2025/04/25	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/04/25	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/04/25	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/04/25	MIS SHREDDING 117	Wall Drywall	complete
2025/04/25	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/04/25	MIS SHREDDING 117	Wall Prime Paint	complete
2025/04/25	OFFICE 128	In Wall Insulation	complete
2025/04/25	OFFICE 128	Overhead Duct Insulation	in progress
2025/04/25	OFFICE 128	Overhead Duct Rough In	in progress
2025/04/25	OFFICE 128	Overhead Plumbing	not started
2025/04/25	OFFICE 128	Wall Drywall	complete
2025/04/25	OFFICE 128	Wall Drywall Finish	complete
2025/04/25	OFFICE 128	Wall Prime Paint	not started
2025/04/25	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	complete
2025/04/25	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	in progress
2025/04/25	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	in progress
2025/04/25	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	not started
2025/04/25	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/04/25	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/04/25	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	in progress
2025/04/25	PARTS STORAGE 189	In Wall Insulation	in progress
2025/04/25	PARTS STORAGE 189	Overhead Duct Insulation	not started
2025/04/25	PARTS STORAGE 189	Overhead Duct Rough In	in progress
2025/04/25	PARTS STORAGE 189	Overhead Plumbing	not started



2025/04/25	PARTS STORAGE 189	Wall Drywall	in progress
2025/04/25	PARTS STORAGE 189	Wall Drywall Finish	in progress
2025/04/25	PARTS STORAGE 189	Wall Prime Paint	not started
2025/04/25	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/04/25	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/04/25	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/04/25	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/04/25	PUBLIC RESTROOM 106	Wall Drywall	no data
2025/04/25	PUBLIC RESTROOM 106	Wall Drywall Finish	no data
2025/04/25	PUBLIC RESTROOM 106	Wall Prime Paint	no data
2025/04/25	Polygraph 152	In Wall Insulation	no data
2025/04/25	Polygraph 152	Overhead Duct Insulation	no data
2025/04/25	Polygraph 152	Overhead Duct Rough In	no data
2025/04/25	Polygraph 152	Overhead Plumbing	no data
2025/04/25	Polygraph 152	Wall Drywall	no data
2025/04/25	Polygraph 152	Wall Drywall Finish	no data
2025/04/25	Polygraph 152	Wall Prime Paint	no data
2025/04/25	RECEPTION 101	In Wall Insulation	not started
2025/04/25	RECEPTION 101	Overhead Duct Insulation	not started
2025/04/25	RECEPTION 101	Overhead Duct Rough In	in progress
2025/04/25	RECEPTION 101	Overhead Plumbing	not started
2025/04/25	RECEPTION 101	Wall Drywall	not started
2025/04/25	RECEPTION 101	Wall Drywall Finish	not started
2025/04/25	RECEPTION 101	Wall Prime Paint	not started
2025/04/25	RECEPTION 147	In Wall Insulation	in progress
2025/04/25	RECEPTION 147	Overhead Duct Insulation	in progress
2025/04/25	RECEPTION 147	Overhead Duct Rough In	in progress
2025/04/25	RECEPTION 147	Overhead Plumbing	in progress
2025/04/25	RECEPTION 147	Wall Drywall	in progress
2025/04/25	RECEPTION 147	Wall Drywall Finish	not started
2025/04/25	RECEPTION 147	Wall Prime Paint	not started
2025/04/25	RECEPTION 179	In Wall Insulation	in progress
2025/04/25	RECEPTION 179	Overhead Duct Insulation	not started
2025/04/25	RECEPTION 179	Overhead Duct Rough In	in progress
2025/04/25	RECEPTION 179	Overhead Plumbing	not started
2025/04/25	RECEPTION 179	Wall Drywall	in progress
2025/04/25	RECEPTION 179	Wall Drywall Finish	not started
2025/04/25	RECEPTION 179	Wall Prime Paint	not started
2025/04/25	RECORDS 130	In Wall Insulation	complete
2025/04/25	RECORDS 130	Overhead Duct Insulation	in progress
2025/04/25	RECORDS 130	Overhead Duct Rough In	in progress
2025/04/25	RECORDS 130	Overhead Plumbing	in progress
2025/04/25	RECORDS 130	Wall Drywall	complete
2025/04/25	RECORDS 130	Wall Drywall Finish	complete
2025/04/25	RECORDS 130	Wall Prime Paint	complete
2025/04/25	RECORDS STORAGE 133	In Wall Insulation	complete
2025/04/25	RECORDS STORAGE 133	Overhead Duct Insulation	in progress
2025/04/25	RECORDS STORAGE 133	Overhead Duct Rough In	in progress
2025/04/25	RECORDS STORAGE 133	Overhead Plumbing	not started
2025/04/25	RECORDS STORAGE 133	Wall Drywall	complete
2025/04/25	RECORDS STORAGE 133	Wall Drywall Finish	complete

2025/04/25	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/04/25	RECORDS SUPERVISOR 131	In Wall Insulation	complete
2025/04/25	RECORDS SUPERVISOR 131	Overhead Duct Insulation	in progress
2025/04/25	RECORDS SUPERVISOR 131	Overhead Duct Rough In	in progress
2025/04/25	RECORDS SUPERVISOR 131	Overhead Plumbing	not started
2025/04/25	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/04/25	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/04/25	RECORDS SUPERVISOR 131	Wall Prime Paint	in progress
2025/04/25	RECORDS SUPERVISOR 132	In Wall Insulation	complete
2025/04/25	RECORDS SUPERVISOR 132	Overhead Duct Insulation	in progress
2025/04/25	RECORDS SUPERVISOR 132	Overhead Duct Rough In	in progress
2025/04/25	RECORDS SUPERVISOR 132	Overhead Plumbing	not started
2025/04/25	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/04/25	RECORDS SUPERVISOR 132	Wall Drywall Finish	in progress
2025/04/25	RECORDS SUPERVISOR 132	Wall Prime Paint	not started
2025/04/25	RESTROOM 183	In Wall Insulation	in progress
2025/04/25	RESTROOM 183	Overhead Duct Insulation	in progress
2025/04/25	RESTROOM 183	Overhead Duct Rough In	in progress
2025/04/25	RESTROOM 183	Overhead Plumbing	in progress
2025/04/25	RESTROOM 183	Wall Drywall	not started
2025/04/25	RESTROOM 183	Wall Drywall Finish	not started
2025/04/25	RESTROOM 183	Wall Prime Paint	not started
2025/04/25	Risk Management - 158	In Wall Insulation	not started
2025/04/25	Risk Management - 158	Overhead Duct Insulation	not started
2025/04/25	Risk Management - 158	Overhead Duct Rough In	in progress
2025/04/25	Risk Management - 158	Overhead Plumbing	in progress
2025/04/25	Risk Management - 158	Wall Drywall	not started
2025/04/25	Risk Management - 158	Wall Drywall Finish	not started
2025/04/25	Risk Management - 158	Wall Prime Paint	not started
2025/04/25	SALLY PORT 105	In Wall Insulation	not started
2025/04/25	SALLY PORT 105	Overhead Duct Insulation	not started
2025/04/25	SALLY PORT 105	Overhead Duct Rough In	in progress
2025/04/25	SALLY PORT 105	Overhead Plumbing	not started
2025/04/25	SALLY PORT 105	Wall Drywall	not started
2025/04/25	SALLY PORT 105	Wall Drywall Finish	not started
2025/04/25	SALLY PORT 105	Wall Prime Paint	not started
2025/04/25	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/04/25	SANE EXAM ROOM 168	Overhead Duct Insulation	in progress
2025/04/25	SANE EXAM ROOM 168	Overhead Duct Rough In	in progress
2025/04/25	SANE EXAM ROOM 168	Overhead Plumbing	complete
2025/04/25	SANE EXAM ROOM 168	Wall Drywall	complete

2025/04/25	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/04/25	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/04/25	SGT 171	In Wall Insulation	complete
2025/04/25	SGT 171	Overhead Duct Insulation	in progress
2025/04/25	SGT 171	Overhead Duct Rough In	in progress
2025/04/25	SGT 171	Overhead Plumbing	in progress
2025/04/25	SGT 171	Wall Drywall	complete
2025/04/25	SGT 171	Wall Drywall Finish	complete
2025/04/25	SGT 171	Wall Prime Paint	complete
2025/04/25	SGT 172	In Wall Insulation	complete
2025/04/25	SGT 172	Overhead Duct Insulation	in progress
2025/04/25	SGT 172	Overhead Duct Rough In	in progress
2025/04/25	SGT 172	Overhead Plumbing	in progress
2025/04/25	SGT 172	Wall Drywall	complete
2025/04/25	SGT 172	Wall Drywall Finish	complete
2025/04/25	SGT 172	Wall Prime Paint	complete
2025/04/25	SHIPPING STORAGE 190	In Wall Insulation	in progress
2025/04/25	SHIPPING STORAGE 190	Overhead Duct Insulation	not started
2025/04/25	SHIPPING STORAGE 190	Overhead Duct Rough In	in progress
2025/04/25	SHIPPING STORAGE 190	Overhead Plumbing	not started
2025/04/25	SHIPPING STORAGE 190	Wall Drywall	in progress
2025/04/25	SHIPPING STORAGE 190	Wall Drywall Finish	not started
2025/04/25	SHIPPING STORAGE 190	Wall Prime Paint	not started
2025/04/25	SHOP FORMAN 184	In Wall Insulation	in progress
2025/04/25	SHOP FORMAN 184	Overhead Duct Insulation	not started
2025/04/25	SHOP FORMAN 184	Overhead Duct Rough In	in progress
2025/04/25	SHOP FORMAN 184	Overhead Plumbing	not started
2025/04/25	SHOP FORMAN 184	Wall Drywall	in progress
2025/04/25	SHOP FORMAN 184	Wall Drywall Finish	not started
2025/04/25	SHOP FORMAN 184	Wall Prime Paint	not started
2025/04/25	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/04/25	SOFT INTERVIEW 161	Overhead Duct Insulation	in progress
2025/04/25	SOFT INTERVIEW 161	Overhead Duct Rough In	in progress
2025/04/25	SOFT INTERVIEW 161	Overhead Plumbing	not started
2025/04/25	SOFT INTERVIEW 161	Wall Drywall	complete
2025/04/25	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/04/25	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/04/25	SOFT INTERVIEW 162	In Wall Insulation	complete
2025/04/25	SOFT INTERVIEW 162	Overhead Duct Insulation	in progress
2025/04/25	SOFT INTERVIEW 162	Overhead Duct Rough In	in progress
2025/04/25	SOFT INTERVIEW 162	Overhead Plumbing	not started
2025/04/25	SOFT INTERVIEW 162	Wall Drywall	complete
2025/04/25	SOFT INTERVIEW 162	Wall Drywall Finish	complete
2025/04/25	SOFT INTERVIEW 162	Wall Prime Paint	complete
2025/04/25	SPECIAL OPERATION LT 143	In Wall Insulation	complete

2025/04/25		SPECIAL OPERATION LT 143		Overhead Duct Insulation		in progress
2025/04/25		SPECIAL OPERATION LT 143		Overhead Duct Rough In		in progress
2025/04/25		SPECIAL OPERATION LT 143		Overhead Plumbing		not started
2025/04/25		SPECIAL OPERATION LT 143		Wall Drywall		complete
2025/04/25		SPECIAL OPERATION LT 143		Wall Drywall Finish		complete
2025/04/25		SPECIAL OPERATION LT 143		Wall Prime Paint		complete
2025/04/25		STAIR A		In Wall Insulation		no data
2025/04/25		STAIR A		Overhead Duct Insulation		no data
2025/04/25		STAIR A		Overhead Duct Rough In		no data
2025/04/25		STAIR A		Overhead Plumbing		no data
2025/04/25		STAIR A		Wall Drywall		no data
2025/04/25		STAIR A		Wall Drywall Finish		no data
2025/04/25		STAIR A		Wall Prime Paint		no data
2025/04/25		STORAGE 104		In Wall Insulation		complete
2025/04/25		STORAGE 104		Overhead Duct Insulation		in progress
2025/04/25		STORAGE 104		Overhead Duct Rough In		in progress
2025/04/25		STORAGE 104		Overhead Plumbing		not started
2025/04/25		STORAGE 104		Wall Drywall		in progress
2025/04/25		STORAGE 104		Wall Drywall Finish		in progress
2025/04/25		STORAGE 104		Wall Prime Paint		not started
2025/04/25		STORAGE 127		In Wall Insulation		complete
2025/04/25		STORAGE 127		Overhead Duct Insulation		in progress
2025/04/25		STORAGE 127		Overhead Duct Rough In		in progress
2025/04/25		STORAGE 127		Overhead Plumbing		not started
2025/04/25		STORAGE 127		Wall Drywall		complete
2025/04/25		STORAGE 127		Wall Drywall Finish		complete
2025/04/25		STORAGE 127		Wall Prime Paint		in progress
2025/04/25		STUDIO 126		In Wall Insulation		complete
2025/04/25		STUDIO 126		Overhead Duct Insulation		in progress
2025/04/25		STUDIO 126		Overhead Duct Rough In		in progress
2025/04/25		STUDIO 126		Overhead Plumbing		not started
2025/04/25		STUDIO 126		Wall Drywall		complete
2025/04/25		STUDIO 126		Wall Drywall Finish		in progress
2025/04/25		STUDIO 126		Wall Prime Paint		in progress
2025/04/25		SUPERVISOR 129		In Wall Insulation		complete
2025/04/25		SUPERVISOR 129		Overhead Duct Insulation		in progress
2025/04/25		SUPERVISOR 129		Overhead Duct Rough In		in progress
2025/04/25		SUPERVISOR 129		Overhead Plumbing		not started
2025/04/25		SUPERVISOR 129		Wall Drywall		complete
2025/04/25		SUPERVISOR 129		Wall Drywall Finish		complete
2025/04/25		SUPERVISOR 129		Wall Prime Paint		not started
2025/04/25		Storage 164		In Wall Insulation		in progress
2025/04/25		Storage 164		Overhead Duct Insulation		in progress
2025/04/25		Storage 164		Overhead Duct Rough In		in progress
2025/04/25		Storage 164		Overhead Plumbing		not started
2025/04/25		Storage 164		Wall Drywall		complete
2025/04/25		Storage 164		Wall Drywall Finish		complete
2025/04/25		Storage 164		Wall Prime Paint		complete
2025/04/25		Storage 177		In Wall Insulation		complete
2025/04/25		Storage 177		Overhead Duct Insulation		in progress

2025/04/25	Storage 177	Overhead Duct Rough In	in progress
2025/04/25	Storage 177	Overhead Plumbing	not started
2025/04/25	Storage 177	Wall Drywall	complete
2025/04/25	Storage 177	Wall Drywall Finish	complete
2025/04/25	Storage 177	Wall Prime Paint	complete
2025/04/25	TECHNICAL SURVEILLANCE 188	In Wall Insulation	in progress
2025/04/25	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	not started
2025/04/25	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	in progress
2025/04/25	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	not started
2025/04/25	TECHNICAL SURVEILLANCE 188	Wall Drywall	in progress
2025/04/25	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	not started
2025/04/25	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	not started
2025/04/25	TRAFFIC SERGEANT 141	In Wall Insulation	complete
2025/04/25	TRAFFIC SERGEANT 141	Overhead Duct Insulation	in progress
2025/04/25	TRAFFIC SERGEANT 141	Overhead Duct Rough In	in progress
2025/04/25	TRAFFIC SERGEANT 141	Overhead Plumbing	in progress
2025/04/25	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/04/25	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/04/25	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/04/25	TRIAGE/RECEPTION 134	In Wall Insulation	complete
2025/04/25	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/04/25	TRIAGE/RECEPTION 134	Overhead Duct Rough In	in progress
2025/04/25	TRIAGE/RECEPTION 134	Overhead Plumbing	not started
2025/04/25	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/04/25	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/04/25	TRIAGE/RECEPTION 134	Wall Prime Paint	in progress
2025/04/25	TST WORKSHOP 187	In Wall Insulation	in progress
2025/04/25	TST WORKSHOP 187	Overhead Duct Insulation	not started
2025/04/25	TST WORKSHOP 187	Overhead Duct Rough In	in progress
2025/04/25	TST WORKSHOP 187	Overhead Plumbing	not started
2025/04/25	TST WORKSHOP 187	Wall Drywall	in progress
2025/04/25	TST WORKSHOP 187	Wall Drywall Finish	not started
2025/04/25	TST WORKSHOP 187	Wall Prime Paint	not started
2025/04/25	UNISEX RESTROOM 169	In Wall Insulation	in progress
2025/04/25	UNISEX RESTROOM 169	Overhead Duct Insulation	in progress
2025/04/25	UNISEX RESTROOM 169	Overhead Duct Rough In	in progress
2025/04/25	UNISEX RESTROOM 169	Overhead Plumbing	in progress
2025/04/25	UNISEX RESTROOM 169	Wall Drywall	in progress
2025/04/25	UNISEX RESTROOM 169	Wall Drywall Finish	not started
2025/04/25	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/04/25	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	in progress

progress  
 2025/04/25 | VEHICLE MAINTENANCE BAYS 186 | Overhead Duct Insulation | not started  
 2025/04/25 | VEHICLE MAINTENANCE BAYS 186 | Overhead Duct Rough In | not started  
 2025/04/25 | VEHICLE MAINTENANCE BAYS 186 | Overhead Plumbing | complete  
 2025/04/25 | VEHICLE MAINTENANCE BAYS 186 | Wall Drywall | in progress  
 2025/04/25 | VEHICLE MAINTENANCE BAYS 186 | Wall Drywall Finish | in progress  
 2025/04/25 | VEHICLE MAINTENANCE BAYS 186 | Wall Prime Paint | not started  
 2025/04/25 | VOLUNTEER/LIGHT DUTY 140 | In Wall Insulation | complete  
 2025/04/25 | VOLUNTEER/LIGHT DUTY 140 | Overhead Duct Insulation | in progress  
 2025/04/25 | VOLUNTEER/LIGHT DUTY 140 | Overhead Duct Rough In | in progress  
 2025/04/25 | VOLUNTEER/LIGHT DUTY 140 | Overhead Plumbing | in progress  
 2025/04/25 | VOLUNTEER/LIGHT DUTY 140 | Wall Drywall | complete  
 2025/04/25 | VOLUNTEER/LIGHT DUTY 140 | Wall Drywall Finish | complete  
 2025/04/25 | VOLUNTEER/LIGHT DUTY 140 | Wall Prime Paint | complete  
 2025/04/25 | WAITING/LOBBY 100 | In Wall Insulation | not started  
 2025/04/25 | WAITING/LOBBY 100 | Overhead Duct Insulation | not started  
 2025/04/25 | WAITING/LOBBY 100 | Overhead Duct Rough In | not started  
 2025/04/25 | WAITING/LOBBY 100 | Overhead Plumbing | not started  
 2025/04/25 | WAITING/LOBBY 100 | Wall Drywall | not started  
 2025/04/25 | WAITING/LOBBY 100 | Wall Drywall Finish | not started  
 2025/04/25 | WAITING/LOBBY 100 | Wall Prime Paint | not started  
 2025/04/25 | WOMENS RESTROOM 113 | In Wall Insulation | in progress  
 2025/04/25 | WOMENS RESTROOM 113 | Overhead Duct Insulation | in progress  
 2025/04/25 | WOMENS RESTROOM 113 | Overhead Duct Rough In | in progress  
 2025/04/25 | WOMENS RESTROOM 113 | Overhead Plumbing | in progress  
 2025/04/25 | WOMENS RESTROOM 113 | Wall Drywall | in progress  
 2025/04/25 | WOMENS RESTROOM 113 | Wall Drywall Finish | not started  
 2025/04/25 | WOMENS RESTROOM 113 | Wall Prime Paint | not started  
 2025/05/06 | ADMIN ASSISTANT 125 | In Wall Insulation | no data  
 2025/05/06 | ADMIN ASSISTANT 125 | Overhead Duct Insulation | no data  
 2025/05/06 | ADMIN ASSISTANT 125 | Overhead Duct Rough In | no data  
 2025/05/06 | ADMIN ASSISTANT 125 | Overhead Plumbing | no data  
 2025/05/06 | ADMIN ASSISTANT 125 | Wall Drywall | no data  
 2025/05/06 | ADMIN ASSISTANT 125 | Wall Drywall Finish | no data  
 2025/05/06 | ADMIN ASSISTANT 125 | Wall Prime Paint | no data  
 2025/05/06 | AV ROOM 103 | In Wall Insulation | complete  
 2025/05/06 | AV ROOM 103 | Overhead Duct Insulation | in progress  
 2025/05/06 | AV ROOM 103 | Overhead Duct Rough In | in progress

2025/05/06	AV ROOM 103	Overhead Plumbing	not started
2025/05/06	AV ROOM 103	Wall Drywall	in progress
2025/05/06	AV ROOM 103	Wall Drywall Finish	in progress
2025/05/06	AV ROOM 103	Wall Prime Paint	in progress
2025/05/06	BREAK ROOM CONFERENCE 182	In Wall Insulation	in progress
2025/05/06	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	in progress
2025/05/06	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	in progress
2025/05/06	BREAK ROOM CONFERENCE 182	Overhead Plumbing	in progress
2025/05/06	BREAK ROOM CONFERENCE 182	Wall Drywall	in progress
2025/05/06	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	not started
2025/05/06	BREAK ROOM CONFERENCE 182	Wall Prime Paint	not started
2025/05/06	Background-159	In Wall Insulation	not started
2025/05/06	Background-159	Overhead Duct Insulation	not started
2025/05/06	Background-159	Overhead Duct Rough In	not started
2025/05/06	Background-159	Overhead Plumbing	not started
2025/05/06	Background-159	Wall Drywall	not started
2025/05/06	Background-159	Wall Drywall Finish	not started
2025/05/06	Background-159	Wall Prime Paint	not started
2025/05/06	CENTRAL BREAKROOM 145	In Wall Insulation	not started
2025/05/06	CENTRAL BREAKROOM 145	Overhead Duct Insulation	not started
2025/05/06	CENTRAL BREAKROOM 145	Overhead Duct Rough In	in progress
2025/05/06	CENTRAL BREAKROOM 145	Overhead Plumbing	not started
2025/05/06	CENTRAL BREAKROOM 145	Wall Drywall	not started
2025/05/06	CENTRAL BREAKROOM 145	Wall Drywall Finish	not started
2025/05/06	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/05/06	COLD CASE 175	In Wall Insulation	complete
2025/05/06	COLD CASE 175	Overhead Duct Insulation	in progress
2025/05/06	COLD CASE 175	Overhead Duct Rough In	in progress
2025/05/06	COLD CASE 175	Overhead Plumbing	in progress
2025/05/06	COLD CASE 175	Wall Drywall	complete
2025/05/06	COLD CASE 175	Wall Drywall Finish	complete
2025/05/06	COLD CASE 175	Wall Prime Paint	in progress
2025/05/06	COMMUNITY AFFAIRS 124	In Wall Insulation	complete
2025/05/06	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	in progress
2025/05/06	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	in progress
2025/05/06	COMMUNITY AFFAIRS 124	Overhead Plumbing	not started
2025/05/06	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/05/06	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/05/06	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/05/06	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	in progress
2025/05/06	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	

in progress  
2025/05/06 | COMMUNITY ROOM 247 PPL 102 | Overhead Duct Rough In |  
in progress  
2025/05/06 | COMMUNITY ROOM 247 PPL 102 | Overhead Plumbing | not  
started  
2025/05/06 | COMMUNITY ROOM 247 PPL 102 | Wall Drywall | in progress  
2025/05/06 | COMMUNITY ROOM 247 PPL 102 | Wall Drywall Finish | not  
started  
2025/05/06 | COMMUNITY ROOM 247 PPL 102 | Wall Prime Paint | not  
started  
2025/05/06 | CONFERENCE ROOM 153 | In Wall Insulation | in progress  
2025/05/06 | CONFERENCE ROOM 153 | Overhead Duct Insulation | in  
progress  
2025/05/06 | CONFERENCE ROOM 153 | Overhead Duct Rough In | in  
progress  
2025/05/06 | CONFERENCE ROOM 153 | Overhead Plumbing | not started  
2025/05/06 | CONFERENCE ROOM 153 | Wall Drywall | in progress  
2025/05/06 | CONFERENCE ROOM 153 | Wall Drywall Finish | not started  
2025/05/06 | CONFERENCE ROOM 153 | Wall Prime Paint | not started  
2025/05/06 | CONFERENCE/WAR ROOM 163 | In Wall Insulation | complete  
2025/05/06 | CONFERENCE/WAR ROOM 163 | Overhead Duct Insulation | in  
progress  
2025/05/06 | CONFERENCE/WAR ROOM 163 | Overhead Duct Rough In | in  
progress  
2025/05/06 | CONFERENCE/WAR ROOM 163 | Overhead Plumbing | not  
started  
2025/05/06 | CONFERENCE/WAR ROOM 163 | Wall Drywall | complete  
2025/05/06 | CONFERENCE/WAR ROOM 163 | Wall Drywall Finish |  
complete  
2025/05/06 | CONFERENCE/WAR ROOM 163 | Wall Prime Paint | complete  
2025/05/06 | COPY 176 | In Wall Insulation | complete  
2025/05/06 | COPY 176 | Overhead Duct Insulation | in progress  
2025/05/06 | COPY 176 | Overhead Duct Rough In | in progress  
2025/05/06 | COPY 176 | Overhead Plumbing | not started  
2025/05/06 | COPY 176 | Wall Drywall | complete  
2025/05/06 | COPY 176 | Wall Drywall Finish | complete  
2025/05/06 | COPY 176 | Wall Prime Paint | complete  
2025/05/06 | COPY/MAIL ROOM 114 | In Wall Insulation | complete  
2025/05/06 | COPY/MAIL ROOM 114 | Overhead Duct Insulation | in  
progress  
2025/05/06 | COPY/MAIL ROOM 114 | Overhead Duct Rough In | in  
progress  
2025/05/06 | COPY/MAIL ROOM 114 | Overhead Plumbing | in progress  
2025/05/06 | COPY/MAIL ROOM 114 | Wall Drywall | complete  
2025/05/06 | COPY/MAIL ROOM 114 | Wall Drywall Finish | complete  
2025/05/06 | COPY/MAIL ROOM 114 | Wall Prime Paint | complete  
2025/05/06 | CORRIDOR 107 | In Wall Insulation | complete  
2025/05/06 | CORRIDOR 107 | Overhead Duct Insulation | in progress  
2025/05/06 | CORRIDOR 107 | Overhead Duct Rough In | in progress  
2025/05/06 | CORRIDOR 107 | Overhead Plumbing | not started  
2025/05/06 | CORRIDOR 107 | Wall Drywall | complete  
2025/05/06 | CORRIDOR 107 | Wall Drywall Finish | complete  
2025/05/06 | CORRIDOR 107 | Wall Prime Paint | in progress  
2025/05/06 | CORRIDOR 108 | In Wall Insulation | complete



2025/05/06	CORRIDOR 108	In Wall Insulation   complete
2025/05/06	CORRIDOR 108	Overhead Duct Insulation   in progress
2025/05/06	CORRIDOR 108	Overhead Duct Insulation   in progress
2025/05/06	CORRIDOR 108	Overhead Duct Rough In   in progress
2025/05/06	CORRIDOR 108	Overhead Duct Rough In   in progress
2025/05/06	CORRIDOR 108	Overhead Plumbing   in progress
2025/05/06	CORRIDOR 108	Overhead Plumbing   not started
2025/05/06	CORRIDOR 108	Wall Drywall   complete
2025/05/06	CORRIDOR 108	Wall Drywall   complete
2025/05/06	CORRIDOR 108	Wall Drywall Finish   complete
2025/05/06	CORRIDOR 108	Wall Drywall Finish   complete
2025/05/06	CORRIDOR 108	Wall Prime Paint   in progress
2025/05/06	CORRIDOR 108	Wall Prime Paint   in progress
2025/05/06	CORRIDOR 109	In Wall Insulation   complete
2025/05/06	CORRIDOR 109	Overhead Duct Insulation   in progress
2025/05/06	CORRIDOR 109	Overhead Duct Rough In   in progress
2025/05/06	CORRIDOR 109	Overhead Plumbing   in progress
2025/05/06	CORRIDOR 109	Wall Drywall   complete
2025/05/06	CORRIDOR 109	Wall Drywall Finish   complete
2025/05/06	CORRIDOR 109	Wall Prime Paint   complete
2025/05/06	CORRIDOR 110	In Wall Insulation   complete
2025/05/06	CORRIDOR 110	In Wall Insulation   complete
2025/05/06	CORRIDOR 110	Overhead Duct Insulation   in progress
2025/05/06	CORRIDOR 110	Overhead Duct Insulation   in progress
2025/05/06	CORRIDOR 110	Overhead Duct Rough In   in progress
2025/05/06	CORRIDOR 110	Overhead Duct Rough In   in progress
2025/05/06	CORRIDOR 110	Overhead Plumbing   in progress
2025/05/06	CORRIDOR 110	Overhead Plumbing   in progress
2025/05/06	CORRIDOR 110	Wall Drywall   complete
2025/05/06	CORRIDOR 110	Wall Drywall   complete
2025/05/06	CORRIDOR 110	Wall Drywall Finish   in progress
2025/05/06	CORRIDOR 110	Wall Drywall Finish   in progress
2025/05/06	CORRIDOR 110	Wall Prime Paint   in progress
2025/05/06	CORRIDOR 110	Wall Prime Paint   in progress
2025/05/06	CORRIDOR 181	In Wall Insulation   in progress
2025/05/06	CORRIDOR 181	Overhead Duct Insulation   not started
2025/05/06	CORRIDOR 181	Overhead Duct Rough In   in progress
2025/05/06	CORRIDOR 181	Overhead Plumbing   in progress
2025/05/06	CORRIDOR 181	Wall Drywall   in progress
2025/05/06	CORRIDOR 181	Wall Drywall Finish   not started
2025/05/06	CORRIDOR 181	Wall Prime Paint   not started
2025/05/06	CORRIDOR144	In Wall Insulation   in progress
2025/05/06	CORRIDOR144	Overhead Duct Insulation   in progress
2025/05/06	CORRIDOR144	Overhead Duct Rough In   in progress
2025/05/06	CORRIDOR144	Overhead Plumbing   in progress
2025/05/06	CORRIDOR144	Wall Drywall   in progress
2025/05/06	CORRIDOR144	Wall Drywall Finish   in progress
2025/05/06	CORRIDOR144	Wall Prime Paint   in progress
2025/05/06	CPL 173	In Wall Insulation   complete
2025/05/06	CPL 173	Overhead Duct Insulation   in progress
2025/05/06	CPL 173	Overhead Duct Rough In   in progress
2025/05/06	CPL 173	Overhead Plumbing   in progress
2025/05/06	CPL 173	Wall Drywall   in progress
2025/05/06	CPL 173	Wall Drywall Finish   in progress

2025/05/06	CPL 173	Wall Prime Paint	in progress
2025/05/06	CPL 174	In Wall Insulation	complete
2025/05/06	CPL 174	Overhead Duct Insulation	in progress
2025/05/06	CPL 174	Overhead Duct Rough In	in progress
2025/05/06	CPL 174	Overhead Plumbing	not started
2025/05/06	CPL 174	Wall Drywall	complete
2025/05/06	CPL 174	Wall Drywall Finish	complete
2025/05/06	CPL 174	Wall Prime Paint	in progress
2025/05/06	DRY STORAGE 146	In Wall Insulation	not started
2025/05/06	DRY STORAGE 146	Overhead Duct Insulation	not started
2025/05/06	DRY STORAGE 146	Overhead Duct Rough In	not started
2025/05/06	DRY STORAGE 146	Overhead Plumbing	not started
2025/05/06	DRY STORAGE 146	Wall Drywall	not started
2025/05/06	DRY STORAGE 146	Wall Drywall Finish	not started
2025/05/06	DRY STORAGE 146	Wall Prime Paint	not started
2025/05/06	FIRE RISER 178	In Wall Insulation	complete
2025/05/06	FIRE RISER 178	Overhead Duct Insulation	not started
2025/05/06	FIRE RISER 178	Overhead Duct Rough In	not started
2025/05/06	FIRE RISER 178	Overhead Plumbing	not started
2025/05/06	FIRE RISER 178	Wall Drywall	complete
2025/05/06	FIRE RISER 178	Wall Drywall Finish	complete
2025/05/06	FIRE RISER 178	Wall Prime Paint	not started
2025/05/06	GREETING ROOM 106	In Wall Insulation	complete
2025/05/06	GREETING ROOM 106	Overhead Duct Insulation	in progress
2025/05/06	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/05/06	GREETING ROOM 106	Overhead Plumbing	not started
2025/05/06	GREETING ROOM 106	Wall Drywall	complete
2025/05/06	GREETING ROOM 106	Wall Drywall Finish	complete
2025/05/06	GREETING ROOM 106	Wall Prime Paint	complete
2025/05/06	HR 149	In Wall Insulation	not started
2025/05/06	HR 149	Overhead Duct Insulation	not started
2025/05/06	HR 149	Overhead Duct Rough In	in progress
2025/05/06	HR 149	Overhead Plumbing	not started
2025/05/06	HR 149	Wall Drywall	not started
2025/05/06	HR 149	Wall Drywall Finish	not started
2025/05/06	HR 149	Wall Prime Paint	not started
2025/05/06	HR 150	In Wall Insulation	not started
2025/05/06	HR 150	Overhead Duct Insulation	no data
2025/05/06	HR 150	Overhead Duct Rough In	no data
2025/05/06	HR 150	Overhead Plumbing	not started
2025/05/06	HR 150	Wall Drywall	no data
2025/05/06	HR 150	Wall Drywall Finish	no data
2025/05/06	HR 150	Wall Prime Paint	no data
2025/05/06	HR 151	In Wall Insulation	not started
2025/05/06	HR 151	Overhead Duct Insulation	not started
2025/05/06	HR 151	Overhead Duct Rough In	in progress
2025/05/06	HR 151	Overhead Plumbing	in progress
2025/05/06	HR 151	Wall Drywall	not started
2025/05/06	HR 151	Wall Drywall Finish	not started
2025/05/06	HR 151	Wall Prime Paint	not started
2025/05/06	HR 154	In Wall Insulation	no data

2025/05/06	HR 154	Overhead Duct Insulation	no data
2025/05/06	HR 154	Overhead Duct Rough In	no data
2025/05/06	HR 154	Overhead Plumbing	no data
2025/05/06	HR 154	Wall Drywall	no data
2025/05/06	HR 154	Wall Drywall Finish	no data
2025/05/06	HR 154	Wall Prime Paint	no data
2025/05/06	HR 155	In Wall Insulation	no data
2025/05/06	HR 155	Overhead Duct Insulation	no data
2025/05/06	HR 155	Overhead Duct Rough In	no data
2025/05/06	HR 155	Overhead Plumbing	no data
2025/05/06	HR 155	Wall Drywall	no data
2025/05/06	HR 155	Wall Drywall Finish	no data
2025/05/06	HR 155	Wall Prime Paint	no data
2025/05/06	HR 156	In Wall Insulation	no data
2025/05/06	HR 156	Overhead Duct Insulation	not started
2025/05/06	HR 156	Overhead Duct Rough In	no data
2025/05/06	HR 156	Overhead Plumbing	not started
2025/05/06	HR 156	Wall Drywall	no data
2025/05/06	HR 156	Wall Drywall Finish	no data
2025/05/06	HR 156	Wall Prime Paint	no data
2025/05/06	HR 157	In Wall Insulation	not started
2025/05/06	HR 157	Overhead Duct Insulation	not started
2025/05/06	HR 157	Overhead Duct Rough In	in progress
2025/05/06	HR 157	Overhead Plumbing	in progress
2025/05/06	HR 157	Wall Drywall	not started
2025/05/06	HR 157	Wall Drywall Finish	not started
2025/05/06	HR 157	Wall Prime Paint	not started
2025/05/06	HUMAN RESOURCES 148	In Wall Insulation	not started
2025/05/06	HUMAN RESOURCES 148	Overhead Duct Insulation	not started
2025/05/06	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/05/06	HUMAN RESOURCES 148	Overhead Plumbing	in progress
2025/05/06	HUMAN RESOURCES 148	Wall Drywall	not started
2025/05/06	HUMAN RESOURCES 148	Wall Drywall Finish	not started
2025/05/06	HUMAN RESOURCES 148	Wall Prime Paint	not started
2025/05/06	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/05/06	INTERNAL AFFAIRS 119	Overhead Duct Insulation	not started
2025/05/06	INTERNAL AFFAIRS 119	Overhead Duct Rough In	in progress
2025/05/06	INTERNAL AFFAIRS 119	Overhead Plumbing	in progress
2025/05/06	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/05/06	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/05/06	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/05/06	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/05/06	INTERNAL AFFAIRS 120	Overhead Duct Insulation	in progress
2025/05/06	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/05/06	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/05/06	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/05/06	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/05/06	INTERNAL AFFAIRS 120	Wall Prime Paint	complete

2025/05/06 | INTERVIEW / REVIEW ROOM 118 | In Wall Insulation | complete  
 2025/05/06 | INTERVIEW / REVIEW ROOM 118 | Overhead Duct Insulation | in progress  
 2025/05/06 | INTERVIEW / REVIEW ROOM 118 | Overhead Duct Rough In | in progress  
 2025/05/06 | INTERVIEW / REVIEW ROOM 118 | Overhead Plumbing | not started  
 2025/05/06 | INTERVIEW / REVIEW ROOM 118 | Wall Drywall | complete  
 2025/05/06 | INTERVIEW / REVIEW ROOM 118 | Wall Drywall Finish | complete  
 2025/05/06 | INTERVIEW / REVIEW ROOM 118 | Wall Prime Paint | complete  
 2025/05/06 | INTERVIEW/ REVIEW ROOM 121 | In Wall Insulation | complete  
 2025/05/06 | INTERVIEW/ REVIEW ROOM 121 | Overhead Duct Insulation | in progress  
 2025/05/06 | INTERVIEW/ REVIEW ROOM 121 | Overhead Duct Rough In | in progress  
 2025/05/06 | INTERVIEW/ REVIEW ROOM 121 | Overhead Plumbing | in progress  
 2025/05/06 | INTERVIEW/ REVIEW ROOM 121 | Wall Drywall | complete  
 2025/05/06 | INTERVIEW/ REVIEW ROOM 121 | Wall Drywall Finish | complete  
 2025/05/06 | INTERVIEW/ REVIEW ROOM 121 | Wall Prime Paint | complete  
 2025/05/06 | INVESTIGATIONS / MAJOR CASE 167 | In Wall Insulation | complete  
 2025/05/06 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Insulation | in progress  
 2025/05/06 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Rough In | in progress  
 2025/05/06 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Plumbing | in progress  
 2025/05/06 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall | complete  
 2025/05/06 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall Finish | complete  
 2025/05/06 | INVESTIGATIONS / MAJOR CASE 167 | Wall Prime Paint | complete  
 2025/05/06 | IT 115 | In Wall Insulation | complete  
 2025/05/06 | IT 115 | Overhead Duct Insulation | not started  
 2025/05/06 | IT 115 | Overhead Duct Rough In | not started  
 2025/05/06 | IT 115 | Overhead Plumbing | in progress  
 2025/05/06 | IT 115 | Wall Drywall | complete  
 2025/05/06 | IT 115 | Wall Drywall Finish | complete  
 2025/05/06 | IT 115 | Wall Prime Paint | in progress  
 2025/05/06 | IT 135 | In Wall Insulation | complete  
 2025/05/06 | IT 135 | Overhead Duct Insulation | in progress  
 2025/05/06 | IT 135 | Overhead Duct Rough In | in progress  
 2025/05/06 | IT 135 | Overhead Plumbing | in progress  
 2025/05/06 | IT 135 | Wall Drywall | complete  
 2025/05/06 | IT 135 | Wall Drywall Finish | complete  
 2025/05/06 | IT 135 | Wall Prime Paint | complete

2025/05/06	IT MANAGER 136	In Wall Insulation	complete
2025/05/06	IT MANAGER 136	Overhead Duct Insulation	in progress
2025/05/06	IT MANAGER 136	Overhead Duct Rough In	in progress
2025/05/06	IT MANAGER 136	Overhead Plumbing	in progress
2025/05/06	IT MANAGER 136	Wall Drywall	complete
2025/05/06	IT MANAGER 136	Wall Drywall Finish	complete
2025/05/06	IT MANAGER 136	Wall Prime Paint	complete
2025/05/06	IT MANAGER 137	In Wall Insulation	complete
2025/05/06	IT MANAGER 137	Overhead Duct Insulation	in progress
2025/05/06	IT MANAGER 137	Overhead Duct Rough In	in progress
2025/05/06	IT MANAGER 137	Overhead Plumbing	in progress
2025/05/06	IT MANAGER 137	Wall Drywall	complete
2025/05/06	IT MANAGER 137	Wall Drywall Finish	complete
2025/05/06	IT MANAGER 137	Wall Prime Paint	complete
2025/05/06	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/05/06	JUVENILE INTERVIEW 165	Overhead Duct Insulation	in progress
2025/05/06	JUVENILE INTERVIEW 165	Overhead Duct Rough In	in progress
2025/05/06	JUVENILE INTERVIEW 165	Overhead Plumbing	complete
2025/05/06	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/05/06	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/05/06	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/05/06	JUVENILE INTERVIEWERS 166	In Wall Insulation	complete
2025/05/06	JUVENILE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/05/06	JUVENILE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/05/06	JUVENILE INTERVIEWERS 166	Overhead Plumbing	not started
2025/05/06	JUVENILE INTERVIEWERS 166	Wall Drywall	complete
2025/05/06	JUVENILE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/05/06	JUVENILE INTERVIEWERS 166	Wall Prime Paint	complete
2025/05/06	KEY ROOM 185	In Wall Insulation	in progress
2025/05/06	KEY ROOM 185	Overhead Duct Insulation	not started
2025/05/06	KEY ROOM 185	Overhead Duct Rough In	in progress
2025/05/06	KEY ROOM 185	Overhead Plumbing	not started
2025/05/06	KEY ROOM 185	Wall Drywall	in progress
2025/05/06	KEY ROOM 185	Wall Drywall Finish	not started
2025/05/06	KEY ROOM 185	Wall Prime Paint	not started
2025/05/06	LT 170	In Wall Insulation	complete
2025/05/06	LT 170	Overhead Duct Insulation	in progress
2025/05/06	LT 170	Overhead Duct Rough In	in progress
2025/05/06	LT 170	Overhead Plumbing	not started
2025/05/06	LT 170	Wall Drywall	complete
2025/05/06	LT 170	Wall Drywall Finish	complete
2025/05/06	LT 170	Wall Prime Paint	complete
2025/05/06	MACHINE ROOM 191	In Wall Insulation	complete
2025/05/06	MACHINE ROOM 191	Overhead Duct Insulation	complete
2025/05/06	MACHINE ROOM 191	Overhead Duct Rough In	in progress
2025/05/06	MACHINE ROOM 191	Overhead Plumbing	not started

2025/05/06	MACHINE ROOM 191	Wall Drywall	complete
2025/05/06	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/05/06	MACHINE ROOM 191	Wall Prime Paint	complete
2025/05/06	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/05/06	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/05/06	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/05/06	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/05/06	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/05/06	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/05/06	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/05/06	MAIN JANITORIAL111	In Wall Insulation	complete
2025/05/06	MAIN JANITORIAL111	Overhead Duct Insulation	in progress
2025/05/06	MAIN JANITORIAL111	Overhead Duct Rough In	in progress
2025/05/06	MAIN JANITORIAL111	Overhead Plumbing	in progress
2025/05/06	MAIN JANITORIAL111	Wall Drywall	complete
2025/05/06	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/05/06	MAIN JANITORIAL111	Wall Prime Paint	in progress
2025/05/06	MARINE SERGEANT 142	In Wall Insulation	complete
2025/05/06	MARINE SERGEANT 142	Overhead Duct Insulation	in progress
2025/05/06	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/05/06	MARINE SERGEANT 142	Overhead Plumbing	in progress
2025/05/06	MARINE SERGEANT 142	Wall Drywall	complete
2025/05/06	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/05/06	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/05/06	MECHANICAL 192	In Wall Insulation	complete
2025/05/06	MECHANICAL 192	Overhead Duct Insulation	not started
2025/05/06	MECHANICAL 192	Overhead Duct Rough In	in progress
2025/05/06	MECHANICAL 192	Overhead Plumbing	in progress
2025/05/06	MECHANICAL 192	Wall Drywall	in progress
2025/05/06	MECHANICAL 192	Wall Drywall Finish	in progress
2025/05/06	MECHANICAL 192	Wall Prime Paint	in progress
2025/05/06	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/05/06	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
2025/05/06	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/05/06	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/05/06	MECHANICAL ROOM 122	Wall Drywall	no data
2025/05/06	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/05/06	MECHANICAL ROOM 122	Wall Prime Paint	no data
2025/05/06	MENS RESTROOM 112	In Wall Insulation	in progress
2025/05/06	MENS RESTROOM 112	Overhead Duct Insulation	in progress
2025/05/06	MENS RESTROOM 112	Overhead Duct Rough In	in progress
2025/05/06	MENS RESTROOM 112	Overhead Plumbing	in progress
2025/05/06	MENS RESTROOM 112	Wall Drywall	not started
2025/05/06	MENS RESTROOM 112	Wall Drywall Finish	not started

2025/05/06	MENS RESTROOM 112	Wall Prime Paint	not started
2025/05/06	MIS EQUIPMENT STORAGE 138	In Wall Insulation	complete
2025/05/06	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/05/06	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	in progress
2025/05/06	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	in progress
2025/05/06	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/05/06	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/05/06	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/05/06	MIS SHREDDING 117	In Wall Insulation	complete
2025/05/06	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/05/06	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/05/06	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/05/06	MIS SHREDDING 117	Wall Drywall	complete
2025/05/06	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/05/06	MIS SHREDDING 117	Wall Prime Paint	complete
2025/05/06	OFFICE 128	In Wall Insulation	complete
2025/05/06	OFFICE 128	Overhead Duct Insulation	in progress
2025/05/06	OFFICE 128	Overhead Duct Rough In	in progress
2025/05/06	OFFICE 128	Overhead Plumbing	not started
2025/05/06	OFFICE 128	Wall Drywall	complete
2025/05/06	OFFICE 128	Wall Drywall Finish	complete
2025/05/06	OFFICE 128	Wall Prime Paint	complete
2025/05/06	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	complete
2025/05/06	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	in progress
2025/05/06	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	in progress
2025/05/06	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	in progress
2025/05/06	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/05/06	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/05/06	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	in progress
2025/05/06	PARTS STORAGE 189	In Wall Insulation	in progress
2025/05/06	PARTS STORAGE 189	Overhead Duct Insulation	not started
2025/05/06	PARTS STORAGE 189	Overhead Duct Rough In	in progress
2025/05/06	PARTS STORAGE 189	Overhead Plumbing	not started
2025/05/06	PARTS STORAGE 189	Wall Drywall	in progress
2025/05/06	PARTS STORAGE 189	Wall Drywall Finish	in progress
2025/05/06	PARTS STORAGE 189	Wall Prime Paint	not started
2025/05/06	PUBLIC RESTROOM 106	In Wall Insulation	not started
2025/05/06	PUBLIC RESTROOM 106	Overhead Duct Insulation	not started

started  
 2025/05/06 | PUBLIC RESTROOM 106 | Overhead Duct Rough In | not started  
 2025/05/06 | PUBLIC RESTROOM 106 | Overhead Plumbing | not started  
 2025/05/06 | PUBLIC RESTROOM 106 | Wall Drywall | not started  
 2025/05/06 | PUBLIC RESTROOM 106 | Wall Drywall Finish | not started  
 2025/05/06 | PUBLIC RESTROOM 106 | Wall Prime Paint | not started  
 2025/05/06 | Polygraph 152 | In Wall Insulation | not started  
 2025/05/06 | Polygraph 152 | Overhead Duct Insulation | not started  
 2025/05/06 | Polygraph 152 | Overhead Duct Rough In | not started  
 2025/05/06 | Polygraph 152 | Overhead Plumbing | not started  
 2025/05/06 | Polygraph 152 | Wall Drywall | not started  
 2025/05/06 | Polygraph 152 | Wall Drywall Finish | not started  
 2025/05/06 | Polygraph 152 | Wall Prime Paint | not started  
 2025/05/06 | RECEPTION 101 | In Wall Insulation | not started  
 2025/05/06 | RECEPTION 101 | Overhead Duct Insulation | not started  
 2025/05/06 | RECEPTION 101 | Overhead Duct Rough In | in progress  
 2025/05/06 | RECEPTION 101 | Overhead Plumbing | not started  
 2025/05/06 | RECEPTION 101 | Wall Drywall | not started  
 2025/05/06 | RECEPTION 101 | Wall Drywall Finish | not started  
 2025/05/06 | RECEPTION 101 | Wall Prime Paint | not started  
 2025/05/06 | RECEPTION 147 | In Wall Insulation | in progress  
 2025/05/06 | RECEPTION 147 | Overhead Duct Insulation | in progress  
 2025/05/06 | RECEPTION 147 | Overhead Duct Rough In | in progress  
 2025/05/06 | RECEPTION 147 | Overhead Plumbing | in progress  
 2025/05/06 | RECEPTION 147 | Wall Drywall | in progress  
 2025/05/06 | RECEPTION 147 | Wall Drywall Finish | not started  
 2025/05/06 | RECEPTION 147 | Wall Prime Paint | not started  
 2025/05/06 | RECEPTION 179 | In Wall Insulation | in progress  
 2025/05/06 | RECEPTION 179 | Overhead Duct Insulation | not started  
 2025/05/06 | RECEPTION 179 | Overhead Duct Rough In | in progress  
 2025/05/06 | RECEPTION 179 | Overhead Plumbing | not started  
 2025/05/06 | RECEPTION 179 | Wall Drywall | in progress  
 2025/05/06 | RECEPTION 179 | Wall Drywall Finish | not started  
 2025/05/06 | RECEPTION 179 | Wall Prime Paint | not started  
 2025/05/06 | RECORDS 130 | In Wall Insulation | complete  
 2025/05/06 | RECORDS 130 | Overhead Duct Insulation | in progress  
 2025/05/06 | RECORDS 130 | Overhead Duct Rough In | in progress  
 2025/05/06 | RECORDS 130 | Overhead Plumbing | in progress  
 2025/05/06 | RECORDS 130 | Wall Drywall | complete  
 2025/05/06 | RECORDS 130 | Wall Drywall Finish | complete  
 2025/05/06 | RECORDS 130 | Wall Prime Paint | complete  
 2025/05/06 | RECORDS STORAGE 133 | In Wall Insulation | complete  
 2025/05/06 | RECORDS STORAGE 133 | Overhead Duct Insulation | in progress  
 2025/05/06 | RECORDS STORAGE 133 | Overhead Duct Rough In | in progress  
 2025/05/06 | RECORDS STORAGE 133 | Overhead Plumbing | not started  
 2025/05/06 | RECORDS STORAGE 133 | Wall Drywall | complete  
 2025/05/06 | RECORDS STORAGE 133 | Wall Drywall Finish | complete  
 2025/05/06 | RECORDS STORAGE 133 | Wall Prime Paint | complete  
 2025/05/06 | RECORDS SUPERVISOR 131 | In Wall Insulation | complete  
 2025/05/06 | RECORDS SUPERVISOR 131 | Overhead Duct Insulation | in progress



2025/05/06	RECORDS SUPERVISOR 131	Overhead Duct Rough In	in progress
2025/05/06	RECORDS SUPERVISOR 131	Overhead Plumbing	not started
2025/05/06	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/05/06	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/05/06	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/05/06	RECORDS SUPERVISOR 132	In Wall Insulation	complete
2025/05/06	RECORDS SUPERVISOR 132	Overhead Duct Insulation	in progress
2025/05/06	RECORDS SUPERVISOR 132	Overhead Duct Rough In	in progress
2025/05/06	RECORDS SUPERVISOR 132	Overhead Plumbing	not started
2025/05/06	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/05/06	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/05/06	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/05/06	RESTROOM 183	In Wall Insulation	in progress
2025/05/06	RESTROOM 183	Overhead Duct Insulation	in progress
2025/05/06	RESTROOM 183	Overhead Duct Rough In	in progress
2025/05/06	RESTROOM 183	Overhead Plumbing	in progress
2025/05/06	RESTROOM 183	Wall Drywall	not started
2025/05/06	RESTROOM 183	Wall Drywall Finish	not started
2025/05/06	RESTROOM 183	Wall Prime Paint	not started
2025/05/06	Risk Management - 158	In Wall Insulation	not started
2025/05/06	Risk Management - 158	Overhead Duct Insulation	not started
2025/05/06	Risk Management - 158	Overhead Duct Rough In	in progress
2025/05/06	Risk Management - 158	Overhead Plumbing	in progress
2025/05/06	Risk Management - 158	Wall Drywall	not started
2025/05/06	Risk Management - 158	Wall Drywall Finish	not started
2025/05/06	Risk Management - 158	Wall Prime Paint	not started
2025/05/06	SALLY PORT 105	In Wall Insulation	not started
2025/05/06	SALLY PORT 105	Overhead Duct Insulation	not started
2025/05/06	SALLY PORT 105	Overhead Duct Rough In	in progress
2025/05/06	SALLY PORT 105	Overhead Plumbing	not started
2025/05/06	SALLY PORT 105	Wall Drywall	not started
2025/05/06	SALLY PORT 105	Wall Drywall Finish	not started
2025/05/06	SALLY PORT 105	Wall Prime Paint	not started
2025/05/06	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/05/06	SANE EXAM ROOM 168	Overhead Duct Insulation	in progress
2025/05/06	SANE EXAM ROOM 168	Overhead Duct Rough In	in progress
2025/05/06	SANE EXAM ROOM 168	Overhead Plumbing	complete
2025/05/06	SANE EXAM ROOM 168	Wall Drywall	complete
2025/05/06	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/05/06	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/05/06	SGT 171	In Wall Insulation	complete
2025/05/06	SGT 171	Overhead Duct Insulation	in progress
2025/05/06	SGT 171	Overhead Duct Rough In	in progress

2025/05/06	SGT 171	Overhead Plumbing	in progress
2025/05/06	SGT 171	Wall Drywall	complete
2025/05/06	SGT 171	Wall Drywall Finish	complete
2025/05/06	SGT 171	Wall Prime Paint	complete
2025/05/06	SGT 172	In Wall Insulation	complete
2025/05/06	SGT 172	Overhead Duct Insulation	complete
2025/05/06	SGT 172	Overhead Duct Rough In	in progress
2025/05/06	SGT 172	Overhead Plumbing	in progress
2025/05/06	SGT 172	Wall Drywall	complete
2025/05/06	SGT 172	Wall Drywall Finish	complete
2025/05/06	SGT 172	Wall Prime Paint	complete
2025/05/06	SHIPPING STORAGE 190	In Wall Insulation	in progress
2025/05/06	SHIPPING STORAGE 190	Overhead Duct Insulation	not started
2025/05/06	SHIPPING STORAGE 190	Overhead Duct Rough In	in progress
2025/05/06	SHIPPING STORAGE 190	Overhead Plumbing	not started
2025/05/06	SHIPPING STORAGE 190	Wall Drywall	in progress
2025/05/06	SHIPPING STORAGE 190	Wall Drywall Finish	not started
2025/05/06	SHIPPING STORAGE 190	Wall Prime Paint	not started
2025/05/06	SHOP FORMAN 184	In Wall Insulation	in progress
2025/05/06	SHOP FORMAN 184	Overhead Duct Insulation	not started
2025/05/06	SHOP FORMAN 184	Overhead Duct Rough In	in progress
2025/05/06	SHOP FORMAN 184	Overhead Plumbing	not started
2025/05/06	SHOP FORMAN 184	Wall Drywall	in progress
2025/05/06	SHOP FORMAN 184	Wall Drywall Finish	not started
2025/05/06	SHOP FORMAN 184	Wall Prime Paint	not started
2025/05/06	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/05/06	SOFT INTERVIEW 161	Overhead Duct Insulation	complete
2025/05/06	SOFT INTERVIEW 161	Overhead Duct Rough In	in progress
2025/05/06	SOFT INTERVIEW 161	Overhead Plumbing	not started
2025/05/06	SOFT INTERVIEW 161	Wall Drywall	complete
2025/05/06	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/05/06	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/05/06	SOFT INTERVIEW 162	In Wall Insulation	complete
2025/05/06	SOFT INTERVIEW 162	Overhead Duct Insulation	in progress
2025/05/06	SOFT INTERVIEW 162	Overhead Duct Rough In	in progress
2025/05/06	SOFT INTERVIEW 162	Overhead Plumbing	not started
2025/05/06	SOFT INTERVIEW 162	Wall Drywall	complete
2025/05/06	SOFT INTERVIEW 162	Wall Drywall Finish	complete
2025/05/06	SOFT INTERVIEW 162	Wall Prime Paint	complete
2025/05/06	SPECIAL OPERATION LT 143	In Wall Insulation	complete
2025/05/06	SPECIAL OPERATION LT 143	Overhead Duct Insulation	in progress
2025/05/06	SPECIAL OPERATION LT 143	Overhead Duct Rough In	in progress
2025/05/06	SPECIAL OPERATION LT 143	Overhead Plumbing	not

started			
2025/05/06		SPECIAL OPERATION LT 143	Wall Drywall   complete
2025/05/06		SPECIAL OPERATION LT 143	Wall Drywall Finish   complete
2025/05/06		SPECIAL OPERATION LT 143	Wall Prime Paint   complete
2025/05/06		STAIR A	In Wall Insulation   not started
2025/05/06		STAIR A	Overhead Duct Insulation   not started
2025/05/06		STAIR A	Overhead Duct Rough In   not started
2025/05/06		STAIR A	Overhead Plumbing   not started
2025/05/06		STAIR A	Wall Drywall   not started
2025/05/06		STAIR A	Wall Drywall Finish   not started
2025/05/06		STAIR A	Wall Prime Paint   not started
2025/05/06		STORAGE 104	In Wall Insulation   complete
2025/05/06		STORAGE 104	Overhead Duct Insulation   no data
2025/05/06		STORAGE 104	Overhead Duct Rough In   no data
2025/05/06		STORAGE 104	Overhead Plumbing   no data
2025/05/06		STORAGE 104	Wall Drywall   no data
2025/05/06		STORAGE 104	Wall Drywall Finish   no data
2025/05/06		STORAGE 104	Wall Prime Paint   no data
2025/05/06		STORAGE 127	In Wall Insulation   complete
2025/05/06		STORAGE 127	Overhead Duct Insulation   in progress
2025/05/06		STORAGE 127	Overhead Duct Rough In   in progress
2025/05/06		STORAGE 127	Overhead Plumbing   not started
2025/05/06		STORAGE 127	Wall Drywall   complete
2025/05/06		STORAGE 127	Wall Drywall Finish   complete
2025/05/06		STORAGE 127	Wall Prime Paint   complete
2025/05/06		STUDIO 126	In Wall Insulation   complete
2025/05/06		STUDIO 126	Overhead Duct Insulation   in progress
2025/05/06		STUDIO 126	Overhead Duct Rough In   in progress
2025/05/06		STUDIO 126	Overhead Plumbing   not started
2025/05/06		STUDIO 126	Wall Drywall   complete
2025/05/06		STUDIO 126	Wall Drywall Finish   complete
2025/05/06		STUDIO 126	Wall Prime Paint   in progress
2025/05/06		SUPERVISOR 129	In Wall Insulation   complete
2025/05/06		SUPERVISOR 129	Overhead Duct Insulation   in progress
2025/05/06		SUPERVISOR 129	Overhead Duct Rough In   in progress
2025/05/06		SUPERVISOR 129	Overhead Plumbing   not started
2025/05/06		SUPERVISOR 129	Wall Drywall   complete
2025/05/06		SUPERVISOR 129	Wall Drywall Finish   complete
2025/05/06		SUPERVISOR 129	Wall Prime Paint   complete
2025/05/06		Storage 164	In Wall Insulation   complete
2025/05/06		Storage 164	Overhead Duct Insulation   in progress
2025/05/06		Storage 164	Overhead Duct Rough In   in progress
2025/05/06		Storage 164	Overhead Plumbing   not started
2025/05/06		Storage 164	Wall Drywall   complete
2025/05/06		Storage 164	Wall Drywall Finish   complete
2025/05/06		Storage 164	Wall Prime Paint   complete
2025/05/06		Storage 177	In Wall Insulation   complete
2025/05/06		Storage 177	Overhead Duct Insulation   in progress
2025/05/06		Storage 177	Overhead Duct Rough In   in progress
2025/05/06		Storage 177	Overhead Plumbing   not started
2025/05/06		Storage 177	Wall Drywall   complete
2025/05/06		Storage 177	Wall Drywall Finish   complete
2025/05/06		Storage 177	Wall Prime Paint   complete

2025/05/06	TECHNICAL SURVEELLANCE 188	In Wall Insulation	in progress
2025/05/06	TECHNICAL SURVEELLANCE 188	Overhead Duct Insulation	not started
2025/05/06	TECHNICAL SURVEELLANCE 188	Overhead Duct Rough In	in progress
2025/05/06	TECHNICAL SURVEELLANCE 188	Overhead Plumbing	not started
2025/05/06	TECHNICAL SURVEELLANCE 188	Wall Drywall	in progress
2025/05/06	TECHNICAL SURVEELLANCE 188	Wall Drywall Finish	not started
2025/05/06	TECHNICAL SURVEELLANCE 188	Wall Prime Paint	not started
2025/05/06	TRAFFIC SERGEANT 141	In Wall Insulation	complete
2025/05/06	TRAFFIC SERGEANT 141	Overhead Duct Insulation	in progress
2025/05/06	TRAFFIC SERGEANT 141	Overhead Duct Rough In	in progress
2025/05/06	TRAFFIC SERGEANT 141	Overhead Plumbing	in progress
2025/05/06	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/05/06	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/05/06	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/05/06	TRIAGE/RECEPTION 134	In Wall Insulation	complete
2025/05/06	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/05/06	TRIAGE/RECEPTION 134	Overhead Duct Rough In	in progress
2025/05/06	TRIAGE/RECEPTION 134	Overhead Plumbing	not started
2025/05/06	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/05/06	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/05/06	TRIAGE/RECEPTION 134	Wall Prime Paint	in progress
2025/05/06	TST WORKSHOP 187	In Wall Insulation	in progress
2025/05/06	TST WORKSHOP 187	Overhead Duct Insulation	not started
2025/05/06	TST WORKSHOP 187	Overhead Duct Rough In	in progress
2025/05/06	TST WORKSHOP 187	Overhead Plumbing	not started
2025/05/06	TST WORKSHOP 187	Wall Drywall	in progress
2025/05/06	TST WORKSHOP 187	Wall Drywall Finish	not started
2025/05/06	TST WORKSHOP 187	Wall Prime Paint	not started
2025/05/06	UNISEX RESTROOM 169	In Wall Insulation	in progress
2025/05/06	UNISEX RESTROOM 169	Overhead Duct Insulation	in progress
2025/05/06	UNISEX RESTROOM 169	Overhead Duct Rough In	in progress
2025/05/06	UNISEX RESTROOM 169	Overhead Plumbing	in progress
2025/05/06	UNISEX RESTROOM 169	Wall Drywall	in progress
2025/05/06	UNISEX RESTROOM 169	Wall Drywall Finish	not started
2025/05/06	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/05/06	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	in progress
2025/05/06	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	not started
2025/05/06	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	not started

2025/05/06	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete
2025/05/06	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	in progress
2025/05/06	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	in progress
2025/05/06	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	not started
2025/05/06	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	complete
2025/05/06	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	in progress
2025/05/06	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	in progress
2025/05/06	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	in progress
2025/05/06	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/05/06	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/05/06	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/05/06	WAITING/LOBBY 100	In Wall Insulation	not started
2025/05/06	WAITING/LOBBY 100	Overhead Duct Insulation	not started
2025/05/06	WAITING/LOBBY 100	Overhead Duct Rough In	not started
2025/05/06	WAITING/LOBBY 100	Overhead Plumbing	not started
2025/05/06	WAITING/LOBBY 100	Wall Drywall	not started
2025/05/06	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/05/06	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/05/06	WOMENS RESTROOM 113	In Wall Insulation	in progress
2025/05/06	WOMENS RESTROOM 113	Overhead Duct Insulation	in progress
2025/05/06	WOMENS RESTROOM 113	Overhead Duct Rough In	in progress
2025/05/06	WOMENS RESTROOM 113	Overhead Plumbing	in progress
2025/05/06	WOMENS RESTROOM 113	Wall Drywall	in progress
2025/05/06	WOMENS RESTROOM 113	Wall Drywall Finish	in progress
2025/05/06	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/05/07	ADMIN ASSISTANT 125	In Wall Insulation	complete
2025/05/07	ADMIN ASSISTANT 125	Overhead Duct Insulation	in progress
2025/05/07	ADMIN ASSISTANT 125	Overhead Duct Rough In	in progress
2025/05/07	ADMIN ASSISTANT 125	Overhead Plumbing	not started
2025/05/07	ADMIN ASSISTANT 125	Wall Drywall	in progress
2025/05/07	ADMIN ASSISTANT 125	Wall Drywall Finish	in progress
2025/05/07	ADMIN ASSISTANT 125	Wall Prime Paint	in progress
2025/05/07	AV ROOM 103	In Wall Insulation	complete
2025/05/07	AV ROOM 103	Overhead Duct Insulation	in progress
2025/05/07	AV ROOM 103	Overhead Duct Rough In	in progress
2025/05/07	AV ROOM 103	Overhead Plumbing	not started
2025/05/07	AV ROOM 103	Wall Drywall	in progress
2025/05/07	AV ROOM 103	Wall Drywall Finish	in progress
2025/05/07	AV ROOM 103	Wall Prime Paint	in progress

2025/05/07	BREAK ROOM CONFERENCE 182	In Wall Insulation	in progress
2025/05/07	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	in progress
2025/05/07	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	in progress
2025/05/07	BREAK ROOM CONFERENCE 182	Overhead Plumbing	in progress
2025/05/07	BREAK ROOM CONFERENCE 182	Wall Drywall	in progress
2025/05/07	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	not started
2025/05/07	BREAK ROOM CONFERENCE 182	Wall Prime Paint	not started
2025/05/07	Background-159	In Wall Insulation	not started
2025/05/07	Background-159	Overhead Duct Insulation	not started
2025/05/07	Background-159	Overhead Duct Rough In	in progress
2025/05/07	Background-159	Overhead Plumbing	not started
2025/05/07	Background-159	Wall Drywall	not started
2025/05/07	Background-159	Wall Drywall Finish	not started
2025/05/07	Background-159	Wall Prime Paint	not started
2025/05/07	CENTRAL BREAKROOM 145	In Wall Insulation	in progress
2025/05/07	CENTRAL BREAKROOM 145	Overhead Duct Insulation	not started
2025/05/07	CENTRAL BREAKROOM 145	Overhead Duct Rough In	in progress
2025/05/07	CENTRAL BREAKROOM 145	Overhead Plumbing	not started
2025/05/07	CENTRAL BREAKROOM 145	Wall Drywall	in progress
2025/05/07	CENTRAL BREAKROOM 145	Wall Drywall Finish	not started
2025/05/07	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/05/07	COLD CASE 175	In Wall Insulation	complete
2025/05/07	COLD CASE 175	Overhead Duct Insulation	in progress
2025/05/07	COLD CASE 175	Overhead Duct Rough In	in progress
2025/05/07	COLD CASE 175	Overhead Plumbing	in progress
2025/05/07	COLD CASE 175	Wall Drywall	complete
2025/05/07	COLD CASE 175	Wall Drywall Finish	complete
2025/05/07	COLD CASE 175	Wall Prime Paint	in progress
2025/05/07	COMMUNITY AFFAIRS 124	In Wall Insulation	complete
2025/05/07	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	in progress
2025/05/07	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	in progress
2025/05/07	COMMUNITY AFFAIRS 124	Overhead Plumbing	not started
2025/05/07	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/05/07	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/05/07	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/05/07	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	in progress
2025/05/07	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	in progress
2025/05/07	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	in progress
2025/05/07	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	not

started  
 2025/05/07 | COMMUNITY ROOM 247 PPL 102 | Wall Drywall | in progress  
 2025/05/07 | COMMUNITY ROOM 247 PPL 102 | Wall Drywall Finish | not  
 started  
 2025/05/07 | COMMUNITY ROOM 247 PPL 102 | Wall Prime Paint | not  
 started  
 2025/05/07 | CONFERENCE ROOM 153 | In Wall Insulation | in progress  
 2025/05/07 | CONFERENCE ROOM 153 | Overhead Duct Insulation | in  
 progress  
 2025/05/07 | CONFERENCE ROOM 153 | Overhead Duct Rough In | in  
 progress  
 2025/05/07 | CONFERENCE ROOM 153 | Overhead Plumbing | not started  
 2025/05/07 | CONFERENCE ROOM 153 | Wall Drywall | in progress  
 2025/05/07 | CONFERENCE ROOM 153 | Wall Drywall Finish | not started  
 2025/05/07 | CONFERENCE ROOM 153 | Wall Prime Paint | not started  
 2025/05/07 | CONFERENCE/WAR ROOM 163 | In Wall Insulation | complete  
 2025/05/07 | CONFERENCE/WAR ROOM 163 | Overhead Duct Insulation | in  
 progress  
 2025/05/07 | CONFERENCE/WAR ROOM 163 | Overhead Duct Rough In | in  
 progress  
 2025/05/07 | CONFERENCE/WAR ROOM 163 | Overhead Plumbing | not  
 started  
 2025/05/07 | CONFERENCE/WAR ROOM 163 | Wall Drywall | complete  
 2025/05/07 | CONFERENCE/WAR ROOM 163 | Wall Drywall Finish |  
 complete  
 2025/05/07 | CONFERENCE/WAR ROOM 163 | Wall Prime Paint | complete  
 2025/05/07 | COPY 176 | In Wall Insulation | complete  
 2025/05/07 | COPY 176 | Overhead Duct Insulation | in progress  
 2025/05/07 | COPY 176 | Overhead Duct Rough In | in progress  
 2025/05/07 | COPY 176 | Overhead Plumbing | not started  
 2025/05/07 | COPY 176 | Wall Drywall | complete  
 2025/05/07 | COPY 176 | Wall Drywall Finish | complete  
 2025/05/07 | COPY 176 | Wall Prime Paint | complete  
 2025/05/07 | COPY/MAIL ROOM 114 | In Wall Insulation | complete  
 2025/05/07 | COPY/MAIL ROOM 114 | Overhead Duct Insulation | in  
 progress  
 2025/05/07 | COPY/MAIL ROOM 114 | Overhead Duct Rough In | in  
 progress  
 2025/05/07 | COPY/MAIL ROOM 114 | Overhead Plumbing | in progress  
 2025/05/07 | COPY/MAIL ROOM 114 | Wall Drywall | complete  
 2025/05/07 | COPY/MAIL ROOM 114 | Wall Drywall Finish | complete  
 2025/05/07 | COPY/MAIL ROOM 114 | Wall Prime Paint | complete  
 2025/05/07 | CORRIDOR 107 | In Wall Insulation | complete  
 2025/05/07 | CORRIDOR 107 | Overhead Duct Insulation | in progress  
 2025/05/07 | CORRIDOR 107 | Overhead Duct Rough In | in progress  
 2025/05/07 | CORRIDOR 107 | Overhead Plumbing | in progress  
 2025/05/07 | CORRIDOR 107 | Wall Drywall | complete  
 2025/05/07 | CORRIDOR 107 | Wall Drywall Finish | complete  
 2025/05/07 | CORRIDOR 107 | Wall Prime Paint | in progress  
 2025/05/07 | CORRIDOR 108 | In Wall Insulation | complete  
 2025/05/07 | CORRIDOR 108 | In Wall Insulation | complete  
 2025/05/07 | CORRIDOR 108 | Overhead Duct Insulation | in progress  
 2025/05/07 | CORRIDOR 108 | Overhead Duct Insulation | in progress  
 2025/05/07 | CORRIDOR 108 | Overhead Duct Rough In | in progress

2025/05/07	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/05/07	CORRIDOR 108	Overhead Plumbing	in progress
2025/05/07	CORRIDOR 108	Overhead Plumbing	in progress
2025/05/07	CORRIDOR 108	Wall Drywall	complete
2025/05/07	CORRIDOR 108	Wall Drywall	complete
2025/05/07	CORRIDOR 108	Wall Drywall Finish	complete
2025/05/07	CORRIDOR 108	Wall Drywall Finish	complete
2025/05/07	CORRIDOR 108	Wall Prime Paint	in progress
2025/05/07	CORRIDOR 108	Wall Prime Paint	in progress
2025/05/07	CORRIDOR 109	In Wall Insulation	complete
2025/05/07	CORRIDOR 109	Overhead Duct Insulation	in progress
2025/05/07	CORRIDOR 109	Overhead Duct Rough In	in progress
2025/05/07	CORRIDOR 109	Overhead Plumbing	in progress
2025/05/07	CORRIDOR 109	Wall Drywall	complete
2025/05/07	CORRIDOR 109	Wall Drywall Finish	complete
2025/05/07	CORRIDOR 109	Wall Prime Paint	complete
2025/05/07	CORRIDOR 110	In Wall Insulation	complete
2025/05/07	CORRIDOR 110	In Wall Insulation	complete
2025/05/07	CORRIDOR 110	Overhead Duct Insulation	in progress
2025/05/07	CORRIDOR 110	Overhead Duct Insulation	in progress
2025/05/07	CORRIDOR 110	Overhead Duct Rough In	in progress
2025/05/07	CORRIDOR 110	Overhead Duct Rough In	in progress
2025/05/07	CORRIDOR 110	Overhead Plumbing	in progress
2025/05/07	CORRIDOR 110	Overhead Plumbing	in progress
2025/05/07	CORRIDOR 110	Wall Drywall	complete
2025/05/07	CORRIDOR 110	Wall Drywall	complete
2025/05/07	CORRIDOR 110	Wall Drywall Finish	in progress
2025/05/07	CORRIDOR 110	Wall Drywall Finish	in progress
2025/05/07	CORRIDOR 110	Wall Prime Paint	in progress
2025/05/07	CORRIDOR 110	Wall Prime Paint	in progress
2025/05/07	CORRIDOR 181	In Wall Insulation	in progress
2025/05/07	CORRIDOR 181	Overhead Duct Insulation	not started
2025/05/07	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/05/07	CORRIDOR 181	Overhead Plumbing	in progress
2025/05/07	CORRIDOR 181	Wall Drywall	in progress
2025/05/07	CORRIDOR 181	Wall Drywall Finish	not started
2025/05/07	CORRIDOR 181	Wall Prime Paint	not started
2025/05/07	CORRIDOR144	In Wall Insulation	in progress
2025/05/07	CORRIDOR144	Overhead Duct Insulation	in progress
2025/05/07	CORRIDOR144	Overhead Duct Rough In	in progress
2025/05/07	CORRIDOR144	Overhead Plumbing	in progress
2025/05/07	CORRIDOR144	Wall Drywall	in progress
2025/05/07	CORRIDOR144	Wall Drywall Finish	in progress
2025/05/07	CORRIDOR144	Wall Prime Paint	in progress
2025/05/07	CPL 173	In Wall Insulation	no data
2025/05/07	CPL 173	Overhead Duct Insulation	no data
2025/05/07	CPL 173	Overhead Duct Rough In	no data
2025/05/07	CPL 173	Overhead Plumbing	no data
2025/05/07	CPL 173	Wall Drywall	no data
2025/05/07	CPL 173	Wall Drywall Finish	no data
2025/05/07	CPL 173	Wall Prime Paint	no data
2025/05/07	CPL 174	In Wall Insulation	no data
2025/05/07	CPL 174	Overhead Duct Insulation	no data
2025/05/07	CPL 174	Overhead Duct Rough In	no data



2025/05/07	CPL 174	Overhead Plumbing	no data
2025/05/07	CPL 174	Wall Drywall	no data
2025/05/07	CPL 174	Wall Drywall Finish	no data
2025/05/07	CPL 174	Wall Prime Paint	no data
2025/05/07	DRY STORAGE 146	In Wall Insulation	no data
2025/05/07	DRY STORAGE 146	Overhead Duct Insulation	no data
2025/05/07	DRY STORAGE 146	Overhead Duct Rough In	no data
2025/05/07	DRY STORAGE 146	Overhead Plumbing	no data
2025/05/07	DRY STORAGE 146	Wall Drywall	no data
2025/05/07	DRY STORAGE 146	Wall Drywall Finish	no data
2025/05/07	DRY STORAGE 146	Wall Prime Paint	no data
2025/05/07	FIRE RISER 178	In Wall Insulation	complete
2025/05/07	FIRE RISER 178	Overhead Duct Insulation	not started
2025/05/07	FIRE RISER 178	Overhead Duct Rough In	not started
2025/05/07	FIRE RISER 178	Overhead Plumbing	not started
2025/05/07	FIRE RISER 178	Wall Drywall	complete
2025/05/07	FIRE RISER 178	Wall Drywall Finish	complete
2025/05/07	FIRE RISER 178	Wall Prime Paint	not started
2025/05/07	GREETING ROOM 106	In Wall Insulation	complete
2025/05/07	GREETING ROOM 106	Overhead Duct Insulation	in progress
2025/05/07	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/05/07	GREETING ROOM 106	Overhead Plumbing	not started
2025/05/07	GREETING ROOM 106	Wall Drywall	complete
2025/05/07	GREETING ROOM 106	Wall Drywall Finish	complete
2025/05/07	GREETING ROOM 106	Wall Prime Paint	complete
2025/05/07	HR 149	In Wall Insulation	not started
2025/05/07	HR 149	Overhead Duct Insulation	not started
2025/05/07	HR 149	Overhead Duct Rough In	in progress
2025/05/07	HR 149	Overhead Plumbing	not started
2025/05/07	HR 149	Wall Drywall	not started
2025/05/07	HR 149	Wall Drywall Finish	not started
2025/05/07	HR 149	Wall Prime Paint	not started
2025/05/07	HR 150	In Wall Insulation	not started
2025/05/07	HR 150	Overhead Duct Insulation	not started
2025/05/07	HR 150	Overhead Duct Rough In	in progress
2025/05/07	HR 150	Overhead Plumbing	not started
2025/05/07	HR 150	Wall Drywall	not started
2025/05/07	HR 150	Wall Drywall Finish	not started
2025/05/07	HR 150	Wall Prime Paint	not started
2025/05/07	HR 151	In Wall Insulation	not started
2025/05/07	HR 151	Overhead Duct Insulation	not started
2025/05/07	HR 151	Overhead Duct Rough In	in progress
2025/05/07	HR 151	Overhead Plumbing	in progress
2025/05/07	HR 151	Wall Drywall	not started
2025/05/07	HR 151	Wall Drywall Finish	not started
2025/05/07	HR 151	Wall Prime Paint	not started
2025/05/07	HR 154	In Wall Insulation	not started
2025/05/07	HR 154	Overhead Duct Insulation	not started
2025/05/07	HR 154	Overhead Duct Rough In	in progress
2025/05/07	HR 154	Overhead Plumbing	in progress
2025/05/07	HR 154	Wall Drywall	not started
2025/05/07	HR 154	Wall Drywall Finish	not started

2025/05/07	HR 154	Wall Prime Paint	not started
2025/05/07	HR 155	In Wall Insulation	not started
2025/05/07	HR 155	Overhead Duct Insulation	in progress
2025/05/07	HR 155	Overhead Duct Rough In	in progress
2025/05/07	HR 155	Overhead Plumbing	not started
2025/05/07	HR 155	Wall Drywall	not started
2025/05/07	HR 155	Wall Drywall Finish	not started
2025/05/07	HR 155	Wall Prime Paint	not started
2025/05/07	HR 156	In Wall Insulation	not started
2025/05/07	HR 156	Overhead Duct Insulation	not started
2025/05/07	HR 156	Overhead Duct Rough In	in progress
2025/05/07	HR 156	Overhead Plumbing	not started
2025/05/07	HR 156	Wall Drywall	not started
2025/05/07	HR 156	Wall Drywall Finish	not started
2025/05/07	HR 156	Wall Prime Paint	not started
2025/05/07	HR 157	In Wall Insulation	not started
2025/05/07	HR 157	Overhead Duct Insulation	not started
2025/05/07	HR 157	Overhead Duct Rough In	in progress
2025/05/07	HR 157	Overhead Plumbing	in progress
2025/05/07	HR 157	Wall Drywall	not started
2025/05/07	HR 157	Wall Drywall Finish	not started
2025/05/07	HR 157	Wall Prime Paint	not started
2025/05/07	HUMAN RESOURCES 148	In Wall Insulation	not started
2025/05/07	HUMAN RESOURCES 148	Overhead Duct Insulation	not started
2025/05/07	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/05/07	HUMAN RESOURCES 148	Overhead Plumbing	in progress
2025/05/07	HUMAN RESOURCES 148	Wall Drywall	not started
2025/05/07	HUMAN RESOURCES 148	Wall Drywall Finish	not started
2025/05/07	HUMAN RESOURCES 148	Wall Prime Paint	not started
2025/05/07	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/05/07	INTERNAL AFFAIRS 119	Overhead Duct Insulation	not started
2025/05/07	INTERNAL AFFAIRS 119	Overhead Duct Rough In	in progress
2025/05/07	INTERNAL AFFAIRS 119	Overhead Plumbing	in progress
2025/05/07	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/05/07	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/05/07	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/05/07	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/05/07	INTERNAL AFFAIRS 120	Overhead Duct Insulation	in progress
2025/05/07	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/05/07	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/05/07	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/05/07	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/05/07	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/05/07	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	complete
2025/05/07	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	in progress
2025/05/07	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	

in progress

2025/05/07 | INTERVIEW / REVIEW ROOM 118 | Overhead Plumbing | not started

2025/05/07 | INTERVIEW / REVIEW ROOM 118 | Wall Drywall | complete

2025/05/07 | INTERVIEW / REVIEW ROOM 118 | Wall Drywall Finish | complete

2025/05/07 | INTERVIEW / REVIEW ROOM 118 | Wall Prime Paint | complete

2025/05/07 | INTERVIEW/ REVIEW ROOM 121 | In Wall Insulation | complete

2025/05/07 | INTERVIEW/ REVIEW ROOM 121 | Overhead Duct Insulation | in progress

2025/05/07 | INTERVIEW/ REVIEW ROOM 121 | Overhead Duct Rough In | in progress

2025/05/07 | INTERVIEW/ REVIEW ROOM 121 | Overhead Plumbing | in progress

2025/05/07 | INTERVIEW/ REVIEW ROOM 121 | Wall Drywall | complete

2025/05/07 | INTERVIEW/ REVIEW ROOM 121 | Wall Drywall Finish | complete

2025/05/07 | INTERVIEW/ REVIEW ROOM 121 | Wall Prime Paint | complete

2025/05/07 | INVESTIGATIONS / MAJOR CASE 167 | In Wall Insulation | complete

2025/05/07 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Insulation | in progress

2025/05/07 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Rough In | in progress

2025/05/07 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Plumbing | in progress

2025/05/07 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall | complete

2025/05/07 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall Finish | complete

2025/05/07 | INVESTIGATIONS / MAJOR CASE 167 | Wall Prime Paint | complete

2025/05/07 | IT 115 | In Wall Insulation | complete

2025/05/07 | IT 115 | Overhead Duct Insulation | not started

2025/05/07 | IT 115 | Overhead Duct Rough In | not started

2025/05/07 | IT 115 | Overhead Plumbing | in progress

2025/05/07 | IT 115 | Wall Drywall | complete

2025/05/07 | IT 115 | Wall Drywall Finish | complete

2025/05/07 | IT 115 | Wall Prime Paint | complete

2025/05/07 | IT 135 | In Wall Insulation | complete

2025/05/07 | IT 135 | Overhead Duct Insulation | in progress

2025/05/07 | IT 135 | Overhead Duct Rough In | in progress

2025/05/07 | IT 135 | Overhead Plumbing | in progress

2025/05/07 | IT 135 | Wall Drywall | complete

2025/05/07 | IT 135 | Wall Drywall Finish | complete

2025/05/07 | IT 135 | Wall Prime Paint | complete

2025/05/07 | IT MANAGER 136 | In Wall Insulation | complete

2025/05/07 | IT MANAGER 136 | Overhead Duct Insulation | in progress

2025/05/07 | IT MANAGER 136 | Overhead Duct Rough In | in progress

2025/05/07 | IT MANAGER 136 | Overhead Plumbing | in progress

2025/05/07 | IT MANAGER 136 | Wall Drywall | complete

2025/05/07	IT MANAGER 136	Wall Drywall Finish	complete
2025/05/07	IT MANAGER 136	Wall Prime Paint	complete
2025/05/07	IT MANAGER 137	In Wall Insulation	complete
2025/05/07	IT MANAGER 137	Overhead Duct Insulation	in progress
2025/05/07	IT MANAGER 137	Overhead Duct Rough In	in progress
2025/05/07	IT MANAGER 137	Overhead Plumbing	in progress
2025/05/07	IT MANAGER 137	Wall Drywall	complete
2025/05/07	IT MANAGER 137	Wall Drywall Finish	complete
2025/05/07	IT MANAGER 137	Wall Prime Paint	complete
2025/05/07	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/05/07	JUVENILE INTERVIEW 165	Overhead Duct Insulation	in progress
2025/05/07	JUVENILE INTERVIEW 165	Overhead Duct Rough In	in progress
2025/05/07	JUVENILE INTERVIEW 165	Overhead Plumbing	complete
2025/05/07	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/05/07	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/05/07	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/05/07	JUVENILLE INTERVIEWERS 166	In Wall Insulation	complete
2025/05/07	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/05/07	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/05/07	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	not started
2025/05/07	JUVENILLE INTERVIEWERS 166	Wall Drywall	complete
2025/05/07	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/05/07	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/05/07	KEY ROOM 185	In Wall Insulation	in progress
2025/05/07	KEY ROOM 185	Overhead Duct Insulation	not started
2025/05/07	KEY ROOM 185	Overhead Duct Rough In	in progress
2025/05/07	KEY ROOM 185	Overhead Plumbing	not started
2025/05/07	KEY ROOM 185	Wall Drywall	in progress
2025/05/07	KEY ROOM 185	Wall Drywall Finish	not started
2025/05/07	KEY ROOM 185	Wall Prime Paint	not started
2025/05/07	LT 170	In Wall Insulation	complete
2025/05/07	LT 170	Overhead Duct Insulation	in progress
2025/05/07	LT 170	Overhead Duct Rough In	in progress
2025/05/07	LT 170	Overhead Plumbing	not started
2025/05/07	LT 170	Wall Drywall	complete
2025/05/07	LT 170	Wall Drywall Finish	complete
2025/05/07	LT 170	Wall Prime Paint	complete
2025/05/07	MACHINE ROOM 191	In Wall Insulation	complete
2025/05/07	MACHINE ROOM 191	Overhead Duct Insulation	complete
2025/05/07	MACHINE ROOM 191	Overhead Duct Rough In	in progress
2025/05/07	MACHINE ROOM 191	Overhead Plumbing	not started
2025/05/07	MACHINE ROOM 191	Wall Drywall	complete
2025/05/07	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/05/07	MACHINE ROOM 191	Wall Prime Paint	complete
2025/05/07	MAIN ELECTRICAL ROOM 123	In Wall Insulation	complete

2025/05/07	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	not started
2025/05/07	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	not started
2025/05/07	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	not started
2025/05/07	MAIN ELECTRICAL ROOM 123	Wall Drywall	complete
2025/05/07	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	complete
2025/05/07	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	in progress
2025/05/07	MAIN JANITORIAL111	In Wall Insulation	complete
2025/05/07	MAIN JANITORIAL111	Overhead Duct Insulation	in progress
2025/05/07	MAIN JANITORIAL111	Overhead Duct Rough In	in progress
2025/05/07	MAIN JANITORIAL111	Overhead Plumbing	in progress
2025/05/07	MAIN JANITORIAL111	Wall Drywall	complete
2025/05/07	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/05/07	MAIN JANITORIAL111	Wall Prime Paint	in progress
2025/05/07	MARINE SERGEANT 142	In Wall Insulation	complete
2025/05/07	MARINE SERGEANT 142	Overhead Duct Insulation	in progress
2025/05/07	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/05/07	MARINE SERGEANT 142	Overhead Plumbing	in progress
2025/05/07	MARINE SERGEANT 142	Wall Drywall	complete
2025/05/07	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/05/07	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/05/07	MECHANICAL 192	In Wall Insulation	complete
2025/05/07	MECHANICAL 192	Overhead Duct Insulation	not started
2025/05/07	MECHANICAL 192	Overhead Duct Rough In	in progress
2025/05/07	MECHANICAL 192	Overhead Plumbing	in progress
2025/05/07	MECHANICAL 192	Wall Drywall	complete
2025/05/07	MECHANICAL 192	Wall Drywall Finish	complete
2025/05/07	MECHANICAL 192	Wall Prime Paint	complete
2025/05/07	MECHANICAL ROOM 122	In Wall Insulation	complete
2025/05/07	MECHANICAL ROOM 122	Overhead Duct Insulation	not started
2025/05/07	MECHANICAL ROOM 122	Overhead Duct Rough In	in progress
2025/05/07	MECHANICAL ROOM 122	Overhead Plumbing	in progress
2025/05/07	MECHANICAL ROOM 122	Wall Drywall	complete
2025/05/07	MECHANICAL ROOM 122	Wall Drywall Finish	complete
2025/05/07	MECHANICAL ROOM 122	Wall Prime Paint	complete
2025/05/07	MENS RESTROOM 112	In Wall Insulation	in progress
2025/05/07	MENS RESTROOM 112	Overhead Duct Insulation	in progress
2025/05/07	MENS RESTROOM 112	Overhead Duct Rough In	in progress
2025/05/07	MENS RESTROOM 112	Overhead Plumbing	in progress
2025/05/07	MENS RESTROOM 112	Wall Drywall	not started
2025/05/07	MENS RESTROOM 112	Wall Drywall Finish	not started
2025/05/07	MENS RESTROOM 112	Wall Prime Paint	not started

2025/05/07	MIS EQUIPMENT STORAGE 138	In Wall Insulation	complete
2025/05/07	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/05/07	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	in progress
2025/05/07	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	in progress
2025/05/07	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/05/07	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/05/07	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/05/07	MIS SHREDDING 117	In Wall Insulation	complete
2025/05/07	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/05/07	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/05/07	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/05/07	MIS SHREDDING 117	Wall Drywall	complete
2025/05/07	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/05/07	MIS SHREDDING 117	Wall Prime Paint	complete
2025/05/07	OFFICE 128	In Wall Insulation	complete
2025/05/07	OFFICE 128	Overhead Duct Insulation	in progress
2025/05/07	OFFICE 128	Overhead Duct Rough In	in progress
2025/05/07	OFFICE 128	Overhead Plumbing	not started
2025/05/07	OFFICE 128	Wall Drywall	complete
2025/05/07	OFFICE 128	Wall Drywall Finish	complete
2025/05/07	OFFICE 128	Wall Prime Paint	complete
2025/05/07	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	complete
2025/05/07	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	in progress
2025/05/07	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	in progress
2025/05/07	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	in progress
2025/05/07	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/05/07	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/05/07	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	in progress
2025/05/07	PARTS STORAGE 189	In Wall Insulation	in progress
2025/05/07	PARTS STORAGE 189	Overhead Duct Insulation	not started
2025/05/07	PARTS STORAGE 189	Overhead Duct Rough In	in progress
2025/05/07	PARTS STORAGE 189	Overhead Plumbing	not started
2025/05/07	PARTS STORAGE 189	Wall Drywall	in progress
2025/05/07	PARTS STORAGE 189	Wall Drywall Finish	in progress
2025/05/07	PARTS STORAGE 189	Wall Prime Paint	not started
2025/05/07	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/05/07	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data

2025/05/07	PUBLIC RESTROOM	106	Overhead Duct Rough In	no data
2025/05/07	PUBLIC RESTROOM	106	Overhead Plumbing	no data
2025/05/07	PUBLIC RESTROOM	106	Wall Drywall	no data
2025/05/07	PUBLIC RESTROOM	106	Wall Drywall Finish	no data
2025/05/07	PUBLIC RESTROOM	106	Wall Prime Paint	no data
2025/05/07	Polygraph	152	In Wall Insulation	no data
2025/05/07	Polygraph	152	Overhead Duct Insulation	no data
2025/05/07	Polygraph	152	Overhead Duct Rough In	no data
2025/05/07	Polygraph	152	Overhead Plumbing	no data
2025/05/07	Polygraph	152	Wall Drywall	no data
2025/05/07	Polygraph	152	Wall Drywall Finish	no data
2025/05/07	Polygraph	152	Wall Prime Paint	no data
2025/05/07	RECEPTION	101	In Wall Insulation	no data
2025/05/07	RECEPTION	101	Overhead Duct Insulation	no data
2025/05/07	RECEPTION	101	Overhead Duct Rough In	no data
2025/05/07	RECEPTION	101	Overhead Plumbing	no data
2025/05/07	RECEPTION	101	Wall Drywall	no data
2025/05/07	RECEPTION	101	Wall Drywall Finish	no data
2025/05/07	RECEPTION	101	Wall Prime Paint	no data
2025/05/07	RECEPTION	147	In Wall Insulation	in progress
2025/05/07	RECEPTION	147	Overhead Duct Insulation	in progress
2025/05/07	RECEPTION	147	Overhead Duct Rough In	in progress
2025/05/07	RECEPTION	147	Overhead Plumbing	in progress
2025/05/07	RECEPTION	147	Wall Drywall	in progress
2025/05/07	RECEPTION	147	Wall Drywall Finish	not started
2025/05/07	RECEPTION	147	Wall Prime Paint	not started
2025/05/07	RECEPTION	179	In Wall Insulation	in progress
2025/05/07	RECEPTION	179	Overhead Duct Insulation	not started
2025/05/07	RECEPTION	179	Overhead Duct Rough In	in progress
2025/05/07	RECEPTION	179	Overhead Plumbing	not started
2025/05/07	RECEPTION	179	Wall Drywall	in progress
2025/05/07	RECEPTION	179	Wall Drywall Finish	not started
2025/05/07	RECEPTION	179	Wall Prime Paint	not started
2025/05/07	RECORDS	130	In Wall Insulation	complete
2025/05/07	RECORDS	130	Overhead Duct Insulation	in progress
2025/05/07	RECORDS	130	Overhead Duct Rough In	in progress
2025/05/07	RECORDS	130	Overhead Plumbing	in progress
2025/05/07	RECORDS	130	Wall Drywall	complete
2025/05/07	RECORDS	130	Wall Drywall Finish	complete
2025/05/07	RECORDS	130	Wall Prime Paint	complete
2025/05/07	RECORDS STORAGE	133	In Wall Insulation	complete
2025/05/07	RECORDS STORAGE	133	Overhead Duct Insulation	in progress
2025/05/07	RECORDS STORAGE	133	Overhead Duct Rough In	in progress
2025/05/07	RECORDS STORAGE	133	Overhead Plumbing	not started
2025/05/07	RECORDS STORAGE	133	Wall Drywall	complete
2025/05/07	RECORDS STORAGE	133	Wall Drywall Finish	complete
2025/05/07	RECORDS STORAGE	133	Wall Prime Paint	complete
2025/05/07	RECORDS SUPERVISOR	131	In Wall Insulation	complete
2025/05/07	RECORDS SUPERVISOR	131	Overhead Duct Insulation	in progress
2025/05/07	RECORDS SUPERVISOR	131	Overhead Duct Rough In	in progress

2025/05/07	RECORDS SUPERVISOR 131	Overhead Plumbing   not started
2025/05/07	RECORDS SUPERVISOR 131	Wall Drywall   complete
2025/05/07	RECORDS SUPERVISOR 131	Wall Drywall Finish   complete
2025/05/07	RECORDS SUPERVISOR 131	Wall Prime Paint   complete
2025/05/07	RECORDS SUPERVISOR 132	In Wall Insulation   complete
2025/05/07	RECORDS SUPERVISOR 132	Overhead Duct Insulation   in progress
2025/05/07	RECORDS SUPERVISOR 132	Overhead Duct Rough In   in progress
2025/05/07	RECORDS SUPERVISOR 132	Overhead Plumbing   not started
2025/05/07	RECORDS SUPERVISOR 132	Wall Drywall   complete
2025/05/07	RECORDS SUPERVISOR 132	Wall Drywall Finish   complete
2025/05/07	RECORDS SUPERVISOR 132	Wall Prime Paint   complete
2025/05/07	RESTROOM 183	In Wall Insulation   in progress
2025/05/07	RESTROOM 183	Overhead Duct Insulation   in progress
2025/05/07	RESTROOM 183	Overhead Duct Rough In   in progress
2025/05/07	RESTROOM 183	Overhead Plumbing   in progress
2025/05/07	RESTROOM 183	Wall Drywall   not started
2025/05/07	RESTROOM 183	Wall Drywall Finish   not started
2025/05/07	RESTROOM 183	Wall Prime Paint   not started
2025/05/07	Risk Management - 158	In Wall Insulation   not started
2025/05/07	Risk Management - 158	Overhead Duct Insulation   not started
2025/05/07	Risk Management - 158	Overhead Duct Rough In   in progress
2025/05/07	Risk Management - 158	Overhead Plumbing   in progress
2025/05/07	Risk Management - 158	Wall Drywall   not started
2025/05/07	Risk Management - 158	Wall Drywall Finish   not started
2025/05/07	Risk Management - 158	Wall Prime Paint   not started
2025/05/07	SALLY PORT 105	In Wall Insulation   not started
2025/05/07	SALLY PORT 105	Overhead Duct Insulation   not started
2025/05/07	SALLY PORT 105	Overhead Duct Rough In   in progress
2025/05/07	SALLY PORT 105	Overhead Plumbing   not started
2025/05/07	SALLY PORT 105	Wall Drywall   not started
2025/05/07	SALLY PORT 105	Wall Drywall Finish   not started
2025/05/07	SALLY PORT 105	Wall Prime Paint   not started
2025/05/07	SANE EXAM ROOM 168	In Wall Insulation   complete
2025/05/07	SANE EXAM ROOM 168	Overhead Duct Insulation   in progress
2025/05/07	SANE EXAM ROOM 168	Overhead Duct Rough In   in progress
2025/05/07	SANE EXAM ROOM 168	Overhead Plumbing   complete
2025/05/07	SANE EXAM ROOM 168	Wall Drywall   complete
2025/05/07	SANE EXAM ROOM 168	Wall Drywall Finish   complete
2025/05/07	SANE EXAM ROOM 168	Wall Prime Paint   complete
2025/05/07	SGT 171	In Wall Insulation   complete
2025/05/07	SGT 171	Overhead Duct Insulation   in progress
2025/05/07	SGT 171	Overhead Duct Rough In   in progress
2025/05/07	SGT 171	Overhead Plumbing   in progress
2025/05/07	SGT 171	Wall Drywall   complete



2025/05/07	SGT 171	Wall Drywall Finish	complete
2025/05/07	SGT 171	Wall Prime Paint	complete
2025/05/07	SGT 172	In Wall Insulation	complete
2025/05/07	SGT 172	Overhead Duct Insulation	complete
2025/05/07	SGT 172	Overhead Duct Rough In	in progress
2025/05/07	SGT 172	Overhead Plumbing	in progress
2025/05/07	SGT 172	Wall Drywall	complete
2025/05/07	SGT 172	Wall Drywall Finish	complete
2025/05/07	SGT 172	Wall Prime Paint	complete
2025/05/07	SHIPPING STORAGE 190	In Wall Insulation	in progress
2025/05/07	SHIPPING STORAGE 190	Overhead Duct Insulation	not started
2025/05/07	SHIPPING STORAGE 190	Overhead Duct Rough In	in progress
2025/05/07	SHIPPING STORAGE 190	Overhead Plumbing	not started
2025/05/07	SHIPPING STORAGE 190	Wall Drywall	in progress
2025/05/07	SHIPPING STORAGE 190	Wall Drywall Finish	not started
2025/05/07	SHIPPING STORAGE 190	Wall Prime Paint	not started
2025/05/07	SHOP FORMAN 184	In Wall Insulation	in progress
2025/05/07	SHOP FORMAN 184	Overhead Duct Insulation	not started
2025/05/07	SHOP FORMAN 184	Overhead Duct Rough In	in progress
2025/05/07	SHOP FORMAN 184	Overhead Plumbing	not started
2025/05/07	SHOP FORMAN 184	Wall Drywall	in progress
2025/05/07	SHOP FORMAN 184	Wall Drywall Finish	not started
2025/05/07	SHOP FORMAN 184	Wall Prime Paint	not started
2025/05/07	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/05/07	SOFT INTERVIEW 161	Overhead Duct Insulation	complete
2025/05/07	SOFT INTERVIEW 161	Overhead Duct Rough In	in progress
2025/05/07	SOFT INTERVIEW 161	Overhead Plumbing	not started
2025/05/07	SOFT INTERVIEW 161	Wall Drywall	complete
2025/05/07	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/05/07	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/05/07	SOFT INTERVIEW 162	In Wall Insulation	complete
2025/05/07	SOFT INTERVIEW 162	Overhead Duct Insulation	in progress
2025/05/07	SOFT INTERVIEW 162	Overhead Duct Rough In	in progress
2025/05/07	SOFT INTERVIEW 162	Overhead Plumbing	not started
2025/05/07	SOFT INTERVIEW 162	Wall Drywall	complete
2025/05/07	SOFT INTERVIEW 162	Wall Drywall Finish	complete
2025/05/07	SOFT INTERVIEW 162	Wall Prime Paint	complete
2025/05/07	SPECIAL OPERATION LT 143	In Wall Insulation	complete
2025/05/07	SPECIAL OPERATION LT 143	Overhead Duct Insulation	in progress
2025/05/07	SPECIAL OPERATION LT 143	Overhead Duct Rough In	in progress
2025/05/07	SPECIAL OPERATION LT 143	Overhead Plumbing	not started
2025/05/07	SPECIAL OPERATION LT 143	Wall Drywall	complete

2025/05/07		SPECIAL OPERATION LT 143		Wall Drywall Finish		complete
2025/05/07		SPECIAL OPERATION LT 143		Wall Prime Paint		complete
2025/05/07		STAIR A		In Wall Insulation		no data
2025/05/07		STAIR A		Overhead Duct Insulation		no data
2025/05/07		STAIR A		Overhead Duct Rough In		no data
2025/05/07		STAIR A		Overhead Plumbing		no data
2025/05/07		STAIR A		Wall Drywall		no data
2025/05/07		STAIR A		Wall Drywall Finish		no data
2025/05/07		STAIR A		Wall Prime Paint		no data
2025/05/07		STORAGE 104		In Wall Insulation		complete
2025/05/07		STORAGE 104		Overhead Duct Insulation		in progress
2025/05/07		STORAGE 104		Overhead Duct Rough In		in progress
2025/05/07		STORAGE 104		Overhead Plumbing		not started
2025/05/07		STORAGE 104		Wall Drywall		in progress
2025/05/07		STORAGE 104		Wall Drywall Finish		in progress
2025/05/07		STORAGE 104		Wall Prime Paint		in progress
2025/05/07		STORAGE 127		In Wall Insulation		complete
2025/05/07		STORAGE 127		Overhead Duct Insulation		in progress
2025/05/07		STORAGE 127		Overhead Duct Rough In		in progress
2025/05/07		STORAGE 127		Overhead Plumbing		not started
2025/05/07		STORAGE 127		Wall Drywall		complete
2025/05/07		STORAGE 127		Wall Drywall Finish		complete
2025/05/07		STORAGE 127		Wall Prime Paint		complete
2025/05/07		STUDIO 126		In Wall Insulation		complete
2025/05/07		STUDIO 126		Overhead Duct Insulation		in progress
2025/05/07		STUDIO 126		Overhead Duct Rough In		in progress
2025/05/07		STUDIO 126		Overhead Plumbing		not started
2025/05/07		STUDIO 126		Wall Drywall		complete
2025/05/07		STUDIO 126		Wall Drywall Finish		complete
2025/05/07		STUDIO 126		Wall Prime Paint		in progress
2025/05/07		SUPERVISOR 129		In Wall Insulation		complete
2025/05/07		SUPERVISOR 129		Overhead Duct Insulation		in progress
2025/05/07		SUPERVISOR 129		Overhead Duct Rough In		in progress
2025/05/07		SUPERVISOR 129		Overhead Plumbing		not started
2025/05/07		SUPERVISOR 129		Wall Drywall		complete
2025/05/07		SUPERVISOR 129		Wall Drywall Finish		complete
2025/05/07		SUPERVISOR 129		Wall Prime Paint		complete
2025/05/07		Storage 164		In Wall Insulation		complete
2025/05/07		Storage 164		Overhead Duct Insulation		in progress
2025/05/07		Storage 164		Overhead Duct Rough In		in progress
2025/05/07		Storage 164		Overhead Plumbing		not started
2025/05/07		Storage 164		Wall Drywall		complete
2025/05/07		Storage 164		Wall Drywall Finish		complete
2025/05/07		Storage 164		Wall Prime Paint		complete
2025/05/07		Storage 177		In Wall Insulation		complete
2025/05/07		Storage 177		Overhead Duct Insulation		in progress
2025/05/07		Storage 177		Overhead Duct Rough In		in progress
2025/05/07		Storage 177		Overhead Plumbing		not started
2025/05/07		Storage 177		Wall Drywall		complete
2025/05/07		Storage 177		Wall Drywall Finish		complete
2025/05/07		Storage 177		Wall Prime Paint		complete
2025/05/07		TECHNICAL SURVEILLANCE 188		In Wall Insulation		in progress

2025/05/07	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	not started
2025/05/07	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	in progress
2025/05/07	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	not started
2025/05/07	TECHNICAL SURVEILLANCE 188	Wall Drywall	in progress
2025/05/07	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	not started
2025/05/07	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	not started
2025/05/07	TRAFFIC SERGEANT 141	In Wall Insulation	complete
2025/05/07	TRAFFIC SERGEANT 141	Overhead Duct Insulation	in progress
2025/05/07	TRAFFIC SERGEANT 141	Overhead Duct Rough In	in progress
2025/05/07	TRAFFIC SERGEANT 141	Overhead Plumbing	in progress
2025/05/07	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/05/07	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/05/07	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/05/07	TRIAGE/RECEPTION 134	In Wall Insulation	complete
2025/05/07	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/05/07	TRIAGE/RECEPTION 134	Overhead Duct Rough In	in progress
2025/05/07	TRIAGE/RECEPTION 134	Overhead Plumbing	not started
2025/05/07	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/05/07	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/05/07	TRIAGE/RECEPTION 134	Wall Prime Paint	in progress
2025/05/07	TST WORKSHOP 187	In Wall Insulation	in progress
2025/05/07	TST WORKSHOP 187	Overhead Duct Insulation	not started
2025/05/07	TST WORKSHOP 187	Overhead Duct Rough In	in progress
2025/05/07	TST WORKSHOP 187	Overhead Plumbing	not started
2025/05/07	TST WORKSHOP 187	Wall Drywall	in progress
2025/05/07	TST WORKSHOP 187	Wall Drywall Finish	not started
2025/05/07	TST WORKSHOP 187	Wall Prime Paint	not started
2025/05/07	UNISEX RESTROOM 169	In Wall Insulation	in progress
2025/05/07	UNISEX RESTROOM 169	Overhead Duct Insulation	in progress
2025/05/07	UNISEX RESTROOM 169	Overhead Duct Rough In	in progress
2025/05/07	UNISEX RESTROOM 169	Overhead Plumbing	in progress
2025/05/07	UNISEX RESTROOM 169	Wall Drywall	in progress
2025/05/07	UNISEX RESTROOM 169	Wall Drywall Finish	not started
2025/05/07	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/05/07	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	in progress
2025/05/07	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	not started
2025/05/07	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	not started
2025/05/07	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete

2025/05/07	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	in progress
2025/05/07	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	in progress
2025/05/07	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	not started
2025/05/07	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	complete
2025/05/07	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	in progress
2025/05/07	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	in progress
2025/05/07	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	in progress
2025/05/07	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/05/07	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/05/07	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/05/07	WAITING/LOBBY 100	In Wall Insulation	not started
2025/05/07	WAITING/LOBBY 100	Overhead Duct Insulation	not started
2025/05/07	WAITING/LOBBY 100	Overhead Duct Rough In	not started
2025/05/07	WAITING/LOBBY 100	Overhead Plumbing	not started
2025/05/07	WAITING/LOBBY 100	Wall Drywall	not started
2025/05/07	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/05/07	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/05/07	WOMENS RESTROOM 113	In Wall Insulation	in progress
2025/05/07	WOMENS RESTROOM 113	Overhead Duct Insulation	in progress
2025/05/07	WOMENS RESTROOM 113	Overhead Duct Rough In	in progress
2025/05/07	WOMENS RESTROOM 113	Overhead Plumbing	in progress
2025/05/07	WOMENS RESTROOM 113	Wall Drywall	in progress
2025/05/07	WOMENS RESTROOM 113	Wall Drywall Finish	in progress
2025/05/07	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/05/14	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/05/14	ADMIN ASSISTANT 125	Overhead Duct Insulation	no data
2025/05/14	ADMIN ASSISTANT 125	Overhead Duct Rough In	no data
2025/05/14	ADMIN ASSISTANT 125	Overhead Plumbing	no data
2025/05/14	ADMIN ASSISTANT 125	Wall Drywall	no data
2025/05/14	ADMIN ASSISTANT 125	Wall Drywall Finish	no data
2025/05/14	ADMIN ASSISTANT 125	Wall Prime Paint	no data
2025/05/14	AV ROOM 103	In Wall Insulation	complete
2025/05/14	AV ROOM 103	Overhead Duct Insulation	in progress
2025/05/14	AV ROOM 103	Overhead Duct Rough In	in progress
2025/05/14	AV ROOM 103	Overhead Plumbing	not started
2025/05/14	AV ROOM 103	Wall Drywall	complete
2025/05/14	AV ROOM 103	Wall Drywall Finish	complete
2025/05/14	AV ROOM 103	Wall Prime Paint	in progress
2025/05/14	BREAK ROOM CONFERENCE 182	In Wall Insulation	in progress
2025/05/14	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	

in progress

2025/05/14 | BREAK ROOM CONFERENCE 182 | Overhead Duct Rough In | in progress

2025/05/14 | BREAK ROOM CONFERENCE 182 | Overhead Plumbing | in progress

2025/05/14 | BREAK ROOM CONFERENCE 182 | Wall Drywall | in progress

2025/05/14 | BREAK ROOM CONFERENCE 182 | Wall Drywall Finish | not started

2025/05/14 | BREAK ROOM CONFERENCE 182 | Wall Prime Paint | not started

2025/05/14 | Background-159 | In Wall Insulation | not started

2025/05/14 | Background-159 | Overhead Duct Insulation | not started

2025/05/14 | Background-159 | Overhead Duct Rough In | in progress

2025/05/14 | Background-159 | Overhead Plumbing | not started

2025/05/14 | Background-159 | Wall Drywall | not started

2025/05/14 | Background-159 | Wall Drywall Finish | not started

2025/05/14 | Background-159 | Wall Prime Paint | not started

2025/05/14 | CENTRAL BREAKROOM 145 | In Wall Insulation | in progress

2025/05/14 | CENTRAL BREAKROOM 145 | Overhead Duct Insulation | not started

2025/05/14 | CENTRAL BREAKROOM 145 | Overhead Duct Rough In | in progress

2025/05/14 | CENTRAL BREAKROOM 145 | Overhead Plumbing | not started

2025/05/14 | CENTRAL BREAKROOM 145 | Wall Drywall | in progress

2025/05/14 | CENTRAL BREAKROOM 145 | Wall Drywall Finish | not started

2025/05/14 | CENTRAL BREAKROOM 145 | Wall Prime Paint | not started

2025/05/14 | COLD CASE 175 | In Wall Insulation | complete

2025/05/14 | COLD CASE 175 | Overhead Duct Insulation | in progress

2025/05/14 | COLD CASE 175 | Overhead Duct Rough In | in progress

2025/05/14 | COLD CASE 175 | Overhead Plumbing | in progress

2025/05/14 | COLD CASE 175 | Wall Drywall | complete

2025/05/14 | COLD CASE 175 | Wall Drywall Finish | complete

2025/05/14 | COLD CASE 175 | Wall Prime Paint | in progress

2025/05/14 | COMMUNITY AFFAIRS 124 | In Wall Insulation | complete

2025/05/14 | COMMUNITY AFFAIRS 124 | Overhead Duct Insulation | in progress

2025/05/14 | COMMUNITY AFFAIRS 124 | Overhead Duct Rough In | in progress

2025/05/14 | COMMUNITY AFFAIRS 124 | Overhead Plumbing | not started

2025/05/14 | COMMUNITY AFFAIRS 124 | Wall Drywall | complete

2025/05/14 | COMMUNITY AFFAIRS 124 | Wall Drywall Finish | complete

2025/05/14 | COMMUNITY AFFAIRS 124 | Wall Prime Paint | complete

2025/05/14 | COMMUNITY ROOM 247 PPL 102 | In Wall Insulation | in progress

2025/05/14 | COMMUNITY ROOM 247 PPL 102 | Overhead Duct Insulation | in progress

2025/05/14 | COMMUNITY ROOM 247 PPL 102 | Overhead Duct Rough In | in progress

2025/05/14 | COMMUNITY ROOM 247 PPL 102 | Overhead Plumbing | not started

2025/05/14 | COMMUNITY ROOM 247 PPL 102 | Wall Drywall | in progress

2025/05/14 | COMMUNITY ROOM 247 PPL 102 | Wall Drywall Finish | not

started  
 2025/05/14 | COMMUNITY ROOM 247 PPL 102 | Wall Prime Paint | not  
 started  
 2025/05/14 | CONFERENCE ROOM 153 | In Wall Insulation | in progress  
 2025/05/14 | CONFERENCE ROOM 153 | Overhead Duct Insulation | in  
 progress  
 2025/05/14 | CONFERENCE ROOM 153 | Overhead Duct Rough In | in  
 progress  
 2025/05/14 | CONFERENCE ROOM 153 | Overhead Plumbing | not started  
 2025/05/14 | CONFERENCE ROOM 153 | Wall Drywall | in progress  
 2025/05/14 | CONFERENCE ROOM 153 | Wall Drywall Finish | not started  
 2025/05/14 | CONFERENCE ROOM 153 | Wall Prime Paint | not started  
 2025/05/14 | CONFERENCE/WAR ROOM 163 | In Wall Insulation | complete  
 2025/05/14 | CONFERENCE/WAR ROOM 163 | Overhead Duct Insulation | in  
 progress  
 2025/05/14 | CONFERENCE/WAR ROOM 163 | Overhead Duct Rough In | in  
 progress  
 2025/05/14 | CONFERENCE/WAR ROOM 163 | Overhead Plumbing | not  
 started  
 2025/05/14 | CONFERENCE/WAR ROOM 163 | Wall Drywall | complete  
 2025/05/14 | CONFERENCE/WAR ROOM 163 | Wall Drywall Finish |  
 complete  
 2025/05/14 | CONFERENCE/WAR ROOM 163 | Wall Prime Paint | complete  
 2025/05/14 | COPY 176 | In Wall Insulation | complete  
 2025/05/14 | COPY 176 | Overhead Duct Insulation | in progress  
 2025/05/14 | COPY 176 | Overhead Duct Rough In | in progress  
 2025/05/14 | COPY 176 | Overhead Plumbing | not started  
 2025/05/14 | COPY 176 | Wall Drywall | complete  
 2025/05/14 | COPY 176 | Wall Drywall Finish | complete  
 2025/05/14 | COPY 176 | Wall Prime Paint | complete  
 2025/05/14 | COPY/MAIL ROOM 114 | In Wall Insulation | complete  
 2025/05/14 | COPY/MAIL ROOM 114 | Overhead Duct Insulation | in  
 progress  
 2025/05/14 | COPY/MAIL ROOM 114 | Overhead Duct Rough In | in  
 progress  
 2025/05/14 | COPY/MAIL ROOM 114 | Overhead Plumbing | in progress  
 2025/05/14 | COPY/MAIL ROOM 114 | Wall Drywall | complete  
 2025/05/14 | COPY/MAIL ROOM 114 | Wall Drywall Finish | complete  
 2025/05/14 | COPY/MAIL ROOM 114 | Wall Prime Paint | complete  
 2025/05/14 | CORRIDOR 107 | In Wall Insulation | complete  
 2025/05/14 | CORRIDOR 107 | Overhead Duct Insulation | in progress  
 2025/05/14 | CORRIDOR 107 | Overhead Duct Rough In | in progress  
 2025/05/14 | CORRIDOR 107 | Overhead Plumbing | in progress  
 2025/05/14 | CORRIDOR 107 | Wall Drywall | complete  
 2025/05/14 | CORRIDOR 107 | Wall Drywall Finish | complete  
 2025/05/14 | CORRIDOR 107 | Wall Prime Paint | in progress  
 2025/05/14 | CORRIDOR 108 | In Wall Insulation | complete  
 2025/05/14 | CORRIDOR 108 | In Wall Insulation | complete  
 2025/05/14 | CORRIDOR 108 | Overhead Duct Insulation | in progress  
 2025/05/14 | CORRIDOR 108 | Overhead Duct Insulation | in progress  
 2025/05/14 | CORRIDOR 108 | Overhead Duct Rough In | in progress  
 2025/05/14 | CORRIDOR 108 | Overhead Duct Rough In | in progress  
 2025/05/14 | CORRIDOR 108 | Overhead Plumbing | in progress  
 2025/05/14 | CORRIDOR 108 | Overhead Plumbing | in progress

2025/05/14	CORRIDOR 108	Wall Drywall	complete
2025/05/14	CORRIDOR 108	Wall Drywall	complete
2025/05/14	CORRIDOR 108	Wall Drywall Finish	complete
2025/05/14	CORRIDOR 108	Wall Drywall Finish	complete
2025/05/14	CORRIDOR 108	Wall Prime Paint	in progress
2025/05/14	CORRIDOR 108	Wall Prime Paint	in progress
2025/05/14	CORRIDOR 109	In Wall Insulation	complete
2025/05/14	CORRIDOR 109	Overhead Duct Insulation	in progress
2025/05/14	CORRIDOR 109	Overhead Duct Rough In	in progress
2025/05/14	CORRIDOR 109	Overhead Plumbing	in progress
2025/05/14	CORRIDOR 109	Wall Drywall	complete
2025/05/14	CORRIDOR 109	Wall Drywall Finish	complete
2025/05/14	CORRIDOR 109	Wall Prime Paint	complete
2025/05/14	CORRIDOR 110	In Wall Insulation	complete
2025/05/14	CORRIDOR 110	In Wall Insulation	complete
2025/05/14	CORRIDOR 110	Overhead Duct Insulation	in progress
2025/05/14	CORRIDOR 110	Overhead Duct Insulation	in progress
2025/05/14	CORRIDOR 110	Overhead Duct Rough In	in progress
2025/05/14	CORRIDOR 110	Overhead Duct Rough In	in progress
2025/05/14	CORRIDOR 110	Overhead Plumbing	in progress
2025/05/14	CORRIDOR 110	Overhead Plumbing	in progress
2025/05/14	CORRIDOR 110	Wall Drywall	complete
2025/05/14	CORRIDOR 110	Wall Drywall	complete
2025/05/14	CORRIDOR 110	Wall Drywall Finish	in progress
2025/05/14	CORRIDOR 110	Wall Drywall Finish	in progress
2025/05/14	CORRIDOR 110	Wall Prime Paint	in progress
2025/05/14	CORRIDOR 110	Wall Prime Paint	in progress
2025/05/14	CORRIDOR 181	In Wall Insulation	in progress
2025/05/14	CORRIDOR 181	Overhead Duct Insulation	not started
2025/05/14	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/05/14	CORRIDOR 181	Overhead Plumbing	in progress
2025/05/14	CORRIDOR 181	Wall Drywall	in progress
2025/05/14	CORRIDOR 181	Wall Drywall Finish	not started
2025/05/14	CORRIDOR 181	Wall Prime Paint	not started
2025/05/14	CORRIDOR144	In Wall Insulation	complete
2025/05/14	CORRIDOR144	Overhead Duct Insulation	in progress
2025/05/14	CORRIDOR144	Overhead Duct Rough In	in progress
2025/05/14	CORRIDOR144	Overhead Plumbing	in progress
2025/05/14	CORRIDOR144	Wall Drywall	in progress
2025/05/14	CORRIDOR144	Wall Drywall Finish	in progress
2025/05/14	CORRIDOR144	Wall Prime Paint	complete
2025/05/14	CPL 173	In Wall Insulation	complete
2025/05/14	CPL 173	Overhead Duct Insulation	in progress
2025/05/14	CPL 173	Overhead Duct Rough In	in progress
2025/05/14	CPL 173	Overhead Plumbing	in progress
2025/05/14	CPL 173	Wall Drywall	complete
2025/05/14	CPL 173	Wall Drywall Finish	in progress
2025/05/14	CPL 173	Wall Prime Paint	in progress
2025/05/14	CPL 174	In Wall Insulation	complete
2025/05/14	CPL 174	Overhead Duct Insulation	in progress
2025/05/14	CPL 174	Overhead Duct Rough In	in progress
2025/05/14	CPL 174	Overhead Plumbing	not started
2025/05/14	CPL 174	Wall Drywall	complete
2025/05/14	CPL 174	Wall Drywall Finish	complete

2025/05/14	CPL 174	Wall Prime Paint	in progress
2025/05/14	DRY STORAGE 146	In Wall Insulation	not started
2025/05/14	DRY STORAGE 146	Overhead Duct Insulation	not started
2025/05/14	DRY STORAGE 146	Overhead Duct Rough In	in progress
2025/05/14	DRY STORAGE 146	Overhead Plumbing	not started
2025/05/14	DRY STORAGE 146	Wall Drywall	not started
2025/05/14	DRY STORAGE 146	Wall Drywall Finish	not started
2025/05/14	DRY STORAGE 146	Wall Prime Paint	not started
2025/05/14	FIRE RISER 178	In Wall Insulation	complete
2025/05/14	FIRE RISER 178	Overhead Duct Insulation	not started
2025/05/14	FIRE RISER 178	Overhead Duct Rough In	not started
2025/05/14	FIRE RISER 178	Overhead Plumbing	not started
2025/05/14	FIRE RISER 178	Wall Drywall	complete
2025/05/14	FIRE RISER 178	Wall Drywall Finish	complete
2025/05/14	FIRE RISER 178	Wall Prime Paint	not started
2025/05/14	GREETING ROOM 106	In Wall Insulation	complete
2025/05/14	GREETING ROOM 106	Overhead Duct Insulation	in progress
2025/05/14	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/05/14	GREETING ROOM 106	Overhead Plumbing	not started
2025/05/14	GREETING ROOM 106	Wall Drywall	complete
2025/05/14	GREETING ROOM 106	Wall Drywall Finish	complete
2025/05/14	GREETING ROOM 106	Wall Prime Paint	complete
2025/05/14	HR 149	In Wall Insulation	not started
2025/05/14	HR 149	Overhead Duct Insulation	not started
2025/05/14	HR 149	Overhead Duct Rough In	in progress
2025/05/14	HR 149	Overhead Plumbing	not started
2025/05/14	HR 149	Wall Drywall	not started
2025/05/14	HR 149	Wall Drywall Finish	not started
2025/05/14	HR 149	Wall Prime Paint	not started
2025/05/14	HR 150	In Wall Insulation	not started
2025/05/14	HR 150	Overhead Duct Insulation	not started
2025/05/14	HR 150	Overhead Duct Rough In	in progress
2025/05/14	HR 150	Overhead Plumbing	not started
2025/05/14	HR 150	Wall Drywall	not started
2025/05/14	HR 150	Wall Drywall Finish	not started
2025/05/14	HR 150	Wall Prime Paint	not started
2025/05/14	HR 151	In Wall Insulation	not started
2025/05/14	HR 151	Overhead Duct Insulation	not started
2025/05/14	HR 151	Overhead Duct Rough In	in progress
2025/05/14	HR 151	Overhead Plumbing	in progress
2025/05/14	HR 151	Wall Drywall	not started
2025/05/14	HR 151	Wall Drywall Finish	not started
2025/05/14	HR 151	Wall Prime Paint	not started
2025/05/14	HR 154	In Wall Insulation	not started
2025/05/14	HR 154	Overhead Duct Insulation	not started
2025/05/14	HR 154	Overhead Duct Rough In	in progress
2025/05/14	HR 154	Overhead Plumbing	in progress
2025/05/14	HR 154	Wall Drywall	not started
2025/05/14	HR 154	Wall Drywall Finish	not started
2025/05/14	HR 154	Wall Prime Paint	not started
2025/05/14	HR 155	In Wall Insulation	not started



2025/05/14	HR 155	Overhead Duct Insulation	in progress
2025/05/14	HR 155	Overhead Duct Rough In	in progress
2025/05/14	HR 155	Overhead Plumbing	not started
2025/05/14	HR 155	Wall Drywall	not started
2025/05/14	HR 155	Wall Drywall Finish	not started
2025/05/14	HR 155	Wall Prime Paint	not started
2025/05/14	HR 156	In Wall Insulation	no data
2025/05/14	HR 156	Overhead Duct Insulation	no data
2025/05/14	HR 156	Overhead Duct Rough In	no data
2025/05/14	HR 156	Overhead Plumbing	no data
2025/05/14	HR 156	Wall Drywall	no data
2025/05/14	HR 156	Wall Drywall Finish	no data
2025/05/14	HR 156	Wall Prime Paint	no data
2025/05/14	HR 157	In Wall Insulation	not started
2025/05/14	HR 157	Overhead Duct Insulation	not started
2025/05/14	HR 157	Overhead Duct Rough In	in progress
2025/05/14	HR 157	Overhead Plumbing	in progress
2025/05/14	HR 157	Wall Drywall	not started
2025/05/14	HR 157	Wall Drywall Finish	not started
2025/05/14	HR 157	Wall Prime Paint	not started
2025/05/14	HUMAN RESOURCES 148	In Wall Insulation	not started
2025/05/14	HUMAN RESOURCES 148	Overhead Duct Insulation	not started
2025/05/14	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/05/14	HUMAN RESOURCES 148	Overhead Plumbing	in progress
2025/05/14	HUMAN RESOURCES 148	Wall Drywall	not started
2025/05/14	HUMAN RESOURCES 148	Wall Drywall Finish	not started
2025/05/14	HUMAN RESOURCES 148	Wall Prime Paint	not started
2025/05/14	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/05/14	INTERNAL AFFAIRS 119	Overhead Duct Insulation	not started
2025/05/14	INTERNAL AFFAIRS 119	Overhead Duct Rough In	in progress
2025/05/14	INTERNAL AFFAIRS 119	Overhead Plumbing	in progress
2025/05/14	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/05/14	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/05/14	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/05/14	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/05/14	INTERNAL AFFAIRS 120	Overhead Duct Insulation	in progress
2025/05/14	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/05/14	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/05/14	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/05/14	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/05/14	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/05/14	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	complete
2025/05/14	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	in progress
2025/05/14	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	in progress
2025/05/14	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	not

started  
 2025/05/14 | INTERVIEW / REVIEW ROOM 118 | Wall Drywall | complete  
 2025/05/14 | INTERVIEW / REVIEW ROOM 118 | Wall Drywall Finish | complete  
 2025/05/14 | INTERVIEW / REVIEW ROOM 118 | Wall Prime Paint | complete  
 2025/05/14 | INTERVIEW/ REVIEW ROOM 121 | In Wall Insulation | complete  
 2025/05/14 | INTERVIEW/ REVIEW ROOM 121 | Overhead Duct Insulation | in progress  
 2025/05/14 | INTERVIEW/ REVIEW ROOM 121 | Overhead Duct Rough In | in progress  
 2025/05/14 | INTERVIEW/ REVIEW ROOM 121 | Overhead Plumbing | in progress  
 2025/05/14 | INTERVIEW/ REVIEW ROOM 121 | Wall Drywall | complete  
 2025/05/14 | INTERVIEW/ REVIEW ROOM 121 | Wall Drywall Finish | complete  
 2025/05/14 | INTERVIEW/ REVIEW ROOM 121 | Wall Prime Paint | complete  
 2025/05/14 | INVESTIGATIONS / MAJOR CASE 167 | In Wall Insulation | complete  
 2025/05/14 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Insulation | in progress  
 2025/05/14 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Rough In | in progress  
 2025/05/14 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Plumbing | in progress  
 2025/05/14 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall | complete  
 2025/05/14 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall Finish | complete  
 2025/05/14 | INVESTIGATIONS / MAJOR CASE 167 | Wall Prime Paint | complete  
 2025/05/14 | IT 115 | In Wall Insulation | complete  
 2025/05/14 | IT 115 | Overhead Duct Insulation | not started  
 2025/05/14 | IT 115 | Overhead Duct Rough In | not started  
 2025/05/14 | IT 115 | Overhead Plumbing | in progress  
 2025/05/14 | IT 115 | Wall Drywall | complete  
 2025/05/14 | IT 115 | Wall Drywall Finish | complete  
 2025/05/14 | IT 115 | Wall Prime Paint | complete  
 2025/05/14 | IT 135 | In Wall Insulation | complete  
 2025/05/14 | IT 135 | Overhead Duct Insulation | in progress  
 2025/05/14 | IT 135 | Overhead Duct Rough In | in progress  
 2025/05/14 | IT 135 | Overhead Plumbing | in progress  
 2025/05/14 | IT 135 | Wall Drywall | complete  
 2025/05/14 | IT 135 | Wall Drywall Finish | complete  
 2025/05/14 | IT 135 | Wall Prime Paint | complete  
 2025/05/14 | IT MANAGER 136 | In Wall Insulation | complete  
 2025/05/14 | IT MANAGER 136 | Overhead Duct Insulation | in progress  
 2025/05/14 | IT MANAGER 136 | Overhead Duct Rough In | in progress  
 2025/05/14 | IT MANAGER 136 | Overhead Plumbing | in progress  
 2025/05/14 | IT MANAGER 136 | Wall Drywall | complete  
 2025/05/14 | IT MANAGER 136 | Wall Drywall Finish | complete  
 2025/05/14 | IT MANAGER 136 | Wall Prime Paint | complete

2025/05/14	IT MANAGER 137	In Wall Insulation	complete
2025/05/14	IT MANAGER 137	Overhead Duct Insulation	in progress
2025/05/14	IT MANAGER 137	Overhead Duct Rough In	in progress
2025/05/14	IT MANAGER 137	Overhead Plumbing	in progress
2025/05/14	IT MANAGER 137	Wall Drywall	complete
2025/05/14	IT MANAGER 137	Wall Drywall Finish	complete
2025/05/14	IT MANAGER 137	Wall Prime Paint	complete
2025/05/14	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/05/14	JUVENILE INTERVIEW 165	Overhead Duct Insulation	complete
2025/05/14	JUVENILE INTERVIEW 165	Overhead Duct Rough In	in progress
2025/05/14	JUVENILE INTERVIEW 165	Overhead Plumbing	complete
2025/05/14	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/05/14	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/05/14	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/05/14	JUVENILLE INTERVIEWERS 166	In Wall Insulation	complete
2025/05/14	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/05/14	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/05/14	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	not started
2025/05/14	JUVENILLE INTERVIEWERS 166	Wall Drywall	complete
2025/05/14	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/05/14	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/05/14	KEY ROOM 185	In Wall Insulation	in progress
2025/05/14	KEY ROOM 185	Overhead Duct Insulation	not started
2025/05/14	KEY ROOM 185	Overhead Duct Rough In	in progress
2025/05/14	KEY ROOM 185	Overhead Plumbing	not started
2025/05/14	KEY ROOM 185	Wall Drywall	in progress
2025/05/14	KEY ROOM 185	Wall Drywall Finish	not started
2025/05/14	KEY ROOM 185	Wall Prime Paint	not started
2025/05/14	LT 170	In Wall Insulation	complete
2025/05/14	LT 170	Overhead Duct Insulation	in progress
2025/05/14	LT 170	Overhead Duct Rough In	in progress
2025/05/14	LT 170	Overhead Plumbing	not started
2025/05/14	LT 170	Wall Drywall	complete
2025/05/14	LT 170	Wall Drywall Finish	complete
2025/05/14	LT 170	Wall Prime Paint	complete
2025/05/14	MACHINE ROOM 191	In Wall Insulation	complete
2025/05/14	MACHINE ROOM 191	Overhead Duct Insulation	complete
2025/05/14	MACHINE ROOM 191	Overhead Duct Rough In	in progress
2025/05/14	MACHINE ROOM 191	Overhead Plumbing	not started
2025/05/14	MACHINE ROOM 191	Wall Drywall	complete
2025/05/14	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/05/14	MACHINE ROOM 191	Wall Prime Paint	complete
2025/05/14	MAIN ELECTRICAL ROOM 123	In Wall Insulation	complete
2025/05/14	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	not started

2025/05/14	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	not started
2025/05/14	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	not started
2025/05/14	MAIN ELECTRICAL ROOM 123	Wall Drywall	complete
2025/05/14	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	complete
2025/05/14	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	in progress
2025/05/14	MAIN JANITORIAL111	In Wall Insulation	complete
2025/05/14	MAIN JANITORIAL111	Overhead Duct Insulation	in progress
2025/05/14	MAIN JANITORIAL111	Overhead Duct Rough In	in progress
2025/05/14	MAIN JANITORIAL111	Overhead Plumbing	in progress
2025/05/14	MAIN JANITORIAL111	Wall Drywall	complete
2025/05/14	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/05/14	MAIN JANITORIAL111	Wall Prime Paint	in progress
2025/05/14	MARINE SERGEANT 142	In Wall Insulation	complete
2025/05/14	MARINE SERGEANT 142	Overhead Duct Insulation	in progress
2025/05/14	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/05/14	MARINE SERGEANT 142	Overhead Plumbing	in progress
2025/05/14	MARINE SERGEANT 142	Wall Drywall	complete
2025/05/14	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/05/14	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/05/14	MECHANICAL 192	In Wall Insulation	complete
2025/05/14	MECHANICAL 192	Overhead Duct Insulation	not started
2025/05/14	MECHANICAL 192	Overhead Duct Rough In	in progress
2025/05/14	MECHANICAL 192	Overhead Plumbing	in progress
2025/05/14	MECHANICAL 192	Wall Drywall	complete
2025/05/14	MECHANICAL 192	Wall Drywall Finish	complete
2025/05/14	MECHANICAL 192	Wall Prime Paint	complete
2025/05/14	MECHANICAL ROOM 122	In Wall Insulation	complete
2025/05/14	MECHANICAL ROOM 122	Overhead Duct Insulation	not started
2025/05/14	MECHANICAL ROOM 122	Overhead Duct Rough In	in progress
2025/05/14	MECHANICAL ROOM 122	Overhead Plumbing	complete
2025/05/14	MECHANICAL ROOM 122	Wall Drywall	complete
2025/05/14	MECHANICAL ROOM 122	Wall Drywall Finish	complete
2025/05/14	MECHANICAL ROOM 122	Wall Prime Paint	complete
2025/05/14	MENS RESTROOM 112	In Wall Insulation	complete
2025/05/14	MENS RESTROOM 112	Overhead Duct Insulation	complete
2025/05/14	MENS RESTROOM 112	Overhead Duct Rough In	in progress
2025/05/14	MENS RESTROOM 112	Overhead Plumbing	complete
2025/05/14	MENS RESTROOM 112	Wall Drywall	complete
2025/05/14	MENS RESTROOM 112	Wall Drywall Finish	in progress
2025/05/14	MENS RESTROOM 112	Wall Prime Paint	not started
2025/05/14	MIS EQUIPMENT STORAGE 138	In Wall Insulation	complete
2025/05/14	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	

in progress

2025/05/14	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	in progress
2025/05/14	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	in progress
2025/05/14	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/05/14	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/05/14	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/05/14	MIS SHREDDING 117	In Wall Insulation	complete
2025/05/14	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/05/14	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/05/14	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/05/14	MIS SHREDDING 117	Wall Drywall	complete
2025/05/14	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/05/14	MIS SHREDDING 117	Wall Prime Paint	complete
2025/05/14	OFFICE 128	In Wall Insulation	complete
2025/05/14	OFFICE 128	Overhead Duct Insulation	in progress
2025/05/14	OFFICE 128	Overhead Duct Rough In	in progress
2025/05/14	OFFICE 128	Overhead Plumbing	not started
2025/05/14	OFFICE 128	Wall Drywall	complete
2025/05/14	OFFICE 128	Wall Drywall Finish	complete
2025/05/14	OFFICE 128	Wall Prime Paint	complete
2025/05/14	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	complete
2025/05/14	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	in progress
2025/05/14	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	in progress
2025/05/14	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	in progress
2025/05/14	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/05/14	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/05/14	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	in progress
2025/05/14	PARTS STORAGE 189	In Wall Insulation	in progress
2025/05/14	PARTS STORAGE 189	Overhead Duct Insulation	not started
2025/05/14	PARTS STORAGE 189	Overhead Duct Rough In	in progress
2025/05/14	PARTS STORAGE 189	Overhead Plumbing	not started
2025/05/14	PARTS STORAGE 189	Wall Drywall	in progress
2025/05/14	PARTS STORAGE 189	Wall Drywall Finish	in progress
2025/05/14	PARTS STORAGE 189	Wall Prime Paint	not started
2025/05/14	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/05/14	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/05/14	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/05/14	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/05/14	PUBLIC RESTROOM 106	Wall Drywall	no data

2025/05/14	PUBLIC RESTROOM	106	Wall Drywall Finish	no data
2025/05/14	PUBLIC RESTROOM	106	Wall Prime Paint	no data
2025/05/14	Polygraph	152	In Wall Insulation	in progress
2025/05/14	Polygraph	152	Overhead Duct Insulation	not started
2025/05/14	Polygraph	152	Overhead Duct Rough In	in progress
2025/05/14	Polygraph	152	Overhead Plumbing	not started
2025/05/14	Polygraph	152	Wall Drywall	in progress
2025/05/14	Polygraph	152	Wall Drywall Finish	not started
2025/05/14	Polygraph	152	Wall Prime Paint	not started
2025/05/14	RECEPTION	101	In Wall Insulation	not started
2025/05/14	RECEPTION	101	Overhead Duct Insulation	not started
2025/05/14	RECEPTION	101	Overhead Duct Rough In	in progress
2025/05/14	RECEPTION	101	Overhead Plumbing	not started
2025/05/14	RECEPTION	101	Wall Drywall	not started
2025/05/14	RECEPTION	101	Wall Drywall Finish	not started
2025/05/14	RECEPTION	101	Wall Prime Paint	not started
2025/05/14	RECEPTION	147	In Wall Insulation	in progress
2025/05/14	RECEPTION	147	Overhead Duct Insulation	in progress
2025/05/14	RECEPTION	147	Overhead Duct Rough In	in progress
2025/05/14	RECEPTION	147	Overhead Plumbing	in progress
2025/05/14	RECEPTION	147	Wall Drywall	in progress
2025/05/14	RECEPTION	147	Wall Drywall Finish	not started
2025/05/14	RECEPTION	147	Wall Prime Paint	not started
2025/05/14	RECEPTION	179	In Wall Insulation	in progress
2025/05/14	RECEPTION	179	Overhead Duct Insulation	not started
2025/05/14	RECEPTION	179	Overhead Duct Rough In	in progress
2025/05/14	RECEPTION	179	Overhead Plumbing	not started
2025/05/14	RECEPTION	179	Wall Drywall	in progress
2025/05/14	RECEPTION	179	Wall Drywall Finish	not started
2025/05/14	RECEPTION	179	Wall Prime Paint	not started
2025/05/14	RECORDS	130	In Wall Insulation	complete
2025/05/14	RECORDS	130	Overhead Duct Insulation	in progress
2025/05/14	RECORDS	130	Overhead Duct Rough In	in progress
2025/05/14	RECORDS	130	Overhead Plumbing	in progress
2025/05/14	RECORDS	130	Wall Drywall	complete
2025/05/14	RECORDS	130	Wall Drywall Finish	complete
2025/05/14	RECORDS	130	Wall Prime Paint	complete
2025/05/14	RECORDS STORAGE	133	In Wall Insulation	complete
2025/05/14	RECORDS STORAGE	133	Overhead Duct Insulation	in progress
2025/05/14	RECORDS STORAGE	133	Overhead Duct Rough In	in progress
2025/05/14	RECORDS STORAGE	133	Overhead Plumbing	not started
2025/05/14	RECORDS STORAGE	133	Wall Drywall	complete
2025/05/14	RECORDS STORAGE	133	Wall Drywall Finish	complete
2025/05/14	RECORDS STORAGE	133	Wall Prime Paint	complete
2025/05/14	RECORDS SUPERVISOR	131	In Wall Insulation	complete
2025/05/14	RECORDS SUPERVISOR	131	Overhead Duct Insulation	in progress
2025/05/14	RECORDS SUPERVISOR	131	Overhead Duct Rough In	in progress
2025/05/14	RECORDS SUPERVISOR	131	Overhead Plumbing	not started
2025/05/14	RECORDS SUPERVISOR	131	Wall Drywall	complete

2025/05/14	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/05/14	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/05/14	RECORDS SUPERVISOR 132	In Wall Insulation	complete
2025/05/14	RECORDS SUPERVISOR 132	Overhead Duct Insulation	in progress
2025/05/14	RECORDS SUPERVISOR 132	Overhead Duct Rough In	in progress
2025/05/14	RECORDS SUPERVISOR 132	Overhead Plumbing	not started
2025/05/14	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/05/14	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/05/14	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/05/14	RESTROOM 183	In Wall Insulation	in progress
2025/05/14	RESTROOM 183	Overhead Duct Insulation	in progress
2025/05/14	RESTROOM 183	Overhead Duct Rough In	in progress
2025/05/14	RESTROOM 183	Overhead Plumbing	in progress
2025/05/14	RESTROOM 183	Wall Drywall	not started
2025/05/14	RESTROOM 183	Wall Drywall Finish	not started
2025/05/14	RESTROOM 183	Wall Prime Paint	not started
2025/05/14	Risk Management - 158	In Wall Insulation	not started
2025/05/14	Risk Management - 158	Overhead Duct Insulation	not started
2025/05/14	Risk Management - 158	Overhead Duct Rough In	in progress
2025/05/14	Risk Management - 158	Overhead Plumbing	in progress
2025/05/14	Risk Management - 158	Wall Drywall	not started
2025/05/14	Risk Management - 158	Wall Drywall Finish	not started
2025/05/14	Risk Management - 158	Wall Prime Paint	not started
2025/05/14	SALLY PORT 105	In Wall Insulation	not started
2025/05/14	SALLY PORT 105	Overhead Duct Insulation	not started
2025/05/14	SALLY PORT 105	Overhead Duct Rough In	in progress
2025/05/14	SALLY PORT 105	Overhead Plumbing	not started
2025/05/14	SALLY PORT 105	Wall Drywall	not started
2025/05/14	SALLY PORT 105	Wall Drywall Finish	not started
2025/05/14	SALLY PORT 105	Wall Prime Paint	not started
2025/05/14	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/05/14	SANE EXAM ROOM 168	Overhead Duct Insulation	complete
2025/05/14	SANE EXAM ROOM 168	Overhead Duct Rough In	in progress
2025/05/14	SANE EXAM ROOM 168	Overhead Plumbing	complete
2025/05/14	SANE EXAM ROOM 168	Wall Drywall	complete
2025/05/14	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/05/14	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/05/14	SGT 171	In Wall Insulation	complete
2025/05/14	SGT 171	Overhead Duct Insulation	in progress
2025/05/14	SGT 171	Overhead Duct Rough In	in progress
2025/05/14	SGT 171	Overhead Plumbing	in progress
2025/05/14	SGT 171	Wall Drywall	complete
2025/05/14	SGT 171	Wall Drywall Finish	complete
2025/05/14	SGT 171	Wall Prime Paint	complete
2025/05/14	SGT 172	In Wall Insulation	complete

2025/05/14	SGT 172	Overhead Duct Insulation	complete
2025/05/14	SGT 172	Overhead Duct Rough In	in progress
2025/05/14	SGT 172	Overhead Plumbing	in progress
2025/05/14	SGT 172	Wall Drywall	complete
2025/05/14	SGT 172	Wall Drywall Finish	complete
2025/05/14	SGT 172	Wall Prime Paint	complete
2025/05/14	SHIPPING STORAGE 190	In Wall Insulation	in progress
2025/05/14	SHIPPING STORAGE 190	Overhead Duct Insulation	not started
2025/05/14	SHIPPING STORAGE 190	Overhead Duct Rough In	in progress
2025/05/14	SHIPPING STORAGE 190	Overhead Plumbing	not started
2025/05/14	SHIPPING STORAGE 190	Wall Drywall	in progress
2025/05/14	SHIPPING STORAGE 190	Wall Drywall Finish	not started
2025/05/14	SHIPPING STORAGE 190	Wall Prime Paint	not started
2025/05/14	SHOP FORMAN 184	In Wall Insulation	in progress
2025/05/14	SHOP FORMAN 184	Overhead Duct Insulation	not started
2025/05/14	SHOP FORMAN 184	Overhead Duct Rough In	in progress
2025/05/14	SHOP FORMAN 184	Overhead Plumbing	not started
2025/05/14	SHOP FORMAN 184	Wall Drywall	in progress
2025/05/14	SHOP FORMAN 184	Wall Drywall Finish	not started
2025/05/14	SHOP FORMAN 184	Wall Prime Paint	not started
2025/05/14	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/05/14	SOFT INTERVIEW 161	Overhead Duct Insulation	complete
2025/05/14	SOFT INTERVIEW 161	Overhead Duct Rough In	in progress
2025/05/14	SOFT INTERVIEW 161	Overhead Plumbing	in progress
2025/05/14	SOFT INTERVIEW 161	Wall Drywall	complete
2025/05/14	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/05/14	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/05/14	SOFT INTERVIEW 162	In Wall Insulation	no data
2025/05/14	SOFT INTERVIEW 162	Overhead Duct Insulation	no data
2025/05/14	SOFT INTERVIEW 162	Overhead Duct Rough In	no data
2025/05/14	SOFT INTERVIEW 162	Overhead Plumbing	no data
2025/05/14	SOFT INTERVIEW 162	Wall Drywall	no data
2025/05/14	SOFT INTERVIEW 162	Wall Drywall Finish	no data
2025/05/14	SOFT INTERVIEW 162	Wall Prime Paint	no data
2025/05/14	SPECIAL OPERATION LT 143	In Wall Insulation	complete
2025/05/14	SPECIAL OPERATION LT 143	Overhead Duct Insulation	in progress
2025/05/14	SPECIAL OPERATION LT 143	Overhead Duct Rough In	in progress
2025/05/14	SPECIAL OPERATION LT 143	Overhead Plumbing	in progress
2025/05/14	SPECIAL OPERATION LT 143	Wall Drywall	complete
2025/05/14	SPECIAL OPERATION LT 143	Wall Drywall Finish	complete
2025/05/14	SPECIAL OPERATION LT 143	Wall Prime Paint	complete
2025/05/14	STAIR A	In Wall Insulation	not started
2025/05/14	STAIR A	Overhead Duct Insulation	not started



2025/05/14	STAIR A	Overhead Duct Rough In	in progress
2025/05/14	STAIR A	Overhead Plumbing	in progress
2025/05/14	STAIR A	Wall Drywall	not started
2025/05/14	STAIR A	Wall Drywall Finish	not started
2025/05/14	STAIR A	Wall Prime Paint	not started
2025/05/14	STORAGE 104	In Wall Insulation	complete
2025/05/14	STORAGE 104	Overhead Duct Insulation	in progress
2025/05/14	STORAGE 104	Overhead Duct Rough In	in progress
2025/05/14	STORAGE 104	Overhead Plumbing	not started
2025/05/14	STORAGE 104	Wall Drywall	complete
2025/05/14	STORAGE 104	Wall Drywall Finish	complete
2025/05/14	STORAGE 104	Wall Prime Paint	in progress
2025/05/14	STORAGE 127	In Wall Insulation	complete
2025/05/14	STORAGE 127	Overhead Duct Insulation	in progress
2025/05/14	STORAGE 127	Overhead Duct Rough In	in progress
2025/05/14	STORAGE 127	Overhead Plumbing	not started
2025/05/14	STORAGE 127	Wall Drywall	complete
2025/05/14	STORAGE 127	Wall Drywall Finish	complete
2025/05/14	STORAGE 127	Wall Prime Paint	complete
2025/05/14	STUDIO 126	In Wall Insulation	complete
2025/05/14	STUDIO 126	Overhead Duct Insulation	in progress
2025/05/14	STUDIO 126	Overhead Duct Rough In	in progress
2025/05/14	STUDIO 126	Overhead Plumbing	not started
2025/05/14	STUDIO 126	Wall Drywall	complete
2025/05/14	STUDIO 126	Wall Drywall Finish	complete
2025/05/14	STUDIO 126	Wall Prime Paint	in progress
2025/05/14	SUPERVISOR 129	In Wall Insulation	complete
2025/05/14	SUPERVISOR 129	Overhead Duct Insulation	in progress
2025/05/14	SUPERVISOR 129	Overhead Duct Rough In	in progress
2025/05/14	SUPERVISOR 129	Overhead Plumbing	not started
2025/05/14	SUPERVISOR 129	Wall Drywall	complete
2025/05/14	SUPERVISOR 129	Wall Drywall Finish	complete
2025/05/14	SUPERVISOR 129	Wall Prime Paint	complete
2025/05/14	Storage 164	In Wall Insulation	complete
2025/05/14	Storage 164	Overhead Duct Insulation	in progress
2025/05/14	Storage 164	Overhead Duct Rough In	in progress
2025/05/14	Storage 164	Overhead Plumbing	not started
2025/05/14	Storage 164	Wall Drywall	complete
2025/05/14	Storage 164	Wall Drywall Finish	complete
2025/05/14	Storage 164	Wall Prime Paint	complete
2025/05/14	Storage 177	In Wall Insulation	complete
2025/05/14	Storage 177	Overhead Duct Insulation	in progress
2025/05/14	Storage 177	Overhead Duct Rough In	in progress
2025/05/14	Storage 177	Overhead Plumbing	not started
2025/05/14	Storage 177	Wall Drywall	complete
2025/05/14	Storage 177	Wall Drywall Finish	complete
2025/05/14	Storage 177	Wall Prime Paint	complete
2025/05/14	TECHNICAL SURVEILLANCE 188	In Wall Insulation	in progress
2025/05/14	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	not started
2025/05/14	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	in progress
2025/05/14	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	not

started  
 2025/05/14 | TECHNICAL SURVEILLANCE 188 | Wall Drywall | in progress  
 2025/05/14 | TECHNICAL SURVEILLANCE 188 | Wall Drywall Finish | not  
 started  
 2025/05/14 | TECHNICAL SURVEILLANCE 188 | Wall Prime Paint | not  
 started  
 2025/05/14 | TRAFFIC SERGEANT 141 | In Wall Insulation | complete  
 2025/05/14 | TRAFFIC SERGEANT 141 | Overhead Duct Insulation | in  
 progress  
 2025/05/14 | TRAFFIC SERGEANT 141 | Overhead Duct Rough In | in  
 progress  
 2025/05/14 | TRAFFIC SERGEANT 141 | Overhead Plumbing | in progress  
 2025/05/14 | TRAFFIC SERGEANT 141 | Wall Drywall | complete  
 2025/05/14 | TRAFFIC SERGEANT 141 | Wall Drywall Finish | complete  
 2025/05/14 | TRAFFIC SERGEANT 141 | Wall Prime Paint | complete  
 2025/05/14 | TRIAGE/RECEPTION 134 | In Wall Insulation | complete  
 2025/05/14 | TRIAGE/RECEPTION 134 | Overhead Duct Insulation | in  
 progress  
 2025/05/14 | TRIAGE/RECEPTION 134 | Overhead Duct Rough In | in  
 progress  
 2025/05/14 | TRIAGE/RECEPTION 134 | Overhead Plumbing | not started  
 2025/05/14 | TRIAGE/RECEPTION 134 | Wall Drywall | complete  
 2025/05/14 | TRIAGE/RECEPTION 134 | Wall Drywall Finish | complete  
 2025/05/14 | TRIAGE/RECEPTION 134 | Wall Prime Paint | in progress  
 2025/05/14 | TST WORKSHOP 187 | In Wall Insulation | in progress  
 2025/05/14 | TST WORKSHOP 187 | Overhead Duct Insulation | not  
 started  
 2025/05/14 | TST WORKSHOP 187 | Overhead Duct Rough In | in progress  
 2025/05/14 | TST WORKSHOP 187 | Overhead Plumbing | not started  
 2025/05/14 | TST WORKSHOP 187 | Wall Drywall | in progress  
 2025/05/14 | TST WORKSHOP 187 | Wall Drywall Finish | not started  
 2025/05/14 | TST WORKSHOP 187 | Wall Prime Paint | not started  
 2025/05/14 | UNISEX RESTROOM 169 | In Wall Insulation | in progress  
 2025/05/14 | UNISEX RESTROOM 169 | Overhead Duct Insulation |  
 complete  
 2025/05/14 | UNISEX RESTROOM 169 | Overhead Duct Rough In | in  
 progress  
 2025/05/14 | UNISEX RESTROOM 169 | Overhead Plumbing | complete  
 2025/05/14 | UNISEX RESTROOM 169 | Wall Drywall | in progress  
 2025/05/14 | UNISEX RESTROOM 169 | Wall Drywall Finish | not started  
 2025/05/14 | UNISEX RESTROOM 169 | Wall Prime Paint | not started  
 2025/05/14 | VEHICLE MAINTENANCE BAYS 186 | In Wall Insulation | in  
 progress  
 2025/05/14 | VEHICLE MAINTENANCE BAYS 186 | Overhead Duct Insulation  
 | not started  
 2025/05/14 | VEHICLE MAINTENANCE BAYS 186 | Overhead Duct Rough In |  
 in progress  
 2025/05/14 | VEHICLE MAINTENANCE BAYS 186 | Overhead Plumbing |  
 complete  
 2025/05/14 | VEHICLE MAINTENANCE BAYS 186 | Wall Drywall | in  
 progress  
 2025/05/14 | VEHICLE MAINTENANCE BAYS 186 | Wall Drywall Finish | in  
 progress  
 2025/05/14 | VEHICLE MAINTENANCE BAYS 186 | Wall Prime Paint | not

started  
 2025/05/14 | VOLUNTEER/LIGHT DUTY 140 | In Wall Insulation | complete  
 2025/05/14 | VOLUNTEER/LIGHT DUTY 140 | Overhead Duct Insulation | in progress  
 2025/05/14 | VOLUNTEER/LIGHT DUTY 140 | Overhead Duct Rough In | in progress  
 2025/05/14 | VOLUNTEER/LIGHT DUTY 140 | Overhead Plumbing | in progress  
 2025/05/14 | VOLUNTEER/LIGHT DUTY 140 | Wall Drywall | complete  
 2025/05/14 | VOLUNTEER/LIGHT DUTY 140 | Wall Drywall Finish | complete  
 2025/05/14 | VOLUNTEER/LIGHT DUTY 140 | Wall Prime Paint | complete  
 2025/05/14 | WAITING/LOBBY 100 | In Wall Insulation | not started  
 2025/05/14 | WAITING/LOBBY 100 | Overhead Duct Insulation | not started  
 2025/05/14 | WAITING/LOBBY 100 | Overhead Duct Rough In | not started  
 2025/05/14 | WAITING/LOBBY 100 | Overhead Plumbing | not started  
 2025/05/14 | WAITING/LOBBY 100 | Wall Drywall | not started  
 2025/05/14 | WAITING/LOBBY 100 | Wall Drywall Finish | not started  
 2025/05/14 | WAITING/LOBBY 100 | Wall Prime Paint | not started  
 2025/05/14 | WOMENS RESTROOM 113 | In Wall Insulation | complete  
 2025/05/14 | WOMENS RESTROOM 113 | Overhead Duct Insulation | complete  
 2025/05/14 | WOMENS RESTROOM 113 | Overhead Duct Rough In | in progress  
 2025/05/14 | WOMENS RESTROOM 113 | Overhead Plumbing | complete  
 2025/05/14 | WOMENS RESTROOM 113 | Wall Drywall | complete  
 2025/05/14 | WOMENS RESTROOM 113 | Wall Drywall Finish | in progress  
 2025/05/14 | WOMENS RESTROOM 113 | Wall Prime Paint | not started  
 2025/05/30 | ADMIN ASSISTANT 125 | In Wall Insulation | complete  
 2025/05/30 | ADMIN ASSISTANT 125 | Overhead Duct Insulation | in progress  
 2025/05/30 | ADMIN ASSISTANT 125 | Overhead Duct Rough In | in progress  
 2025/05/30 | ADMIN ASSISTANT 125 | Overhead Plumbing | not started  
 2025/05/30 | ADMIN ASSISTANT 125 | Wall Drywall | complete  
 2025/05/30 | ADMIN ASSISTANT 125 | Wall Drywall Finish | complete  
 2025/05/30 | ADMIN ASSISTANT 125 | Wall Prime Paint | complete  
 2025/05/30 | AV ROOM 103 | In Wall Insulation | complete  
 2025/05/30 | AV ROOM 103 | Overhead Duct Insulation | in progress  
 2025/05/30 | AV ROOM 103 | Overhead Duct Rough In | in progress  
 2025/05/30 | AV ROOM 103 | Overhead Plumbing | not started  
 2025/05/30 | AV ROOM 103 | Wall Drywall | complete  
 2025/05/30 | AV ROOM 103 | Wall Drywall Finish | complete  
 2025/05/30 | AV ROOM 103 | Wall Prime Paint | in progress  
 2025/05/30 | BREAK ROOM CONFERENCE 182 | In Wall Insulation | complete  
 2025/05/30 | BREAK ROOM CONFERENCE 182 | Overhead Duct Insulation | in progress  
 2025/05/30 | BREAK ROOM CONFERENCE 182 | Overhead Duct Rough In | in progress  
 2025/05/30 | BREAK ROOM CONFERENCE 182 | Overhead Plumbing | in

progress

2025/05/30		BREAK ROOM CONFERENCE 182		Wall Drywall		complete
2025/05/30		BREAK ROOM CONFERENCE 182		Wall Drywall Finish		not started
2025/05/30		BREAK ROOM CONFERENCE 182		Wall Prime Paint		not started
2025/05/30		Background-159		In Wall Insulation		not started
2025/05/30		Background-159		Overhead Duct Insulation		not started
2025/05/30		Background-159		Overhead Duct Rough In		in progress
2025/05/30		Background-159		Overhead Plumbing		not started
2025/05/30		Background-159		Wall Drywall		not started
2025/05/30		Background-159		Wall Drywall Finish		not started
2025/05/30		Background-159		Wall Prime Paint		not started
2025/05/30		CENTRAL BREAKROOM 145		In Wall Insulation		in progress

progress

2025/05/30		CENTRAL BREAKROOM 145		Overhead Duct Insulation		not started
2025/05/30		CENTRAL BREAKROOM 145		Overhead Duct Rough In		in progress

progress

2025/05/30		CENTRAL BREAKROOM 145		Overhead Plumbing		not started
2025/05/30		CENTRAL BREAKROOM 145		Wall Drywall		in progress
2025/05/30		CENTRAL BREAKROOM 145		Wall Drywall Finish		not started

2025/05/30		CENTRAL BREAKROOM 145		Wall Prime Paint		not started
2025/05/30		COLD CASE 175		In Wall Insulation		complete
2025/05/30		COLD CASE 175		Overhead Duct Insulation		in progress
2025/05/30		COLD CASE 175		Overhead Duct Rough In		in progress
2025/05/30		COLD CASE 175		Overhead Plumbing		in progress
2025/05/30		COLD CASE 175		Wall Drywall		complete
2025/05/30		COLD CASE 175		Wall Drywall Finish		complete
2025/05/30		COLD CASE 175		Wall Prime Paint		in progress

2025/05/30		COMMUNITY AFFAIRS 124		In Wall Insulation		complete
2025/05/30		COMMUNITY AFFAIRS 124		Overhead Duct Insulation		in progress

progress

2025/05/30		COMMUNITY AFFAIRS 124		Overhead Duct Rough In		in progress
------------	--	-----------------------	--	------------------------	--	-------------

progress

2025/05/30		COMMUNITY AFFAIRS 124		Overhead Plumbing		not started
2025/05/30		COMMUNITY AFFAIRS 124		Wall Drywall		complete
2025/05/30		COMMUNITY AFFAIRS 124		Wall Drywall Finish		complete
2025/05/30		COMMUNITY AFFAIRS 124		Wall Prime Paint		complete

2025/05/30		COMMUNITY ROOM 247 PPL 102		In Wall Insulation		complete
------------	--	----------------------------	--	--------------------	--	----------

2025/05/30		COMMUNITY ROOM 247 PPL 102		Overhead Duct Insulation		in progress
------------	--	----------------------------	--	--------------------------	--	-------------

2025/05/30		COMMUNITY ROOM 247 PPL 102		Overhead Duct Rough In		in progress
------------	--	----------------------------	--	------------------------	--	-------------

2025/05/30		COMMUNITY ROOM 247 PPL 102		Overhead Plumbing		not started
------------	--	----------------------------	--	-------------------	--	-------------

2025/05/30		COMMUNITY ROOM 247 PPL 102		Wall Drywall		complete
------------	--	----------------------------	--	--------------	--	----------

2025/05/30		COMMUNITY ROOM 247 PPL 102		Wall Drywall Finish		not started
------------	--	----------------------------	--	---------------------	--	-------------

2025/05/30		COMMUNITY ROOM 247 PPL 102		Wall Prime Paint		not started
------------	--	----------------------------	--	------------------	--	-------------

2025/05/30		CONFERENCE ROOM 153		In Wall Insulation		in progress
------------	--	---------------------	--	--------------------	--	-------------

2025/05/30	CONFERENCE ROOM 153	Overhead Duct Insulation	no data
2025/05/30	CONFERENCE ROOM 153	Overhead Duct Rough In	in progress
2025/05/30	CONFERENCE ROOM 153	Overhead Plumbing	not started
2025/05/30	CONFERENCE ROOM 153	Wall Drywall	in progress
2025/05/30	CONFERENCE ROOM 153	Wall Drywall Finish	no data
2025/05/30	CONFERENCE ROOM 153	Wall Prime Paint	not started
2025/05/30	CONFERENCE/WAR ROOM 163	In Wall Insulation	complete
2025/05/30	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	in progress
2025/05/30	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	in progress
2025/05/30	CONFERENCE/WAR ROOM 163	Overhead Plumbing	not started
2025/05/30	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/05/30	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete
2025/05/30	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/05/30	COPY 176	In Wall Insulation	complete
2025/05/30	COPY 176	Overhead Duct Insulation	in progress
2025/05/30	COPY 176	Overhead Duct Rough In	in progress
2025/05/30	COPY 176	Overhead Plumbing	not started
2025/05/30	COPY 176	Wall Drywall	complete
2025/05/30	COPY 176	Wall Drywall Finish	complete
2025/05/30	COPY 176	Wall Prime Paint	complete
2025/05/30	COPY/MAIL ROOM 114	In Wall Insulation	complete
2025/05/30	COPY/MAIL ROOM 114	Overhead Duct Insulation	no data
2025/05/30	COPY/MAIL ROOM 114	Overhead Duct Rough In	in progress
2025/05/30	COPY/MAIL ROOM 114	Overhead Plumbing	no data
2025/05/30	COPY/MAIL ROOM 114	Wall Drywall	complete
2025/05/30	COPY/MAIL ROOM 114	Wall Drywall Finish	no data
2025/05/30	COPY/MAIL ROOM 114	Wall Prime Paint	complete
2025/05/30	CORRIDOR 107	In Wall Insulation	complete
2025/05/30	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/05/30	CORRIDOR 107	Overhead Duct Rough In	in progress
2025/05/30	CORRIDOR 107	Overhead Plumbing	in progress
2025/05/30	CORRIDOR 107	Wall Drywall	complete
2025/05/30	CORRIDOR 107	Wall Drywall Finish	complete
2025/05/30	CORRIDOR 107	Wall Prime Paint	in progress
2025/05/30	CORRIDOR 108	In Wall Insulation	complete
2025/05/30	CORRIDOR 108	In Wall Insulation	complete
2025/05/30	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/05/30	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/05/30	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/05/30	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/05/30	CORRIDOR 108	Overhead Plumbing	in progress
2025/05/30	CORRIDOR 108	Overhead Plumbing	in progress
2025/05/30	CORRIDOR 108	Wall Drywall	complete
2025/05/30	CORRIDOR 108	Wall Drywall	complete
2025/05/30	CORRIDOR 108	Wall Drywall Finish	complete
2025/05/30	CORRIDOR 108	Wall Drywall Finish	complete
2025/05/30	CORRIDOR 108	Wall Prime Paint	in progress

2025/05/30	CORRIDOR 108	Wall Prime Paint   in progress
2025/05/30	CORRIDOR 109	In Wall Insulation   complete
2025/05/30	CORRIDOR 109	Overhead Duct Insulation   in progress
2025/05/30	CORRIDOR 109	Overhead Duct Rough In   in progress
2025/05/30	CORRIDOR 109	Overhead Plumbing   in progress
2025/05/30	CORRIDOR 109	Wall Drywall   complete
2025/05/30	CORRIDOR 109	Wall Drywall Finish   complete
2025/05/30	CORRIDOR 109	Wall Prime Paint   complete
2025/05/30	CORRIDOR 110	In Wall Insulation   complete
2025/05/30	CORRIDOR 110	In Wall Insulation   complete
2025/05/30	CORRIDOR 110	Overhead Duct Insulation   in progress
2025/05/30	CORRIDOR 110	Overhead Duct Insulation   in progress
2025/05/30	CORRIDOR 110	Overhead Duct Rough In   in progress
2025/05/30	CORRIDOR 110	Overhead Duct Rough In   in progress
2025/05/30	CORRIDOR 110	Overhead Plumbing   in progress
2025/05/30	CORRIDOR 110	Overhead Plumbing   in progress
2025/05/30	CORRIDOR 110	Wall Drywall   complete
2025/05/30	CORRIDOR 110	Wall Drywall   complete
2025/05/30	CORRIDOR 110	Wall Drywall Finish   in progress
2025/05/30	CORRIDOR 110	Wall Drywall Finish   in progress
2025/05/30	CORRIDOR 110	Wall Prime Paint   in progress
2025/05/30	CORRIDOR 110	Wall Prime Paint   in progress
2025/05/30	CORRIDOR 181	In Wall Insulation   in progress
2025/05/30	CORRIDOR 181	Overhead Duct Insulation   not started
2025/05/30	CORRIDOR 181	Overhead Duct Rough In   in progress
2025/05/30	CORRIDOR 181	Overhead Plumbing   in progress
2025/05/30	CORRIDOR 181	Wall Drywall   in progress
2025/05/30	CORRIDOR 181	Wall Drywall Finish   not started
2025/05/30	CORRIDOR 181	Wall Prime Paint   not started
2025/05/30	CORRIDOR144	In Wall Insulation   complete
2025/05/30	CORRIDOR144	Overhead Duct Insulation   in progress
2025/05/30	CORRIDOR144	Overhead Duct Rough In   in progress
2025/05/30	CORRIDOR144	Overhead Plumbing   in progress
2025/05/30	CORRIDOR144	Wall Drywall   in progress
2025/05/30	CORRIDOR144	Wall Drywall Finish   in progress
2025/05/30	CORRIDOR144	Wall Prime Paint   complete
2025/05/30	CPL 173	In Wall Insulation   complete
2025/05/30	CPL 173	Overhead Duct Insulation   no data
2025/05/30	CPL 173	Overhead Duct Rough In   in progress
2025/05/30	CPL 173	Overhead Plumbing   no data
2025/05/30	CPL 173	Wall Drywall   complete
2025/05/30	CPL 173	Wall Drywall Finish   no data
2025/05/30	CPL 173	Wall Prime Paint   in progress
2025/05/30	CPL 174	In Wall Insulation   complete
2025/05/30	CPL 174	Overhead Duct Insulation   no data
2025/05/30	CPL 174	Overhead Duct Rough In   in progress
2025/05/30	CPL 174	Overhead Plumbing   no data
2025/05/30	CPL 174	Wall Drywall   complete
2025/05/30	CPL 174	Wall Drywall Finish   no data
2025/05/30	CPL 174	Wall Prime Paint   in progress
2025/05/30	DRY STORAGE 146	In Wall Insulation   no data
2025/05/30	DRY STORAGE 146	Overhead Duct Insulation   no data
2025/05/30	DRY STORAGE 146	Overhead Duct Rough In   no data
2025/05/30	DRY STORAGE 146	Overhead Plumbing   no data

2025/05/30	DRY STORAGE 146	Wall Drywall	no data
2025/05/30	DRY STORAGE 146	Wall Drywall Finish	no data
2025/05/30	DRY STORAGE 146	Wall Prime Paint	no data
2025/05/30	FIRE RISER 178	In Wall Insulation	no data
2025/05/30	FIRE RISER 178	Overhead Duct Insulation	no data
2025/05/30	FIRE RISER 178	Overhead Duct Rough In	not started
2025/05/30	FIRE RISER 178	Overhead Plumbing	no data
2025/05/30	FIRE RISER 178	Wall Drywall	complete
2025/05/30	FIRE RISER 178	Wall Drywall Finish	no data
2025/05/30	FIRE RISER 178	Wall Prime Paint	no data
2025/05/30	GREETING ROOM 106	In Wall Insulation	complete
2025/05/30	GREETING ROOM 106	Overhead Duct Insulation	in progress
2025/05/30	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/05/30	GREETING ROOM 106	Overhead Plumbing	not started
2025/05/30	GREETING ROOM 106	Wall Drywall	complete
2025/05/30	GREETING ROOM 106	Wall Drywall Finish	complete
2025/05/30	GREETING ROOM 106	Wall Prime Paint	complete
2025/05/30	HR 149	In Wall Insulation	not started
2025/05/30	HR 149	Overhead Duct Insulation	not started
2025/05/30	HR 149	Overhead Duct Rough In	in progress
2025/05/30	HR 149	Overhead Plumbing	not started
2025/05/30	HR 149	Wall Drywall	not started
2025/05/30	HR 149	Wall Drywall Finish	not started
2025/05/30	HR 149	Wall Prime Paint	not started
2025/05/30	HR 150	In Wall Insulation	not started
2025/05/30	HR 150	Overhead Duct Insulation	not started
2025/05/30	HR 150	Overhead Duct Rough In	in progress
2025/05/30	HR 150	Overhead Plumbing	not started
2025/05/30	HR 150	Wall Drywall	not started
2025/05/30	HR 150	Wall Drywall Finish	not started
2025/05/30	HR 150	Wall Prime Paint	not started
2025/05/30	HR 151	In Wall Insulation	not started
2025/05/30	HR 151	Overhead Duct Insulation	not started
2025/05/30	HR 151	Overhead Duct Rough In	in progress
2025/05/30	HR 151	Overhead Plumbing	in progress
2025/05/30	HR 151	Wall Drywall	not started
2025/05/30	HR 151	Wall Drywall Finish	not started
2025/05/30	HR 151	Wall Prime Paint	not started
2025/05/30	HR 154	In Wall Insulation	no data
2025/05/30	HR 154	Overhead Duct Insulation	no data
2025/05/30	HR 154	Overhead Duct Rough In	no data
2025/05/30	HR 154	Overhead Plumbing	no data
2025/05/30	HR 154	Wall Drywall	no data
2025/05/30	HR 154	Wall Drywall Finish	no data
2025/05/30	HR 154	Wall Prime Paint	no data
2025/05/30	HR 155	In Wall Insulation	no data
2025/05/30	HR 155	Overhead Duct Insulation	no data
2025/05/30	HR 155	Overhead Duct Rough In	in progress
2025/05/30	HR 155	Overhead Plumbing	no data
2025/05/30	HR 155	Wall Drywall	not started
2025/05/30	HR 155	Wall Drywall Finish	no data
2025/05/30	HR 155	Wall Prime Paint	no data

2025/05/30	HR 156	In Wall Insulation	not started
2025/05/30	HR 156	Overhead Duct Insulation	not started
2025/05/30	HR 156	Overhead Duct Rough In	in progress
2025/05/30	HR 156	Overhead Plumbing	not started
2025/05/30	HR 156	Wall Drywall	not started
2025/05/30	HR 156	Wall Drywall Finish	not started
2025/05/30	HR 156	Wall Prime Paint	not started
2025/05/30	HR 157	In Wall Insulation	not started
2025/05/30	HR 157	Overhead Duct Insulation	not started
2025/05/30	HR 157	Overhead Duct Rough In	in progress
2025/05/30	HR 157	Overhead Plumbing	in progress
2025/05/30	HR 157	Wall Drywall	not started
2025/05/30	HR 157	Wall Drywall Finish	not started
2025/05/30	HR 157	Wall Prime Paint	not started
2025/05/30	HUMAN RESOURCES 148	In Wall Insulation	in progress
2025/05/30	HUMAN RESOURCES 148	Overhead Duct Insulation	not started
2025/05/30	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/05/30	HUMAN RESOURCES 148	Overhead Plumbing	in progress
2025/05/30	HUMAN RESOURCES 148	Wall Drywall	not started
2025/05/30	HUMAN RESOURCES 148	Wall Drywall Finish	not started
2025/05/30	HUMAN RESOURCES 148	Wall Prime Paint	not started
2025/05/30	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/05/30	INTERNAL AFFAIRS 119	Overhead Duct Insulation	no data
2025/05/30	INTERNAL AFFAIRS 119	Overhead Duct Rough In	in progress
2025/05/30	INTERNAL AFFAIRS 119	Overhead Plumbing	no data
2025/05/30	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/05/30	INTERNAL AFFAIRS 119	Wall Drywall Finish	no data
2025/05/30	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/05/30	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/05/30	INTERNAL AFFAIRS 120	Overhead Duct Insulation	in progress
2025/05/30	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/05/30	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/05/30	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/05/30	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/05/30	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/05/30	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	complete
2025/05/30	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	in progress
2025/05/30	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	in progress
2025/05/30	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	not started
2025/05/30	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/05/30	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/05/30	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete



2025/05/30	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	no data
2025/05/30	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	no data
2025/05/30	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	in progress
2025/05/30	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	no data
2025/05/30	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/05/30	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	no data
2025/05/30	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	no data
2025/05/30	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	complete
2025/05/30	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	in progress
2025/05/30	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	in progress
2025/05/30	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	in progress
2025/05/30	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/05/30	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/05/30	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	complete
2025/05/30	IT 115	In Wall Insulation	complete
2025/05/30	IT 115	Overhead Duct Insulation	no data
2025/05/30	IT 115	Overhead Duct Rough In	not started
2025/05/30	IT 115	Overhead Plumbing	no data
2025/05/30	IT 115	Wall Drywall	complete
2025/05/30	IT 115	Wall Drywall Finish	no data
2025/05/30	IT 115	Wall Prime Paint	complete
2025/05/30	IT 135	In Wall Insulation	complete
2025/05/30	IT 135	Overhead Duct Insulation	in progress
2025/05/30	IT 135	Overhead Duct Rough In	in progress
2025/05/30	IT 135	Overhead Plumbing	in progress
2025/05/30	IT 135	Wall Drywall	complete
2025/05/30	IT 135	Wall Drywall Finish	complete
2025/05/30	IT 135	Wall Prime Paint	complete
2025/05/30	IT MANAGER 136	In Wall Insulation	complete
2025/05/30	IT MANAGER 136	Overhead Duct Insulation	in progress
2025/05/30	IT MANAGER 136	Overhead Duct Rough In	in progress
2025/05/30	IT MANAGER 136	Overhead Plumbing	in progress
2025/05/30	IT MANAGER 136	Wall Drywall	complete
2025/05/30	IT MANAGER 136	Wall Drywall Finish	complete
2025/05/30	IT MANAGER 136	Wall Prime Paint	complete
2025/05/30	IT MANAGER 137	In Wall Insulation	complete
2025/05/30	IT MANAGER 137	Overhead Duct Insulation	in progress
2025/05/30	IT MANAGER 137	Overhead Duct Rough In	in progress
2025/05/30	IT MANAGER 137	Overhead Plumbing	in progress
2025/05/30	IT MANAGER 137	Wall Drywall	complete
2025/05/30	IT MANAGER 137	Wall Drywall Finish	complete
2025/05/30	IT MANAGER 137	Wall Prime Paint	complete

2025/05/30	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/05/30	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data
2025/05/30	JUVENILE INTERVIEW 165	Overhead Duct Rough In	in progress
2025/05/30	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/05/30	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/05/30	JUVENILE INTERVIEW 165	Wall Drywall Finish	no data
2025/05/30	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/05/30	JUVENILLE INTERVIEWERS 166	In Wall Insulation	complete
2025/05/30	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/05/30	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/05/30	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	not started
2025/05/30	JUVENILLE INTERVIEWERS 166	Wall Drywall	complete
2025/05/30	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/05/30	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/05/30	KEY ROOM 185	In Wall Insulation	in progress
2025/05/30	KEY ROOM 185	Overhead Duct Insulation	no data
2025/05/30	KEY ROOM 185	Overhead Duct Rough In	in progress
2025/05/30	KEY ROOM 185	Overhead Plumbing	no data
2025/05/30	KEY ROOM 185	Wall Drywall	in progress
2025/05/30	KEY ROOM 185	Wall Drywall Finish	no data
2025/05/30	KEY ROOM 185	Wall Prime Paint	not started
2025/05/30	LT 170	In Wall Insulation	complete
2025/05/30	LT 170	Overhead Duct Insulation	in progress
2025/05/30	LT 170	Overhead Duct Rough In	in progress
2025/05/30	LT 170	Overhead Plumbing	not started
2025/05/30	LT 170	Wall Drywall	complete
2025/05/30	LT 170	Wall Drywall Finish	complete
2025/05/30	LT 170	Wall Prime Paint	complete
2025/05/30	MACHINE ROOM 191	In Wall Insulation	complete
2025/05/30	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/05/30	MACHINE ROOM 191	Overhead Duct Rough In	in progress
2025/05/30	MACHINE ROOM 191	Overhead Plumbing	in progress
2025/05/30	MACHINE ROOM 191	Wall Drywall	complete
2025/05/30	MACHINE ROOM 191	Wall Drywall Finish	no data
2025/05/30	MACHINE ROOM 191	Wall Prime Paint	complete
2025/05/30	MAIN ELECTRICAL ROOM 123	In Wall Insulation	complete
2025/05/30	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	not started
2025/05/30	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	not started
2025/05/30	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	not started
2025/05/30	MAIN ELECTRICAL ROOM 123	Wall Drywall	complete
2025/05/30	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	complete

2025/05/30	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	in progress
2025/05/30	MAIN JANITORIAL111	In Wall Insulation	complete
2025/05/30	MAIN JANITORIAL111	Overhead Duct Insulation	no data
2025/05/30	MAIN JANITORIAL111	Overhead Duct Rough In	in progress
2025/05/30	MAIN JANITORIAL111	Overhead Plumbing	no data
2025/05/30	MAIN JANITORIAL111	Wall Drywall	complete
2025/05/30	MAIN JANITORIAL111	Wall Drywall Finish	no data
2025/05/30	MAIN JANITORIAL111	Wall Prime Paint	in progress
2025/05/30	MARINE SERGEANT 142	In Wall Insulation	complete
2025/05/30	MARINE SERGEANT 142	Overhead Duct Insulation	no data
2025/05/30	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/05/30	MARINE SERGEANT 142	Overhead Plumbing	no data
2025/05/30	MARINE SERGEANT 142	Wall Drywall	complete
2025/05/30	MARINE SERGEANT 142	Wall Drywall Finish	no data
2025/05/30	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/05/30	MECHANICAL 192	In Wall Insulation	complete
2025/05/30	MECHANICAL 192	Overhead Duct Insulation	not started
2025/05/30	MECHANICAL 192	Overhead Duct Rough In	in progress
2025/05/30	MECHANICAL 192	Overhead Plumbing	in progress
2025/05/30	MECHANICAL 192	Wall Drywall	complete
2025/05/30	MECHANICAL 192	Wall Drywall Finish	complete
2025/05/30	MECHANICAL 192	Wall Prime Paint	complete
2025/05/30	MECHANICAL ROOM 122	In Wall Insulation	complete
2025/05/30	MECHANICAL ROOM 122	Overhead Duct Insulation	not started
2025/05/30	MECHANICAL ROOM 122	Overhead Duct Rough In	in progress
2025/05/30	MECHANICAL ROOM 122	Overhead Plumbing	complete
2025/05/30	MECHANICAL ROOM 122	Wall Drywall	complete
2025/05/30	MECHANICAL ROOM 122	Wall Drywall Finish	complete
2025/05/30	MECHANICAL ROOM 122	Wall Prime Paint	complete
2025/05/30	MENS RESTROOM 112	In Wall Insulation	complete
2025/05/30	MENS RESTROOM 112	Overhead Duct Insulation	complete
2025/05/30	MENS RESTROOM 112	Overhead Duct Rough In	in progress
2025/05/30	MENS RESTROOM 112	Overhead Plumbing	complete
2025/05/30	MENS RESTROOM 112	Wall Drywall	complete
2025/05/30	MENS RESTROOM 112	Wall Drywall Finish	in progress
2025/05/30	MENS RESTROOM 112	Wall Prime Paint	not started
2025/05/30	MIS EQUIPMENT STORAGE 138	In Wall Insulation	complete
2025/05/30	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/05/30	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	in progress
2025/05/30	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	in progress
2025/05/30	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/05/30	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete

2025/05/30	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/05/30	MIS SHREDDING 117	In Wall Insulation	complete
2025/05/30	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/05/30	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/05/30	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/05/30	MIS SHREDDING 117	Wall Drywall	complete
2025/05/30	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/05/30	MIS SHREDDING 117	Wall Prime Paint	complete
2025/05/30	OFFICE 128	In Wall Insulation	complete
2025/05/30	OFFICE 128	Overhead Duct Insulation	no data
2025/05/30	OFFICE 128	Overhead Duct Rough In	in progress
2025/05/30	OFFICE 128	Overhead Plumbing	not started
2025/05/30	OFFICE 128	Wall Drywall	complete
2025/05/30	OFFICE 128	Wall Drywall Finish	no data
2025/05/30	OFFICE 128	Wall Prime Paint	complete
2025/05/30	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	complete
2025/05/30	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	in progress
2025/05/30	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	in progress
2025/05/30	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	in progress
2025/05/30	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/05/30	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/05/30	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	in progress
2025/05/30	PARTS STORAGE 189	In Wall Insulation	in progress
2025/05/30	PARTS STORAGE 189	Overhead Duct Insulation	no data
2025/05/30	PARTS STORAGE 189	Overhead Duct Rough In	in progress
2025/05/30	PARTS STORAGE 189	Overhead Plumbing	no data
2025/05/30	PARTS STORAGE 189	Wall Drywall	in progress
2025/05/30	PARTS STORAGE 189	Wall Drywall Finish	no data
2025/05/30	PARTS STORAGE 189	Wall Prime Paint	not started
2025/05/30	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/05/30	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/05/30	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/05/30	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/05/30	PUBLIC RESTROOM 106	Wall Drywall	no data
2025/05/30	PUBLIC RESTROOM 106	Wall Drywall Finish	no data
2025/05/30	PUBLIC RESTROOM 106	Wall Prime Paint	no data
2025/05/30	Polygraph 152	In Wall Insulation	in progress
2025/05/30	Polygraph 152	Overhead Duct Insulation	not started
2025/05/30	Polygraph 152	Overhead Duct Rough In	in progress
2025/05/30	Polygraph 152	Overhead Plumbing	not started
2025/05/30	Polygraph 152	Wall Drywall	in progress
2025/05/30	Polygraph 152	Wall Drywall Finish	not started
2025/05/30	Polygraph 152	Wall Prime Paint	not started

2025/05/30	RECEPTION 101	In Wall Insulation	not started
2025/05/30	RECEPTION 101	Overhead Duct Insulation	no data
2025/05/30	RECEPTION 101	Overhead Duct Rough In	in progress
2025/05/30	RECEPTION 101	Overhead Plumbing	not started
2025/05/30	RECEPTION 101	Wall Drywall	not started
2025/05/30	RECEPTION 101	Wall Drywall Finish	no data
2025/05/30	RECEPTION 101	Wall Prime Paint	not started
2025/05/30	RECEPTION 147	In Wall Insulation	in progress
2025/05/30	RECEPTION 147	Overhead Duct Insulation	in progress
2025/05/30	RECEPTION 147	Overhead Duct Rough In	in progress
2025/05/30	RECEPTION 147	Overhead Plumbing	in progress
2025/05/30	RECEPTION 147	Wall Drywall	in progress
2025/05/30	RECEPTION 147	Wall Drywall Finish	no data
2025/05/30	RECEPTION 147	Wall Prime Paint	not started
2025/05/30	RECEPTION 179	In Wall Insulation	in progress
2025/05/30	RECEPTION 179	Overhead Duct Insulation	no data
2025/05/30	RECEPTION 179	Overhead Duct Rough In	in progress
2025/05/30	RECEPTION 179	Overhead Plumbing	no data
2025/05/30	RECEPTION 179	Wall Drywall	in progress
2025/05/30	RECEPTION 179	Wall Drywall Finish	no data
2025/05/30	RECEPTION 179	Wall Prime Paint	not started
2025/05/30	RECORDS 130	In Wall Insulation	complete
2025/05/30	RECORDS 130	Overhead Duct Insulation	in progress
2025/05/30	RECORDS 130	Overhead Duct Rough In	in progress
2025/05/30	RECORDS 130	Overhead Plumbing	in progress
2025/05/30	RECORDS 130	Wall Drywall	complete
2025/05/30	RECORDS 130	Wall Drywall Finish	complete
2025/05/30	RECORDS 130	Wall Prime Paint	complete
2025/05/30	RECORDS STORAGE 133	In Wall Insulation	complete
2025/05/30	RECORDS STORAGE 133	Overhead Duct Insulation	in progress
2025/05/30	RECORDS STORAGE 133	Overhead Duct Rough In	in progress
2025/05/30	RECORDS STORAGE 133	Overhead Plumbing	not started
2025/05/30	RECORDS STORAGE 133	Wall Drywall	complete
2025/05/30	RECORDS STORAGE 133	Wall Drywall Finish	complete
2025/05/30	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/05/30	RECORDS SUPERVISOR 131	In Wall Insulation	complete
2025/05/30	RECORDS SUPERVISOR 131	Overhead Duct Insulation	in progress
2025/05/30	RECORDS SUPERVISOR 131	Overhead Duct Rough In	in progress
2025/05/30	RECORDS SUPERVISOR 131	Overhead Plumbing	not started
2025/05/30	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/05/30	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/05/30	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/05/30	RECORDS SUPERVISOR 132	In Wall Insulation	complete
2025/05/30	RECORDS SUPERVISOR 132	Overhead Duct Insulation	in progress
2025/05/30	RECORDS SUPERVISOR 132	Overhead Duct Rough In	in progress
2025/05/30	RECORDS SUPERVISOR 132	Overhead Plumbing	not started

2025/05/30	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/05/30	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/05/30	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/05/30	RESTROOM 183	In Wall Insulation	in progress
2025/05/30	RESTROOM 183	Overhead Duct Insulation	in progress
2025/05/30	RESTROOM 183	Overhead Duct Rough In	in progress
2025/05/30	RESTROOM 183	Overhead Plumbing	in progress
2025/05/30	RESTROOM 183	Wall Drywall	not started
2025/05/30	RESTROOM 183	Wall Drywall Finish	not started
2025/05/30	RESTROOM 183	Wall Prime Paint	not started
2025/05/30	Risk Management - 158	In Wall Insulation	not started
2025/05/30	Risk Management - 158	Overhead Duct Insulation	not started
2025/05/30	Risk Management - 158	Overhead Duct Rough In	in progress
2025/05/30	Risk Management - 158	Overhead Plumbing	in progress
2025/05/30	Risk Management - 158	Wall Drywall	not started
2025/05/30	Risk Management - 158	Wall Drywall Finish	not started
2025/05/30	Risk Management - 158	Wall Prime Paint	not started
2025/05/30	SALLY PORT 105	In Wall Insulation	not started
2025/05/30	SALLY PORT 105	Overhead Duct Insulation	no data
2025/05/30	SALLY PORT 105	Overhead Duct Rough In	in progress
2025/05/30	SALLY PORT 105	Overhead Plumbing	no data
2025/05/30	SALLY PORT 105	Wall Drywall	not started
2025/05/30	SALLY PORT 105	Wall Drywall Finish	no data
2025/05/30	SALLY PORT 105	Wall Prime Paint	not started
2025/05/30	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/05/30	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/05/30	SANE EXAM ROOM 168	Overhead Duct Rough In	in progress
2025/05/30	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/05/30	SANE EXAM ROOM 168	Wall Drywall	complete
2025/05/30	SANE EXAM ROOM 168	Wall Drywall Finish	no data
2025/05/30	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/05/30	SGT 171	In Wall Insulation	complete
2025/05/30	SGT 171	Overhead Duct Insulation	in progress
2025/05/30	SGT 171	Overhead Duct Rough In	in progress
2025/05/30	SGT 171	Overhead Plumbing	in progress
2025/05/30	SGT 171	Wall Drywall	complete
2025/05/30	SGT 171	Wall Drywall Finish	complete
2025/05/30	SGT 171	Wall Prime Paint	complete
2025/05/30	SGT 172	In Wall Insulation	complete
2025/05/30	SGT 172	Overhead Duct Insulation	no data
2025/05/30	SGT 172	Overhead Duct Rough In	in progress
2025/05/30	SGT 172	Overhead Plumbing	no data
2025/05/30	SGT 172	Wall Drywall	complete
2025/05/30	SGT 172	Wall Drywall Finish	no data
2025/05/30	SGT 172	Wall Prime Paint	complete
2025/05/30	SHIPPING STORAGE 190	In Wall Insulation	in progress
2025/05/30	SHIPPING STORAGE 190	Overhead Duct Insulation	no data
2025/05/30	SHIPPING STORAGE 190	Overhead Duct Rough In	in progress

progress

2025/05/30		SHIPPING STORAGE 190		Overhead Plumbing		no data
2025/05/30		SHIPPING STORAGE 190		Wall Drywall		in progress
2025/05/30		SHIPPING STORAGE 190		Wall Drywall Finish		no data
2025/05/30		SHIPPING STORAGE 190		Wall Prime Paint		not started
2025/05/30		SHOP FORMAN 184		In Wall Insulation		in progress
2025/05/30		SHOP FORMAN 184		Overhead Duct Insulation		no data
2025/05/30		SHOP FORMAN 184		Overhead Duct Rough In		in progress
2025/05/30		SHOP FORMAN 184		Overhead Plumbing		no data
2025/05/30		SHOP FORMAN 184		Wall Drywall		in progress
2025/05/30		SHOP FORMAN 184		Wall Drywall Finish		no data
2025/05/30		SHOP FORMAN 184		Wall Prime Paint		not started
2025/05/30		SOFT INTERVIEW 161		In Wall Insulation		complete
2025/05/30		SOFT INTERVIEW 161		Overhead Duct Insulation		no data
2025/05/30		SOFT INTERVIEW 161		Overhead Duct Rough In		in

progress

2025/05/30		SOFT INTERVIEW 161		Overhead Plumbing		complete
2025/05/30		SOFT INTERVIEW 161		Wall Drywall		complete
2025/05/30		SOFT INTERVIEW 161		Wall Drywall Finish		no data
2025/05/30		SOFT INTERVIEW 161		Wall Prime Paint		complete
2025/05/30		SOFT INTERVIEW 162		In Wall Insulation		complete
2025/05/30		SOFT INTERVIEW 162		Overhead Duct Insulation		in

progress

2025/05/30		SOFT INTERVIEW 162		Overhead Duct Rough In		in
------------	--	--------------------	--	------------------------	--	----

progress

2025/05/30		SOFT INTERVIEW 162		Overhead Plumbing		in progress
2025/05/30		SOFT INTERVIEW 162		Wall Drywall		complete
2025/05/30		SOFT INTERVIEW 162		Wall Drywall Finish		complete
2025/05/30		SOFT INTERVIEW 162		Wall Prime Paint		complete
2025/05/30		SPECIAL OPERATION LT 143		In Wall Insulation		

complete

2025/05/30		SPECIAL OPERATION LT 143		Overhead Duct Insulation		no data
------------	--	--------------------------	--	--------------------------	--	---------

2025/05/30		SPECIAL OPERATION LT 143		Overhead Duct Rough In		in
------------	--	--------------------------	--	------------------------	--	----

progress

2025/05/30		SPECIAL OPERATION LT 143		Overhead Plumbing		in
------------	--	--------------------------	--	-------------------	--	----

progress

2025/05/30		SPECIAL OPERATION LT 143		Wall Drywall		complete
2025/05/30		SPECIAL OPERATION LT 143		Wall Drywall Finish		no data

data

2025/05/30		SPECIAL OPERATION LT 143		Wall Prime Paint		complete
------------	--	--------------------------	--	------------------	--	----------

2025/05/30		STAIR A		In Wall Insulation		no data
------------	--	---------	--	--------------------	--	---------

2025/05/30		STAIR A		Overhead Duct Insulation		no data
------------	--	---------	--	--------------------------	--	---------

2025/05/30		STAIR A		Overhead Duct Rough In		in progress
------------	--	---------	--	------------------------	--	-------------

2025/05/30		STAIR A		Overhead Plumbing		no data
------------	--	---------	--	-------------------	--	---------

2025/05/30		STAIR A		Wall Drywall		not started
------------	--	---------	--	--------------	--	-------------

2025/05/30		STAIR A		Wall Drywall Finish		no data
------------	--	---------	--	---------------------	--	---------

2025/05/30		STAIR A		Wall Prime Paint		no data
------------	--	---------	--	------------------	--	---------

2025/05/30		STORAGE 104		In Wall Insulation		complete
------------	--	-------------	--	--------------------	--	----------

2025/05/30		STORAGE 104		Overhead Duct Insulation		in progress
------------	--	-------------	--	--------------------------	--	-------------

2025/05/30		STORAGE 104		Overhead Duct Rough In		in progress
------------	--	-------------	--	------------------------	--	-------------

2025/05/30		STORAGE 104		Overhead Plumbing		not started
------------	--	-------------	--	-------------------	--	-------------

2025/05/30		STORAGE 104		Wall Drywall		complete
------------	--	-------------	--	--------------	--	----------

2025/05/30		STORAGE 104		Wall Drywall Finish		complete
------------	--	-------------	--	---------------------	--	----------

2025/05/30	STORAGE 104	Wall Prime Paint	in progress
2025/05/30	STORAGE 127	In Wall Insulation	complete
2025/05/30	STORAGE 127	Overhead Duct Insulation	no data
2025/05/30	STORAGE 127	Overhead Duct Rough In	in progress
2025/05/30	STORAGE 127	Overhead Plumbing	not started
2025/05/30	STORAGE 127	Wall Drywall	complete
2025/05/30	STORAGE 127	Wall Drywall Finish	no data
2025/05/30	STORAGE 127	Wall Prime Paint	complete
2025/05/30	STUDIO 126	In Wall Insulation	complete
2025/05/30	STUDIO 126	Overhead Duct Insulation	in progress
2025/05/30	STUDIO 126	Overhead Duct Rough In	in progress
2025/05/30	STUDIO 126	Overhead Plumbing	not started
2025/05/30	STUDIO 126	Wall Drywall	complete
2025/05/30	STUDIO 126	Wall Drywall Finish	complete
2025/05/30	STUDIO 126	Wall Prime Paint	in progress
2025/05/30	SUPERVISOR 129	In Wall Insulation	complete
2025/05/30	SUPERVISOR 129	Overhead Duct Insulation	in progress
2025/05/30	SUPERVISOR 129	Overhead Duct Rough In	in progress
2025/05/30	SUPERVISOR 129	Overhead Plumbing	not started
2025/05/30	SUPERVISOR 129	Wall Drywall	complete
2025/05/30	SUPERVISOR 129	Wall Drywall Finish	complete
2025/05/30	SUPERVISOR 129	Wall Prime Paint	complete
2025/05/30	Storage 164	In Wall Insulation	complete
2025/05/30	Storage 164	Overhead Duct Insulation	in progress
2025/05/30	Storage 164	Overhead Duct Rough In	in progress
2025/05/30	Storage 164	Overhead Plumbing	not started
2025/05/30	Storage 164	Wall Drywall	complete
2025/05/30	Storage 164	Wall Drywall Finish	complete
2025/05/30	Storage 164	Wall Prime Paint	complete
2025/05/30	Storage 177	In Wall Insulation	complete
2025/05/30	Storage 177	Overhead Duct Insulation	in progress
2025/05/30	Storage 177	Overhead Duct Rough In	in progress
2025/05/30	Storage 177	Overhead Plumbing	not started
2025/05/30	Storage 177	Wall Drywall	complete
2025/05/30	Storage 177	Wall Drywall Finish	complete
2025/05/30	Storage 177	Wall Prime Paint	complete
2025/05/30	TECHNICAL SURVEILLANCE 188	In Wall Insulation	in progress
2025/05/30	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	not started
2025/05/30	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	in progress
2025/05/30	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	not started
2025/05/30	TECHNICAL SURVEILLANCE 188	Wall Drywall	in progress
2025/05/30	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	not started
2025/05/30	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	not started
2025/05/30	TRAFFIC SERGEANT 141	In Wall Insulation	complete
2025/05/30	TRAFFIC SERGEANT 141	Overhead Duct Insulation	in progress
2025/05/30	TRAFFIC SERGEANT 141	Overhead Duct Rough In	in progress



2025/05/30	TRAFFIC SERGEANT 141	Overhead Plumbing	in progress
2025/05/30	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/05/30	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/05/30	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/05/30	TRIAGE/RECEPTION 134	In Wall Insulation	complete
2025/05/30	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/05/30	TRIAGE/RECEPTION 134	Overhead Duct Rough In	in progress
2025/05/30	TRIAGE/RECEPTION 134	Overhead Plumbing	not started
2025/05/30	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/05/30	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/05/30	TRIAGE/RECEPTION 134	Wall Prime Paint	in progress
2025/05/30	TST WORKSHOP 187	In Wall Insulation	in progress
2025/05/30	TST WORKSHOP 187	Overhead Duct Insulation	no data
2025/05/30	TST WORKSHOP 187	Overhead Duct Rough In	in progress
2025/05/30	TST WORKSHOP 187	Overhead Plumbing	no data
2025/05/30	TST WORKSHOP 187	Wall Drywall	in progress
2025/05/30	TST WORKSHOP 187	Wall Drywall Finish	no data
2025/05/30	TST WORKSHOP 187	Wall Prime Paint	not started
2025/05/30	UNISEX RESTROOM 169	In Wall Insulation	complete
2025/05/30	UNISEX RESTROOM 169	Overhead Duct Insulation	no data
2025/05/30	UNISEX RESTROOM 169	Overhead Duct Rough In	in progress
2025/05/30	UNISEX RESTROOM 169	Overhead Plumbing	no data
2025/05/30	UNISEX RESTROOM 169	Wall Drywall	complete
2025/05/30	UNISEX RESTROOM 169	Wall Drywall Finish	no data
2025/05/30	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/05/30	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	in progress
2025/05/30	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	not started
2025/05/30	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	in progress
2025/05/30	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete
2025/05/30	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	in progress
2025/05/30	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	no data
2025/05/30	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	in progress
2025/05/30	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	complete
2025/05/30	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	no data
2025/05/30	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	in progress
2025/05/30	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	no data
2025/05/30	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/05/30	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	no data
2025/05/30	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete

2025/05/30	WAITING/LOBBY 100	In Wall Insulation	not started
2025/05/30	WAITING/LOBBY 100	Overhead Duct Insulation	no data
2025/05/30	WAITING/LOBBY 100	Overhead Duct Rough In	not started
2025/05/30	WAITING/LOBBY 100	Overhead Plumbing	not started
2025/05/30	WAITING/LOBBY 100	Wall Drywall	not started
2025/05/30	WAITING/LOBBY 100	Wall Drywall Finish	no data
2025/05/30	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/05/30	WOMENS RESTROOM 113	In Wall Insulation	complete
2025/05/30	WOMENS RESTROOM 113	Overhead Duct Insulation	complete
2025/05/30	WOMENS RESTROOM 113	Overhead Duct Rough In	in progress
2025/05/30	WOMENS RESTROOM 113	Overhead Plumbing	complete
2025/05/30	WOMENS RESTROOM 113	Wall Drywall	complete
2025/05/30	WOMENS RESTROOM 113	Wall Drywall Finish	in progress
2025/05/30	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/06/06	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/06/06	ADMIN ASSISTANT 125	Overhead Duct Insulation	no data
2025/06/06	ADMIN ASSISTANT 125	Overhead Duct Rough In	no data
2025/06/06	ADMIN ASSISTANT 125	Overhead Plumbing	not started
2025/06/06	ADMIN ASSISTANT 125	Wall Drywall	complete
2025/06/06	ADMIN ASSISTANT 125	Wall Drywall Finish	complete
2025/06/06	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/06/06	AV ROOM 103	In Wall Insulation	no data
2025/06/06	AV ROOM 103	Overhead Duct Insulation	no data
2025/06/06	AV ROOM 103	Overhead Duct Rough In	no data
2025/06/06	AV ROOM 103	Overhead Plumbing	no data
2025/06/06	AV ROOM 103	Wall Drywall	complete
2025/06/06	AV ROOM 103	Wall Drywall Finish	complete
2025/06/06	AV ROOM 103	Wall Prime Paint	complete
2025/06/06	BREAK ROOM CONFERENCE 182	In Wall Insulation	no data
2025/06/06	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	no data
2025/06/06	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	no data
2025/06/06	BREAK ROOM CONFERENCE 182	Overhead Plumbing	no data
2025/06/06	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/06/06	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	in progress
2025/06/06	BREAK ROOM CONFERENCE 182	Wall Prime Paint	not started
2025/06/06	Background-159	In Wall Insulation	in progress
2025/06/06	Background-159	Overhead Duct Insulation	not started
2025/06/06	Background-159	Overhead Duct Rough In	in progress
2025/06/06	Background-159	Overhead Plumbing	not started
2025/06/06	Background-159	Wall Drywall	in progress
2025/06/06	Background-159	Wall Drywall Finish	not started
2025/06/06	Background-159	Wall Prime Paint	not started
2025/06/06	CENTRAL BREAKROOM 145	In Wall Insulation	no data
2025/06/06	CENTRAL BREAKROOM 145	Overhead Duct Insulation	no data

2025/06/06	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/06/06	CENTRAL BREAKROOM 145	Overhead Plumbing	not started
2025/06/06	CENTRAL BREAKROOM 145	Wall Drywall	in progress
2025/06/06	CENTRAL BREAKROOM 145	Wall Drywall Finish	not started
2025/06/06	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/06/06	COLD CASE 175	In Wall Insulation	no data
2025/06/06	COLD CASE 175	Overhead Duct Insulation	no data
2025/06/06	COLD CASE 175	Overhead Duct Rough In	no data
2025/06/06	COLD CASE 175	Overhead Plumbing	no data
2025/06/06	COLD CASE 175	Wall Drywall	complete
2025/06/06	COLD CASE 175	Wall Drywall Finish	complete
2025/06/06	COLD CASE 175	Wall Prime Paint	in progress
2025/06/06	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/06/06	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	no data
2025/06/06	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	no data
2025/06/06	COMMUNITY AFFAIRS 124	Overhead Plumbing	no data
2025/06/06	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/06/06	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/06/06	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/06/06	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/06/06	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	no data
2025/06/06	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	no data
2025/06/06	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	no data
2025/06/06	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete
2025/06/06	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	not started
2025/06/06	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	not started
2025/06/06	CONFERENCE ROOM 153	In Wall Insulation	in progress
2025/06/06	CONFERENCE ROOM 153	Overhead Duct Insulation	no data
2025/06/06	CONFERENCE ROOM 153	Overhead Duct Rough In	no data
2025/06/06	CONFERENCE ROOM 153	Overhead Plumbing	not started
2025/06/06	CONFERENCE ROOM 153	Wall Drywall	in progress
2025/06/06	CONFERENCE ROOM 153	Wall Drywall Finish	not started
2025/06/06	CONFERENCE ROOM 153	Wall Prime Paint	not started
2025/06/06	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/06/06	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	no data
2025/06/06	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	no data
2025/06/06	CONFERENCE/WAR ROOM 163	Overhead Plumbing	not started
2025/06/06	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/06/06	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete

2025/06/06	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/06/06	COPY 176	In Wall Insulation	complete
2025/06/06	COPY 176	Overhead Duct Insulation	in progress
2025/06/06	COPY 176	Overhead Duct Rough In	in progress
2025/06/06	COPY 176	Overhead Plumbing	not started
2025/06/06	COPY 176	Wall Drywall	complete
2025/06/06	COPY 176	Wall Drywall Finish	complete
2025/06/06	COPY 176	Wall Prime Paint	complete
2025/06/06	COPY/MAIL ROOM 114	In Wall Insulation	complete
2025/06/06	COPY/MAIL ROOM 114	Overhead Duct Insulation	no data
2025/06/06	COPY/MAIL ROOM 114	Overhead Duct Rough In	no data
2025/06/06	COPY/MAIL ROOM 114	Overhead Plumbing	no data
2025/06/06	COPY/MAIL ROOM 114	Wall Drywall	complete
2025/06/06	COPY/MAIL ROOM 114	Wall Drywall Finish	complete
2025/06/06	COPY/MAIL ROOM 114	Wall Prime Paint	complete
2025/06/06	CORRIDOR 107	In Wall Insulation	complete
2025/06/06	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/06/06	CORRIDOR 107	Overhead Duct Rough In	in progress
2025/06/06	CORRIDOR 107	Overhead Plumbing	in progress
2025/06/06	CORRIDOR 107	Wall Drywall	complete
2025/06/06	CORRIDOR 107	Wall Drywall Finish	complete
2025/06/06	CORRIDOR 107	Wall Prime Paint	in progress
2025/06/06	CORRIDOR 108	In Wall Insulation	complete
2025/06/06	CORRIDOR 108	In Wall Insulation	no data
2025/06/06	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/06/06	CORRIDOR 108	Overhead Duct Insulation	no data
2025/06/06	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/06/06	CORRIDOR 108	Overhead Duct Rough In	no data
2025/06/06	CORRIDOR 108	Overhead Plumbing	in progress
2025/06/06	CORRIDOR 108	Overhead Plumbing	no data
2025/06/06	CORRIDOR 108	Wall Drywall	complete
2025/06/06	CORRIDOR 108	Wall Drywall	complete
2025/06/06	CORRIDOR 108	Wall Drywall Finish	complete
2025/06/06	CORRIDOR 108	Wall Drywall Finish	complete
2025/06/06	CORRIDOR 108	Wall Prime Paint	in progress
2025/06/06	CORRIDOR 108	Wall Prime Paint	in progress
2025/06/06	CORRIDOR 109	In Wall Insulation	complete
2025/06/06	CORRIDOR 109	Overhead Duct Insulation	in progress
2025/06/06	CORRIDOR 109	Overhead Duct Rough In	in progress
2025/06/06	CORRIDOR 109	Overhead Plumbing	in progress
2025/06/06	CORRIDOR 109	Wall Drywall	complete
2025/06/06	CORRIDOR 109	Wall Drywall Finish	complete
2025/06/06	CORRIDOR 109	Wall Prime Paint	complete
2025/06/06	CORRIDOR 110	In Wall Insulation	no data
2025/06/06	CORRIDOR 110	In Wall Insulation	no data
2025/06/06	CORRIDOR 110	Overhead Duct Insulation	no data
2025/06/06	CORRIDOR 110	Overhead Duct Insulation	no data
2025/06/06	CORRIDOR 110	Overhead Duct Rough In	no data
2025/06/06	CORRIDOR 110	Overhead Duct Rough In	no data
2025/06/06	CORRIDOR 110	Overhead Plumbing	no data
2025/06/06	CORRIDOR 110	Overhead Plumbing	in progress
2025/06/06	CORRIDOR 110	Wall Drywall	complete
2025/06/06	CORRIDOR 110	Wall Drywall	complete
2025/06/06	CORRIDOR 110	Wall Drywall Finish	in progress

2025/06/06	CORRIDOR 110	Wall Drywall Finish	in progress
2025/06/06	CORRIDOR 110	Wall Prime Paint	in progress
2025/06/06	CORRIDOR 110	Wall Prime Paint	in progress
2025/06/06	CORRIDOR 181	In Wall Insulation	complete
2025/06/06	CORRIDOR 181	Overhead Duct Insulation	not started
2025/06/06	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/06/06	CORRIDOR 181	Overhead Plumbing	in progress
2025/06/06	CORRIDOR 181	Wall Drywall	complete
2025/06/06	CORRIDOR 181	Wall Drywall Finish	in progress
2025/06/06	CORRIDOR 181	Wall Prime Paint	not started
2025/06/06	CORRIDOR144	In Wall Insulation	no data
2025/06/06	CORRIDOR144	Overhead Duct Insulation	no data
2025/06/06	CORRIDOR144	Overhead Duct Rough In	no data
2025/06/06	CORRIDOR144	Overhead Plumbing	no data
2025/06/06	CORRIDOR144	Wall Drywall	complete
2025/06/06	CORRIDOR144	Wall Drywall Finish	complete
2025/06/06	CORRIDOR144	Wall Prime Paint	complete
2025/06/06	CPL 173	In Wall Insulation	complete
2025/06/06	CPL 173	Overhead Duct Insulation	no data
2025/06/06	CPL 173	Overhead Duct Rough In	no data
2025/06/06	CPL 173	Overhead Plumbing	no data
2025/06/06	CPL 173	Wall Drywall	complete
2025/06/06	CPL 173	Wall Drywall Finish	complete
2025/06/06	CPL 173	Wall Prime Paint	in progress
2025/06/06	CPL 174	In Wall Insulation	complete
2025/06/06	CPL 174	Overhead Duct Insulation	no data
2025/06/06	CPL 174	Overhead Duct Rough In	no data
2025/06/06	CPL 174	Overhead Plumbing	no data
2025/06/06	CPL 174	Wall Drywall	complete
2025/06/06	CPL 174	Wall Drywall Finish	complete
2025/06/06	CPL 174	Wall Prime Paint	in progress
2025/06/06	DRY STORAGE 146	In Wall Insulation	complete
2025/06/06	DRY STORAGE 146	Overhead Duct Insulation	not started
2025/06/06	DRY STORAGE 146	Overhead Duct Rough In	in progress
2025/06/06	DRY STORAGE 146	Overhead Plumbing	not started
2025/06/06	DRY STORAGE 146	Wall Drywall	in progress
2025/06/06	DRY STORAGE 146	Wall Drywall Finish	in progress
2025/06/06	DRY STORAGE 146	Wall Prime Paint	not started
2025/06/06	FIRE RISER 178	In Wall Insulation	complete
2025/06/06	FIRE RISER 178	Overhead Duct Insulation	no data
2025/06/06	FIRE RISER 178	Overhead Duct Rough In	no data
2025/06/06	FIRE RISER 178	Overhead Plumbing	no data
2025/06/06	FIRE RISER 178	Wall Drywall	complete
2025/06/06	FIRE RISER 178	Wall Drywall Finish	complete
2025/06/06	FIRE RISER 178	Wall Prime Paint	not started
2025/06/06	GREETING ROOM 106	In Wall Insulation	no data
2025/06/06	GREETING ROOM 106	Overhead Duct Insulation	no data
2025/06/06	GREETING ROOM 106	Overhead Duct Rough In	no data
2025/06/06	GREETING ROOM 106	Overhead Plumbing	not started
2025/06/06	GREETING ROOM 106	Wall Drywall	complete
2025/06/06	GREETING ROOM 106	Wall Drywall Finish	complete
2025/06/06	GREETING ROOM 106	Wall Prime Paint	complete
2025/06/06	HR 149	In Wall Insulation	complete

2025/06/06	HR 149	Overhead Duct Insulation	not started
2025/06/06	HR 149	Overhead Duct Rough In	in progress
2025/06/06	HR 149	Overhead Plumbing	not started
2025/06/06	HR 149	Wall Drywall	complete
2025/06/06	HR 149	Wall Drywall Finish	not started
2025/06/06	HR 149	Wall Prime Paint	not started
2025/06/06	HR 150	In Wall Insulation	complete
2025/06/06	HR 150	Overhead Duct Insulation	not started
2025/06/06	HR 150	Overhead Duct Rough In	in progress
2025/06/06	HR 150	Overhead Plumbing	not started
2025/06/06	HR 150	Wall Drywall	in progress
2025/06/06	HR 150	Wall Drywall Finish	not started
2025/06/06	HR 150	Wall Prime Paint	not started
2025/06/06	HR 151	In Wall Insulation	complete
2025/06/06	HR 151	Overhead Duct Insulation	not started
2025/06/06	HR 151	Overhead Duct Rough In	in progress
2025/06/06	HR 151	Overhead Plumbing	in progress
2025/06/06	HR 151	Wall Drywall	complete
2025/06/06	HR 151	Wall Drywall Finish	in progress
2025/06/06	HR 151	Wall Prime Paint	not started
2025/06/06	HR 154	In Wall Insulation	complete
2025/06/06	HR 154	Overhead Duct Insulation	not started
2025/06/06	HR 154	Overhead Duct Rough In	in progress
2025/06/06	HR 154	Overhead Plumbing	in progress
2025/06/06	HR 154	Wall Drywall	complete
2025/06/06	HR 154	Wall Drywall Finish	not started
2025/06/06	HR 154	Wall Prime Paint	not started
2025/06/06	HR 155	In Wall Insulation	complete
2025/06/06	HR 155	Overhead Duct Insulation	in progress
2025/06/06	HR 155	Overhead Duct Rough In	in progress
2025/06/06	HR 155	Overhead Plumbing	not started
2025/06/06	HR 155	Wall Drywall	in progress
2025/06/06	HR 155	Wall Drywall Finish	not started
2025/06/06	HR 155	Wall Prime Paint	not started
2025/06/06	HR 156	In Wall Insulation	in progress
2025/06/06	HR 156	Overhead Duct Insulation	not started
2025/06/06	HR 156	Overhead Duct Rough In	in progress
2025/06/06	HR 156	Overhead Plumbing	not started
2025/06/06	HR 156	Wall Drywall	in progress
2025/06/06	HR 156	Wall Drywall Finish	not started
2025/06/06	HR 156	Wall Prime Paint	not started
2025/06/06	HR 157	In Wall Insulation	in progress
2025/06/06	HR 157	Overhead Duct Insulation	not started
2025/06/06	HR 157	Overhead Duct Rough In	in progress
2025/06/06	HR 157	Overhead Plumbing	in progress
2025/06/06	HR 157	Wall Drywall	in progress
2025/06/06	HR 157	Wall Drywall Finish	not started
2025/06/06	HR 157	Wall Prime Paint	not started
2025/06/06	HUMAN RESOURCES 148	In Wall Insulation	in progress
2025/06/06	HUMAN RESOURCES 148	Overhead Duct Insulation	not started
2025/06/06	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/06/06	HUMAN RESOURCES 148	Overhead Plumbing	in progress

2025/06/06	HUMAN RESOURCES 148	Wall Drywall	in progress
2025/06/06	HUMAN RESOURCES 148	Wall Drywall Finish	not started
2025/06/06	HUMAN RESOURCES 148	Wall Prime Paint	not started
2025/06/06	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/06/06	INTERNAL AFFAIRS 119	Overhead Duct Insulation	no data
2025/06/06	INTERNAL AFFAIRS 119	Overhead Duct Rough In	no data
2025/06/06	INTERNAL AFFAIRS 119	Overhead Plumbing	no data
2025/06/06	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/06/06	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/06/06	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/06/06	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/06/06	INTERNAL AFFAIRS 120	Overhead Duct Insulation	in progress
2025/06/06	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/06/06	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/06/06	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/06/06	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/06/06	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/06/06	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/06/06	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	no data
2025/06/06	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	no data
2025/06/06	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	no data
2025/06/06	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/06/06	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/06/06	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/06/06	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	complete
2025/06/06	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	no data
2025/06/06	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	no data
2025/06/06	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	no data
2025/06/06	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/06/06	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	complete
2025/06/06	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	complete
2025/06/06	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	no data
2025/06/06	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	no data
2025/06/06	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	no data
2025/06/06	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	no data

2025/06/06	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/06/06	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/06/06	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	complete
2025/06/06	IT 115	In Wall Insulation	complete
2025/06/06	IT 115	Overhead Duct Insulation	no data
2025/06/06	IT 115	Overhead Duct Rough In	no data
2025/06/06	IT 115	Overhead Plumbing	no data
2025/06/06	IT 115	Wall Drywall	complete
2025/06/06	IT 115	Wall Drywall Finish	complete
2025/06/06	IT 115	Wall Prime Paint	complete
2025/06/06	IT 135	In Wall Insulation	complete
2025/06/06	IT 135	Overhead Duct Insulation	in progress
2025/06/06	IT 135	Overhead Duct Rough In	in progress
2025/06/06	IT 135	Overhead Plumbing	in progress
2025/06/06	IT 135	Wall Drywall	complete
2025/06/06	IT 135	Wall Drywall Finish	complete
2025/06/06	IT 135	Wall Prime Paint	complete
2025/06/06	IT MANAGER 136	In Wall Insulation	no data
2025/06/06	IT MANAGER 136	Overhead Duct Insulation	no data
2025/06/06	IT MANAGER 136	Overhead Duct Rough In	no data
2025/06/06	IT MANAGER 136	Overhead Plumbing	no data
2025/06/06	IT MANAGER 136	Wall Drywall	complete
2025/06/06	IT MANAGER 136	Wall Drywall Finish	complete
2025/06/06	IT MANAGER 136	Wall Prime Paint	complete
2025/06/06	IT MANAGER 137	In Wall Insulation	no data
2025/06/06	IT MANAGER 137	Overhead Duct Insulation	no data
2025/06/06	IT MANAGER 137	Overhead Duct Rough In	no data
2025/06/06	IT MANAGER 137	Overhead Plumbing	no data
2025/06/06	IT MANAGER 137	Wall Drywall	complete
2025/06/06	IT MANAGER 137	Wall Drywall Finish	complete
2025/06/06	IT MANAGER 137	Wall Prime Paint	complete
2025/06/06	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/06/06	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data
2025/06/06	JUVENILE INTERVIEW 165	Overhead Duct Rough In	no data
2025/06/06	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/06/06	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/06/06	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/06/06	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/06/06	JUVENILE INTERVIEWERS 166	In Wall Insulation	no data
2025/06/06	JUVENILE INTERVIEWERS 166	Overhead Duct Insulation	no data
2025/06/06	JUVENILE INTERVIEWERS 166	Overhead Duct Rough In	no data
2025/06/06	JUVENILE INTERVIEWERS 166	Overhead Plumbing	no data
2025/06/06	JUVENILE INTERVIEWERS 166	Wall Drywall	complete
2025/06/06	JUVENILE INTERVIEWERS 166	Wall Drywall Finish	complete



2025/06/06		JUVENILE INTERVIEWERS 166		Wall Prime Paint		complete
2025/06/06		KEY ROOM 185		In Wall Insulation		in progress
2025/06/06		KEY ROOM 185		Overhead Duct Insulation		no data
2025/06/06		KEY ROOM 185		Overhead Duct Rough In		no data
2025/06/06		KEY ROOM 185		Overhead Plumbing		no data
2025/06/06		KEY ROOM 185		Wall Drywall		in progress
2025/06/06		KEY ROOM 185		Wall Drywall Finish		not started
2025/06/06		KEY ROOM 185		Wall Prime Paint		not started
2025/06/06		LT 170		In Wall Insulation		complete
2025/06/06		LT 170		Overhead Duct Insulation		in progress
2025/06/06		LT 170		Overhead Duct Rough In		in progress
2025/06/06		LT 170		Overhead Plumbing		not started
2025/06/06		LT 170		Wall Drywall		complete
2025/06/06		LT 170		Wall Drywall Finish		complete
2025/06/06		LT 170		Wall Prime Paint		complete
2025/06/06		MACHINE ROOM 191		In Wall Insulation		no data
2025/06/06		MACHINE ROOM 191		Overhead Duct Insulation		no data
2025/06/06		MACHINE ROOM 191		Overhead Duct Rough In		no data
2025/06/06		MACHINE ROOM 191		Overhead Plumbing		no data
2025/06/06		MACHINE ROOM 191		Wall Drywall		complete
2025/06/06		MACHINE ROOM 191		Wall Drywall Finish		complete
2025/06/06		MACHINE ROOM 191		Wall Prime Paint		complete
2025/06/06		MAIN ELECTRICAL ROOM 123		In Wall Insulation		no data
2025/06/06		MAIN ELECTRICAL ROOM 123		Overhead Duct Insulation		no data
2025/06/06		MAIN ELECTRICAL ROOM 123		Overhead Duct Rough In		no data
2025/06/06		MAIN ELECTRICAL ROOM 123		Overhead Plumbing		no data
2025/06/06		MAIN ELECTRICAL ROOM 123		Wall Drywall		no data
2025/06/06		MAIN ELECTRICAL ROOM 123		Wall Drywall Finish		no data
2025/06/06		MAIN ELECTRICAL ROOM 123		Wall Prime Paint		no data
2025/06/06		MAIN JANITORIAL111		In Wall Insulation		complete
2025/06/06		MAIN JANITORIAL111		Overhead Duct Insulation		no data
2025/06/06		MAIN JANITORIAL111		Overhead Duct Rough In		in progress
2025/06/06		MAIN JANITORIAL111		Overhead Plumbing		no data
2025/06/06		MAIN JANITORIAL111		Wall Drywall		complete
2025/06/06		MAIN JANITORIAL111		Wall Drywall Finish		complete
2025/06/06		MAIN JANITORIAL111		Wall Prime Paint		complete
2025/06/06		MARINE SERGEANT 142		In Wall Insulation		complete
2025/06/06		MARINE SERGEANT 142		Overhead Duct Insulation		no data
2025/06/06		MARINE SERGEANT 142		Overhead Duct Rough In		no data
2025/06/06		MARINE SERGEANT 142		Overhead Plumbing		no data
2025/06/06		MARINE SERGEANT 142		Wall Drywall		complete
2025/06/06		MARINE SERGEANT 142		Wall Drywall Finish		complete
2025/06/06		MARINE SERGEANT 142		Wall Prime Paint		complete
2025/06/06		MECHANICAL 192		In Wall Insulation		no data
2025/06/06		MECHANICAL 192		Overhead Duct Insulation		not started
2025/06/06		MECHANICAL 192		Overhead Duct Rough In		in progress
2025/06/06		MECHANICAL 192		Overhead Plumbing		in progress
2025/06/06		MECHANICAL 192		Wall Drywall		complete

2025/06/06	MECHANICAL 192	Wall Drywall Finish	complete
2025/06/06	MECHANICAL 192	Wall Prime Paint	complete
2025/06/06	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/06/06	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
2025/06/06	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/06/06	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/06/06	MECHANICAL ROOM 122	Wall Drywall	no data
2025/06/06	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/06/06	MECHANICAL ROOM 122	Wall Prime Paint	complete
2025/06/06	MENS RESTROOM 112	In Wall Insulation	no data
2025/06/06	MENS RESTROOM 112	Overhead Duct Insulation	no data
2025/06/06	MENS RESTROOM 112	Overhead Duct Rough In	no data
2025/06/06	MENS RESTROOM 112	Overhead Plumbing	no data
2025/06/06	MENS RESTROOM 112	Wall Drywall	complete
2025/06/06	MENS RESTROOM 112	Wall Drywall Finish	in progress
2025/06/06	MENS RESTROOM 112	Wall Prime Paint	not started
2025/06/06	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
2025/06/06	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	no data
2025/06/06	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	no data
2025/06/06	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	no data
2025/06/06	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/06/06	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/06/06	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/06/06	MIS SHREDDING 117	In Wall Insulation	complete
2025/06/06	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/06/06	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/06/06	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/06/06	MIS SHREDDING 117	Wall Drywall	complete
2025/06/06	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/06/06	MIS SHREDDING 117	Wall Prime Paint	complete
2025/06/06	OFFICE 128	In Wall Insulation	no data
2025/06/06	OFFICE 128	Overhead Duct Insulation	no data
2025/06/06	OFFICE 128	Overhead Duct Rough In	no data
2025/06/06	OFFICE 128	Overhead Plumbing	not started
2025/06/06	OFFICE 128	Wall Drywall	complete
2025/06/06	OFFICE 128	Wall Drywall Finish	complete
2025/06/06	OFFICE 128	Wall Prime Paint	complete
2025/06/06	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	no data
2025/06/06	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	no data
2025/06/06	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	no data
2025/06/06	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	no data
2025/06/06	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete

2025/06/06	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/06/06	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	in progress
2025/06/06	PARTS STORAGE 189	In Wall Insulation	no data
2025/06/06	PARTS STORAGE 189	Overhead Duct Insulation	no data
2025/06/06	PARTS STORAGE 189	Overhead Duct Rough In	no data
2025/06/06	PARTS STORAGE 189	Overhead Plumbing	no data
2025/06/06	PARTS STORAGE 189	Wall Drywall	in progress
2025/06/06	PARTS STORAGE 189	Wall Drywall Finish	in progress
2025/06/06	PARTS STORAGE 189	Wall Prime Paint	not started
2025/06/06	PUBLIC RESTROOM 106	In Wall Insulation	in progress
2025/06/06	PUBLIC RESTROOM 106	Overhead Duct Insulation	not started
2025/06/06	PUBLIC RESTROOM 106	Overhead Duct Rough In	in progress
2025/06/06	PUBLIC RESTROOM 106	Overhead Plumbing	in progress
2025/06/06	PUBLIC RESTROOM 106	Wall Drywall	not started
2025/06/06	PUBLIC RESTROOM 106	Wall Drywall Finish	not started
2025/06/06	PUBLIC RESTROOM 106	Wall Prime Paint	not started
2025/06/06	Polygraph 152	In Wall Insulation	in progress
2025/06/06	Polygraph 152	Overhead Duct Insulation	not started
2025/06/06	Polygraph 152	Overhead Duct Rough In	in progress
2025/06/06	Polygraph 152	Overhead Plumbing	not started
2025/06/06	Polygraph 152	Wall Drywall	in progress
2025/06/06	Polygraph 152	Wall Drywall Finish	not started
2025/06/06	Polygraph 152	Wall Prime Paint	not started
2025/06/06	RECEPTION 101	In Wall Insulation	no data
2025/06/06	RECEPTION 101	Overhead Duct Insulation	no data
2025/06/06	RECEPTION 101	Overhead Duct Rough In	no data
2025/06/06	RECEPTION 101	Overhead Plumbing	no data
2025/06/06	RECEPTION 101	Wall Drywall	no data
2025/06/06	RECEPTION 101	Wall Drywall Finish	no data
2025/06/06	RECEPTION 101	Wall Prime Paint	not started
2025/06/06	RECEPTION 147	In Wall Insulation	no data
2025/06/06	RECEPTION 147	Overhead Duct Insulation	no data
2025/06/06	RECEPTION 147	Overhead Duct Rough In	no data
2025/06/06	RECEPTION 147	Overhead Plumbing	in progress
2025/06/06	RECEPTION 147	Wall Drywall	in progress
2025/06/06	RECEPTION 147	Wall Drywall Finish	in progress
2025/06/06	RECEPTION 147	Wall Prime Paint	not started
2025/06/06	RECEPTION 179	In Wall Insulation	in progress
2025/06/06	RECEPTION 179	Overhead Duct Insulation	no data
2025/06/06	RECEPTION 179	Overhead Duct Rough In	no data
2025/06/06	RECEPTION 179	Overhead Plumbing	no data
2025/06/06	RECEPTION 179	Wall Drywall	in progress
2025/06/06	RECEPTION 179	Wall Drywall Finish	not started
2025/06/06	RECEPTION 179	Wall Prime Paint	not started
2025/06/06	RECORDS 130	In Wall Insulation	no data
2025/06/06	RECORDS 130	Overhead Duct Insulation	no data
2025/06/06	RECORDS 130	Overhead Duct Rough In	no data
2025/06/06	RECORDS 130	Overhead Plumbing	no data
2025/06/06	RECORDS 130	Wall Drywall	complete
2025/06/06	RECORDS 130	Wall Drywall Finish	complete

2025/06/06	RECORDS 130	Wall Prime Paint	complete
2025/06/06	RECORDS STORAGE 133	In Wall Insulation	complete
2025/06/06	RECORDS STORAGE 133	Overhead Duct Insulation	in progress
2025/06/06	RECORDS STORAGE 133	Overhead Duct Rough In	in progress
2025/06/06	RECORDS STORAGE 133	Overhead Plumbing	not started
2025/06/06	RECORDS STORAGE 133	Wall Drywall	complete
2025/06/06	RECORDS STORAGE 133	Wall Drywall Finish	complete
2025/06/06	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/06/06	RECORDS SUPERVISOR 131	In Wall Insulation	no data
2025/06/06	RECORDS SUPERVISOR 131	Overhead Duct Insulation	no data
2025/06/06	RECORDS SUPERVISOR 131	Overhead Duct Rough In	no data
2025/06/06	RECORDS SUPERVISOR 131	Overhead Plumbing	no data
2025/06/06	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/06/06	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/06/06	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/06/06	RECORDS SUPERVISOR 132	In Wall Insulation	no data
2025/06/06	RECORDS SUPERVISOR 132	Overhead Duct Insulation	no data
2025/06/06	RECORDS SUPERVISOR 132	Overhead Duct Rough In	no data
2025/06/06	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/06/06	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/06/06	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/06/06	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/06/06	RESTRROOM 183	In Wall Insulation	in progress
2025/06/06	RESTRROOM 183	Overhead Duct Insulation	in progress
2025/06/06	RESTRROOM 183	Overhead Duct Rough In	in progress
2025/06/06	RESTRROOM 183	Overhead Plumbing	complete
2025/06/06	RESTRROOM 183	Wall Drywall	in progress
2025/06/06	RESTRROOM 183	Wall Drywall Finish	not started
2025/06/06	RESTRROOM 183	Wall Prime Paint	not started
2025/06/06	Risk Management - 158	In Wall Insulation	in progress
2025/06/06	Risk Management - 158	Overhead Duct Insulation	not started
2025/06/06	Risk Management - 158	Overhead Duct Rough In	in progress
2025/06/06	Risk Management - 158	Overhead Plumbing	in progress
2025/06/06	Risk Management - 158	Wall Drywall	in progress
2025/06/06	Risk Management - 158	Wall Drywall Finish	not started
2025/06/06	Risk Management - 158	Wall Prime Paint	not started
2025/06/06	SALLY PORT 105	In Wall Insulation	not started
2025/06/06	SALLY PORT 105	Overhead Duct Insulation	no data
2025/06/06	SALLY PORT 105	Overhead Duct Rough In	no data
2025/06/06	SALLY PORT 105	Overhead Plumbing	no data
2025/06/06	SALLY PORT 105	Wall Drywall	no data
2025/06/06	SALLY PORT 105	Wall Drywall Finish	no data
2025/06/06	SALLY PORT 105	Wall Prime Paint	no data
2025/06/06	SANE EXAM ROOM 168	In Wall Insulation	complete

2025/06/06	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/06/06	SANE EXAM ROOM 168	Overhead Duct Rough In	no data
2025/06/06	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/06/06	SANE EXAM ROOM 168	Wall Drywall	complete
2025/06/06	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/06/06	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/06/06	SGT 171	In Wall Insulation	no data
2025/06/06	SGT 171	Overhead Duct Insulation	no data
2025/06/06	SGT 171	Overhead Duct Rough In	no data
2025/06/06	SGT 171	Overhead Plumbing	no data
2025/06/06	SGT 171	Wall Drywall	complete
2025/06/06	SGT 171	Wall Drywall Finish	complete
2025/06/06	SGT 171	Wall Prime Paint	complete
2025/06/06	SGT 172	In Wall Insulation	complete
2025/06/06	SGT 172	Overhead Duct Insulation	complete
2025/06/06	SGT 172	Overhead Duct Rough In	in progress
2025/06/06	SGT 172	Overhead Plumbing	in progress
2025/06/06	SGT 172	Wall Drywall	complete
2025/06/06	SGT 172	Wall Drywall Finish	complete
2025/06/06	SGT 172	Wall Prime Paint	complete
2025/06/06	SHIPPING STORAGE 190	In Wall Insulation	in progress
2025/06/06	SHIPPING STORAGE 190	Overhead Duct Insulation	no data
2025/06/06	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/06/06	SHIPPING STORAGE 190	Overhead Plumbing	no data
2025/06/06	SHIPPING STORAGE 190	Wall Drywall	in progress
2025/06/06	SHIPPING STORAGE 190	Wall Drywall Finish	not started
2025/06/06	SHIPPING STORAGE 190	Wall Prime Paint	not started
2025/06/06	SHOP FORMAN 184	In Wall Insulation	in progress
2025/06/06	SHOP FORMAN 184	Overhead Duct Insulation	no data
2025/06/06	SHOP FORMAN 184	Overhead Duct Rough In	no data
2025/06/06	SHOP FORMAN 184	Overhead Plumbing	no data
2025/06/06	SHOP FORMAN 184	Wall Drywall	in progress
2025/06/06	SHOP FORMAN 184	Wall Drywall Finish	not started
2025/06/06	SHOP FORMAN 184	Wall Prime Paint	not started
2025/06/06	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/06/06	SOFT INTERVIEW 161	Overhead Duct Insulation	complete
2025/06/06	SOFT INTERVIEW 161	Overhead Duct Rough In	in progress
2025/06/06	SOFT INTERVIEW 161	Overhead Plumbing	complete
2025/06/06	SOFT INTERVIEW 161	Wall Drywall	complete
2025/06/06	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/06/06	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/06/06	SOFT INTERVIEW 162	In Wall Insulation	complete
2025/06/06	SOFT INTERVIEW 162	Overhead Duct Insulation	complete
2025/06/06	SOFT INTERVIEW 162	Overhead Duct Rough In	in progress
2025/06/06	SOFT INTERVIEW 162	Overhead Plumbing	in progress
2025/06/06	SOFT INTERVIEW 162	Wall Drywall	complete
2025/06/06	SOFT INTERVIEW 162	Wall Drywall Finish	complete
2025/06/06	SOFT INTERVIEW 162	Wall Prime Paint	complete

2025/06/06		SPECIAL OPERATION LT 143		In Wall Insulation		complete
2025/06/06		SPECIAL OPERATION LT 143		Overhead Duct Insulation		no data
2025/06/06		SPECIAL OPERATION LT 143		Overhead Duct Rough In		no data
2025/06/06		SPECIAL OPERATION LT 143		Overhead Plumbing		in progress
2025/06/06		SPECIAL OPERATION LT 143		Wall Drywall		complete
2025/06/06		SPECIAL OPERATION LT 143		Wall Drywall Finish		complete
2025/06/06		SPECIAL OPERATION LT 143		Wall Prime Paint		complete
2025/06/06		STAIR A		In Wall Insulation		not started
2025/06/06		STAIR A		Overhead Duct Insulation		no data
2025/06/06		STAIR A		Overhead Duct Rough In		no data
2025/06/06		STAIR A		Overhead Plumbing		no data
2025/06/06		STAIR A		Wall Drywall		not started
2025/06/06		STAIR A		Wall Drywall Finish		not started
2025/06/06		STAIR A		Wall Prime Paint		not started
2025/06/06		STORAGE 104		In Wall Insulation		no data
2025/06/06		STORAGE 104		Overhead Duct Insulation		no data
2025/06/06		STORAGE 104		Overhead Duct Rough In		no data
2025/06/06		STORAGE 104		Overhead Plumbing		not started
2025/06/06		STORAGE 104		Wall Drywall		complete
2025/06/06		STORAGE 104		Wall Drywall Finish		complete
2025/06/06		STORAGE 104		Wall Prime Paint		in progress
2025/06/06		STORAGE 127		In Wall Insulation		no data
2025/06/06		STORAGE 127		Overhead Duct Insulation		no data
2025/06/06		STORAGE 127		Overhead Duct Rough In		no data
2025/06/06		STORAGE 127		Overhead Plumbing		not started
2025/06/06		STORAGE 127		Wall Drywall		complete
2025/06/06		STORAGE 127		Wall Drywall Finish		complete
2025/06/06		STORAGE 127		Wall Prime Paint		complete
2025/06/06		STUDIO 126		In Wall Insulation		complete
2025/06/06		STUDIO 126		Overhead Duct Insulation		in progress
2025/06/06		STUDIO 126		Overhead Duct Rough In		in progress
2025/06/06		STUDIO 126		Overhead Plumbing		not started
2025/06/06		STUDIO 126		Wall Drywall		complete
2025/06/06		STUDIO 126		Wall Drywall Finish		complete
2025/06/06		STUDIO 126		Wall Prime Paint		in progress
2025/06/06		SUPERVISOR 129		In Wall Insulation		complete
2025/06/06		SUPERVISOR 129		Overhead Duct Insulation		in progress
2025/06/06		SUPERVISOR 129		Overhead Duct Rough In		in progress
2025/06/06		SUPERVISOR 129		Overhead Plumbing		not started
2025/06/06		SUPERVISOR 129		Wall Drywall		complete
2025/06/06		SUPERVISOR 129		Wall Drywall Finish		complete
2025/06/06		SUPERVISOR 129		Wall Prime Paint		complete
2025/06/06		Storage 164		In Wall Insulation		complete
2025/06/06		Storage 164		Overhead Duct Insulation		in progress
2025/06/06		Storage 164		Overhead Duct Rough In		in progress
2025/06/06		Storage 164		Overhead Plumbing		not started
2025/06/06		Storage 164		Wall Drywall		complete
2025/06/06		Storage 164		Wall Drywall Finish		complete
2025/06/06		Storage 164		Wall Prime Paint		complete

2025/06/06	Storage 177	In Wall Insulation	complete
2025/06/06	Storage 177	Overhead Duct Insulation	in progress
2025/06/06	Storage 177	Overhead Duct Rough In	in progress
2025/06/06	Storage 177	Overhead Plumbing	not started
2025/06/06	Storage 177	Wall Drywall	complete
2025/06/06	Storage 177	Wall Drywall Finish	complete
2025/06/06	Storage 177	Wall Prime Paint	complete
2025/06/06	TECHNICAL SURVEILLANCE 188	In Wall Insulation	no data
2025/06/06	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	no data
2025/06/06	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	no data
2025/06/06	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	no data
2025/06/06	TECHNICAL SURVEILLANCE 188	Wall Drywall	in progress
2025/06/06	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	not started
2025/06/06	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	not started
2025/06/06	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/06/06	TRAFFIC SERGEANT 141	Overhead Duct Insulation	no data
2025/06/06	TRAFFIC SERGEANT 141	Overhead Duct Rough In	no data
2025/06/06	TRAFFIC SERGEANT 141	Overhead Plumbing	no data
2025/06/06	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/06/06	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/06/06	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/06/06	TRIAGE/RECEPTION 134	In Wall Insulation	no data
2025/06/06	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/06/06	TRIAGE/RECEPTION 134	Overhead Duct Rough In	no data
2025/06/06	TRIAGE/RECEPTION 134	Overhead Plumbing	no data
2025/06/06	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/06/06	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/06/06	TRIAGE/RECEPTION 134	Wall Prime Paint	in progress
2025/06/06	TST WORKSHOP 187	In Wall Insulation	in progress
2025/06/06	TST WORKSHOP 187	Overhead Duct Insulation	no data
2025/06/06	TST WORKSHOP 187	Overhead Duct Rough In	no data
2025/06/06	TST WORKSHOP 187	Overhead Plumbing	no data
2025/06/06	TST WORKSHOP 187	Wall Drywall	in progress
2025/06/06	TST WORKSHOP 187	Wall Drywall Finish	not started
2025/06/06	TST WORKSHOP 187	Wall Prime Paint	not started
2025/06/06	UNISEX RESTROOM 169	In Wall Insulation	complete
2025/06/06	UNISEX RESTROOM 169	Overhead Duct Insulation	complete
2025/06/06	UNISEX RESTROOM 169	Overhead Duct Rough In	complete
2025/06/06	UNISEX RESTROOM 169	Overhead Plumbing	complete
2025/06/06	UNISEX RESTROOM 169	Wall Drywall	complete
2025/06/06	UNISEX RESTROOM 169	Wall Drywall Finish	not started
2025/06/06	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/06/06	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	no data
2025/06/06	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	

no data			
2025/06/06	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	
no data			
2025/06/06	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	
complete			
2025/06/06	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	in
progress			
2025/06/06	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	in
progress			
2025/06/06	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	in
progress			
2025/06/06	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	no data
2025/06/06	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	
no data			
2025/06/06	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	no
data			
2025/06/06	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	no data
2025/06/06	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/06/06	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	
complete			
2025/06/06	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/06/06	WAITING/LOBBY 100	In Wall Insulation	not started
2025/06/06	WAITING/LOBBY 100	Overhead Duct Insulation	no data
2025/06/06	WAITING/LOBBY 100	Overhead Duct Rough In	no data
2025/06/06	WAITING/LOBBY 100	Overhead Plumbing	not started
2025/06/06	WAITING/LOBBY 100	Wall Drywall	not started
2025/06/06	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/06/06	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/06/06	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/06/06	WOMENS RESTROOM 113	Overhead Duct Insulation	no
data			
2025/06/06	WOMENS RESTROOM 113	Overhead Duct Rough In	no data
2025/06/06	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/06/06	WOMENS RESTROOM 113	Wall Drywall	complete
2025/06/06	WOMENS RESTROOM 113	Wall Drywall Finish	in progress
2025/06/06	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/06/13	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/06/13	ADMIN ASSISTANT 125	Overhead Duct Insulation	no
data			
2025/06/13	ADMIN ASSISTANT 125	Overhead Duct Rough In	no data
2025/06/13	ADMIN ASSISTANT 125	Overhead Plumbing	not started
2025/06/13	ADMIN ASSISTANT 125	Wall Drywall	complete
2025/06/13	ADMIN ASSISTANT 125	Wall Drywall Finish	complete
2025/06/13	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/06/13	AV ROOM 103	In Wall Insulation	no data
2025/06/13	AV ROOM 103	Overhead Duct Insulation	no data
2025/06/13	AV ROOM 103	Overhead Duct Rough In	no data
2025/06/13	AV ROOM 103	Overhead Plumbing	no data
2025/06/13	AV ROOM 103	Wall Drywall	complete
2025/06/13	AV ROOM 103	Wall Drywall Finish	complete
2025/06/13	AV ROOM 103	Wall Prime Paint	complete
2025/06/13	BREAK ROOM CONFERENCE 182	In Wall Insulation	no
data			
2025/06/13	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	



no data

2025/06/13	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	no data
2025/06/13	BREAK ROOM CONFERENCE 182	Overhead Plumbing	no data
2025/06/13	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/06/13	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	in progress
2025/06/13	BREAK ROOM CONFERENCE 182	Wall Prime Paint	not started
2025/06/13	Background-159	In Wall Insulation	complete
2025/06/13	Background-159	Overhead Duct Insulation	not started
2025/06/13	Background-159	Overhead Duct Rough In	in progress
2025/06/13	Background-159	Overhead Plumbing	not started
2025/06/13	Background-159	Wall Drywall	complete
2025/06/13	Background-159	Wall Drywall Finish	in progress
2025/06/13	Background-159	Wall Prime Paint	not started
2025/06/13	CENTRAL BREAKROOM 145	In Wall Insulation	no data
2025/06/13	CENTRAL BREAKROOM 145	Overhead Duct Insulation	no data
2025/06/13	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/06/13	CENTRAL BREAKROOM 145	Overhead Plumbing	not started
2025/06/13	CENTRAL BREAKROOM 145	Wall Drywall	in progress
2025/06/13	CENTRAL BREAKROOM 145	Wall Drywall Finish	not started
2025/06/13	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/06/13	COLD CASE 175	In Wall Insulation	no data
2025/06/13	COLD CASE 175	Overhead Duct Insulation	no data
2025/06/13	COLD CASE 175	Overhead Duct Rough In	no data
2025/06/13	COLD CASE 175	Overhead Plumbing	no data
2025/06/13	COLD CASE 175	Wall Drywall	complete
2025/06/13	COLD CASE 175	Wall Drywall Finish	complete
2025/06/13	COLD CASE 175	Wall Prime Paint	in progress
2025/06/13	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/06/13	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	no data
2025/06/13	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	in progress
2025/06/13	COMMUNITY AFFAIRS 124	Overhead Plumbing	not started
2025/06/13	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/06/13	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/06/13	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/06/13	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/06/13	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	no data
2025/06/13	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	no data
2025/06/13	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	no data
2025/06/13	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete
2025/06/13	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	complete
2025/06/13	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	not

started  
 2025/06/13 | CONFERENCE ROOM 153 | In Wall Insulation | complete  
 2025/06/13 | CONFERENCE ROOM 153 | Overhead Duct Insulation | no  
 data  
 2025/06/13 | CONFERENCE ROOM 153 | Overhead Duct Rough In | no data  
 2025/06/13 | CONFERENCE ROOM 153 | Overhead Plumbing | not started  
 2025/06/13 | CONFERENCE ROOM 153 | Wall Drywall | complete  
 2025/06/13 | CONFERENCE ROOM 153 | Wall Drywall Finish | in progress  
 2025/06/13 | CONFERENCE ROOM 153 | Wall Prime Paint | not started  
 2025/06/13 | CONFERENCE/WAR ROOM 163 | In Wall Insulation | no data  
 2025/06/13 | CONFERENCE/WAR ROOM 163 | Overhead Duct Insulation | no  
 data  
 2025/06/13 | CONFERENCE/WAR ROOM 163 | Overhead Duct Rough In | no  
 data  
 2025/06/13 | CONFERENCE/WAR ROOM 163 | Overhead Plumbing | not  
 started  
 2025/06/13 | CONFERENCE/WAR ROOM 163 | Wall Drywall | complete  
 2025/06/13 | CONFERENCE/WAR ROOM 163 | Wall Drywall Finish |  
 complete  
 2025/06/13 | CONFERENCE/WAR ROOM 163 | Wall Prime Paint | complete  
 2025/06/13 | COPY 176 | In Wall Insulation | complete  
 2025/06/13 | COPY 176 | Overhead Duct Insulation | in progress  
 2025/06/13 | COPY 176 | Overhead Duct Rough In | in progress  
 2025/06/13 | COPY 176 | Overhead Plumbing | not started  
 2025/06/13 | COPY 176 | Wall Drywall | complete  
 2025/06/13 | COPY 176 | Wall Drywall Finish | complete  
 2025/06/13 | COPY 176 | Wall Prime Paint | complete  
 2025/06/13 | COPY/MAIL ROOM 114 | In Wall Insulation | complete  
 2025/06/13 | COPY/MAIL ROOM 114 | Overhead Duct Insulation | no data  
 2025/06/13 | COPY/MAIL ROOM 114 | Overhead Duct Rough In | no data  
 2025/06/13 | COPY/MAIL ROOM 114 | Overhead Plumbing | no data  
 2025/06/13 | COPY/MAIL ROOM 114 | Wall Drywall | complete  
 2025/06/13 | COPY/MAIL ROOM 114 | Wall Drywall Finish | complete  
 2025/06/13 | COPY/MAIL ROOM 114 | Wall Prime Paint | complete  
 2025/06/13 | CORRIDOR 107 | In Wall Insulation | complete  
 2025/06/13 | CORRIDOR 107 | Overhead Duct Insulation | in progress  
 2025/06/13 | CORRIDOR 107 | Overhead Duct Rough In | in progress  
 2025/06/13 | CORRIDOR 107 | Overhead Plumbing | in progress  
 2025/06/13 | CORRIDOR 107 | Wall Drywall | complete  
 2025/06/13 | CORRIDOR 107 | Wall Drywall Finish | complete  
 2025/06/13 | CORRIDOR 107 | Wall Prime Paint | in progress  
 2025/06/13 | CORRIDOR 108 | In Wall Insulation | complete  
 2025/06/13 | CORRIDOR 108 | In Wall Insulation | no data  
 2025/06/13 | CORRIDOR 108 | Overhead Duct Insulation | in progress  
 2025/06/13 | CORRIDOR 108 | Overhead Duct Insulation | no data  
 2025/06/13 | CORRIDOR 108 | Overhead Duct Rough In | in progress  
 2025/06/13 | CORRIDOR 108 | Overhead Duct Rough In | no data  
 2025/06/13 | CORRIDOR 108 | Overhead Plumbing | in progress  
 2025/06/13 | CORRIDOR 108 | Overhead Plumbing | no data  
 2025/06/13 | CORRIDOR 108 | Wall Drywall | complete  
 2025/06/13 | CORRIDOR 108 | Wall Drywall | complete  
 2025/06/13 | CORRIDOR 108 | Wall Drywall Finish | complete  
 2025/06/13 | CORRIDOR 108 | Wall Drywall Finish | complete  
 2025/06/13 | CORRIDOR 108 | Wall Prime Paint | in progress

2025/06/13	CORRIDOR 108	Wall Prime Paint   in progress
2025/06/13	CORRIDOR 109	In Wall Insulation   complete
2025/06/13	CORRIDOR 109	Overhead Duct Insulation   in progress
2025/06/13	CORRIDOR 109	Overhead Duct Rough In   in progress
2025/06/13	CORRIDOR 109	Overhead Plumbing   in progress
2025/06/13	CORRIDOR 109	Wall Drywall   complete
2025/06/13	CORRIDOR 109	Wall Drywall Finish   complete
2025/06/13	CORRIDOR 109	Wall Prime Paint   complete
2025/06/13	CORRIDOR 110	In Wall Insulation   no data
2025/06/13	CORRIDOR 110	In Wall Insulation   no data
2025/06/13	CORRIDOR 110	Overhead Duct Insulation   no data
2025/06/13	CORRIDOR 110	Overhead Duct Insulation   no data
2025/06/13	CORRIDOR 110	Overhead Duct Rough In   no data
2025/06/13	CORRIDOR 110	Overhead Duct Rough In   no data
2025/06/13	CORRIDOR 110	Overhead Plumbing   in progress
2025/06/13	CORRIDOR 110	Overhead Plumbing   in progress
2025/06/13	CORRIDOR 110	Wall Drywall   complete
2025/06/13	CORRIDOR 110	Wall Drywall   complete
2025/06/13	CORRIDOR 110	Wall Drywall Finish   in progress
2025/06/13	CORRIDOR 110	Wall Drywall Finish   complete
2025/06/13	CORRIDOR 110	Wall Prime Paint   in progress
2025/06/13	CORRIDOR 110	Wall Prime Paint   in progress
2025/06/13	CORRIDOR 181	In Wall Insulation   complete
2025/06/13	CORRIDOR 181	Overhead Duct Insulation   not started
2025/06/13	CORRIDOR 181	Overhead Duct Rough In   in progress
2025/06/13	CORRIDOR 181	Overhead Plumbing   in progress
2025/06/13	CORRIDOR 181	Wall Drywall   complete
2025/06/13	CORRIDOR 181	Wall Drywall Finish   in progress
2025/06/13	CORRIDOR 181	Wall Prime Paint   not started
2025/06/13	CORRIDOR144	In Wall Insulation   no data
2025/06/13	CORRIDOR144	Overhead Duct Insulation   no data
2025/06/13	CORRIDOR144	Overhead Duct Rough In   no data
2025/06/13	CORRIDOR144	Overhead Plumbing   in progress
2025/06/13	CORRIDOR144	Wall Drywall   complete
2025/06/13	CORRIDOR144	Wall Drywall Finish   complete
2025/06/13	CORRIDOR144	Wall Prime Paint   complete
2025/06/13	CPL 173	In Wall Insulation   complete
2025/06/13	CPL 173	Overhead Duct Insulation   no data
2025/06/13	CPL 173	Overhead Duct Rough In   no data
2025/06/13	CPL 173	Overhead Plumbing   no data
2025/06/13	CPL 173	Wall Drywall   complete
2025/06/13	CPL 173	Wall Drywall Finish   complete
2025/06/13	CPL 173	Wall Prime Paint   in progress
2025/06/13	CPL 174	In Wall Insulation   complete
2025/06/13	CPL 174	Overhead Duct Insulation   no data
2025/06/13	CPL 174	Overhead Duct Rough In   no data
2025/06/13	CPL 174	Overhead Plumbing   no data
2025/06/13	CPL 174	Wall Drywall   complete
2025/06/13	CPL 174	Wall Drywall Finish   complete
2025/06/13	CPL 174	Wall Prime Paint   in progress
2025/06/13	DRY STORAGE 146	In Wall Insulation   complete
2025/06/13	DRY STORAGE 146	Overhead Duct Insulation   no data
2025/06/13	DRY STORAGE 146	Overhead Duct Rough In   no data
2025/06/13	DRY STORAGE 146	Overhead Plumbing   no data

2025/06/13	DRY STORAGE 146	Wall Drywall	complete
2025/06/13	DRY STORAGE 146	Wall Drywall Finish	complete
2025/06/13	DRY STORAGE 146	Wall Prime Paint	not started
2025/06/13	FIRE RISER 178	In Wall Insulation	no data
2025/06/13	FIRE RISER 178	Overhead Duct Insulation	no data
2025/06/13	FIRE RISER 178	Overhead Duct Rough In	no data
2025/06/13	FIRE RISER 178	Overhead Plumbing	no data
2025/06/13	FIRE RISER 178	Wall Drywall	no data
2025/06/13	FIRE RISER 178	Wall Drywall Finish	no data
2025/06/13	FIRE RISER 178	Wall Prime Paint	no data
2025/06/13	GREETING ROOM 106	In Wall Insulation	no data
2025/06/13	GREETING ROOM 106	Overhead Duct Insulation	no data
2025/06/13	GREETING ROOM 106	Overhead Duct Rough In	no data
2025/06/13	GREETING ROOM 106	Overhead Plumbing	not started
2025/06/13	GREETING ROOM 106	Wall Drywall	complete
2025/06/13	GREETING ROOM 106	Wall Drywall Finish	complete
2025/06/13	GREETING ROOM 106	Wall Prime Paint	complete
2025/06/13	HR 149	In Wall Insulation	complete
2025/06/13	HR 149	Overhead Duct Insulation	not started
2025/06/13	HR 149	Overhead Duct Rough In	in progress
2025/06/13	HR 149	Overhead Plumbing	not started
2025/06/13	HR 149	Wall Drywall	complete
2025/06/13	HR 149	Wall Drywall Finish	not started
2025/06/13	HR 149	Wall Prime Paint	not started
2025/06/13	HR 150	In Wall Insulation	complete
2025/06/13	HR 150	Overhead Duct Insulation	no data
2025/06/13	HR 150	Overhead Duct Rough In	no data
2025/06/13	HR 150	Overhead Plumbing	no data
2025/06/13	HR 150	Wall Drywall	complete
2025/06/13	HR 150	Wall Drywall Finish	in progress
2025/06/13	HR 150	Wall Prime Paint	not started
2025/06/13	HR 151	In Wall Insulation	complete
2025/06/13	HR 151	Overhead Duct Insulation	not started
2025/06/13	HR 151	Overhead Duct Rough In	in progress
2025/06/13	HR 151	Overhead Plumbing	in progress
2025/06/13	HR 151	Wall Drywall	complete
2025/06/13	HR 151	Wall Drywall Finish	in progress
2025/06/13	HR 151	Wall Prime Paint	not started
2025/06/13	HR 154	In Wall Insulation	complete
2025/06/13	HR 154	Overhead Duct Insulation	not started
2025/06/13	HR 154	Overhead Duct Rough In	in progress
2025/06/13	HR 154	Overhead Plumbing	in progress
2025/06/13	HR 154	Wall Drywall	complete
2025/06/13	HR 154	Wall Drywall Finish	in progress
2025/06/13	HR 154	Wall Prime Paint	not started
2025/06/13	HR 155	In Wall Insulation	complete
2025/06/13	HR 155	Overhead Duct Insulation	in progress
2025/06/13	HR 155	Overhead Duct Rough In	in progress
2025/06/13	HR 155	Overhead Plumbing	not started
2025/06/13	HR 155	Wall Drywall	complete
2025/06/13	HR 155	Wall Drywall Finish	in progress
2025/06/13	HR 155	Wall Prime Paint	not started
2025/06/13	HR 156	In Wall Insulation	complete
2025/06/13	HR 156	Overhead Duct Insulation	not started

2025/06/13	HR 156	Overhead Duct Rough In	in progress
2025/06/13	HR 156	Overhead Plumbing	not started
2025/06/13	HR 156	Wall Drywall	complete
2025/06/13	HR 156	Wall Drywall Finish	in progress
2025/06/13	HR 156	Wall Prime Paint	not started
2025/06/13	HR 157	In Wall Insulation	complete
2025/06/13	HR 157	Overhead Duct Insulation	not started
2025/06/13	HR 157	Overhead Duct Rough In	in progress
2025/06/13	HR 157	Overhead Plumbing	in progress
2025/06/13	HR 157	Wall Drywall	complete
2025/06/13	HR 157	Wall Drywall Finish	in progress
2025/06/13	HR 157	Wall Prime Paint	not started
2025/06/13	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/06/13	HUMAN RESOURCES 148	Overhead Duct Insulation	not started
2025/06/13	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/06/13	HUMAN RESOURCES 148	Overhead Plumbing	in progress
2025/06/13	HUMAN RESOURCES 148	Wall Drywall	complete
2025/06/13	HUMAN RESOURCES 148	Wall Drywall Finish	in progress
2025/06/13	HUMAN RESOURCES 148	Wall Prime Paint	not started
2025/06/13	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/06/13	INTERNAL AFFAIRS 119	Overhead Duct Insulation	no data
2025/06/13	INTERNAL AFFAIRS 119	Overhead Duct Rough In	no data
2025/06/13	INTERNAL AFFAIRS 119	Overhead Plumbing	no data
2025/06/13	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/06/13	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/06/13	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/06/13	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/06/13	INTERNAL AFFAIRS 120	Overhead Duct Insulation	in progress
2025/06/13	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/06/13	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/06/13	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/06/13	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/06/13	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/06/13	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/06/13	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	no data
2025/06/13	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	no data
2025/06/13	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	no data
2025/06/13	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/06/13	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/06/13	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/06/13	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	complete
2025/06/13	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	

no data			
2025/06/13	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	
no data			
2025/06/13	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	no data
2025/06/13	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/06/13	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	complete
2025/06/13	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	complete
2025/06/13	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	no data
2025/06/13	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	no data
2025/06/13	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	no data
2025/06/13	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	no data
2025/06/13	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/06/13	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/06/13	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	complete
2025/06/13	IT 115	In Wall Insulation	complete
2025/06/13	IT 115	Overhead Duct Insulation	no data
2025/06/13	IT 115	Overhead Duct Rough In	no data
2025/06/13	IT 115	Overhead Plumbing	no data
2025/06/13	IT 115	Wall Drywall	complete
2025/06/13	IT 115	Wall Drywall Finish	complete
2025/06/13	IT 115	Wall Prime Paint	complete
2025/06/13	IT 135	In Wall Insulation	complete
2025/06/13	IT 135	Overhead Duct Insulation	in progress
2025/06/13	IT 135	Overhead Duct Rough In	in progress
2025/06/13	IT 135	Overhead Plumbing	in progress
2025/06/13	IT 135	Wall Drywall	complete
2025/06/13	IT 135	Wall Drywall Finish	complete
2025/06/13	IT 135	Wall Prime Paint	complete
2025/06/13	IT MANAGER 136	In Wall Insulation	no data
2025/06/13	IT MANAGER 136	Overhead Duct Insulation	no data
2025/06/13	IT MANAGER 136	Overhead Duct Rough In	no data
2025/06/13	IT MANAGER 136	Overhead Plumbing	no data
2025/06/13	IT MANAGER 136	Wall Drywall	complete
2025/06/13	IT MANAGER 136	Wall Drywall Finish	complete
2025/06/13	IT MANAGER 136	Wall Prime Paint	complete
2025/06/13	IT MANAGER 137	In Wall Insulation	no data
2025/06/13	IT MANAGER 137	Overhead Duct Insulation	no data
2025/06/13	IT MANAGER 137	Overhead Duct Rough In	no data
2025/06/13	IT MANAGER 137	Overhead Plumbing	no data
2025/06/13	IT MANAGER 137	Wall Drywall	complete
2025/06/13	IT MANAGER 137	Wall Drywall Finish	complete
2025/06/13	IT MANAGER 137	Wall Prime Paint	complete
2025/06/13	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/06/13	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data

data

2025/06/13	JUVENILE INTERVIEW 165	Overhead Duct Rough In	no data
2025/06/13	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/06/13	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/06/13	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/06/13	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/06/13	JUVENILLE INTERVIEWERS 166	In Wall Insulation	no data
2025/06/13	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	no data
2025/06/13	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	no data
2025/06/13	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	not started
2025/06/13	JUVENILLE INTERVIEWERS 166	Wall Drywall	complete
2025/06/13	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/06/13	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/06/13	KEY ROOM 185	In Wall Insulation	complete
2025/06/13	KEY ROOM 185	Overhead Duct Insulation	no data
2025/06/13	KEY ROOM 185	Overhead Duct Rough In	no data
2025/06/13	KEY ROOM 185	Overhead Plumbing	no data
2025/06/13	KEY ROOM 185	Wall Drywall	complete
2025/06/13	KEY ROOM 185	Wall Drywall Finish	in progress
2025/06/13	KEY ROOM 185	Wall Prime Paint	not started
2025/06/13	LT 170	In Wall Insulation	complete
2025/06/13	LT 170	Overhead Duct Insulation	in progress
2025/06/13	LT 170	Overhead Duct Rough In	in progress
2025/06/13	LT 170	Overhead Plumbing	not started
2025/06/13	LT 170	Wall Drywall	complete
2025/06/13	LT 170	Wall Drywall Finish	complete
2025/06/13	LT 170	Wall Prime Paint	complete
2025/06/13	MACHINE ROOM 191	In Wall Insulation	no data
2025/06/13	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/06/13	MACHINE ROOM 191	Overhead Duct Rough In	no data
2025/06/13	MACHINE ROOM 191	Overhead Plumbing	no data
2025/06/13	MACHINE ROOM 191	Wall Drywall	complete
2025/06/13	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/06/13	MACHINE ROOM 191	Wall Prime Paint	complete
2025/06/13	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/06/13	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/06/13	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/06/13	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/06/13	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/06/13	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/06/13	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/06/13	MAIN JANITORIAL111	In Wall Insulation	no data
2025/06/13	MAIN JANITORIAL111	Overhead Duct Insulation	no data
2025/06/13	MAIN JANITORIAL111	Overhead Duct Rough In	no data

2025/06/13	MAIN JANITORIAL111	Overhead Plumbing	no data
2025/06/13	MAIN JANITORIAL111	Wall Drywall	no data
2025/06/13	MAIN JANITORIAL111	Wall Drywall Finish	no data
2025/06/13	MAIN JANITORIAL111	Wall Prime Paint	no data
2025/06/13	MARINE SERGEANT 142	In Wall Insulation	complete
2025/06/13	MARINE SERGEANT 142	Overhead Duct Insulation	no data
2025/06/13	MARINE SERGEANT 142	Overhead Duct Rough In	no data
2025/06/13	MARINE SERGEANT 142	Overhead Plumbing	no data
2025/06/13	MARINE SERGEANT 142	Wall Drywall	complete
2025/06/13	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/06/13	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/06/13	MECHANICAL 192	In Wall Insulation	no data
2025/06/13	MECHANICAL 192	Overhead Duct Insulation	no data
2025/06/13	MECHANICAL 192	Overhead Duct Rough In	no data
2025/06/13	MECHANICAL 192	Overhead Plumbing	no data
2025/06/13	MECHANICAL 192	Wall Drywall	no data
2025/06/13	MECHANICAL 192	Wall Drywall Finish	no data
2025/06/13	MECHANICAL 192	Wall Prime Paint	no data
2025/06/13	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/06/13	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
2025/06/13	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/06/13	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/06/13	MECHANICAL ROOM 122	Wall Drywall	no data
2025/06/13	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/06/13	MECHANICAL ROOM 122	Wall Prime Paint	complete
2025/06/13	MENS RESTROOM 112	In Wall Insulation	no data
2025/06/13	MENS RESTROOM 112	Overhead Duct Insulation	no data
2025/06/13	MENS RESTROOM 112	Overhead Duct Rough In	in progress
2025/06/13	MENS RESTROOM 112	Overhead Plumbing	no data
2025/06/13	MENS RESTROOM 112	Wall Drywall	complete
2025/06/13	MENS RESTROOM 112	Wall Drywall Finish	in progress
2025/06/13	MENS RESTROOM 112	Wall Prime Paint	not started
2025/06/13	MIS EQUIPMENT STORAGE 138	In Wall Insulation	complete
2025/06/13	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/06/13	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	in progress
2025/06/13	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	in progress
2025/06/13	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/06/13	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/06/13	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/06/13	MIS SHREDDING 117	In Wall Insulation	complete
2025/06/13	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/06/13	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/06/13	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/06/13	MIS SHREDDING 117	Wall Drywall	complete



2025/06/13	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/06/13	MIS SHREDDING 117	Wall Prime Paint	complete
2025/06/13	OFFICE 128	In Wall Insulation	no data
2025/06/13	OFFICE 128	Overhead Duct Insulation	no data
2025/06/13	OFFICE 128	Overhead Duct Rough In	no data
2025/06/13	OFFICE 128	Overhead Plumbing	not started
2025/06/13	OFFICE 128	Wall Drywall	complete
2025/06/13	OFFICE 128	Wall Drywall Finish	complete
2025/06/13	OFFICE 128	Wall Prime Paint	complete
2025/06/13	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	no data
2025/06/13	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	no data
2025/06/13	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	no data
2025/06/13	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	no data
2025/06/13	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/06/13	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/06/13	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	in progress
2025/06/13	PARTS STORAGE 189	In Wall Insulation	no data
2025/06/13	PARTS STORAGE 189	Overhead Duct Insulation	no data
2025/06/13	PARTS STORAGE 189	Overhead Duct Rough In	no data
2025/06/13	PARTS STORAGE 189	Overhead Plumbing	no data
2025/06/13	PARTS STORAGE 189	Wall Drywall	in progress
2025/06/13	PARTS STORAGE 189	Wall Drywall Finish	in progress
2025/06/13	PARTS STORAGE 189	Wall Prime Paint	not started
2025/06/13	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/06/13	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/06/13	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/06/13	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/06/13	PUBLIC RESTROOM 106	Wall Drywall	no data
2025/06/13	PUBLIC RESTROOM 106	Wall Drywall Finish	no data
2025/06/13	PUBLIC RESTROOM 106	Wall Prime Paint	no data
2025/06/13	Polygraph 152	In Wall Insulation	complete
2025/06/13	Polygraph 152	Overhead Duct Insulation	not started
2025/06/13	Polygraph 152	Overhead Duct Rough In	in progress
2025/06/13	Polygraph 152	Overhead Plumbing	not started
2025/06/13	Polygraph 152	Wall Drywall	complete
2025/06/13	Polygraph 152	Wall Drywall Finish	in progress
2025/06/13	Polygraph 152	Wall Prime Paint	not started
2025/06/13	RECEPTION 101	In Wall Insulation	not started
2025/06/13	RECEPTION 101	Overhead Duct Insulation	no data
2025/06/13	RECEPTION 101	Overhead Duct Rough In	no data
2025/06/13	RECEPTION 101	Overhead Plumbing	not started
2025/06/13	RECEPTION 101	Wall Drywall	not started
2025/06/13	RECEPTION 101	Wall Drywall Finish	not started
2025/06/13	RECEPTION 101	Wall Prime Paint	not started
2025/06/13	RECEPTION 147	In Wall Insulation	no data
2025/06/13	RECEPTION 147	Overhead Duct Insulation	no data

2025/06/13	RECEPTION 147	Overhead Duct Rough In	no data
2025/06/13	RECEPTION 147	Overhead Plumbing	in progress
2025/06/13	RECEPTION 147	Wall Drywall	complete
2025/06/13	RECEPTION 147	Wall Drywall Finish	in progress
2025/06/13	RECEPTION 147	Wall Prime Paint	not started
2025/06/13	RECEPTION 179	In Wall Insulation	in progress
2025/06/13	RECEPTION 179	Overhead Duct Insulation	not started
2025/06/13	RECEPTION 179	Overhead Duct Rough In	no data
2025/06/13	RECEPTION 179	Overhead Plumbing	not started
2025/06/13	RECEPTION 179	Wall Drywall	in progress
2025/06/13	RECEPTION 179	Wall Drywall Finish	in progress
2025/06/13	RECEPTION 179	Wall Prime Paint	not started
2025/06/13	RECORDS 130	In Wall Insulation	no data
2025/06/13	RECORDS 130	Overhead Duct Insulation	no data
2025/06/13	RECORDS 130	Overhead Duct Rough In	no data
2025/06/13	RECORDS 130	Overhead Plumbing	no data
2025/06/13	RECORDS 130	Wall Drywall	complete
2025/06/13	RECORDS 130	Wall Drywall Finish	complete
2025/06/13	RECORDS 130	Wall Prime Paint	complete
2025/06/13	RECORDS STORAGE 133	In Wall Insulation	complete
2025/06/13	RECORDS STORAGE 133	Overhead Duct Insulation	in progress
2025/06/13	RECORDS STORAGE 133	Overhead Duct Rough In	in progress
2025/06/13	RECORDS STORAGE 133	Overhead Plumbing	not started
2025/06/13	RECORDS STORAGE 133	Wall Drywall	complete
2025/06/13	RECORDS STORAGE 133	Wall Drywall Finish	complete
2025/06/13	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/06/13	RECORDS SUPERVISOR 131	In Wall Insulation	no data
2025/06/13	RECORDS SUPERVISOR 131	Overhead Duct Insulation	no data
2025/06/13	RECORDS SUPERVISOR 131	Overhead Duct Rough In	no data
2025/06/13	RECORDS SUPERVISOR 131	Overhead Plumbing	no data
2025/06/13	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/06/13	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/06/13	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/06/13	RECORDS SUPERVISOR 132	In Wall Insulation	no data
2025/06/13	RECORDS SUPERVISOR 132	Overhead Duct Insulation	no data
2025/06/13	RECORDS SUPERVISOR 132	Overhead Duct Rough In	no data
2025/06/13	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/06/13	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/06/13	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/06/13	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/06/13	RESTROOM 183	In Wall Insulation	in progress
2025/06/13	RESTROOM 183	Overhead Duct Insulation	in progress
2025/06/13	RESTROOM 183	Overhead Duct Rough In	in progress
2025/06/13	RESTROOM 183	Overhead Plumbing	complete
2025/06/13	RESTROOM 183	Wall Drywall	in progress
2025/06/13	RESTROOM 183	Wall Drywall Finish	not started
2025/06/13	RESTROOM 183	Wall Prime Paint	not started
2025/06/13	Risk Management - 158	In Wall Insulation	complete

2025/06/13	Risk Management - 158	Overhead Duct Insulation	not started
2025/06/13	Risk Management - 158	Overhead Duct Rough In	in progress
2025/06/13	Risk Management - 158	Overhead Plumbing	in progress
2025/06/13	Risk Management - 158	Wall Drywall	complete
2025/06/13	Risk Management - 158	Wall Drywall Finish	in progress
2025/06/13	Risk Management - 158	Wall Prime Paint	not started
2025/06/13	SALLY PORT 105	In Wall Insulation	not started
2025/06/13	SALLY PORT 105	Overhead Duct Insulation	no data
2025/06/13	SALLY PORT 105	Overhead Duct Rough In	no data
2025/06/13	SALLY PORT 105	Overhead Plumbing	no data
2025/06/13	SALLY PORT 105	Wall Drywall	not started
2025/06/13	SALLY PORT 105	Wall Drywall Finish	not started
2025/06/13	SALLY PORT 105	Wall Prime Paint	not started
2025/06/13	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/06/13	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/06/13	SANE EXAM ROOM 168	Overhead Duct Rough In	no data
2025/06/13	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/06/13	SANE EXAM ROOM 168	Wall Drywall	complete
2025/06/13	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/06/13	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/06/13	SGT 171	In Wall Insulation	no data
2025/06/13	SGT 171	Overhead Duct Insulation	no data
2025/06/13	SGT 171	Overhead Duct Rough In	no data
2025/06/13	SGT 171	Overhead Plumbing	no data
2025/06/13	SGT 171	Wall Drywall	complete
2025/06/13	SGT 171	Wall Drywall Finish	complete
2025/06/13	SGT 171	Wall Prime Paint	complete
2025/06/13	SGT 172	In Wall Insulation	complete
2025/06/13	SGT 172	Overhead Duct Insulation	no data
2025/06/13	SGT 172	Overhead Duct Rough In	no data
2025/06/13	SGT 172	Overhead Plumbing	no data
2025/06/13	SGT 172	Wall Drywall	complete
2025/06/13	SGT 172	Wall Drywall Finish	complete
2025/06/13	SGT 172	Wall Prime Paint	complete
2025/06/13	SHIPPING STORAGE 190	In Wall Insulation	in progress
2025/06/13	SHIPPING STORAGE 190	Overhead Duct Insulation	no data
2025/06/13	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/06/13	SHIPPING STORAGE 190	Overhead Plumbing	no data
2025/06/13	SHIPPING STORAGE 190	Wall Drywall	in progress
2025/06/13	SHIPPING STORAGE 190	Wall Drywall Finish	not started
2025/06/13	SHIPPING STORAGE 190	Wall Prime Paint	not started
2025/06/13	SHOP FORMAN 184	In Wall Insulation	complete
2025/06/13	SHOP FORMAN 184	Overhead Duct Insulation	no data
2025/06/13	SHOP FORMAN 184	Overhead Duct Rough In	no data
2025/06/13	SHOP FORMAN 184	Overhead Plumbing	no data
2025/06/13	SHOP FORMAN 184	Wall Drywall	in progress
2025/06/13	SHOP FORMAN 184	Wall Drywall Finish	not started
2025/06/13	SHOP FORMAN 184	Wall Prime Paint	not started
2025/06/13	SOFT INTERVIEW 161	In Wall Insulation	complete

2025/06/13	SOFT INTERVIEW 161	Overhead Duct Insulation	no data
2025/06/13	SOFT INTERVIEW 161	Overhead Duct Rough In	in progress
2025/06/13	SOFT INTERVIEW 161	Overhead Plumbing	complete
2025/06/13	SOFT INTERVIEW 161	Wall Drywall	complete
2025/06/13	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/06/13	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/06/13	SOFT INTERVIEW 162	In Wall Insulation	complete
2025/06/13	SOFT INTERVIEW 162	Overhead Duct Insulation	no data
2025/06/13	SOFT INTERVIEW 162	Overhead Duct Rough In	no data
2025/06/13	SOFT INTERVIEW 162	Overhead Plumbing	no data
2025/06/13	SOFT INTERVIEW 162	Wall Drywall	complete
2025/06/13	SOFT INTERVIEW 162	Wall Drywall Finish	complete
2025/06/13	SOFT INTERVIEW 162	Wall Prime Paint	complete
2025/06/13	SPECIAL OPERATION LT 143	In Wall Insulation	complete
2025/06/13	SPECIAL OPERATION LT 143	Overhead Duct Insulation	no data
2025/06/13	SPECIAL OPERATION LT 143	Overhead Duct Rough In	no data
2025/06/13	SPECIAL OPERATION LT 143	Overhead Plumbing	in progress
2025/06/13	SPECIAL OPERATION LT 143	Wall Drywall	complete
2025/06/13	SPECIAL OPERATION LT 143	Wall Drywall Finish	complete
2025/06/13	SPECIAL OPERATION LT 143	Wall Prime Paint	complete
2025/06/13	STAIR A	In Wall Insulation	not started
2025/06/13	STAIR A	Overhead Duct Insulation	no data
2025/06/13	STAIR A	Overhead Duct Rough In	no data
2025/06/13	STAIR A	Overhead Plumbing	no data
2025/06/13	STAIR A	Wall Drywall	not started
2025/06/13	STAIR A	Wall Drywall Finish	not started
2025/06/13	STAIR A	Wall Prime Paint	not started
2025/06/13	STORAGE 104	In Wall Insulation	no data
2025/06/13	STORAGE 104	Overhead Duct Insulation	no data
2025/06/13	STORAGE 104	Overhead Duct Rough In	no data
2025/06/13	STORAGE 104	Overhead Plumbing	not started
2025/06/13	STORAGE 104	Wall Drywall	complete
2025/06/13	STORAGE 104	Wall Drywall Finish	complete
2025/06/13	STORAGE 104	Wall Prime Paint	in progress
2025/06/13	STORAGE 127	In Wall Insulation	no data
2025/06/13	STORAGE 127	Overhead Duct Insulation	no data
2025/06/13	STORAGE 127	Overhead Duct Rough In	no data
2025/06/13	STORAGE 127	Overhead Plumbing	not started
2025/06/13	STORAGE 127	Wall Drywall	complete
2025/06/13	STORAGE 127	Wall Drywall Finish	complete
2025/06/13	STORAGE 127	Wall Prime Paint	complete
2025/06/13	STUDIO 126	In Wall Insulation	complete
2025/06/13	STUDIO 126	Overhead Duct Insulation	in progress
2025/06/13	STUDIO 126	Overhead Duct Rough In	in progress
2025/06/13	STUDIO 126	Overhead Plumbing	not started
2025/06/13	STUDIO 126	Wall Drywall	complete
2025/06/13	STUDIO 126	Wall Drywall Finish	complete
2025/06/13	STUDIO 126	Wall Prime Paint	in progress

2025/06/13	SUPERVISOR 129	In Wall Insulation	complete
2025/06/13	SUPERVISOR 129	Overhead Duct Insulation	in progress
2025/06/13	SUPERVISOR 129	Overhead Duct Rough In	in progress
2025/06/13	SUPERVISOR 129	Overhead Plumbing	not started
2025/06/13	SUPERVISOR 129	Wall Drywall	complete
2025/06/13	SUPERVISOR 129	Wall Drywall Finish	complete
2025/06/13	SUPERVISOR 129	Wall Prime Paint	complete
2025/06/13	Storage 164	In Wall Insulation	complete
2025/06/13	Storage 164	Overhead Duct Insulation	in progress
2025/06/13	Storage 164	Overhead Duct Rough In	in progress
2025/06/13	Storage 164	Overhead Plumbing	not started
2025/06/13	Storage 164	Wall Drywall	complete
2025/06/13	Storage 164	Wall Drywall Finish	complete
2025/06/13	Storage 164	Wall Prime Paint	complete
2025/06/13	Storage 177	In Wall Insulation	complete
2025/06/13	Storage 177	Overhead Duct Insulation	in progress
2025/06/13	Storage 177	Overhead Duct Rough In	in progress
2025/06/13	Storage 177	Overhead Plumbing	not started
2025/06/13	Storage 177	Wall Drywall	complete
2025/06/13	Storage 177	Wall Drywall Finish	complete
2025/06/13	Storage 177	Wall Prime Paint	complete
2025/06/13	TECHNICAL SURVEILLANCE 188	In Wall Insulation	no data
2025/06/13	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	not started
2025/06/13	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	no data
2025/06/13	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	not started
2025/06/13	TECHNICAL SURVEILLANCE 188	Wall Drywall	in progress
2025/06/13	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	in progress
2025/06/13	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	not started
2025/06/13	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/06/13	TRAFFIC SERGEANT 141	Overhead Duct Insulation	no data
2025/06/13	TRAFFIC SERGEANT 141	Overhead Duct Rough In	no data
2025/06/13	TRAFFIC SERGEANT 141	Overhead Plumbing	no data
2025/06/13	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/06/13	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/06/13	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/06/13	TRIAGE/RECEPTION 134	In Wall Insulation	no data
2025/06/13	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/06/13	TRIAGE/RECEPTION 134	Overhead Duct Rough In	no data
2025/06/13	TRIAGE/RECEPTION 134	Overhead Plumbing	not started
2025/06/13	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/06/13	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/06/13	TRIAGE/RECEPTION 134	Wall Prime Paint	in progress
2025/06/13	TST WORKSHOP 187	In Wall Insulation	in progress
2025/06/13	TST WORKSHOP 187	Overhead Duct Insulation	no data
2025/06/13	TST WORKSHOP 187	Overhead Duct Rough In	no data
2025/06/13	TST WORKSHOP 187	Overhead Plumbing	no data

2025/06/13	TST WORKSHOP 187	Wall Drywall	in progress
2025/06/13	TST WORKSHOP 187	Wall Drywall Finish	in progress
2025/06/13	TST WORKSHOP 187	Wall Prime Paint	in progress
2025/06/13	UNISEX RESTROOM 169	In Wall Insulation	complete
2025/06/13	UNISEX RESTROOM 169	Overhead Duct Insulation	complete
2025/06/13	UNISEX RESTROOM 169	Overhead Duct Rough In	complete
2025/06/13	UNISEX RESTROOM 169	Overhead Plumbing	complete
2025/06/13	UNISEX RESTROOM 169	Wall Drywall	complete
2025/06/13	UNISEX RESTROOM 169	Wall Drywall Finish	in progress
2025/06/13	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/06/13	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	no data
2025/06/13	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	not started
2025/06/13	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	no data
2025/06/13	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete
2025/06/13	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	in progress
2025/06/13	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	in progress
2025/06/13	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	in progress
2025/06/13	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	no data
2025/06/13	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	no data
2025/06/13	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	no data
2025/06/13	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	no data
2025/06/13	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/06/13	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/06/13	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/06/13	WAITING/LOBBY 100	In Wall Insulation	not started
2025/06/13	WAITING/LOBBY 100	Overhead Duct Insulation	no data
2025/06/13	WAITING/LOBBY 100	Overhead Duct Rough In	no data
2025/06/13	WAITING/LOBBY 100	Overhead Plumbing	not started
2025/06/13	WAITING/LOBBY 100	Wall Drywall	not started
2025/06/13	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/06/13	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/06/13	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/06/13	WOMENS RESTROOM 113	Overhead Duct Insulation	no data
2025/06/13	WOMENS RESTROOM 113	Overhead Duct Rough In	no data
2025/06/13	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/06/13	WOMENS RESTROOM 113	Wall Drywall	complete
2025/06/13	WOMENS RESTROOM 113	Wall Drywall Finish	in progress
2025/06/13	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/06/20	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/06/20	ADMIN ASSISTANT 125	Overhead Duct Insulation	no data
2025/06/20	ADMIN ASSISTANT 125	Overhead Duct Rough In	no data

2025/06/20	ADMIN ASSISTANT 125	Overhead Plumbing	not started
2025/06/20	ADMIN ASSISTANT 125	Wall Drywall	complete
2025/06/20	ADMIN ASSISTANT 125	Wall Drywall Finish	complete
2025/06/20	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/06/20	AV ROOM 103	In Wall Insulation	no data
2025/06/20	AV ROOM 103	Overhead Duct Insulation	no data
2025/06/20	AV ROOM 103	Overhead Duct Rough In	no data
2025/06/20	AV ROOM 103	Overhead Plumbing	no data
2025/06/20	AV ROOM 103	Wall Drywall	complete
2025/06/20	AV ROOM 103	Wall Drywall Finish	complete
2025/06/20	AV ROOM 103	Wall Prime Paint	complete
2025/06/20	BREAK ROOM CONFERENCE 182	In Wall Insulation	no data
2025/06/20	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	no data
2025/06/20	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	no data
2025/06/20	BREAK ROOM CONFERENCE 182	Overhead Plumbing	no data
2025/06/20	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/06/20	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	complete
2025/06/20	BREAK ROOM CONFERENCE 182	Wall Prime Paint	not started
2025/06/20	Background-159	In Wall Insulation	complete
2025/06/20	Background-159	Overhead Duct Insulation	not started
2025/06/20	Background-159	Overhead Duct Rough In	in progress
2025/06/20	Background-159	Overhead Plumbing	not started
2025/06/20	Background-159	Wall Drywall	complete
2025/06/20	Background-159	Wall Drywall Finish	in progress
2025/06/20	Background-159	Wall Prime Paint	not started
2025/06/20	CENTRAL BREAKROOM 145	In Wall Insulation	no data
2025/06/20	CENTRAL BREAKROOM 145	Overhead Duct Insulation	in progress
2025/06/20	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/06/20	CENTRAL BREAKROOM 145	Overhead Plumbing	not started
2025/06/20	CENTRAL BREAKROOM 145	Wall Drywall	in progress
2025/06/20	CENTRAL BREAKROOM 145	Wall Drywall Finish	in progress
2025/06/20	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/06/20	COLD CASE 175	In Wall Insulation	no data
2025/06/20	COLD CASE 175	Overhead Duct Insulation	no data
2025/06/20	COLD CASE 175	Overhead Duct Rough In	no data
2025/06/20	COLD CASE 175	Overhead Plumbing	no data
2025/06/20	COLD CASE 175	Wall Drywall	complete
2025/06/20	COLD CASE 175	Wall Drywall Finish	complete
2025/06/20	COLD CASE 175	Wall Prime Paint	in progress
2025/06/20	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/06/20	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	in progress
2025/06/20	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	no data
2025/06/20	COMMUNITY AFFAIRS 124	Overhead Plumbing	no data
2025/06/20	COMMUNITY AFFAIRS 124	Wall Drywall	complete

2025/06/20	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/06/20	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/06/20	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/06/20	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	no data
2025/06/20	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	no data
2025/06/20	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	no data
2025/06/20	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete
2025/06/20	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	complete
2025/06/20	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	not started
2025/06/20	CONFERENCE ROOM 153	In Wall Insulation	complete
2025/06/20	CONFERENCE ROOM 153	Overhead Duct Insulation	no data
2025/06/20	CONFERENCE ROOM 153	Overhead Duct Rough In	no data
2025/06/20	CONFERENCE ROOM 153	Overhead Plumbing	not started
2025/06/20	CONFERENCE ROOM 153	Wall Drywall	complete
2025/06/20	CONFERENCE ROOM 153	Wall Drywall Finish	complete
2025/06/20	CONFERENCE ROOM 153	Wall Prime Paint	not started
2025/06/20	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/06/20	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	in progress
2025/06/20	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	no data
2025/06/20	CONFERENCE/WAR ROOM 163	Overhead Plumbing	not started
2025/06/20	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/06/20	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete
2025/06/20	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/06/20	COPY 176	In Wall Insulation	complete
2025/06/20	COPY 176	Overhead Duct Insulation	complete
2025/06/20	COPY 176	Overhead Duct Rough In	in progress
2025/06/20	COPY 176	Overhead Plumbing	not started
2025/06/20	COPY 176	Wall Drywall	complete
2025/06/20	COPY 176	Wall Drywall Finish	complete
2025/06/20	COPY 176	Wall Prime Paint	complete
2025/06/20	COPY/MAIL ROOM 114	In Wall Insulation	complete
2025/06/20	COPY/MAIL ROOM 114	Overhead Duct Insulation	no data
2025/06/20	COPY/MAIL ROOM 114	Overhead Duct Rough In	no data
2025/06/20	COPY/MAIL ROOM 114	Overhead Plumbing	in progress
2025/06/20	COPY/MAIL ROOM 114	Wall Drywall	complete
2025/06/20	COPY/MAIL ROOM 114	Wall Drywall Finish	complete
2025/06/20	COPY/MAIL ROOM 114	Wall Prime Paint	complete
2025/06/20	CORRIDOR 107	In Wall Insulation	complete
2025/06/20	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/06/20	CORRIDOR 107	Overhead Duct Rough In	in progress
2025/06/20	CORRIDOR 107	Overhead Plumbing	in progress
2025/06/20	CORRIDOR 107	Wall Drywall	complete
2025/06/20	CORRIDOR 107	Wall Drywall Finish	complete



2025/06/20	CORRIDOR 107	Wall Prime Paint   in progress
2025/06/20	CORRIDOR 108	In Wall Insulation   complete
2025/06/20	CORRIDOR 108	In Wall Insulation   no data
2025/06/20	CORRIDOR 108	Overhead Duct Insulation   in progress
2025/06/20	CORRIDOR 108	Overhead Duct Insulation   no data
2025/06/20	CORRIDOR 108	Overhead Duct Rough In   in progress
2025/06/20	CORRIDOR 108	Overhead Duct Rough In   no data
2025/06/20	CORRIDOR 108	Overhead Plumbing   in progress
2025/06/20	CORRIDOR 108	Overhead Plumbing   in progress
2025/06/20	CORRIDOR 108	Wall Drywall   complete
2025/06/20	CORRIDOR 108	Wall Drywall   complete
2025/06/20	CORRIDOR 108	Wall Drywall Finish   complete
2025/06/20	CORRIDOR 108	Wall Drywall Finish   complete
2025/06/20	CORRIDOR 108	Wall Prime Paint   in progress
2025/06/20	CORRIDOR 108	Wall Prime Paint   in progress
2025/06/20	CORRIDOR 109	In Wall Insulation   complete
2025/06/20	CORRIDOR 109	Overhead Duct Insulation   in progress
2025/06/20	CORRIDOR 109	Overhead Duct Rough In   in progress
2025/06/20	CORRIDOR 109	Overhead Plumbing   in progress
2025/06/20	CORRIDOR 109	Wall Drywall   complete
2025/06/20	CORRIDOR 109	Wall Drywall Finish   complete
2025/06/20	CORRIDOR 109	Wall Prime Paint   complete
2025/06/20	CORRIDOR 110	In Wall Insulation   no data
2025/06/20	CORRIDOR 110	In Wall Insulation   no data
2025/06/20	CORRIDOR 110	Overhead Duct Insulation   no data
2025/06/20	CORRIDOR 110	Overhead Duct Insulation   no data
2025/06/20	CORRIDOR 110	Overhead Duct Rough In   no data
2025/06/20	CORRIDOR 110	Overhead Duct Rough In   no data
2025/06/20	CORRIDOR 110	Overhead Plumbing   in progress
2025/06/20	CORRIDOR 110	Overhead Plumbing   in progress
2025/06/20	CORRIDOR 110	Wall Drywall   complete
2025/06/20	CORRIDOR 110	Wall Drywall   complete
2025/06/20	CORRIDOR 110	Wall Drywall Finish   complete
2025/06/20	CORRIDOR 110	Wall Drywall Finish   complete
2025/06/20	CORRIDOR 110	Wall Prime Paint   in progress
2025/06/20	CORRIDOR 110	Wall Prime Paint   in progress
2025/06/20	CORRIDOR 181	In Wall Insulation   complete
2025/06/20	CORRIDOR 181	Overhead Duct Insulation   not started
2025/06/20	CORRIDOR 181	Overhead Duct Rough In   in progress
2025/06/20	CORRIDOR 181	Overhead Plumbing   in progress
2025/06/20	CORRIDOR 181	Wall Drywall   complete
2025/06/20	CORRIDOR 181	Wall Drywall Finish   complete
2025/06/20	CORRIDOR 181	Wall Prime Paint   not started
2025/06/20	CORRIDOR144	In Wall Insulation   no data
2025/06/20	CORRIDOR144	Overhead Duct Insulation   no data
2025/06/20	CORRIDOR144	Overhead Duct Rough In   no data
2025/06/20	CORRIDOR144	Overhead Plumbing   in progress
2025/06/20	CORRIDOR144	Wall Drywall   complete
2025/06/20	CORRIDOR144	Wall Drywall Finish   complete
2025/06/20	CORRIDOR144	Wall Prime Paint   complete
2025/06/20	CPL 173	In Wall Insulation   complete
2025/06/20	CPL 173	Overhead Duct Insulation   no data
2025/06/20	CPL 173	Overhead Duct Rough In   no data
2025/06/20	CPL 173	Overhead Plumbing   no data

2025/06/20	CPL 173	Wall Drywall	complete
2025/06/20	CPL 173	Wall Drywall Finish	complete
2025/06/20	CPL 173	Wall Prime Paint	in progress
2025/06/20	CPL 174	In Wall Insulation	complete
2025/06/20	CPL 174	Overhead Duct Insulation	no data
2025/06/20	CPL 174	Overhead Duct Rough In	no data
2025/06/20	CPL 174	Overhead Plumbing	no data
2025/06/20	CPL 174	Wall Drywall	complete
2025/06/20	CPL 174	Wall Drywall Finish	complete
2025/06/20	CPL 174	Wall Prime Paint	in progress
2025/06/20	DRY STORAGE 146	In Wall Insulation	complete
2025/06/20	DRY STORAGE 146	Overhead Duct Insulation	no data
2025/06/20	DRY STORAGE 146	Overhead Duct Rough In	no data
2025/06/20	DRY STORAGE 146	Overhead Plumbing	no data
2025/06/20	DRY STORAGE 146	Wall Drywall	complete
2025/06/20	DRY STORAGE 146	Wall Drywall Finish	complete
2025/06/20	DRY STORAGE 146	Wall Prime Paint	not started
2025/06/20	FIRE RISER 178	In Wall Insulation	no data
2025/06/20	FIRE RISER 178	Overhead Duct Insulation	no data
2025/06/20	FIRE RISER 178	Overhead Duct Rough In	no data
2025/06/20	FIRE RISER 178	Overhead Plumbing	no data
2025/06/20	FIRE RISER 178	Wall Drywall	no data
2025/06/20	FIRE RISER 178	Wall Drywall Finish	no data
2025/06/20	FIRE RISER 178	Wall Prime Paint	no data
2025/06/20	GREETING ROOM 106	In Wall Insulation	no data
2025/06/20	GREETING ROOM 106	Overhead Duct Insulation	no data
2025/06/20	GREETING ROOM 106	Overhead Duct Rough In	no data
2025/06/20	GREETING ROOM 106	Overhead Plumbing	not started
2025/06/20	GREETING ROOM 106	Wall Drywall	complete
2025/06/20	GREETING ROOM 106	Wall Drywall Finish	complete
2025/06/20	GREETING ROOM 106	Wall Prime Paint	complete
2025/06/20	HR 149	In Wall Insulation	complete
2025/06/20	HR 149	Overhead Duct Insulation	not started
2025/06/20	HR 149	Overhead Duct Rough In	in progress
2025/06/20	HR 149	Overhead Plumbing	not started
2025/06/20	HR 149	Wall Drywall	complete
2025/06/20	HR 149	Wall Drywall Finish	in progress
2025/06/20	HR 149	Wall Prime Paint	not started
2025/06/20	HR 150	In Wall Insulation	complete
2025/06/20	HR 150	Overhead Duct Insulation	not started
2025/06/20	HR 150	Overhead Duct Rough In	no data
2025/06/20	HR 150	Overhead Plumbing	no data
2025/06/20	HR 150	Wall Drywall	complete
2025/06/20	HR 150	Wall Drywall Finish	in progress
2025/06/20	HR 150	Wall Prime Paint	not started
2025/06/20	HR 151	In Wall Insulation	complete
2025/06/20	HR 151	Overhead Duct Insulation	in progress
2025/06/20	HR 151	Overhead Duct Rough In	in progress
2025/06/20	HR 151	Overhead Plumbing	in progress
2025/06/20	HR 151	Wall Drywall	complete
2025/06/20	HR 151	Wall Drywall Finish	in progress
2025/06/20	HR 151	Wall Prime Paint	not started
2025/06/20	HR 154	In Wall Insulation	complete
2025/06/20	HR 154	Overhead Duct Insulation	not started

2025/06/20	HR 154	Overhead Duct Rough In	in progress
2025/06/20	HR 154	Overhead Plumbing	in progress
2025/06/20	HR 154	Wall Drywall	complete
2025/06/20	HR 154	Wall Drywall Finish	in progress
2025/06/20	HR 154	Wall Prime Paint	not started
2025/06/20	HR 155	In Wall Insulation	complete
2025/06/20	HR 155	Overhead Duct Insulation	in progress
2025/06/20	HR 155	Overhead Duct Rough In	in progress
2025/06/20	HR 155	Overhead Plumbing	not started
2025/06/20	HR 155	Wall Drywall	complete
2025/06/20	HR 155	Wall Drywall Finish	in progress
2025/06/20	HR 155	Wall Prime Paint	not started
2025/06/20	HR 156	In Wall Insulation	complete
2025/06/20	HR 156	Overhead Duct Insulation	complete
2025/06/20	HR 156	Overhead Duct Rough In	in progress
2025/06/20	HR 156	Overhead Plumbing	not started
2025/06/20	HR 156	Wall Drywall	complete
2025/06/20	HR 156	Wall Drywall Finish	complete
2025/06/20	HR 156	Wall Prime Paint	not started
2025/06/20	HR 157	In Wall Insulation	complete
2025/06/20	HR 157	Overhead Duct Insulation	not started
2025/06/20	HR 157	Overhead Duct Rough In	in progress
2025/06/20	HR 157	Overhead Plumbing	in progress
2025/06/20	HR 157	Wall Drywall	complete
2025/06/20	HR 157	Wall Drywall Finish	in progress
2025/06/20	HR 157	Wall Prime Paint	not started
2025/06/20	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/06/20	HUMAN RESOURCES 148	Overhead Duct Insulation	not started
2025/06/20	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/06/20	HUMAN RESOURCES 148	Overhead Plumbing	in progress
2025/06/20	HUMAN RESOURCES 148	Wall Drywall	complete
2025/06/20	HUMAN RESOURCES 148	Wall Drywall Finish	complete
2025/06/20	HUMAN RESOURCES 148	Wall Prime Paint	in progress
2025/06/20	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/06/20	INTERNAL AFFAIRS 119	Overhead Duct Insulation	in progress
2025/06/20	INTERNAL AFFAIRS 119	Overhead Duct Rough In	no data
2025/06/20	INTERNAL AFFAIRS 119	Overhead Plumbing	no data
2025/06/20	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/06/20	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/06/20	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/06/20	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/06/20	INTERNAL AFFAIRS 120	Overhead Duct Insulation	in progress
2025/06/20	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/06/20	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/06/20	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/06/20	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/06/20	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/06/20	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data

2025/06/20	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	no data
2025/06/20	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	no data
2025/06/20	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	not started
2025/06/20	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/06/20	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/06/20	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/06/20	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	no data
2025/06/20	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	no data
2025/06/20	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	no data
2025/06/20	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	complete
2025/06/20	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/06/20	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	complete
2025/06/20	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	complete
2025/06/20	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	no data
2025/06/20	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	in progress
2025/06/20	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	in progress
2025/06/20	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	no data
2025/06/20	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/06/20	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/06/20	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	complete
2025/06/20	IT 115	In Wall Insulation	complete
2025/06/20	IT 115	Overhead Duct Insulation	no data
2025/06/20	IT 115	Overhead Duct Rough In	no data
2025/06/20	IT 115	Overhead Plumbing	no data
2025/06/20	IT 115	Wall Drywall	complete
2025/06/20	IT 115	Wall Drywall Finish	complete
2025/06/20	IT 115	Wall Prime Paint	complete
2025/06/20	IT 135	In Wall Insulation	complete
2025/06/20	IT 135	Overhead Duct Insulation	in progress
2025/06/20	IT 135	Overhead Duct Rough In	in progress
2025/06/20	IT 135	Overhead Plumbing	complete
2025/06/20	IT 135	Wall Drywall	complete
2025/06/20	IT 135	Wall Drywall Finish	complete
2025/06/20	IT 135	Wall Prime Paint	complete
2025/06/20	IT MANAGER 136	In Wall Insulation	no data
2025/06/20	IT MANAGER 136	Overhead Duct Insulation	no data

2025/06/20	IT MANAGER 136	Overhead Duct Rough In	no data
2025/06/20	IT MANAGER 136	Overhead Plumbing	complete
2025/06/20	IT MANAGER 136	Wall Drywall	complete
2025/06/20	IT MANAGER 136	Wall Drywall Finish	complete
2025/06/20	IT MANAGER 136	Wall Prime Paint	complete
2025/06/20	IT MANAGER 137	In Wall Insulation	no data
2025/06/20	IT MANAGER 137	Overhead Duct Insulation	no data
2025/06/20	IT MANAGER 137	Overhead Duct Rough In	no data
2025/06/20	IT MANAGER 137	Overhead Plumbing	no data
2025/06/20	IT MANAGER 137	Wall Drywall	complete
2025/06/20	IT MANAGER 137	Wall Drywall Finish	complete
2025/06/20	IT MANAGER 137	Wall Prime Paint	complete
2025/06/20	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/06/20	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data
2025/06/20	JUVENILE INTERVIEW 165	Overhead Duct Rough In	in progress
2025/06/20	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/06/20	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/06/20	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/06/20	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/06/20	JUVENILLE INTERVIEWERS 166	In Wall Insulation	no data
2025/06/20	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/06/20	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/06/20	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	not started
2025/06/20	JUVENILLE INTERVIEWERS 166	Wall Drywall	complete
2025/06/20	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/06/20	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/06/20	KEY ROOM 185	In Wall Insulation	complete
2025/06/20	KEY ROOM 185	Overhead Duct Insulation	no data
2025/06/20	KEY ROOM 185	Overhead Duct Rough In	no data
2025/06/20	KEY ROOM 185	Overhead Plumbing	no data
2025/06/20	KEY ROOM 185	Wall Drywall	complete
2025/06/20	KEY ROOM 185	Wall Drywall Finish	in progress
2025/06/20	KEY ROOM 185	Wall Prime Paint	not started
2025/06/20	LT 170	In Wall Insulation	complete
2025/06/20	LT 170	Overhead Duct Insulation	in progress
2025/06/20	LT 170	Overhead Duct Rough In	in progress
2025/06/20	LT 170	Overhead Plumbing	not started
2025/06/20	LT 170	Wall Drywall	complete
2025/06/20	LT 170	Wall Drywall Finish	complete
2025/06/20	LT 170	Wall Prime Paint	complete
2025/06/20	MACHINE ROOM 191	In Wall Insulation	no data
2025/06/20	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/06/20	MACHINE ROOM 191	Overhead Duct Rough In	no data
2025/06/20	MACHINE ROOM 191	Overhead Plumbing	no data
2025/06/20	MACHINE ROOM 191	Wall Drywall	complete
2025/06/20	MACHINE ROOM 191	Wall Drywall Finish	complete

2025/06/20	MACHINE ROOM 191	Wall Prime Paint	complete
2025/06/20	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/06/20	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/06/20	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/06/20	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/06/20	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/06/20	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/06/20	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/06/20	MAIN JANITORIAL111	In Wall Insulation	no data
2025/06/20	MAIN JANITORIAL111	Overhead Duct Insulation	no data
2025/06/20	MAIN JANITORIAL111	Overhead Duct Rough In	in progress
2025/06/20	MAIN JANITORIAL111	Overhead Plumbing	no data
2025/06/20	MAIN JANITORIAL111	Wall Drywall	complete
2025/06/20	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/06/20	MAIN JANITORIAL111	Wall Prime Paint	complete
2025/06/20	MARINE SERGEANT 142	In Wall Insulation	complete
2025/06/20	MARINE SERGEANT 142	Overhead Duct Insulation	no data
2025/06/20	MARINE SERGEANT 142	Overhead Duct Rough In	no data
2025/06/20	MARINE SERGEANT 142	Overhead Plumbing	no data
2025/06/20	MARINE SERGEANT 142	Wall Drywall	complete
2025/06/20	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/06/20	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/06/20	MECHANICAL 192	In Wall Insulation	no data
2025/06/20	MECHANICAL 192	Overhead Duct Insulation	no data
2025/06/20	MECHANICAL 192	Overhead Duct Rough In	no data
2025/06/20	MECHANICAL 192	Overhead Plumbing	no data
2025/06/20	MECHANICAL 192	Wall Drywall	no data
2025/06/20	MECHANICAL 192	Wall Drywall Finish	no data
2025/06/20	MECHANICAL 192	Wall Prime Paint	no data
2025/06/20	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/06/20	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
2025/06/20	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/06/20	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/06/20	MECHANICAL ROOM 122	Wall Drywall	no data
2025/06/20	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/06/20	MECHANICAL ROOM 122	Wall Prime Paint	complete
2025/06/20	MENS RESTROOM 112	In Wall Insulation	no data
2025/06/20	MENS RESTROOM 112	Overhead Duct Insulation	no data
2025/06/20	MENS RESTROOM 112	Overhead Duct Rough In	in progress
2025/06/20	MENS RESTROOM 112	Overhead Plumbing	no data
2025/06/20	MENS RESTROOM 112	Wall Drywall	complete
2025/06/20	MENS RESTROOM 112	Wall Drywall Finish	in progress
2025/06/20	MENS RESTROOM 112	Wall Prime Paint	not started
2025/06/20	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
2025/06/20	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	no data

2025/06/20	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	no data
2025/06/20	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	no data
2025/06/20	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/06/20	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/06/20	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/06/20	MIS SHREDDING 117	In Wall Insulation	complete
2025/06/20	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/06/20	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/06/20	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/06/20	MIS SHREDDING 117	Wall Drywall	complete
2025/06/20	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/06/20	MIS SHREDDING 117	Wall Prime Paint	complete
2025/06/20	OFFICE 128	In Wall Insulation	no data
2025/06/20	OFFICE 128	Overhead Duct Insulation	in progress
2025/06/20	OFFICE 128	Overhead Duct Rough In	in progress
2025/06/20	OFFICE 128	Overhead Plumbing	not started
2025/06/20	OFFICE 128	Wall Drywall	complete
2025/06/20	OFFICE 128	Wall Drywall Finish	complete
2025/06/20	OFFICE 128	Wall Prime Paint	complete
2025/06/20	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	no data
2025/06/20	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	no data
2025/06/20	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	no data
2025/06/20	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	no data
2025/06/20	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/06/20	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/06/20	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	in progress
2025/06/20	PARTS STORAGE 189	In Wall Insulation	in progress
2025/06/20	PARTS STORAGE 189	Overhead Duct Insulation	no data
2025/06/20	PARTS STORAGE 189	Overhead Duct Rough In	no data
2025/06/20	PARTS STORAGE 189	Overhead Plumbing	no data
2025/06/20	PARTS STORAGE 189	Wall Drywall	complete
2025/06/20	PARTS STORAGE 189	Wall Drywall Finish	complete
2025/06/20	PARTS STORAGE 189	Wall Prime Paint	not started
2025/06/20	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/06/20	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/06/20	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/06/20	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/06/20	PUBLIC RESTROOM 106	Wall Drywall	no data
2025/06/20	PUBLIC RESTROOM 106	Wall Drywall Finish	no data
2025/06/20	PUBLIC RESTROOM 106	Wall Prime Paint	no data
2025/06/20	Polygraph 152	In Wall Insulation	complete
2025/06/20	Polygraph 152	Overhead Duct Insulation	in progress

2025/06/20	Polygraph	152	Overhead Duct Rough In	in progress
2025/06/20	Polygraph	152	Overhead Plumbing	not started
2025/06/20	Polygraph	152	Wall Drywall	complete
2025/06/20	Polygraph	152	Wall Drywall Finish	in progress
2025/06/20	Polygraph	152	Wall Prime Paint	not started
2025/06/20	RECEPTION	101	In Wall Insulation	not started
2025/06/20	RECEPTION	101	Overhead Duct Insulation	no data
2025/06/20	RECEPTION	101	Overhead Duct Rough In	no data
2025/06/20	RECEPTION	101	Overhead Plumbing	not started
2025/06/20	RECEPTION	101	Wall Drywall	not started
2025/06/20	RECEPTION	101	Wall Drywall Finish	not started
2025/06/20	RECEPTION	101	Wall Prime Paint	not started
2025/06/20	RECEPTION	147	In Wall Insulation	complete
2025/06/20	RECEPTION	147	Overhead Duct Insulation	no data
2025/06/20	RECEPTION	147	Overhead Duct Rough In	no data
2025/06/20	RECEPTION	147	Overhead Plumbing	in progress
2025/06/20	RECEPTION	147	Wall Drywall	complete
2025/06/20	RECEPTION	147	Wall Drywall Finish	complete
2025/06/20	RECEPTION	147	Wall Prime Paint	in progress
2025/06/20	RECEPTION	179	In Wall Insulation	complete
2025/06/20	RECEPTION	179	Overhead Duct Insulation	not started
2025/06/20	RECEPTION	179	Overhead Duct Rough In	no data
2025/06/20	RECEPTION	179	Overhead Plumbing	not started
2025/06/20	RECEPTION	179	Wall Drywall	complete
2025/06/20	RECEPTION	179	Wall Drywall Finish	complete
2025/06/20	RECEPTION	179	Wall Prime Paint	not started
2025/06/20	RECORDS	130	In Wall Insulation	no data
2025/06/20	RECORDS	130	Overhead Duct Insulation	no data
2025/06/20	RECORDS	130	Overhead Duct Rough In	no data
2025/06/20	RECORDS	130	Overhead Plumbing	no data
2025/06/20	RECORDS	130	Wall Drywall	complete
2025/06/20	RECORDS	130	Wall Drywall Finish	complete
2025/06/20	RECORDS	130	Wall Prime Paint	complete
2025/06/20	RECORDS STORAGE	133	In Wall Insulation	complete
2025/06/20	RECORDS STORAGE	133	Overhead Duct Insulation	in progress
2025/06/20	RECORDS STORAGE	133	Overhead Duct Rough In	in progress
2025/06/20	RECORDS STORAGE	133	Overhead Plumbing	not started
2025/06/20	RECORDS STORAGE	133	Wall Drywall	complete
2025/06/20	RECORDS STORAGE	133	Wall Drywall Finish	complete
2025/06/20	RECORDS STORAGE	133	Wall Prime Paint	complete
2025/06/20	RECORDS SUPERVISOR	131	In Wall Insulation	no data
2025/06/20	RECORDS SUPERVISOR	131	Overhead Duct Insulation	no data
2025/06/20	RECORDS SUPERVISOR	131	Overhead Duct Rough In	no data
2025/06/20	RECORDS SUPERVISOR	131	Overhead Plumbing	no data
2025/06/20	RECORDS SUPERVISOR	131	Wall Drywall	complete
2025/06/20	RECORDS SUPERVISOR	131	Wall Drywall Finish	complete
2025/06/20	RECORDS SUPERVISOR	131	Wall Prime Paint	complete
2025/06/20	RECORDS SUPERVISOR	132	In Wall Insulation	no data
2025/06/20	RECORDS SUPERVISOR	132	Overhead Duct Insulation	no data



2025/06/20	RECORDS SUPERVISOR 132	Overhead Duct Rough In	no data
2025/06/20	RECORDS SUPERVISOR 132	Overhead Plumbing	not started
2025/06/20	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/06/20	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/06/20	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/06/20	RESTROOM 183	In Wall Insulation	complete
2025/06/20	RESTROOM 183	Overhead Duct Insulation	complete
2025/06/20	RESTROOM 183	Overhead Duct Rough In	complete
2025/06/20	RESTROOM 183	Overhead Plumbing	complete
2025/06/20	RESTROOM 183	Wall Drywall	complete
2025/06/20	RESTROOM 183	Wall Drywall Finish	in progress
2025/06/20	RESTROOM 183	Wall Prime Paint	not started
2025/06/20	Risk Management - 158	In Wall Insulation	complete
2025/06/20	Risk Management - 158	Overhead Duct Insulation	not started
2025/06/20	Risk Management - 158	Overhead Duct Rough In	in progress
2025/06/20	Risk Management - 158	Overhead Plumbing	complete
2025/06/20	Risk Management - 158	Wall Drywall	complete
2025/06/20	Risk Management - 158	Wall Drywall Finish	in progress
2025/06/20	Risk Management - 158	Wall Prime Paint	not started
2025/06/20	SALLY PORT 105	In Wall Insulation	not started
2025/06/20	SALLY PORT 105	Overhead Duct Insulation	in progress
2025/06/20	SALLY PORT 105	Overhead Duct Rough In	no data
2025/06/20	SALLY PORT 105	Overhead Plumbing	no data
2025/06/20	SALLY PORT 105	Wall Drywall	not started
2025/06/20	SALLY PORT 105	Wall Drywall Finish	not started
2025/06/20	SALLY PORT 105	Wall Prime Paint	not started
2025/06/20	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/06/20	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/06/20	SANE EXAM ROOM 168	Overhead Duct Rough In	in progress
2025/06/20	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/06/20	SANE EXAM ROOM 168	Wall Drywall	complete
2025/06/20	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/06/20	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/06/20	SGT 171	In Wall Insulation	no data
2025/06/20	SGT 171	Overhead Duct Insulation	no data
2025/06/20	SGT 171	Overhead Duct Rough In	no data
2025/06/20	SGT 171	Overhead Plumbing	no data
2025/06/20	SGT 171	Wall Drywall	complete
2025/06/20	SGT 171	Wall Drywall Finish	complete
2025/06/20	SGT 171	Wall Prime Paint	complete
2025/06/20	SGT 172	In Wall Insulation	complete
2025/06/20	SGT 172	Overhead Duct Insulation	no data
2025/06/20	SGT 172	Overhead Duct Rough In	no data
2025/06/20	SGT 172	Overhead Plumbing	no data
2025/06/20	SGT 172	Wall Drywall	complete
2025/06/20	SGT 172	Wall Drywall Finish	complete
2025/06/20	SGT 172	Wall Prime Paint	complete
2025/06/20	SHIPPING STORAGE 190	In Wall Insulation	complete

2025/06/20	SHIPPING STORAGE 190	Overhead Duct Insulation	no data
2025/06/20	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/06/20	SHIPPING STORAGE 190	Overhead Plumbing	no data
2025/06/20	SHIPPING STORAGE 190	Wall Drywall	complete
2025/06/20	SHIPPING STORAGE 190	Wall Drywall Finish	in progress
2025/06/20	SHIPPING STORAGE 190	Wall Prime Paint	not started
2025/06/20	SHOP FORMAN 184	In Wall Insulation	complete
2025/06/20	SHOP FORMAN 184	Overhead Duct Insulation	no data
2025/06/20	SHOP FORMAN 184	Overhead Duct Rough In	no data
2025/06/20	SHOP FORMAN 184	Overhead Plumbing	no data
2025/06/20	SHOP FORMAN 184	Wall Drywall	complete
2025/06/20	SHOP FORMAN 184	Wall Drywall Finish	in progress
2025/06/20	SHOP FORMAN 184	Wall Prime Paint	not started
2025/06/20	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/06/20	SOFT INTERVIEW 161	Overhead Duct Insulation	no data
2025/06/20	SOFT INTERVIEW 161	Overhead Duct Rough In	in progress
2025/06/20	SOFT INTERVIEW 161	Overhead Plumbing	complete
2025/06/20	SOFT INTERVIEW 161	Wall Drywall	complete
2025/06/20	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/06/20	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/06/20	SOFT INTERVIEW 162	In Wall Insulation	complete
2025/06/20	SOFT INTERVIEW 162	Overhead Duct Insulation	no data
2025/06/20	SOFT INTERVIEW 162	Overhead Duct Rough In	no data
2025/06/20	SOFT INTERVIEW 162	Overhead Plumbing	complete
2025/06/20	SOFT INTERVIEW 162	Wall Drywall	complete
2025/06/20	SOFT INTERVIEW 162	Wall Drywall Finish	complete
2025/06/20	SOFT INTERVIEW 162	Wall Prime Paint	complete
2025/06/20	SPECIAL OPERATION LT 143	In Wall Insulation	no data
2025/06/20	SPECIAL OPERATION LT 143	Overhead Duct Insulation	no data
2025/06/20	SPECIAL OPERATION LT 143	Overhead Duct Rough In	no data
2025/06/20	SPECIAL OPERATION LT 143	Overhead Plumbing	no data
2025/06/20	SPECIAL OPERATION LT 143	Wall Drywall	complete
2025/06/20	SPECIAL OPERATION LT 143	Wall Drywall Finish	complete
2025/06/20	SPECIAL OPERATION LT 143	Wall Prime Paint	complete
2025/06/20	STAIR A	In Wall Insulation	no data
2025/06/20	STAIR A	Overhead Duct Insulation	no data
2025/06/20	STAIR A	Overhead Duct Rough In	no data
2025/06/20	STAIR A	Overhead Plumbing	in progress
2025/06/20	STAIR A	Wall Drywall	not started
2025/06/20	STAIR A	Wall Drywall Finish	not started
2025/06/20	STAIR A	Wall Prime Paint	not started
2025/06/20	STORAGE 104	In Wall Insulation	no data
2025/06/20	STORAGE 104	Overhead Duct Insulation	no data
2025/06/20	STORAGE 104	Overhead Duct Rough In	no data
2025/06/20	STORAGE 104	Overhead Plumbing	not started
2025/06/20	STORAGE 104	Wall Drywall	complete
2025/06/20	STORAGE 104	Wall Drywall Finish	complete
2025/06/20	STORAGE 104	Wall Prime Paint	in progress

2025/06/20	STORAGE 127	In Wall Insulation	no data
2025/06/20	STORAGE 127	Overhead Duct Insulation	no data
2025/06/20	STORAGE 127	Overhead Duct Rough In	no data
2025/06/20	STORAGE 127	Overhead Plumbing	not started
2025/06/20	STORAGE 127	Wall Drywall	complete
2025/06/20	STORAGE 127	Wall Drywall Finish	complete
2025/06/20	STORAGE 127	Wall Prime Paint	complete
2025/06/20	STUDIO 126	In Wall Insulation	complete
2025/06/20	STUDIO 126	Overhead Duct Insulation	complete
2025/06/20	STUDIO 126	Overhead Duct Rough In	in progress
2025/06/20	STUDIO 126	Overhead Plumbing	not started
2025/06/20	STUDIO 126	Wall Drywall	complete
2025/06/20	STUDIO 126	Wall Drywall Finish	complete
2025/06/20	STUDIO 126	Wall Prime Paint	in progress
2025/06/20	SUPERVISOR 129	In Wall Insulation	complete
2025/06/20	SUPERVISOR 129	Overhead Duct Insulation	in progress
2025/06/20	SUPERVISOR 129	Overhead Duct Rough In	in progress
2025/06/20	SUPERVISOR 129	Overhead Plumbing	not started
2025/06/20	SUPERVISOR 129	Wall Drywall	complete
2025/06/20	SUPERVISOR 129	Wall Drywall Finish	complete
2025/06/20	SUPERVISOR 129	Wall Prime Paint	complete
2025/06/20	Storage 164	In Wall Insulation	complete
2025/06/20	Storage 164	Overhead Duct Insulation	in progress
2025/06/20	Storage 164	Overhead Duct Rough In	in progress
2025/06/20	Storage 164	Overhead Plumbing	not started
2025/06/20	Storage 164	Wall Drywall	complete
2025/06/20	Storage 164	Wall Drywall Finish	complete
2025/06/20	Storage 164	Wall Prime Paint	complete
2025/06/20	Storage 177	In Wall Insulation	complete
2025/06/20	Storage 177	Overhead Duct Insulation	in progress
2025/06/20	Storage 177	Overhead Duct Rough In	in progress
2025/06/20	Storage 177	Overhead Plumbing	not started
2025/06/20	Storage 177	Wall Drywall	complete
2025/06/20	Storage 177	Wall Drywall Finish	complete
2025/06/20	Storage 177	Wall Prime Paint	complete
2025/06/20	TECHNICAL SURVEILLANCE 188	In Wall Insulation	no data
2025/06/20	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	not started
2025/06/20	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	no data
2025/06/20	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	no data
2025/06/20	TECHNICAL SURVEILLANCE 188	Wall Drywall	complete
2025/06/20	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	in progress
2025/06/20	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	not started
2025/06/20	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/06/20	TRAFFIC SERGEANT 141	Overhead Duct Insulation	no data
2025/06/20	TRAFFIC SERGEANT 141	Overhead Duct Rough In	no data
2025/06/20	TRAFFIC SERGEANT 141	Overhead Plumbing	no data
2025/06/20	TRAFFIC SERGEANT 141	Wall Drywall	complete

2025/06/20	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/06/20	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/06/20	TRIAGE/RECEPTION 134	In Wall Insulation	no data
2025/06/20	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/06/20	TRIAGE/RECEPTION 134	Overhead Duct Rough In	in progress
2025/06/20	TRIAGE/RECEPTION 134	Overhead Plumbing	not started
2025/06/20	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/06/20	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/06/20	TRIAGE/RECEPTION 134	Wall Prime Paint	in progress
2025/06/20	TST WORKSHOP 187	In Wall Insulation	complete
2025/06/20	TST WORKSHOP 187	Overhead Duct Insulation	no data
2025/06/20	TST WORKSHOP 187	Overhead Duct Rough In	no data
2025/06/20	TST WORKSHOP 187	Overhead Plumbing	no data
2025/06/20	TST WORKSHOP 187	Wall Drywall	complete
2025/06/20	TST WORKSHOP 187	Wall Drywall Finish	in progress
2025/06/20	TST WORKSHOP 187	Wall Prime Paint	in progress
2025/06/20	UNISEX RESTROOM 169	In Wall Insulation	complete
2025/06/20	UNISEX RESTROOM 169	Overhead Duct Insulation	no data
2025/06/20	UNISEX RESTROOM 169	Overhead Duct Rough In	complete
2025/06/20	UNISEX RESTROOM 169	Overhead Plumbing	no data
2025/06/20	UNISEX RESTROOM 169	Wall Drywall	complete
2025/06/20	UNISEX RESTROOM 169	Wall Drywall Finish	in progress
2025/06/20	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/06/20	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	no data
2025/06/20	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	not started
2025/06/20	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	no data
2025/06/20	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete
2025/06/20	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	complete
2025/06/20	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	in progress
2025/06/20	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	in progress
2025/06/20	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	no data
2025/06/20	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	no data
2025/06/20	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	no data
2025/06/20	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	no data
2025/06/20	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/06/20	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/06/20	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/06/20	WAITING/LOBBY 100	In Wall Insulation	not started
2025/06/20	WAITING/LOBBY 100	Overhead Duct Insulation	no data
2025/06/20	WAITING/LOBBY 100	Overhead Duct Rough In	no data
2025/06/20	WAITING/LOBBY 100	Overhead Plumbing	not started
2025/06/20	WAITING/LOBBY 100	Wall Drywall	not started

2025/06/20	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/06/20	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/06/20	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/06/20	WOMENS RESTROOM 113	Overhead Duct Insulation	no data
2025/06/20	WOMENS RESTROOM 113	Overhead Duct Rough In	no data
2025/06/20	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/06/20	WOMENS RESTROOM 113	Wall Drywall	complete
2025/06/20	WOMENS RESTROOM 113	Wall Drywall Finish	in progress
2025/06/20	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/07/07	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/07/07	ADMIN ASSISTANT 125	Overhead Duct Insulation	no data
2025/07/07	ADMIN ASSISTANT 125	Overhead Duct Rough In	no data
2025/07/07	ADMIN ASSISTANT 125	Overhead Plumbing	no data
2025/07/07	ADMIN ASSISTANT 125	Wall Drywall	complete
2025/07/07	ADMIN ASSISTANT 125	Wall Drywall Finish	complete
2025/07/07	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/07/07	AV ROOM 103	In Wall Insulation	no data
2025/07/07	AV ROOM 103	Overhead Duct Insulation	no data
2025/07/07	AV ROOM 103	Overhead Duct Rough In	no data
2025/07/07	AV ROOM 103	Overhead Plumbing	no data
2025/07/07	AV ROOM 103	Wall Drywall	no data
2025/07/07	AV ROOM 103	Wall Drywall Finish	no data
2025/07/07	AV ROOM 103	Wall Prime Paint	no data
2025/07/07	BREAK ROOM CONFERENCE 182	In Wall Insulation	no data
2025/07/07	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	no data
2025/07/07	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	no data
2025/07/07	BREAK ROOM CONFERENCE 182	Overhead Plumbing	no data
2025/07/07	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/07/07	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	complete
2025/07/07	BREAK ROOM CONFERENCE 182	Wall Prime Paint	complete
2025/07/07	Background-159	In Wall Insulation	complete
2025/07/07	Background-159	Overhead Duct Insulation	in progress
2025/07/07	Background-159	Overhead Duct Rough In	in progress
2025/07/07	Background-159	Overhead Plumbing	not started
2025/07/07	Background-159	Wall Drywall	complete
2025/07/07	Background-159	Wall Drywall Finish	complete
2025/07/07	Background-159	Wall Prime Paint	complete
2025/07/07	CENTRAL BREAKROOM 145	In Wall Insulation	no data
2025/07/07	CENTRAL BREAKROOM 145	Overhead Duct Insulation	in progress
2025/07/07	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/07/07	CENTRAL BREAKROOM 145	Overhead Plumbing	in progress
2025/07/07	CENTRAL BREAKROOM 145	Wall Drywall	in progress
2025/07/07	CENTRAL BREAKROOM 145	Wall Drywall Finish	in progress
2025/07/07	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/07/07	COLD CASE 175	In Wall Insulation	no data

2025/07/07	COLD CASE 175	Overhead Duct Insulation	complete
2025/07/07	COLD CASE 175	Overhead Duct Rough In	no data
2025/07/07	COLD CASE 175	Overhead Plumbing	in progress
2025/07/07	COLD CASE 175	Wall Drywall	complete
2025/07/07	COLD CASE 175	Wall Drywall Finish	complete
2025/07/07	COLD CASE 175	Wall Prime Paint	complete
2025/07/07	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/07/07	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	no data
2025/07/07	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	no data
2025/07/07	COMMUNITY AFFAIRS 124	Overhead Plumbing	no data
2025/07/07	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/07/07	COMMUNITY AFFAIRS 124	Wall Drywall Finish	no data
2025/07/07	COMMUNITY AFFAIRS 124	Wall Prime Paint	no data
2025/07/07	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/07/07	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	in progress
2025/07/07	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	no data
2025/07/07	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	not started
2025/07/07	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete
2025/07/07	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	complete
2025/07/07	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	complete
2025/07/07	CONFERENCE ROOM 153	In Wall Insulation	complete
2025/07/07	CONFERENCE ROOM 153	Overhead Duct Insulation	no data
2025/07/07	CONFERENCE ROOM 153	Overhead Duct Rough In	no data
2025/07/07	CONFERENCE ROOM 153	Overhead Plumbing	not started
2025/07/07	CONFERENCE ROOM 153	Wall Drywall	complete
2025/07/07	CONFERENCE ROOM 153	Wall Drywall Finish	complete
2025/07/07	CONFERENCE ROOM 153	Wall Prime Paint	complete
2025/07/07	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/07/07	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	in progress
2025/07/07	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	no data
2025/07/07	CONFERENCE/WAR ROOM 163	Overhead Plumbing	not started
2025/07/07	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/07/07	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete
2025/07/07	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/07/07	COPY 176	In Wall Insulation	complete
2025/07/07	COPY 176	Overhead Duct Insulation	complete
2025/07/07	COPY 176	Overhead Duct Rough In	in progress
2025/07/07	COPY 176	Overhead Plumbing	not started
2025/07/07	COPY 176	Wall Drywall	complete
2025/07/07	COPY 176	Wall Drywall Finish	complete
2025/07/07	COPY 176	Wall Prime Paint	complete

2025/07/07	COPY/MAIL ROOM	114	In Wall Insulation	complete
2025/07/07	COPY/MAIL ROOM	114	Overhead Duct Insulation	no data
2025/07/07	COPY/MAIL ROOM	114	Overhead Duct Rough In	no data
2025/07/07	COPY/MAIL ROOM	114	Overhead Plumbing	in progress
2025/07/07	COPY/MAIL ROOM	114	Wall Drywall	complete
2025/07/07	COPY/MAIL ROOM	114	Wall Drywall Finish	complete
2025/07/07	COPY/MAIL ROOM	114	Wall Prime Paint	complete
2025/07/07	CORRIDOR	107	In Wall Insulation	complete
2025/07/07	CORRIDOR	107	Overhead Duct Insulation	in progress
2025/07/07	CORRIDOR	107	Overhead Duct Rough In	in progress
2025/07/07	CORRIDOR	107	Overhead Plumbing	in progress
2025/07/07	CORRIDOR	107	Wall Drywall	complete
2025/07/07	CORRIDOR	107	Wall Drywall Finish	complete
2025/07/07	CORRIDOR	107	Wall Prime Paint	complete
2025/07/07	CORRIDOR	108	In Wall Insulation	complete
2025/07/07	CORRIDOR	108	In Wall Insulation	no data
2025/07/07	CORRIDOR	108	Overhead Duct Insulation	in progress
2025/07/07	CORRIDOR	108	Overhead Duct Insulation	no data
2025/07/07	CORRIDOR	108	Overhead Duct Rough In	in progress
2025/07/07	CORRIDOR	108	Overhead Duct Rough In	no data
2025/07/07	CORRIDOR	108	Overhead Plumbing	in progress
2025/07/07	CORRIDOR	108	Overhead Plumbing	no data
2025/07/07	CORRIDOR	108	Wall Drywall	complete
2025/07/07	CORRIDOR	108	Wall Drywall	complete
2025/07/07	CORRIDOR	108	Wall Drywall Finish	complete
2025/07/07	CORRIDOR	108	Wall Drywall Finish	complete
2025/07/07	CORRIDOR	108	Wall Prime Paint	complete
2025/07/07	CORRIDOR	108	Wall Prime Paint	in progress
2025/07/07	CORRIDOR	109	In Wall Insulation	complete
2025/07/07	CORRIDOR	109	Overhead Duct Insulation	in progress
2025/07/07	CORRIDOR	109	Overhead Duct Rough In	in progress
2025/07/07	CORRIDOR	109	Overhead Plumbing	in progress
2025/07/07	CORRIDOR	109	Wall Drywall	complete
2025/07/07	CORRIDOR	109	Wall Drywall Finish	complete
2025/07/07	CORRIDOR	109	Wall Prime Paint	complete
2025/07/07	CORRIDOR	110	In Wall Insulation	no data
2025/07/07	CORRIDOR	110	In Wall Insulation	no data
2025/07/07	CORRIDOR	110	Overhead Duct Insulation	no data
2025/07/07	CORRIDOR	110	Overhead Duct Insulation	no data
2025/07/07	CORRIDOR	110	Overhead Duct Rough In	no data
2025/07/07	CORRIDOR	110	Overhead Duct Rough In	no data
2025/07/07	CORRIDOR	110	Overhead Plumbing	in progress
2025/07/07	CORRIDOR	110	Overhead Plumbing	in progress
2025/07/07	CORRIDOR	110	Wall Drywall	complete
2025/07/07	CORRIDOR	110	Wall Drywall	complete
2025/07/07	CORRIDOR	110	Wall Drywall Finish	complete
2025/07/07	CORRIDOR	110	Wall Drywall Finish	complete
2025/07/07	CORRIDOR	110	Wall Prime Paint	complete
2025/07/07	CORRIDOR	110	Wall Prime Paint	in progress
2025/07/07	CORRIDOR	181	In Wall Insulation	complete
2025/07/07	CORRIDOR	181	Overhead Duct Insulation	not started
2025/07/07	CORRIDOR	181	Overhead Duct Rough In	in progress
2025/07/07	CORRIDOR	181	Overhead Plumbing	in progress
2025/07/07	CORRIDOR	181	Wall Drywall	complete

2025/07/07	CORRIDOR 181	Wall Drywall Finish	complete
2025/07/07	CORRIDOR 181	Wall Prime Paint	complete
2025/07/07	CORRIDOR144	In Wall Insulation	no data
2025/07/07	CORRIDOR144	Overhead Duct Insulation	in progress
2025/07/07	CORRIDOR144	Overhead Duct Rough In	no data
2025/07/07	CORRIDOR144	Overhead Plumbing	no data
2025/07/07	CORRIDOR144	Wall Drywall	complete
2025/07/07	CORRIDOR144	Wall Drywall Finish	complete
2025/07/07	CORRIDOR144	Wall Prime Paint	complete
2025/07/07	CPL 173	In Wall Insulation	complete
2025/07/07	CPL 173	Overhead Duct Insulation	complete
2025/07/07	CPL 173	Overhead Duct Rough In	in progress
2025/07/07	CPL 173	Overhead Plumbing	in progress
2025/07/07	CPL 173	Wall Drywall	complete
2025/07/07	CPL 173	Wall Drywall Finish	complete
2025/07/07	CPL 173	Wall Prime Paint	complete
2025/07/07	CPL 174	In Wall Insulation	complete
2025/07/07	CPL 174	Overhead Duct Insulation	no data
2025/07/07	CPL 174	Overhead Duct Rough In	no data
2025/07/07	CPL 174	Overhead Plumbing	no data
2025/07/07	CPL 174	Wall Drywall	complete
2025/07/07	CPL 174	Wall Drywall Finish	complete
2025/07/07	CPL 174	Wall Prime Paint	in progress
2025/07/07	DRY STORAGE 146	In Wall Insulation	complete
2025/07/07	DRY STORAGE 146	Overhead Duct Insulation	not started
2025/07/07	DRY STORAGE 146	Overhead Duct Rough In	in progress
2025/07/07	DRY STORAGE 146	Overhead Plumbing	not started
2025/07/07	DRY STORAGE 146	Wall Drywall	complete
2025/07/07	DRY STORAGE 146	Wall Drywall Finish	complete
2025/07/07	DRY STORAGE 146	Wall Prime Paint	in progress
2025/07/07	FIRE RISER 178	In Wall Insulation	no data
2025/07/07	FIRE RISER 178	Overhead Duct Insulation	no data
2025/07/07	FIRE RISER 178	Overhead Duct Rough In	no data
2025/07/07	FIRE RISER 178	Overhead Plumbing	no data
2025/07/07	FIRE RISER 178	Wall Drywall	no data
2025/07/07	FIRE RISER 178	Wall Drywall Finish	no data
2025/07/07	FIRE RISER 178	Wall Prime Paint	no data
2025/07/07	GREETING ROOM 106	In Wall Insulation	no data
2025/07/07	GREETING ROOM 106	Overhead Duct Insulation	complete
2025/07/07	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/07/07	GREETING ROOM 106	Overhead Plumbing	not started
2025/07/07	GREETING ROOM 106	Wall Drywall	complete
2025/07/07	GREETING ROOM 106	Wall Drywall Finish	complete
2025/07/07	GREETING ROOM 106	Wall Prime Paint	complete
2025/07/07	HR 149	In Wall Insulation	complete
2025/07/07	HR 149	Overhead Duct Insulation	complete
2025/07/07	HR 149	Overhead Duct Rough In	in progress
2025/07/07	HR 149	Overhead Plumbing	not started
2025/07/07	HR 149	Wall Drywall	complete
2025/07/07	HR 149	Wall Drywall Finish	complete
2025/07/07	HR 149	Wall Prime Paint	complete
2025/07/07	HR 150	In Wall Insulation	complete



2025/07/07	HR 150	Overhead Duct Insulation	complete
2025/07/07	HR 150	Overhead Duct Rough In	no data
2025/07/07	HR 150	Overhead Plumbing	no data
2025/07/07	HR 150	Wall Drywall	complete
2025/07/07	HR 150	Wall Drywall Finish	complete
2025/07/07	HR 150	Wall Prime Paint	complete
2025/07/07	HR 151	In Wall Insulation	complete
2025/07/07	HR 151	Overhead Duct Insulation	in progress
2025/07/07	HR 151	Overhead Duct Rough In	in progress
2025/07/07	HR 151	Overhead Plumbing	complete
2025/07/07	HR 151	Wall Drywall	complete
2025/07/07	HR 151	Wall Drywall Finish	complete
2025/07/07	HR 151	Wall Prime Paint	complete
2025/07/07	HR 154	In Wall Insulation	complete
2025/07/07	HR 154	Overhead Duct Insulation	in progress
2025/07/07	HR 154	Overhead Duct Rough In	in progress
2025/07/07	HR 154	Overhead Plumbing	in progress
2025/07/07	HR 154	Wall Drywall	complete
2025/07/07	HR 154	Wall Drywall Finish	complete
2025/07/07	HR 154	Wall Prime Paint	complete
2025/07/07	HR 155	In Wall Insulation	complete
2025/07/07	HR 155	Overhead Duct Insulation	in progress
2025/07/07	HR 155	Overhead Duct Rough In	in progress
2025/07/07	HR 155	Overhead Plumbing	not started
2025/07/07	HR 155	Wall Drywall	complete
2025/07/07	HR 155	Wall Drywall Finish	complete
2025/07/07	HR 155	Wall Prime Paint	complete
2025/07/07	HR 156	In Wall Insulation	complete
2025/07/07	HR 156	Overhead Duct Insulation	complete
2025/07/07	HR 156	Overhead Duct Rough In	in progress
2025/07/07	HR 156	Overhead Plumbing	not started
2025/07/07	HR 156	Wall Drywall	complete
2025/07/07	HR 156	Wall Drywall Finish	complete
2025/07/07	HR 156	Wall Prime Paint	complete
2025/07/07	HR 157	In Wall Insulation	complete
2025/07/07	HR 157	Overhead Duct Insulation	not started
2025/07/07	HR 157	Overhead Duct Rough In	in progress
2025/07/07	HR 157	Overhead Plumbing	in progress
2025/07/07	HR 157	Wall Drywall	complete
2025/07/07	HR 157	Wall Drywall Finish	complete
2025/07/07	HR 157	Wall Prime Paint	complete
2025/07/07	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/07/07	HUMAN RESOURCES 148	Overhead Duct Insulation	in progress
2025/07/07	HUMAN RESOURCES 148	Overhead Duct Rough In	no data
2025/07/07	HUMAN RESOURCES 148	Overhead Plumbing	no data
2025/07/07	HUMAN RESOURCES 148	Wall Drywall	complete
2025/07/07	HUMAN RESOURCES 148	Wall Drywall Finish	complete
2025/07/07	HUMAN RESOURCES 148	Wall Prime Paint	in progress
2025/07/07	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/07/07	INTERNAL AFFAIRS 119	Overhead Duct Insulation	in progress
2025/07/07	INTERNAL AFFAIRS 119	Overhead Duct Rough In	no data
2025/07/07	INTERNAL AFFAIRS 119	Overhead Plumbing	complete

2025/07/07	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/07/07	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/07/07	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/07/07	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/07/07	INTERNAL AFFAIRS 120	Overhead Duct Insulation	complete
2025/07/07	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/07/07	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/07/07	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/07/07	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/07/07	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/07/07	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/07/07	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	in progress
2025/07/07	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	in progress
2025/07/07	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	in progress
2025/07/07	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/07/07	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/07/07	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/07/07	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	no data
2025/07/07	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	complete
2025/07/07	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	no data
2025/07/07	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	complete
2025/07/07	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/07/07	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	complete
2025/07/07	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	complete
2025/07/07	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	no data
2025/07/07	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	in progress
2025/07/07	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	in progress
2025/07/07	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	in progress
2025/07/07	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/07/07	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/07/07	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	complete
2025/07/07	IT 115	In Wall Insulation	complete
2025/07/07	IT 115	Overhead Duct Insulation	no data

2025/07/07	IT 115	Overhead Duct Rough In	no data
2025/07/07	IT 115	Overhead Plumbing	no data
2025/07/07	IT 115	Wall Drywall	complete
2025/07/07	IT 115	Wall Drywall Finish	complete
2025/07/07	IT 115	Wall Prime Paint	complete
2025/07/07	IT 135	In Wall Insulation	complete
2025/07/07	IT 135	Overhead Duct Insulation	in progress
2025/07/07	IT 135	Overhead Duct Rough In	in progress
2025/07/07	IT 135	Overhead Plumbing	complete
2025/07/07	IT 135	Wall Drywall	complete
2025/07/07	IT 135	Wall Drywall Finish	complete
2025/07/07	IT 135	Wall Prime Paint	complete
2025/07/07	IT MANAGER 136	In Wall Insulation	no data
2025/07/07	IT MANAGER 136	Overhead Duct Insulation	no data
2025/07/07	IT MANAGER 136	Overhead Duct Rough In	no data
2025/07/07	IT MANAGER 136	Overhead Plumbing	complete
2025/07/07	IT MANAGER 136	Wall Drywall	complete
2025/07/07	IT MANAGER 136	Wall Drywall Finish	complete
2025/07/07	IT MANAGER 136	Wall Prime Paint	complete
2025/07/07	IT MANAGER 137	In Wall Insulation	no data
2025/07/07	IT MANAGER 137	Overhead Duct Insulation	complete
2025/07/07	IT MANAGER 137	Overhead Duct Rough In	no data
2025/07/07	IT MANAGER 137	Overhead Plumbing	no data
2025/07/07	IT MANAGER 137	Wall Drywall	complete
2025/07/07	IT MANAGER 137	Wall Drywall Finish	complete
2025/07/07	IT MANAGER 137	Wall Prime Paint	complete
2025/07/07	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/07/07	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data
2025/07/07	JUVENILE INTERVIEW 165	Overhead Duct Rough In	in progress
2025/07/07	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/07/07	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/07/07	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/07/07	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/07/07	JUVENILLE INTERVIEWERS 166	In Wall Insulation	no data
2025/07/07	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/07/07	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/07/07	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	no data
2025/07/07	JUVENILLE INTERVIEWERS 166	Wall Drywall	complete
2025/07/07	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/07/07	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/07/07	KEY ROOM 185	In Wall Insulation	complete
2025/07/07	KEY ROOM 185	Overhead Duct Insulation	no data
2025/07/07	KEY ROOM 185	Overhead Duct Rough In	no data
2025/07/07	KEY ROOM 185	Overhead Plumbing	no data
2025/07/07	KEY ROOM 185	Wall Drywall	complete
2025/07/07	KEY ROOM 185	Wall Drywall Finish	complete

2025/07/07	KEY ROOM 185	Wall Prime Paint	complete
2025/07/07	LT 170	In Wall Insulation	complete
2025/07/07	LT 170	Overhead Duct Insulation	complete
2025/07/07	LT 170	Overhead Duct Rough In	in progress
2025/07/07	LT 170	Overhead Plumbing	not started
2025/07/07	LT 170	Wall Drywall	complete
2025/07/07	LT 170	Wall Drywall Finish	complete
2025/07/07	LT 170	Wall Prime Paint	complete
2025/07/07	MACHINE ROOM 191	In Wall Insulation	no data
2025/07/07	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/07/07	MACHINE ROOM 191	Overhead Duct Rough In	no data
2025/07/07	MACHINE ROOM 191	Overhead Plumbing	no data
2025/07/07	MACHINE ROOM 191	Wall Drywall	complete
2025/07/07	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/07/07	MACHINE ROOM 191	Wall Prime Paint	complete
2025/07/07	MAIN ELECTRICAL ROOM 123	In Wall Insulation	complete
2025/07/07	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	not started
2025/07/07	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	not started
2025/07/07	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	not started
2025/07/07	MAIN ELECTRICAL ROOM 123	Wall Drywall	complete
2025/07/07	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	complete
2025/07/07	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	in progress
2025/07/07	MAIN JANITORIAL111	In Wall Insulation	no data
2025/07/07	MAIN JANITORIAL111	Overhead Duct Insulation	no data
2025/07/07	MAIN JANITORIAL111	Overhead Duct Rough In	no data
2025/07/07	MAIN JANITORIAL111	Overhead Plumbing	no data
2025/07/07	MAIN JANITORIAL111	Wall Drywall	no data
2025/07/07	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/07/07	MAIN JANITORIAL111	Wall Prime Paint	complete
2025/07/07	MARINE SERGEANT 142	In Wall Insulation	complete
2025/07/07	MARINE SERGEANT 142	Overhead Duct Insulation	in progress
2025/07/07	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/07/07	MARINE SERGEANT 142	Overhead Plumbing	in progress
2025/07/07	MARINE SERGEANT 142	Wall Drywall	complete
2025/07/07	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/07/07	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/07/07	MECHANICAL 192	In Wall Insulation	no data
2025/07/07	MECHANICAL 192	Overhead Duct Insulation	not started
2025/07/07	MECHANICAL 192	Overhead Duct Rough In	in progress
2025/07/07	MECHANICAL 192	Overhead Plumbing	in progress
2025/07/07	MECHANICAL 192	Wall Drywall	complete
2025/07/07	MECHANICAL 192	Wall Drywall Finish	complete
2025/07/07	MECHANICAL 192	Wall Prime Paint	complete
2025/07/07	MECHANICAL ROOM 122	In Wall Insulation	complete
2025/07/07	MECHANICAL ROOM 122	Overhead Duct Insulation	not started

2025/07/07	MECHANICAL ROOM 122	Overhead Duct Rough In	in progress
2025/07/07	MECHANICAL ROOM 122	Overhead Plumbing	complete
2025/07/07	MECHANICAL ROOM 122	Wall Drywall	complete
2025/07/07	MECHANICAL ROOM 122	Wall Drywall Finish	complete
2025/07/07	MECHANICAL ROOM 122	Wall Prime Paint	complete
2025/07/07	MENS RESTROOM 112	In Wall Insulation	no data
2025/07/07	MENS RESTROOM 112	Overhead Duct Insulation	no data
2025/07/07	MENS RESTROOM 112	Overhead Duct Rough In	no data
2025/07/07	MENS RESTROOM 112	Overhead Plumbing	no data
2025/07/07	MENS RESTROOM 112	Wall Drywall	no data
2025/07/07	MENS RESTROOM 112	Wall Drywall Finish	no data
2025/07/07	MENS RESTROOM 112	Wall Prime Paint	no data
2025/07/07	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
2025/07/07	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/07/07	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	no data
2025/07/07	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	no data
2025/07/07	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/07/07	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/07/07	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/07/07	MIS SHREDDING 117	In Wall Insulation	complete
2025/07/07	MIS SHREDDING 117	Overhead Duct Insulation	not started
2025/07/07	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/07/07	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/07/07	MIS SHREDDING 117	Wall Drywall	complete
2025/07/07	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/07/07	MIS SHREDDING 117	Wall Prime Paint	complete
2025/07/07	OFFICE 128	In Wall Insulation	no data
2025/07/07	OFFICE 128	Overhead Duct Insulation	in progress
2025/07/07	OFFICE 128	Overhead Duct Rough In	in progress
2025/07/07	OFFICE 128	Overhead Plumbing	not started
2025/07/07	OFFICE 128	Wall Drywall	complete
2025/07/07	OFFICE 128	Wall Drywall Finish	complete
2025/07/07	OFFICE 128	Wall Prime Paint	complete
2025/07/07	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	no data
2025/07/07	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	no data
2025/07/07	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	no data
2025/07/07	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	in progress
2025/07/07	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/07/07	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/07/07	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	complete

2025/07/07	PARTS STORAGE 189	In Wall Insulation	in progress
2025/07/07	PARTS STORAGE 189	Overhead Duct Insulation	no data
2025/07/07	PARTS STORAGE 189	Overhead Duct Rough In	no data
2025/07/07	PARTS STORAGE 189	Overhead Plumbing	no data
2025/07/07	PARTS STORAGE 189	Wall Drywall	complete
2025/07/07	PARTS STORAGE 189	Wall Drywall Finish	complete
2025/07/07	PARTS STORAGE 189	Wall Prime Paint	not started
2025/07/07	PUBLIC RESTROOM 106	In Wall Insulation	complete
2025/07/07	PUBLIC RESTROOM 106	Overhead Duct Insulation	in progress
2025/07/07	PUBLIC RESTROOM 106	Overhead Duct Rough In	in progress
2025/07/07	PUBLIC RESTROOM 106	Overhead Plumbing	in progress
2025/07/07	PUBLIC RESTROOM 106	Wall Drywall	complete
2025/07/07	PUBLIC RESTROOM 106	Wall Drywall Finish	complete
2025/07/07	PUBLIC RESTROOM 106	Wall Prime Paint	not started
2025/07/07	Polygraph 152	In Wall Insulation	complete
2025/07/07	Polygraph 152	Overhead Duct Insulation	in progress
2025/07/07	Polygraph 152	Overhead Duct Rough In	in progress
2025/07/07	Polygraph 152	Overhead Plumbing	not started
2025/07/07	Polygraph 152	Wall Drywall	complete
2025/07/07	Polygraph 152	Wall Drywall Finish	complete
2025/07/07	Polygraph 152	Wall Prime Paint	complete
2025/07/07	RECEPTION 101	In Wall Insulation	no data
2025/07/07	RECEPTION 101	Overhead Duct Insulation	no data
2025/07/07	RECEPTION 101	Overhead Duct Rough In	no data
2025/07/07	RECEPTION 101	Overhead Plumbing	no data
2025/07/07	RECEPTION 101	Wall Drywall	no data
2025/07/07	RECEPTION 101	Wall Drywall Finish	no data
2025/07/07	RECEPTION 101	Wall Prime Paint	no data
2025/07/07	RECEPTION 147	In Wall Insulation	complete
2025/07/07	RECEPTION 147	Overhead Duct Insulation	complete
2025/07/07	RECEPTION 147	Overhead Duct Rough In	no data
2025/07/07	RECEPTION 147	Overhead Plumbing	in progress
2025/07/07	RECEPTION 147	Wall Drywall	complete
2025/07/07	RECEPTION 147	Wall Drywall Finish	complete
2025/07/07	RECEPTION 147	Wall Prime Paint	complete
2025/07/07	RECEPTION 179	In Wall Insulation	complete
2025/07/07	RECEPTION 179	Overhead Duct Insulation	no data
2025/07/07	RECEPTION 179	Overhead Duct Rough In	no data
2025/07/07	RECEPTION 179	Overhead Plumbing	not started
2025/07/07	RECEPTION 179	Wall Drywall	complete
2025/07/07	RECEPTION 179	Wall Drywall Finish	complete
2025/07/07	RECEPTION 179	Wall Prime Paint	complete
2025/07/07	RECORDS 130	In Wall Insulation	no data
2025/07/07	RECORDS 130	Overhead Duct Insulation	no data
2025/07/07	RECORDS 130	Overhead Duct Rough In	no data
2025/07/07	RECORDS 130	Overhead Plumbing	no data
2025/07/07	RECORDS 130	Wall Drywall	no data
2025/07/07	RECORDS 130	Wall Drywall Finish	no data
2025/07/07	RECORDS 130	Wall Prime Paint	no data
2025/07/07	RECORDS STORAGE 133	In Wall Insulation	no data
2025/07/07	RECORDS STORAGE 133	Overhead Duct Insulation	no data

2025/07/07	RECORDS STORAGE 133	Overhead Duct Rough In	no data
2025/07/07	RECORDS STORAGE 133	Overhead Plumbing	no data
2025/07/07	RECORDS STORAGE 133	Wall Drywall	no data
2025/07/07	RECORDS STORAGE 133	Wall Drywall Finish	no data
2025/07/07	RECORDS STORAGE 133	Wall Prime Paint	no data
2025/07/07	RECORDS SUPERVISOR 131	In Wall Insulation	no data
2025/07/07	RECORDS SUPERVISOR 131	Overhead Duct Insulation	no data
2025/07/07	RECORDS SUPERVISOR 131	Overhead Duct Rough In	no data
2025/07/07	RECORDS SUPERVISOR 131	Overhead Plumbing	no data
2025/07/07	RECORDS SUPERVISOR 131	Wall Drywall	no data
2025/07/07	RECORDS SUPERVISOR 131	Wall Drywall Finish	no data
2025/07/07	RECORDS SUPERVISOR 131	Wall Prime Paint	no data
2025/07/07	RECORDS SUPERVISOR 132	In Wall Insulation	no data
2025/07/07	RECORDS SUPERVISOR 132	Overhead Duct Insulation	no data
2025/07/07	RECORDS SUPERVISOR 132	Overhead Duct Rough In	no data
2025/07/07	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/07/07	RECORDS SUPERVISOR 132	Wall Drywall	no data
2025/07/07	RECORDS SUPERVISOR 132	Wall Drywall Finish	no data
2025/07/07	RECORDS SUPERVISOR 132	Wall Prime Paint	no data
2025/07/07	RESTROOM 183	In Wall Insulation	complete
2025/07/07	RESTROOM 183	Overhead Duct Insulation	complete
2025/07/07	RESTROOM 183	Overhead Duct Rough In	complete
2025/07/07	RESTROOM 183	Overhead Plumbing	complete
2025/07/07	RESTROOM 183	Wall Drywall	complete
2025/07/07	RESTROOM 183	Wall Drywall Finish	in progress
2025/07/07	RESTROOM 183	Wall Prime Paint	not started
2025/07/07	Risk Management - 158	In Wall Insulation	complete
2025/07/07	Risk Management - 158	Overhead Duct Insulation	in progress
2025/07/07	Risk Management - 158	Overhead Duct Rough In	in progress
2025/07/07	Risk Management - 158	Overhead Plumbing	complete
2025/07/07	Risk Management - 158	Wall Drywall	complete
2025/07/07	Risk Management - 158	Wall Drywall Finish	complete
2025/07/07	Risk Management - 158	Wall Prime Paint	complete
2025/07/07	SALLY PORT 105	In Wall Insulation	no data
2025/07/07	SALLY PORT 105	Overhead Duct Insulation	no data
2025/07/07	SALLY PORT 105	Overhead Duct Rough In	no data
2025/07/07	SALLY PORT 105	Overhead Plumbing	no data
2025/07/07	SALLY PORT 105	Wall Drywall	no data
2025/07/07	SALLY PORT 105	Wall Drywall Finish	no data
2025/07/07	SALLY PORT 105	Wall Prime Paint	no data
2025/07/07	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/07/07	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/07/07	SANE EXAM ROOM 168	Overhead Duct Rough In	in progress
2025/07/07	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/07/07	SANE EXAM ROOM 168	Wall Drywall	complete
2025/07/07	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/07/07	SANE EXAM ROOM 168	Wall Prime Paint	complete

2025/07/07	SGT 171	In Wall Insulation	no data
2025/07/07	SGT 171	Overhead Duct Insulation	in progress
2025/07/07	SGT 171	Overhead Duct Rough In	in progress
2025/07/07	SGT 171	Overhead Plumbing	in progress
2025/07/07	SGT 171	Wall Drywall	complete
2025/07/07	SGT 171	Wall Drywall Finish	complete
2025/07/07	SGT 171	Wall Prime Paint	complete
2025/07/07	SGT 172	In Wall Insulation	complete
2025/07/07	SGT 172	Overhead Duct Insulation	no data
2025/07/07	SGT 172	Overhead Duct Rough In	in progress
2025/07/07	SGT 172	Overhead Plumbing	in progress
2025/07/07	SGT 172	Wall Drywall	complete
2025/07/07	SGT 172	Wall Drywall Finish	complete
2025/07/07	SGT 172	Wall Prime Paint	complete
2025/07/07	SHIPPING STORAGE 190	In Wall Insulation	complete
2025/07/07	SHIPPING STORAGE 190	Overhead Duct Insulation	no data
2025/07/07	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/07/07	SHIPPING STORAGE 190	Overhead Plumbing	no data
2025/07/07	SHIPPING STORAGE 190	Wall Drywall	complete
2025/07/07	SHIPPING STORAGE 190	Wall Drywall Finish	complete
2025/07/07	SHIPPING STORAGE 190	Wall Prime Paint	complete
2025/07/07	SHOP FORMAN 184	In Wall Insulation	complete
2025/07/07	SHOP FORMAN 184	Overhead Duct Insulation	no data
2025/07/07	SHOP FORMAN 184	Overhead Duct Rough In	no data
2025/07/07	SHOP FORMAN 184	Overhead Plumbing	no data
2025/07/07	SHOP FORMAN 184	Wall Drywall	complete
2025/07/07	SHOP FORMAN 184	Wall Drywall Finish	complete
2025/07/07	SHOP FORMAN 184	Wall Prime Paint	complete
2025/07/07	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/07/07	SOFT INTERVIEW 161	Overhead Duct Insulation	no data
2025/07/07	SOFT INTERVIEW 161	Overhead Duct Rough In	in progress
2025/07/07	SOFT INTERVIEW 161	Overhead Plumbing	complete
2025/07/07	SOFT INTERVIEW 161	Wall Drywall	complete
2025/07/07	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/07/07	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/07/07	SOFT INTERVIEW 162	In Wall Insulation	complete
2025/07/07	SOFT INTERVIEW 162	Overhead Duct Insulation	no data
2025/07/07	SOFT INTERVIEW 162	Overhead Duct Rough In	no data
2025/07/07	SOFT INTERVIEW 162	Overhead Plumbing	complete
2025/07/07	SOFT INTERVIEW 162	Wall Drywall	complete
2025/07/07	SOFT INTERVIEW 162	Wall Drywall Finish	complete
2025/07/07	SOFT INTERVIEW 162	Wall Prime Paint	complete
2025/07/07	SPECIAL OPERATION LT 143	In Wall Insulation	no data
2025/07/07	SPECIAL OPERATION LT 143	Overhead Duct Insulation	no data
2025/07/07	SPECIAL OPERATION LT 143	Overhead Duct Rough In	no data
2025/07/07	SPECIAL OPERATION LT 143	Overhead Plumbing	no data
2025/07/07	SPECIAL OPERATION LT 143	Wall Drywall	complete
2025/07/07	SPECIAL OPERATION LT 143	Wall Drywall Finish	complete
2025/07/07	SPECIAL OPERATION LT 143	Wall Prime Paint	complete



2025/07/07	STAIR A	In Wall Insulation	no data
2025/07/07	STAIR A	Overhead Duct Insulation	no data
2025/07/07	STAIR A	Overhead Duct Rough In	no data
2025/07/07	STAIR A	Overhead Plumbing	in progress
2025/07/07	STAIR A	Wall Drywall	not started
2025/07/07	STAIR A	Wall Drywall Finish	not started
2025/07/07	STAIR A	Wall Prime Paint	not started
2025/07/07	STORAGE 104	In Wall Insulation	no data
2025/07/07	STORAGE 104	Overhead Duct Insulation	no data
2025/07/07	STORAGE 104	Overhead Duct Rough In	no data
2025/07/07	STORAGE 104	Overhead Plumbing	not started
2025/07/07	STORAGE 104	Wall Drywall	complete
2025/07/07	STORAGE 104	Wall Drywall Finish	complete
2025/07/07	STORAGE 104	Wall Prime Paint	complete
2025/07/07	STORAGE 127	In Wall Insulation	no data
2025/07/07	STORAGE 127	Overhead Duct Insulation	no data
2025/07/07	STORAGE 127	Overhead Duct Rough In	no data
2025/07/07	STORAGE 127	Overhead Plumbing	no data
2025/07/07	STORAGE 127	Wall Drywall	complete
2025/07/07	STORAGE 127	Wall Drywall Finish	complete
2025/07/07	STORAGE 127	Wall Prime Paint	complete
2025/07/07	STUDIO 126	In Wall Insulation	no data
2025/07/07	STUDIO 126	Overhead Duct Insulation	no data
2025/07/07	STUDIO 126	Overhead Duct Rough In	no data
2025/07/07	STUDIO 126	Overhead Plumbing	no data
2025/07/07	STUDIO 126	Wall Drywall	no data
2025/07/07	STUDIO 126	Wall Drywall Finish	no data
2025/07/07	STUDIO 126	Wall Prime Paint	no data
2025/07/07	SUPERVISOR 129	In Wall Insulation	complete
2025/07/07	SUPERVISOR 129	Overhead Duct Insulation	in progress
2025/07/07	SUPERVISOR 129	Overhead Duct Rough In	in progress
2025/07/07	SUPERVISOR 129	Overhead Plumbing	not started
2025/07/07	SUPERVISOR 129	Wall Drywall	complete
2025/07/07	SUPERVISOR 129	Wall Drywall Finish	complete
2025/07/07	SUPERVISOR 129	Wall Prime Paint	complete
2025/07/07	Storage 164	In Wall Insulation	complete
2025/07/07	Storage 164	Overhead Duct Insulation	in progress
2025/07/07	Storage 164	Overhead Duct Rough In	in progress
2025/07/07	Storage 164	Overhead Plumbing	not started
2025/07/07	Storage 164	Wall Drywall	complete
2025/07/07	Storage 164	Wall Drywall Finish	complete
2025/07/07	Storage 164	Wall Prime Paint	complete
2025/07/07	Storage 177	In Wall Insulation	complete
2025/07/07	Storage 177	Overhead Duct Insulation	in progress
2025/07/07	Storage 177	Overhead Duct Rough In	in progress
2025/07/07	Storage 177	Overhead Plumbing	not started
2025/07/07	Storage 177	Wall Drywall	complete
2025/07/07	Storage 177	Wall Drywall Finish	complete
2025/07/07	Storage 177	Wall Prime Paint	complete
2025/07/07	TECHNICAL SURVEILLANCE 188	In Wall Insulation	complete
2025/07/07	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	no data
2025/07/07	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	

no data

2025/07/07	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	no data
2025/07/07	TECHNICAL SURVEILLANCE 188	Wall Drywall	complete
2025/07/07	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	in progress
2025/07/07	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	not started
2025/07/07	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/07/07	TRAFFIC SERGEANT 141	Overhead Duct Insulation	in progress
2025/07/07	TRAFFIC SERGEANT 141	Overhead Duct Rough In	no data
2025/07/07	TRAFFIC SERGEANT 141	Overhead Plumbing	in progress
2025/07/07	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/07/07	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/07/07	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/07/07	TRIAGE/RECEPTION 134	In Wall Insulation	no data
2025/07/07	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/07/07	TRIAGE/RECEPTION 134	Overhead Duct Rough In	in progress
2025/07/07	TRIAGE/RECEPTION 134	Overhead Plumbing	not started
2025/07/07	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/07/07	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/07/07	TRIAGE/RECEPTION 134	Wall Prime Paint	in progress
2025/07/07	TST WORKSHOP 187	In Wall Insulation	complete
2025/07/07	TST WORKSHOP 187	Overhead Duct Insulation	no data
2025/07/07	TST WORKSHOP 187	Overhead Duct Rough In	no data
2025/07/07	TST WORKSHOP 187	Overhead Plumbing	no data
2025/07/07	TST WORKSHOP 187	Wall Drywall	complete
2025/07/07	TST WORKSHOP 187	Wall Drywall Finish	in progress
2025/07/07	TST WORKSHOP 187	Wall Prime Paint	in progress
2025/07/07	UNISEX RESTROOM 169	In Wall Insulation	complete
2025/07/07	UNISEX RESTROOM 169	Overhead Duct Insulation	no data
2025/07/07	UNISEX RESTROOM 169	Overhead Duct Rough In	complete
2025/07/07	UNISEX RESTROOM 169	Overhead Plumbing	no data
2025/07/07	UNISEX RESTROOM 169	Wall Drywall	complete
2025/07/07	UNISEX RESTROOM 169	Wall Drywall Finish	in progress
2025/07/07	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/07/07	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	in progress
2025/07/07	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	not started
2025/07/07	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	no data
2025/07/07	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete
2025/07/07	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	complete
2025/07/07	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	complete
2025/07/07	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	complete
2025/07/07	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	no data

2025/07/07	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	no data
2025/07/07	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	no data
2025/07/07	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	in progress
2025/07/07	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/07/07	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/07/07	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/07/07	WAITING/LOBBY 100	In Wall Insulation	not started
2025/07/07	WAITING/LOBBY 100	Overhead Duct Insulation	no data
2025/07/07	WAITING/LOBBY 100	Overhead Duct Rough In	no data
2025/07/07	WAITING/LOBBY 100	Overhead Plumbing	not started
2025/07/07	WAITING/LOBBY 100	Wall Drywall	not started
2025/07/07	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/07/07	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/07/07	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/07/07	WOMENS RESTROOM 113	Overhead Duct Insulation	no data
2025/07/07	WOMENS RESTROOM 113	Overhead Duct Rough In	in progress
2025/07/07	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/07/07	WOMENS RESTROOM 113	Wall Drywall	complete
2025/07/07	WOMENS RESTROOM 113	Wall Drywall Finish	in progress
2025/07/07	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/07/17	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/07/17	ADMIN ASSISTANT 125	Overhead Duct Insulation	in progress
2025/07/17	ADMIN ASSISTANT 125	Overhead Duct Rough In	no data
2025/07/17	ADMIN ASSISTANT 125	Overhead Plumbing	not started
2025/07/17	ADMIN ASSISTANT 125	Wall Drywall	complete
2025/07/17	ADMIN ASSISTANT 125	Wall Drywall Finish	complete
2025/07/17	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/07/17	AV ROOM 103	In Wall Insulation	no data
2025/07/17	AV ROOM 103	Overhead Duct Insulation	complete
2025/07/17	AV ROOM 103	Overhead Duct Rough In	no data
2025/07/17	AV ROOM 103	Overhead Plumbing	not started
2025/07/17	AV ROOM 103	Wall Drywall	complete
2025/07/17	AV ROOM 103	Wall Drywall Finish	complete
2025/07/17	AV ROOM 103	Wall Prime Paint	complete
2025/07/17	BREAK ROOM CONFERENCE 182	In Wall Insulation	no data
2025/07/17	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	no data
2025/07/17	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	no data
2025/07/17	BREAK ROOM CONFERENCE 182	Overhead Plumbing	no data
2025/07/17	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/07/17	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	complete
2025/07/17	BREAK ROOM CONFERENCE 182	Wall Prime Paint	complete
2025/07/17	Background-159	In Wall Insulation	complete
2025/07/17	Background-159	Overhead Duct Insulation	complete

2025/07/17	Background-159	Overhead Duct Rough In	in progress
2025/07/17	Background-159	Overhead Plumbing	not started
2025/07/17	Background-159	Wall Drywall	complete
2025/07/17	Background-159	Wall Drywall Finish	complete
2025/07/17	Background-159	Wall Prime Paint	complete
2025/07/17	CENTRAL BREAKROOM 145	In Wall Insulation	in progress
2025/07/17	CENTRAL BREAKROOM 145	Overhead Duct Insulation	in progress
2025/07/17	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/07/17	CENTRAL BREAKROOM 145	Overhead Plumbing	in progress
2025/07/17	CENTRAL BREAKROOM 145	Wall Drywall	in progress
2025/07/17	CENTRAL BREAKROOM 145	Wall Drywall Finish	in progress
2025/07/17	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/07/17	COLD CASE 175	In Wall Insulation	no data
2025/07/17	COLD CASE 175	Overhead Duct Insulation	complete
2025/07/17	COLD CASE 175	Overhead Duct Rough In	no data
2025/07/17	COLD CASE 175	Overhead Plumbing	in progress
2025/07/17	COLD CASE 175	Wall Drywall	complete
2025/07/17	COLD CASE 175	Wall Drywall Finish	complete
2025/07/17	COLD CASE 175	Wall Prime Paint	complete
2025/07/17	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/07/17	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	complete
2025/07/17	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	no data
2025/07/17	COMMUNITY AFFAIRS 124	Overhead Plumbing	no data
2025/07/17	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/07/17	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/07/17	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/07/17	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/07/17	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	in progress
2025/07/17	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	no data
2025/07/17	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	not started
2025/07/17	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete
2025/07/17	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	complete
2025/07/17	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	complete
2025/07/17	CONFERENCE ROOM 153	In Wall Insulation	complete
2025/07/17	CONFERENCE ROOM 153	Overhead Duct Insulation	in progress
2025/07/17	CONFERENCE ROOM 153	Overhead Duct Rough In	in progress
2025/07/17	CONFERENCE ROOM 153	Overhead Plumbing	not started
2025/07/17	CONFERENCE ROOM 153	Wall Drywall	complete
2025/07/17	CONFERENCE ROOM 153	Wall Drywall Finish	complete
2025/07/17	CONFERENCE ROOM 153	Wall Prime Paint	complete

2025/07/17	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/07/17	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	in progress
2025/07/17	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	no data
2025/07/17	CONFERENCE/WAR ROOM 163	Overhead Plumbing	not started
2025/07/17	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/07/17	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete
2025/07/17	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/07/17	COPY 176	In Wall Insulation	complete
2025/07/17	COPY 176	Overhead Duct Insulation	complete
2025/07/17	COPY 176	Overhead Duct Rough In	in progress
2025/07/17	COPY 176	Overhead Plumbing	not started
2025/07/17	COPY 176	Wall Drywall	complete
2025/07/17	COPY 176	Wall Drywall Finish	complete
2025/07/17	COPY 176	Wall Prime Paint	complete
2025/07/17	COPY/MAIL ROOM 114	In Wall Insulation	complete
2025/07/17	COPY/MAIL ROOM 114	Overhead Duct Insulation	no data
2025/07/17	COPY/MAIL ROOM 114	Overhead Duct Rough In	no data
2025/07/17	COPY/MAIL ROOM 114	Overhead Plumbing	in progress
2025/07/17	COPY/MAIL ROOM 114	Wall Drywall	complete
2025/07/17	COPY/MAIL ROOM 114	Wall Drywall Finish	complete
2025/07/17	COPY/MAIL ROOM 114	Wall Prime Paint	complete
2025/07/17	CORRIDOR 107	In Wall Insulation	complete
2025/07/17	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/07/17	CORRIDOR 107	Overhead Duct Rough In	in progress
2025/07/17	CORRIDOR 107	Overhead Plumbing	in progress
2025/07/17	CORRIDOR 107	Wall Drywall	complete
2025/07/17	CORRIDOR 107	Wall Drywall Finish	complete
2025/07/17	CORRIDOR 107	Wall Prime Paint	complete
2025/07/17	CORRIDOR 108	In Wall Insulation	complete
2025/07/17	CORRIDOR 108	In Wall Insulation	no data
2025/07/17	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/07/17	CORRIDOR 108	Overhead Duct Insulation	no data
2025/07/17	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/07/17	CORRIDOR 108	Overhead Duct Rough In	no data
2025/07/17	CORRIDOR 108	Overhead Plumbing	in progress
2025/07/17	CORRIDOR 108	Overhead Plumbing	no data
2025/07/17	CORRIDOR 108	Wall Drywall	complete
2025/07/17	CORRIDOR 108	Wall Drywall	complete
2025/07/17	CORRIDOR 108	Wall Drywall Finish	complete
2025/07/17	CORRIDOR 108	Wall Drywall Finish	complete
2025/07/17	CORRIDOR 108	Wall Prime Paint	complete
2025/07/17	CORRIDOR 108	Wall Prime Paint	in progress
2025/07/17	CORRIDOR 109	In Wall Insulation	complete
2025/07/17	CORRIDOR 109	Overhead Duct Insulation	in progress
2025/07/17	CORRIDOR 109	Overhead Duct Rough In	in progress
2025/07/17	CORRIDOR 109	Overhead Plumbing	in progress
2025/07/17	CORRIDOR 109	Wall Drywall	complete
2025/07/17	CORRIDOR 109	Wall Drywall Finish	complete
2025/07/17	CORRIDOR 109	Wall Prime Paint	complete
2025/07/17	CORRIDOR 110	In Wall Insulation	no data

2025/07/17	CORRIDOR 110	In Wall Insulation	no data
2025/07/17	CORRIDOR 110	Overhead Duct Insulation	no data
2025/07/17	CORRIDOR 110	Overhead Duct Insulation	no data
2025/07/17	CORRIDOR 110	Overhead Duct Rough In	no data
2025/07/17	CORRIDOR 110	Overhead Duct Rough In	no data
2025/07/17	CORRIDOR 110	Overhead Plumbing	no data
2025/07/17	CORRIDOR 110	Overhead Plumbing	in progress
2025/07/17	CORRIDOR 110	Wall Drywall	complete
2025/07/17	CORRIDOR 110	Wall Drywall	complete
2025/07/17	CORRIDOR 110	Wall Drywall Finish	complete
2025/07/17	CORRIDOR 110	Wall Drywall Finish	complete
2025/07/17	CORRIDOR 110	Wall Prime Paint	complete
2025/07/17	CORRIDOR 110	Wall Prime Paint	in progress
2025/07/17	CORRIDOR 181	In Wall Insulation	complete
2025/07/17	CORRIDOR 181	Overhead Duct Insulation	in progress
2025/07/17	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/07/17	CORRIDOR 181	Overhead Plumbing	in progress
2025/07/17	CORRIDOR 181	Wall Drywall	complete
2025/07/17	CORRIDOR 181	Wall Drywall Finish	complete
2025/07/17	CORRIDOR 181	Wall Prime Paint	complete
2025/07/17	CORRIDOR144	In Wall Insulation	no data
2025/07/17	CORRIDOR144	Overhead Duct Insulation	in progress
2025/07/17	CORRIDOR144	Overhead Duct Rough In	no data
2025/07/17	CORRIDOR144	Overhead Plumbing	no data
2025/07/17	CORRIDOR144	Wall Drywall	complete
2025/07/17	CORRIDOR144	Wall Drywall Finish	complete
2025/07/17	CORRIDOR144	Wall Prime Paint	complete
2025/07/17	CPL 173	In Wall Insulation	complete
2025/07/17	CPL 173	Overhead Duct Insulation	complete
2025/07/17	CPL 173	Overhead Duct Rough In	in progress
2025/07/17	CPL 173	Overhead Plumbing	in progress
2025/07/17	CPL 173	Wall Drywall	complete
2025/07/17	CPL 173	Wall Drywall Finish	complete
2025/07/17	CPL 173	Wall Prime Paint	complete
2025/07/17	CPL 174	In Wall Insulation	complete
2025/07/17	CPL 174	Overhead Duct Insulation	in progress
2025/07/17	CPL 174	Overhead Duct Rough In	no data
2025/07/17	CPL 174	Overhead Plumbing	no data
2025/07/17	CPL 174	Wall Drywall	complete
2025/07/17	CPL 174	Wall Drywall Finish	complete
2025/07/17	CPL 174	Wall Prime Paint	in progress
2025/07/17	DRY STORAGE 146	In Wall Insulation	complete
2025/07/17	DRY STORAGE 146	Overhead Duct Insulation	not started
2025/07/17	DRY STORAGE 146	Overhead Duct Rough In	in progress
2025/07/17	DRY STORAGE 146	Overhead Plumbing	not started
2025/07/17	DRY STORAGE 146	Wall Drywall	complete
2025/07/17	DRY STORAGE 146	Wall Drywall Finish	complete
2025/07/17	DRY STORAGE 146	Wall Prime Paint	in progress
2025/07/17	FIRE RISER 178	In Wall Insulation	no data
2025/07/17	FIRE RISER 178	Overhead Duct Insulation	no data
2025/07/17	FIRE RISER 178	Overhead Duct Rough In	no data
2025/07/17	FIRE RISER 178	Overhead Plumbing	no data
2025/07/17	FIRE RISER 178	Wall Drywall	no data

2025/07/17	FIRE RISER 178	Wall Drywall Finish	no data
2025/07/17	FIRE RISER 178	Wall Prime Paint	no data
2025/07/17	GREETING ROOM 106	In Wall Insulation	no data
2025/07/17	GREETING ROOM 106	Overhead Duct Insulation	complete
2025/07/17	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/07/17	GREETING ROOM 106	Overhead Plumbing	not started
2025/07/17	GREETING ROOM 106	Wall Drywall	complete
2025/07/17	GREETING ROOM 106	Wall Drywall Finish	complete
2025/07/17	GREETING ROOM 106	Wall Prime Paint	complete
2025/07/17	HR 149	In Wall Insulation	complete
2025/07/17	HR 149	Overhead Duct Insulation	complete
2025/07/17	HR 149	Overhead Duct Rough In	in progress
2025/07/17	HR 149	Overhead Plumbing	not started
2025/07/17	HR 149	Wall Drywall	complete
2025/07/17	HR 149	Wall Drywall Finish	complete
2025/07/17	HR 149	Wall Prime Paint	complete
2025/07/17	HR 150	In Wall Insulation	complete
2025/07/17	HR 150	Overhead Duct Insulation	complete
2025/07/17	HR 150	Overhead Duct Rough In	no data
2025/07/17	HR 150	Overhead Plumbing	not started
2025/07/17	HR 150	Wall Drywall	complete
2025/07/17	HR 150	Wall Drywall Finish	complete
2025/07/17	HR 150	Wall Prime Paint	complete
2025/07/17	HR 151	In Wall Insulation	complete
2025/07/17	HR 151	Overhead Duct Insulation	in progress
2025/07/17	HR 151	Overhead Duct Rough In	in progress
2025/07/17	HR 151	Overhead Plumbing	complete
2025/07/17	HR 151	Wall Drywall	complete
2025/07/17	HR 151	Wall Drywall Finish	complete
2025/07/17	HR 151	Wall Prime Paint	complete
2025/07/17	HR 154	In Wall Insulation	complete
2025/07/17	HR 154	Overhead Duct Insulation	complete
2025/07/17	HR 154	Overhead Duct Rough In	in progress
2025/07/17	HR 154	Overhead Plumbing	in progress
2025/07/17	HR 154	Wall Drywall	complete
2025/07/17	HR 154	Wall Drywall Finish	complete
2025/07/17	HR 154	Wall Prime Paint	complete
2025/07/17	HR 155	In Wall Insulation	complete
2025/07/17	HR 155	Overhead Duct Insulation	complete
2025/07/17	HR 155	Overhead Duct Rough In	in progress
2025/07/17	HR 155	Overhead Plumbing	not started
2025/07/17	HR 155	Wall Drywall	complete
2025/07/17	HR 155	Wall Drywall Finish	complete
2025/07/17	HR 155	Wall Prime Paint	complete
2025/07/17	HR 156	In Wall Insulation	complete
2025/07/17	HR 156	Overhead Duct Insulation	complete
2025/07/17	HR 156	Overhead Duct Rough In	in progress
2025/07/17	HR 156	Overhead Plumbing	not started
2025/07/17	HR 156	Wall Drywall	complete
2025/07/17	HR 156	Wall Drywall Finish	complete
2025/07/17	HR 156	Wall Prime Paint	complete
2025/07/17	HR 157	In Wall Insulation	complete
2025/07/17	HR 157	Overhead Duct Insulation	complete

2025/07/17	HR 157	Overhead Duct Rough In	in progress
2025/07/17	HR 157	Overhead Plumbing	in progress
2025/07/17	HR 157	Wall Drywall	complete
2025/07/17	HR 157	Wall Drywall Finish	complete
2025/07/17	HR 157	Wall Prime Paint	complete
2025/07/17	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/07/17	HUMAN RESOURCES 148	Overhead Duct Insulation	in progress
2025/07/17	HUMAN RESOURCES 148	Overhead Duct Rough In	no data
2025/07/17	HUMAN RESOURCES 148	Overhead Plumbing	no data
2025/07/17	HUMAN RESOURCES 148	Wall Drywall	complete
2025/07/17	HUMAN RESOURCES 148	Wall Drywall Finish	complete
2025/07/17	HUMAN RESOURCES 148	Wall Prime Paint	complete
2025/07/17	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/07/17	INTERNAL AFFAIRS 119	Overhead Duct Insulation	complete
2025/07/17	INTERNAL AFFAIRS 119	Overhead Duct Rough In	in progress
2025/07/17	INTERNAL AFFAIRS 119	Overhead Plumbing	complete
2025/07/17	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/07/17	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/07/17	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/07/17	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/07/17	INTERNAL AFFAIRS 120	Overhead Duct Insulation	complete
2025/07/17	INTERNAL AFFAIRS 120	Overhead Duct Rough In	in progress
2025/07/17	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/07/17	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/07/17	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/07/17	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/07/17	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/07/17	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	in progress
2025/07/17	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	in progress
2025/07/17	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	complete
2025/07/17	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/07/17	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/07/17	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/07/17	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	no data
2025/07/17	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	complete
2025/07/17	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	no data
2025/07/17	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	complete
2025/07/17	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/07/17	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	



complete  
2025/07/17 | INTERVIEW/ REVIEW ROOM 121 | Wall Prime Paint | complete  
2025/07/17 | INVESTIGATIONS / MAJOR CASE 167 | In Wall Insulation | no data  
2025/07/17 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Insulation | in progress  
2025/07/17 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Rough In | in progress  
2025/07/17 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Plumbing | in progress  
2025/07/17 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall | complete  
2025/07/17 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall Finish | complete  
2025/07/17 | INVESTIGATIONS / MAJOR CASE 167 | Wall Prime Paint | complete  
2025/07/17 | IT 115 | In Wall Insulation | complete  
2025/07/17 | IT 115 | Overhead Duct Insulation | no data  
2025/07/17 | IT 115 | Overhead Duct Rough In | no data  
2025/07/17 | IT 115 | Overhead Plumbing | no data  
2025/07/17 | IT 115 | Wall Drywall | complete  
2025/07/17 | IT 115 | Wall Drywall Finish | complete  
2025/07/17 | IT 115 | Wall Prime Paint | complete  
2025/07/17 | IT 135 | In Wall Insulation | complete  
2025/07/17 | IT 135 | Overhead Duct Insulation | in progress  
2025/07/17 | IT 135 | Overhead Duct Rough In | in progress  
2025/07/17 | IT 135 | Overhead Plumbing | complete  
2025/07/17 | IT 135 | Wall Drywall | complete  
2025/07/17 | IT 135 | Wall Drywall Finish | complete  
2025/07/17 | IT 135 | Wall Prime Paint | complete  
2025/07/17 | IT MANAGER 136 | In Wall Insulation | no data  
2025/07/17 | IT MANAGER 136 | Overhead Duct Insulation | no data  
2025/07/17 | IT MANAGER 136 | Overhead Duct Rough In | no data  
2025/07/17 | IT MANAGER 136 | Overhead Plumbing | complete  
2025/07/17 | IT MANAGER 136 | Wall Drywall | complete  
2025/07/17 | IT MANAGER 136 | Wall Drywall Finish | complete  
2025/07/17 | IT MANAGER 136 | Wall Prime Paint | complete  
2025/07/17 | IT MANAGER 137 | In Wall Insulation | no data  
2025/07/17 | IT MANAGER 137 | Overhead Duct Insulation | complete  
2025/07/17 | IT MANAGER 137 | Overhead Duct Rough In | no data  
2025/07/17 | IT MANAGER 137 | Overhead Plumbing | no data  
2025/07/17 | IT MANAGER 137 | Wall Drywall | complete  
2025/07/17 | IT MANAGER 137 | Wall Drywall Finish | complete  
2025/07/17 | IT MANAGER 137 | Wall Prime Paint | complete  
2025/07/17 | JUVENILE INTERVIEW 165 | In Wall Insulation | complete  
2025/07/17 | JUVENILE INTERVIEW 165 | Overhead Duct Insulation | no data  
2025/07/17 | JUVENILE INTERVIEW 165 | Overhead Duct Rough In | in progress  
2025/07/17 | JUVENILE INTERVIEW 165 | Overhead Plumbing | no data  
2025/07/17 | JUVENILE INTERVIEW 165 | Wall Drywall | complete  
2025/07/17 | JUVENILE INTERVIEW 165 | Wall Drywall Finish | complete  
2025/07/17 | JUVENILE INTERVIEW 165 | Wall Prime Paint | complete

2025/07/17	JUVENILE INTERVIEWERS 166	In Wall Insulation	no data
2025/07/17	JUVENILE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/07/17	JUVENILE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/07/17	JUVENILE INTERVIEWERS 166	Overhead Plumbing	no data
2025/07/17	JUVENILE INTERVIEWERS 166	Wall Drywall	complete
2025/07/17	JUVENILE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/07/17	JUVENILE INTERVIEWERS 166	Wall Prime Paint	complete
2025/07/17	KEY ROOM 185	In Wall Insulation	complete
2025/07/17	KEY ROOM 185	Overhead Duct Insulation	in progress
2025/07/17	KEY ROOM 185	Overhead Duct Rough In	no data
2025/07/17	KEY ROOM 185	Overhead Plumbing	not started
2025/07/17	KEY ROOM 185	Wall Drywall	complete
2025/07/17	KEY ROOM 185	Wall Drywall Finish	complete
2025/07/17	KEY ROOM 185	Wall Prime Paint	complete
2025/07/17	LT 170	In Wall Insulation	complete
2025/07/17	LT 170	Overhead Duct Insulation	complete
2025/07/17	LT 170	Overhead Duct Rough In	in progress
2025/07/17	LT 170	Overhead Plumbing	not started
2025/07/17	LT 170	Wall Drywall	complete
2025/07/17	LT 170	Wall Drywall Finish	complete
2025/07/17	LT 170	Wall Prime Paint	complete
2025/07/17	MACHINE ROOM 191	In Wall Insulation	no data
2025/07/17	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/07/17	MACHINE ROOM 191	Overhead Duct Rough In	no data
2025/07/17	MACHINE ROOM 191	Overhead Plumbing	no data
2025/07/17	MACHINE ROOM 191	Wall Drywall	complete
2025/07/17	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/07/17	MACHINE ROOM 191	Wall Prime Paint	complete
2025/07/17	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/07/17	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/07/17	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/07/17	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/07/17	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/07/17	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/07/17	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/07/17	MAIN JANITORIAL111	In Wall Insulation	no data
2025/07/17	MAIN JANITORIAL111	Overhead Duct Insulation	no data
2025/07/17	MAIN JANITORIAL111	Overhead Duct Rough In	complete
2025/07/17	MAIN JANITORIAL111	Overhead Plumbing	no data
2025/07/17	MAIN JANITORIAL111	Wall Drywall	complete
2025/07/17	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/07/17	MAIN JANITORIAL111	Wall Prime Paint	complete
2025/07/17	MARINE SERGEANT 142	In Wall Insulation	complete
2025/07/17	MARINE SERGEANT 142	Overhead Duct Insulation	in progress

2025/07/17	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/07/17	MARINE SERGEANT 142	Overhead Plumbing	in progress
2025/07/17	MARINE SERGEANT 142	Wall Drywall	complete
2025/07/17	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/07/17	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/07/17	MECHANICAL 192	In Wall Insulation	no data
2025/07/17	MECHANICAL 192	Overhead Duct Insulation	not started
2025/07/17	MECHANICAL 192	Overhead Duct Rough In	in progress
2025/07/17	MECHANICAL 192	Overhead Plumbing	in progress
2025/07/17	MECHANICAL 192	Wall Drywall	complete
2025/07/17	MECHANICAL 192	Wall Drywall Finish	complete
2025/07/17	MECHANICAL 192	Wall Prime Paint	complete
2025/07/17	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/07/17	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
2025/07/17	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/07/17	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/07/17	MECHANICAL ROOM 122	Wall Drywall	complete
2025/07/17	MECHANICAL ROOM 122	Wall Drywall Finish	complete
2025/07/17	MECHANICAL ROOM 122	Wall Prime Paint	complete
2025/07/17	MENS RESTROOM 112	In Wall Insulation	no data
2025/07/17	MENS RESTROOM 112	Overhead Duct Insulation	no data
2025/07/17	MENS RESTROOM 112	Overhead Duct Rough In	no data
2025/07/17	MENS RESTROOM 112	Overhead Plumbing	no data
2025/07/17	MENS RESTROOM 112	Wall Drywall	no data
2025/07/17	MENS RESTROOM 112	Wall Drywall Finish	no data
2025/07/17	MENS RESTROOM 112	Wall Prime Paint	no data
2025/07/17	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
2025/07/17	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/07/17	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	no data
2025/07/17	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	no data
2025/07/17	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/07/17	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/07/17	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/07/17	MIS SHREDDING 117	In Wall Insulation	complete
2025/07/17	MIS SHREDDING 117	Overhead Duct Insulation	in progress
2025/07/17	MIS SHREDDING 117	Overhead Duct Rough In	in progress
2025/07/17	MIS SHREDDING 117	Overhead Plumbing	in progress
2025/07/17	MIS SHREDDING 117	Wall Drywall	complete
2025/07/17	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/07/17	MIS SHREDDING 117	Wall Prime Paint	complete
2025/07/17	OFFICE 128	In Wall Insulation	no data
2025/07/17	OFFICE 128	Overhead Duct Insulation	no data
2025/07/17	OFFICE 128	Overhead Duct Rough In	no data
2025/07/17	OFFICE 128	Overhead Plumbing	no data
2025/07/17	OFFICE 128	Wall Drywall	complete
2025/07/17	OFFICE 128	Wall Drywall Finish	complete

2025/07/17	OFFICE 128	Wall Prime Paint	complete
2025/07/17	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	no data
2025/07/17	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	no data
2025/07/17	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	no data
2025/07/17	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	in progress
2025/07/17	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/07/17	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/07/17	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	complete
2025/07/17	PARTS STORAGE 189	In Wall Insulation	no data
2025/07/17	PARTS STORAGE 189	Overhead Duct Insulation	no data
2025/07/17	PARTS STORAGE 189	Overhead Duct Rough In	no data
2025/07/17	PARTS STORAGE 189	Overhead Plumbing	no data
2025/07/17	PARTS STORAGE 189	Wall Drywall	complete
2025/07/17	PARTS STORAGE 189	Wall Drywall Finish	complete
2025/07/17	PARTS STORAGE 189	Wall Prime Paint	not started
2025/07/17	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/07/17	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/07/17	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/07/17	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/07/17	PUBLIC RESTROOM 106	Wall Drywall	no data
2025/07/17	PUBLIC RESTROOM 106	Wall Drywall Finish	no data
2025/07/17	PUBLIC RESTROOM 106	Wall Prime Paint	no data
2025/07/17	Polygraph 152	In Wall Insulation	complete
2025/07/17	Polygraph 152	Overhead Duct Insulation	in progress
2025/07/17	Polygraph 152	Overhead Duct Rough In	in progress
2025/07/17	Polygraph 152	Overhead Plumbing	not started
2025/07/17	Polygraph 152	Wall Drywall	complete
2025/07/17	Polygraph 152	Wall Drywall Finish	complete
2025/07/17	Polygraph 152	Wall Prime Paint	complete
2025/07/17	RECEPTION 101	In Wall Insulation	no data
2025/07/17	RECEPTION 101	Overhead Duct Insulation	no data
2025/07/17	RECEPTION 101	Overhead Duct Rough In	no data
2025/07/17	RECEPTION 101	Overhead Plumbing	no data
2025/07/17	RECEPTION 101	Wall Drywall	no data
2025/07/17	RECEPTION 101	Wall Drywall Finish	no data
2025/07/17	RECEPTION 101	Wall Prime Paint	no data
2025/07/17	RECEPTION 147	In Wall Insulation	complete
2025/07/17	RECEPTION 147	Overhead Duct Insulation	complete
2025/07/17	RECEPTION 147	Overhead Duct Rough In	no data
2025/07/17	RECEPTION 147	Overhead Plumbing	in progress
2025/07/17	RECEPTION 147	Wall Drywall	complete
2025/07/17	RECEPTION 147	Wall Drywall Finish	complete
2025/07/17	RECEPTION 147	Wall Prime Paint	complete
2025/07/17	RECEPTION 179	In Wall Insulation	complete
2025/07/17	RECEPTION 179	Overhead Duct Insulation	in progress
2025/07/17	RECEPTION 179	Overhead Duct Rough In	no data

2025/07/17	RECEPTION 179	Overhead Plumbing	not started
2025/07/17	RECEPTION 179	Wall Drywall	complete
2025/07/17	RECEPTION 179	Wall Drywall Finish	complete
2025/07/17	RECEPTION 179	Wall Prime Paint	complete
2025/07/17	RECORDS 130	In Wall Insulation	no data
2025/07/17	RECORDS 130	Overhead Duct Insulation	in progress
2025/07/17	RECORDS 130	Overhead Duct Rough In	no data
2025/07/17	RECORDS 130	Overhead Plumbing	in progress
2025/07/17	RECORDS 130	Wall Drywall	complete
2025/07/17	RECORDS 130	Wall Drywall Finish	complete
2025/07/17	RECORDS 130	Wall Prime Paint	complete
2025/07/17	RECORDS STORAGE 133	In Wall Insulation	complete
2025/07/17	RECORDS STORAGE 133	Overhead Duct Insulation	in progress
2025/07/17	RECORDS STORAGE 133	Overhead Duct Rough In	in progress
2025/07/17	RECORDS STORAGE 133	Overhead Plumbing	in progress
2025/07/17	RECORDS STORAGE 133	Wall Drywall	complete
2025/07/17	RECORDS STORAGE 133	Wall Drywall Finish	complete
2025/07/17	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/07/17	RECORDS SUPERVISOR 131	In Wall Insulation	no data
2025/07/17	RECORDS SUPERVISOR 131	Overhead Duct Insulation	complete
2025/07/17	RECORDS SUPERVISOR 131	Overhead Duct Rough In	no data
2025/07/17	RECORDS SUPERVISOR 131	Overhead Plumbing	not started
2025/07/17	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/07/17	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/07/17	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/07/17	RECORDS SUPERVISOR 132	In Wall Insulation	no data
2025/07/17	RECORDS SUPERVISOR 132	Overhead Duct Insulation	complete
2025/07/17	RECORDS SUPERVISOR 132	Overhead Duct Rough In	no data
2025/07/17	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/07/17	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/07/17	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/07/17	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/07/17	RESTROOM 183	In Wall Insulation	no data
2025/07/17	RESTROOM 183	Overhead Duct Insulation	no data
2025/07/17	RESTROOM 183	Overhead Duct Rough In	no data
2025/07/17	RESTROOM 183	Overhead Plumbing	no data
2025/07/17	RESTROOM 183	Wall Drywall	no data
2025/07/17	RESTROOM 183	Wall Drywall Finish	no data
2025/07/17	RESTROOM 183	Wall Prime Paint	no data
2025/07/17	Risk Management - 158	In Wall Insulation	complete
2025/07/17	Risk Management - 158	Overhead Duct Insulation	complete
2025/07/17	Risk Management - 158	Overhead Duct Rough In	in progress
2025/07/17	Risk Management - 158	Overhead Plumbing	complete
2025/07/17	Risk Management - 158	Wall Drywall	complete
2025/07/17	Risk Management - 158	Wall Drywall Finish	complete

2025/07/17	Risk Management – 158	Wall Prime Paint	complete
2025/07/17	SALLY PORT 105	In Wall Insulation	no data
2025/07/17	SALLY PORT 105	Overhead Duct Insulation	no data
2025/07/17	SALLY PORT 105	Overhead Duct Rough In	no data
2025/07/17	SALLY PORT 105	Overhead Plumbing	no data
2025/07/17	SALLY PORT 105	Wall Drywall	no data
2025/07/17	SALLY PORT 105	Wall Drywall Finish	no data
2025/07/17	SALLY PORT 105	Wall Prime Paint	no data
2025/07/17	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/07/17	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/07/17	SANE EXAM ROOM 168	Overhead Duct Rough In	complete
2025/07/17	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/07/17	SANE EXAM ROOM 168	Wall Drywall	complete
2025/07/17	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/07/17	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/07/17	SGT 171	In Wall Insulation	no data
2025/07/17	SGT 171	Overhead Duct Insulation	in progress
2025/07/17	SGT 171	Overhead Duct Rough In	in progress
2025/07/17	SGT 171	Overhead Plumbing	in progress
2025/07/17	SGT 171	Wall Drywall	complete
2025/07/17	SGT 171	Wall Drywall Finish	complete
2025/07/17	SGT 171	Wall Prime Paint	complete
2025/07/17	SGT 172	In Wall Insulation	complete
2025/07/17	SGT 172	Overhead Duct Insulation	no data
2025/07/17	SGT 172	Overhead Duct Rough In	in progress
2025/07/17	SGT 172	Overhead Plumbing	in progress
2025/07/17	SGT 172	Wall Drywall	complete
2025/07/17	SGT 172	Wall Drywall Finish	complete
2025/07/17	SGT 172	Wall Prime Paint	complete
2025/07/17	SHIPPING STORAGE 190	In Wall Insulation	complete
2025/07/17	SHIPPING STORAGE 190	Overhead Duct Insulation	no data
2025/07/17	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/07/17	SHIPPING STORAGE 190	Overhead Plumbing	no data
2025/07/17	SHIPPING STORAGE 190	Wall Drywall	complete
2025/07/17	SHIPPING STORAGE 190	Wall Drywall Finish	complete
2025/07/17	SHIPPING STORAGE 190	Wall Prime Paint	complete
2025/07/17	SHOP FORMAN 184	In Wall Insulation	complete
2025/07/17	SHOP FORMAN 184	Overhead Duct Insulation	in progress
2025/07/17	SHOP FORMAN 184	Overhead Duct Rough In	no data
2025/07/17	SHOP FORMAN 184	Overhead Plumbing	not started
2025/07/17	SHOP FORMAN 184	Wall Drywall	complete
2025/07/17	SHOP FORMAN 184	Wall Drywall Finish	complete
2025/07/17	SHOP FORMAN 184	Wall Prime Paint	complete
2025/07/17	SOFT INTERVIEW 161	In Wall Insulation	no data
2025/07/17	SOFT INTERVIEW 161	Overhead Duct Insulation	no data
2025/07/17	SOFT INTERVIEW 161	Overhead Duct Rough In	no data
2025/07/17	SOFT INTERVIEW 161	Overhead Plumbing	no data
2025/07/17	SOFT INTERVIEW 161	Wall Drywall	no data
2025/07/17	SOFT INTERVIEW 161	Wall Drywall Finish	no data
2025/07/17	SOFT INTERVIEW 161	Wall Prime Paint	no data
2025/07/17	SOFT INTERVIEW 162	In Wall Insulation	no data
2025/07/17	SOFT INTERVIEW 162	Overhead Duct Insulation	no data

2025/07/17		SOFT INTERVIEW 162		Overhead Duct Rough In		no data
2025/07/17		SOFT INTERVIEW 162		Overhead Plumbing		no data
2025/07/17		SOFT INTERVIEW 162		Wall Drywall		no data
2025/07/17		SOFT INTERVIEW 162		Wall Drywall Finish		no data
2025/07/17		SOFT INTERVIEW 162		Wall Prime Paint		no data
2025/07/17		SPECIAL OPERATION LT 143		In Wall Insulation		no data
2025/07/17		SPECIAL OPERATION LT 143		Overhead Duct Insulation		no data
2025/07/17		SPECIAL OPERATION LT 143		Overhead Duct Rough In		no data
2025/07/17		SPECIAL OPERATION LT 143		Overhead Plumbing		no data
2025/07/17		SPECIAL OPERATION LT 143		Wall Drywall		complete
2025/07/17		SPECIAL OPERATION LT 143		Wall Drywall Finish		complete
2025/07/17		SPECIAL OPERATION LT 143		Wall Prime Paint		complete
2025/07/17		STAIR A		In Wall Insulation		no data
2025/07/17		STAIR A		Overhead Duct Insulation		no data
2025/07/17		STAIR A		Overhead Duct Rough In		no data
2025/07/17		STAIR A		Overhead Plumbing		complete
2025/07/17		STAIR A		Wall Drywall		not started
2025/07/17		STAIR A		Wall Drywall Finish		not started
2025/07/17		STAIR A		Wall Prime Paint		not started
2025/07/17		STORAGE 104		In Wall Insulation		no data
2025/07/17		STORAGE 104		Overhead Duct Insulation		no data
2025/07/17		STORAGE 104		Overhead Duct Rough In		no data
2025/07/17		STORAGE 104		Overhead Plumbing		not started
2025/07/17		STORAGE 104		Wall Drywall		complete
2025/07/17		STORAGE 104		Wall Drywall Finish		complete
2025/07/17		STORAGE 104		Wall Prime Paint		complete
2025/07/17		STORAGE 127		In Wall Insulation		no data
2025/07/17		STORAGE 127		Overhead Duct Insulation		in progress
2025/07/17		STORAGE 127		Overhead Duct Rough In		no data
2025/07/17		STORAGE 127		Overhead Plumbing		not started
2025/07/17		STORAGE 127		Wall Drywall		complete
2025/07/17		STORAGE 127		Wall Drywall Finish		complete
2025/07/17		STORAGE 127		Wall Prime Paint		complete
2025/07/17		STUDIO 126		In Wall Insulation		complete
2025/07/17		STUDIO 126		Overhead Duct Insulation		complete
2025/07/17		STUDIO 126		Overhead Duct Rough In		complete
2025/07/17		STUDIO 126		Overhead Plumbing		complete
2025/07/17		STUDIO 126		Wall Drywall		complete
2025/07/17		STUDIO 126		Wall Drywall Finish		complete
2025/07/17		STUDIO 126		Wall Prime Paint		complete
2025/07/17		SUPERVISOR 129		In Wall Insulation		complete
2025/07/17		SUPERVISOR 129		Overhead Duct Insulation		complete
2025/07/17		SUPERVISOR 129		Overhead Duct Rough In		in progress
2025/07/17		SUPERVISOR 129		Overhead Plumbing		not started
2025/07/17		SUPERVISOR 129		Wall Drywall		complete
2025/07/17		SUPERVISOR 129		Wall Drywall Finish		complete
2025/07/17		SUPERVISOR 129		Wall Prime Paint		complete
2025/07/17		Storage 164		In Wall Insulation		complete
2025/07/17		Storage 164		Overhead Duct Insulation		in progress
2025/07/17		Storage 164		Overhead Duct Rough In		in progress
2025/07/17		Storage 164		Overhead Plumbing		not started

2025/07/17	Storage 164	Wall Drywall	complete
2025/07/17	Storage 164	Wall Drywall Finish	complete
2025/07/17	Storage 164	Wall Prime Paint	complete
2025/07/17	Storage 177	In Wall Insulation	complete
2025/07/17	Storage 177	Overhead Duct Insulation	in progress
2025/07/17	Storage 177	Overhead Duct Rough In	in progress
2025/07/17	Storage 177	Overhead Plumbing	not started
2025/07/17	Storage 177	Wall Drywall	complete
2025/07/17	Storage 177	Wall Drywall Finish	complete
2025/07/17	Storage 177	Wall Prime Paint	complete
2025/07/17	TECHNICAL SURVEILLANCE 188	In Wall Insulation	complete
2025/07/17	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	in progress
2025/07/17	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	no data
2025/07/17	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	not started
2025/07/17	TECHNICAL SURVEILLANCE 188	Wall Drywall	complete
2025/07/17	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	complete
2025/07/17	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	not started
2025/07/17	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/07/17	TRAFFIC SERGEANT 141	Overhead Duct Insulation	in progress
2025/07/17	TRAFFIC SERGEANT 141	Overhead Duct Rough In	in progress
2025/07/17	TRAFFIC SERGEANT 141	Overhead Plumbing	in progress
2025/07/17	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/07/17	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/07/17	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/07/17	TRIAGE/RECEPTION 134	In Wall Insulation	no data
2025/07/17	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/07/17	TRIAGE/RECEPTION 134	Overhead Duct Rough In	in progress
2025/07/17	TRIAGE/RECEPTION 134	Overhead Plumbing	no data
2025/07/17	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/07/17	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/07/17	TRIAGE/RECEPTION 134	Wall Prime Paint	in progress
2025/07/17	TST WORKSHOP 187	In Wall Insulation	complete
2025/07/17	TST WORKSHOP 187	Overhead Duct Insulation	not started
2025/07/17	TST WORKSHOP 187	Overhead Duct Rough In	no data
2025/07/17	TST WORKSHOP 187	Overhead Plumbing	no data
2025/07/17	TST WORKSHOP 187	Wall Drywall	complete
2025/07/17	TST WORKSHOP 187	Wall Drywall Finish	complete
2025/07/17	TST WORKSHOP 187	Wall Prime Paint	in progress
2025/07/17	UNISEX RESTROOM 169	In Wall Insulation	no data
2025/07/17	UNISEX RESTROOM 169	Overhead Duct Insulation	no data
2025/07/17	UNISEX RESTROOM 169	Overhead Duct Rough In	no data
2025/07/17	UNISEX RESTROOM 169	Overhead Plumbing	no data



2025/07/17	UNISEX RESTROOM 169	Wall Drywall	no data
2025/07/17	UNISEX RESTROOM 169	Wall Drywall Finish	no data
2025/07/17	UNISEX RESTROOM 169	Wall Prime Paint	no data
2025/07/17	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	in progress
2025/07/17	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	not started
2025/07/17	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	no data
2025/07/17	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete
2025/07/17	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	complete
2025/07/17	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	complete
2025/07/17	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	complete
2025/07/17	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	no data
2025/07/17	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	no data
2025/07/17	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	no data
2025/07/17	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	in progress
2025/07/17	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/07/17	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/07/17	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/07/17	WAITING/LOBBY 100	In Wall Insulation	not started
2025/07/17	WAITING/LOBBY 100	Overhead Duct Insulation	no data
2025/07/17	WAITING/LOBBY 100	Overhead Duct Rough In	no data
2025/07/17	WAITING/LOBBY 100	Overhead Plumbing	not started
2025/07/17	WAITING/LOBBY 100	Wall Drywall	not started
2025/07/17	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/07/17	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/07/17	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/07/17	WOMENS RESTROOM 113	Overhead Duct Insulation	no data
2025/07/17	WOMENS RESTROOM 113	Overhead Duct Rough In	in progress
2025/07/17	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/07/17	WOMENS RESTROOM 113	Wall Drywall	complete
2025/07/17	WOMENS RESTROOM 113	Wall Drywall Finish	in progress
2025/07/17	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/07/25	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/07/25	ADMIN ASSISTANT 125	Overhead Duct Insulation	complete
2025/07/25	ADMIN ASSISTANT 125	Overhead Duct Rough In	in progress
2025/07/25	ADMIN ASSISTANT 125	Overhead Plumbing	not started
2025/07/25	ADMIN ASSISTANT 125	Wall Drywall	complete
2025/07/25	ADMIN ASSISTANT 125	Wall Drywall Finish	complete
2025/07/25	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/07/25	AV ROOM 103	In Wall Insulation	no data
2025/07/25	AV ROOM 103	Overhead Duct Insulation	complete

2025/07/25	AV ROOM 103	Overhead Duct Rough In	no data
2025/07/25	AV ROOM 103	Overhead Plumbing	not started
2025/07/25	AV ROOM 103	Wall Drywall	complete
2025/07/25	AV ROOM 103	Wall Drywall Finish	complete
2025/07/25	AV ROOM 103	Wall Prime Paint	complete
2025/07/25	BREAK ROOM CONFERENCE 182	In Wall Insulation	no data
2025/07/25	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	in progress
2025/07/25	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	no data
2025/07/25	BREAK ROOM CONFERENCE 182	Overhead Plumbing	complete
2025/07/25	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/07/25	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	complete
2025/07/25	BREAK ROOM CONFERENCE 182	Wall Prime Paint	complete
2025/07/25	Background-159	In Wall Insulation	complete
2025/07/25	Background-159	Overhead Duct Insulation	complete
2025/07/25	Background-159	Overhead Duct Rough In	in progress
2025/07/25	Background-159	Overhead Plumbing	not started
2025/07/25	Background-159	Wall Drywall	complete
2025/07/25	Background-159	Wall Drywall Finish	complete
2025/07/25	Background-159	Wall Prime Paint	complete
2025/07/25	CENTRAL BREAKROOM 145	In Wall Insulation	in progress
2025/07/25	CENTRAL BREAKROOM 145	Overhead Duct Insulation	complete
2025/07/25	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/07/25	CENTRAL BREAKROOM 145	Overhead Plumbing	complete
2025/07/25	CENTRAL BREAKROOM 145	Wall Drywall	in progress
2025/07/25	CENTRAL BREAKROOM 145	Wall Drywall Finish	in progress
2025/07/25	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/07/25	COLD CASE 175	In Wall Insulation	no data
2025/07/25	COLD CASE 175	Overhead Duct Insulation	complete
2025/07/25	COLD CASE 175	Overhead Duct Rough In	in progress
2025/07/25	COLD CASE 175	Overhead Plumbing	complete
2025/07/25	COLD CASE 175	Wall Drywall	complete
2025/07/25	COLD CASE 175	Wall Drywall Finish	complete
2025/07/25	COLD CASE 175	Wall Prime Paint	complete
2025/07/25	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/07/25	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	complete
2025/07/25	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	no data
2025/07/25	COMMUNITY AFFAIRS 124	Overhead Plumbing	no data
2025/07/25	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/07/25	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/07/25	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/07/25	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/07/25	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	

in progress

2025/07/25		COMMUNITY ROOM 247 PPL 102		Overhead Duct Rough In		no data
2025/07/25		COMMUNITY ROOM 247 PPL 102		Overhead Plumbing		not started
2025/07/25		COMMUNITY ROOM 247 PPL 102		Wall Drywall		complete
2025/07/25		COMMUNITY ROOM 247 PPL 102		Wall Drywall Finish		complete
2025/07/25		COMMUNITY ROOM 247 PPL 102		Wall Prime Paint		complete
2025/07/25		CONFERENCE ROOM 153		In Wall Insulation		complete
2025/07/25		CONFERENCE ROOM 153		Overhead Duct Insulation		in progress
2025/07/25		CONFERENCE ROOM 153		Overhead Duct Rough In		in progress
2025/07/25		CONFERENCE ROOM 153		Overhead Plumbing		not started
2025/07/25		CONFERENCE ROOM 153		Wall Drywall		complete
2025/07/25		CONFERENCE ROOM 153		Wall Drywall Finish		complete
2025/07/25		CONFERENCE ROOM 153		Wall Prime Paint		complete
2025/07/25		CONFERENCE/WAR ROOM 163		In Wall Insulation		no data
2025/07/25		CONFERENCE/WAR ROOM 163		Overhead Duct Insulation		in progress
2025/07/25		CONFERENCE/WAR ROOM 163		Overhead Duct Rough In		in progress
2025/07/25		CONFERENCE/WAR ROOM 163		Overhead Plumbing		not started
2025/07/25		CONFERENCE/WAR ROOM 163		Wall Drywall		complete
2025/07/25		CONFERENCE/WAR ROOM 163		Wall Drywall Finish		complete
2025/07/25		CONFERENCE/WAR ROOM 163		Wall Prime Paint		complete
2025/07/25		COPY 176		In Wall Insulation		complete
2025/07/25		COPY 176		Overhead Duct Insulation		complete
2025/07/25		COPY 176		Overhead Duct Rough In		in progress
2025/07/25		COPY 176		Overhead Plumbing		not started
2025/07/25		COPY 176		Wall Drywall		complete
2025/07/25		COPY 176		Wall Drywall Finish		complete
2025/07/25		COPY 176		Wall Prime Paint		complete
2025/07/25		COPY/MAIL ROOM 114		In Wall Insulation		complete
2025/07/25		COPY/MAIL ROOM 114		Overhead Duct Insulation		complete
2025/07/25		COPY/MAIL ROOM 114		Overhead Duct Rough In		in progress
2025/07/25		COPY/MAIL ROOM 114		Overhead Plumbing		complete
2025/07/25		COPY/MAIL ROOM 114		Wall Drywall		complete
2025/07/25		COPY/MAIL ROOM 114		Wall Drywall Finish		complete
2025/07/25		COPY/MAIL ROOM 114		Wall Prime Paint		complete
2025/07/25		CORRIDOR 107		In Wall Insulation		complete
2025/07/25		CORRIDOR 107		Overhead Duct Insulation		in progress
2025/07/25		CORRIDOR 107		Overhead Duct Rough In		in progress
2025/07/25		CORRIDOR 107		Overhead Plumbing		in progress
2025/07/25		CORRIDOR 107		Wall Drywall		complete
2025/07/25		CORRIDOR 107		Wall Drywall Finish		complete
2025/07/25		CORRIDOR 107		Wall Prime Paint		complete
2025/07/25		CORRIDOR 108		In Wall Insulation		complete

2025/07/25	CORRIDOR 108	In Wall Insulation	no data
2025/07/25	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/07/25	CORRIDOR 108	Overhead Duct Insulation	no data
2025/07/25	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/07/25	CORRIDOR 108	Overhead Duct Rough In	no data
2025/07/25	CORRIDOR 108	Overhead Plumbing	in progress
2025/07/25	CORRIDOR 108	Overhead Plumbing	no data
2025/07/25	CORRIDOR 108	Wall Drywall	complete
2025/07/25	CORRIDOR 108	Wall Drywall	complete
2025/07/25	CORRIDOR 108	Wall Drywall Finish	complete
2025/07/25	CORRIDOR 108	Wall Drywall Finish	complete
2025/07/25	CORRIDOR 108	Wall Prime Paint	complete
2025/07/25	CORRIDOR 108	Wall Prime Paint	complete
2025/07/25	CORRIDOR 109	In Wall Insulation	complete
2025/07/25	CORRIDOR 109	Overhead Duct Insulation	in progress
2025/07/25	CORRIDOR 109	Overhead Duct Rough In	in progress
2025/07/25	CORRIDOR 109	Overhead Plumbing	in progress
2025/07/25	CORRIDOR 109	Wall Drywall	complete
2025/07/25	CORRIDOR 109	Wall Drywall Finish	complete
2025/07/25	CORRIDOR 109	Wall Prime Paint	complete
2025/07/25	CORRIDOR 110	In Wall Insulation	no data
2025/07/25	CORRIDOR 110	In Wall Insulation	no data
2025/07/25	CORRIDOR 110	Overhead Duct Insulation	in progress
2025/07/25	CORRIDOR 110	Overhead Duct Insulation	no data
2025/07/25	CORRIDOR 110	Overhead Duct Rough In	no data
2025/07/25	CORRIDOR 110	Overhead Duct Rough In	no data
2025/07/25	CORRIDOR 110	Overhead Plumbing	no data
2025/07/25	CORRIDOR 110	Overhead Plumbing	in progress
2025/07/25	CORRIDOR 110	Wall Drywall	complete
2025/07/25	CORRIDOR 110	Wall Drywall	complete
2025/07/25	CORRIDOR 110	Wall Drywall Finish	complete
2025/07/25	CORRIDOR 110	Wall Drywall Finish	complete
2025/07/25	CORRIDOR 110	Wall Prime Paint	complete
2025/07/25	CORRIDOR 110	Wall Prime Paint	complete
2025/07/25	CORRIDOR 181	In Wall Insulation	complete
2025/07/25	CORRIDOR 181	Overhead Duct Insulation	in progress
2025/07/25	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/07/25	CORRIDOR 181	Overhead Plumbing	in progress
2025/07/25	CORRIDOR 181	Wall Drywall	complete
2025/07/25	CORRIDOR 181	Wall Drywall Finish	complete
2025/07/25	CORRIDOR 181	Wall Prime Paint	complete
2025/07/25	CORRIDOR144	In Wall Insulation	no data
2025/07/25	CORRIDOR144	Overhead Duct Insulation	in progress
2025/07/25	CORRIDOR144	Overhead Duct Rough In	in progress
2025/07/25	CORRIDOR144	Overhead Plumbing	in progress
2025/07/25	CORRIDOR144	Wall Drywall	complete
2025/07/25	CORRIDOR144	Wall Drywall Finish	complete
2025/07/25	CORRIDOR144	Wall Prime Paint	complete
2025/07/25	CPL 173	In Wall Insulation	complete
2025/07/25	CPL 173	Overhead Duct Insulation	complete
2025/07/25	CPL 173	Overhead Duct Rough In	in progress
2025/07/25	CPL 173	Overhead Plumbing	complete
2025/07/25	CPL 173	Wall Drywall	complete
2025/07/25	CPL 173	Wall Drywall Finish	complete

2025/07/25	CPL 173	Wall Prime Paint	complete
2025/07/25	CPL 174	In Wall Insulation	complete
2025/07/25	CPL 174	Overhead Duct Insulation	in progress
2025/07/25	CPL 174	Overhead Duct Rough In	in progress
2025/07/25	CPL 174	Overhead Plumbing	no data
2025/07/25	CPL 174	Wall Drywall	complete
2025/07/25	CPL 174	Wall Drywall Finish	complete
2025/07/25	CPL 174	Wall Prime Paint	in progress
2025/07/25	DRY STORAGE 146	In Wall Insulation	complete
2025/07/25	DRY STORAGE 146	Overhead Duct Insulation	complete
2025/07/25	DRY STORAGE 146	Overhead Duct Rough In	complete
2025/07/25	DRY STORAGE 146	Overhead Plumbing	not started
2025/07/25	DRY STORAGE 146	Wall Drywall	complete
2025/07/25	DRY STORAGE 146	Wall Drywall Finish	complete
2025/07/25	DRY STORAGE 146	Wall Prime Paint	in progress
2025/07/25	FIRE RISER 178	In Wall Insulation	no data
2025/07/25	FIRE RISER 178	Overhead Duct Insulation	no data
2025/07/25	FIRE RISER 178	Overhead Duct Rough In	no data
2025/07/25	FIRE RISER 178	Overhead Plumbing	no data
2025/07/25	FIRE RISER 178	Wall Drywall	no data
2025/07/25	FIRE RISER 178	Wall Drywall Finish	no data
2025/07/25	FIRE RISER 178	Wall Prime Paint	no data
2025/07/25	GREETING ROOM 106	In Wall Insulation	no data
2025/07/25	GREETING ROOM 106	Overhead Duct Insulation	complete
2025/07/25	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/07/25	GREETING ROOM 106	Overhead Plumbing	not started
2025/07/25	GREETING ROOM 106	Wall Drywall	complete
2025/07/25	GREETING ROOM 106	Wall Drywall Finish	complete
2025/07/25	GREETING ROOM 106	Wall Prime Paint	complete
2025/07/25	HR 149	In Wall Insulation	complete
2025/07/25	HR 149	Overhead Duct Insulation	complete
2025/07/25	HR 149	Overhead Duct Rough In	complete
2025/07/25	HR 149	Overhead Plumbing	not started
2025/07/25	HR 149	Wall Drywall	complete
2025/07/25	HR 149	Wall Drywall Finish	complete
2025/07/25	HR 149	Wall Prime Paint	complete
2025/07/25	HR 150	In Wall Insulation	complete
2025/07/25	HR 150	Overhead Duct Insulation	complete
2025/07/25	HR 150	Overhead Duct Rough In	complete
2025/07/25	HR 150	Overhead Plumbing	not started
2025/07/25	HR 150	Wall Drywall	complete
2025/07/25	HR 150	Wall Drywall Finish	complete
2025/07/25	HR 150	Wall Prime Paint	complete
2025/07/25	HR 151	In Wall Insulation	complete
2025/07/25	HR 151	Overhead Duct Insulation	complete
2025/07/25	HR 151	Overhead Duct Rough In	complete
2025/07/25	HR 151	Overhead Plumbing	complete
2025/07/25	HR 151	Wall Drywall	complete
2025/07/25	HR 151	Wall Drywall Finish	complete
2025/07/25	HR 151	Wall Prime Paint	complete
2025/07/25	HR 154	In Wall Insulation	complete
2025/07/25	HR 154	Overhead Duct Insulation	complete
2025/07/25	HR 154	Overhead Duct Rough In	complete

2025/07/25	HR 154	Overhead Plumbing	complete
2025/07/25	HR 154	Wall Drywall	complete
2025/07/25	HR 154	Wall Drywall Finish	complete
2025/07/25	HR 154	Wall Prime Paint	complete
2025/07/25	HR 155	In Wall Insulation	complete
2025/07/25	HR 155	Overhead Duct Insulation	complete
2025/07/25	HR 155	Overhead Duct Rough In	complete
2025/07/25	HR 155	Overhead Plumbing	not started
2025/07/25	HR 155	Wall Drywall	complete
2025/07/25	HR 155	Wall Drywall Finish	complete
2025/07/25	HR 155	Wall Prime Paint	complete
2025/07/25	HR 156	In Wall Insulation	complete
2025/07/25	HR 156	Overhead Duct Insulation	complete
2025/07/25	HR 156	Overhead Duct Rough In	complete
2025/07/25	HR 156	Overhead Plumbing	not started
2025/07/25	HR 156	Wall Drywall	complete
2025/07/25	HR 156	Wall Drywall Finish	complete
2025/07/25	HR 156	Wall Prime Paint	complete
2025/07/25	HR 157	In Wall Insulation	complete
2025/07/25	HR 157	Overhead Duct Insulation	complete
2025/07/25	HR 157	Overhead Duct Rough In	complete
2025/07/25	HR 157	Overhead Plumbing	complete
2025/07/25	HR 157	Wall Drywall	complete
2025/07/25	HR 157	Wall Drywall Finish	complete
2025/07/25	HR 157	Wall Prime Paint	complete
2025/07/25	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/07/25	HUMAN RESOURCES 148	Overhead Duct Insulation	in progress
2025/07/25	HUMAN RESOURCES 148	Overhead Duct Rough In	no data
2025/07/25	HUMAN RESOURCES 148	Overhead Plumbing	no data
2025/07/25	HUMAN RESOURCES 148	Wall Drywall	complete
2025/07/25	HUMAN RESOURCES 148	Wall Drywall Finish	complete
2025/07/25	HUMAN RESOURCES 148	Wall Prime Paint	complete
2025/07/25	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/07/25	INTERNAL AFFAIRS 119	Overhead Duct Insulation	complete
2025/07/25	INTERNAL AFFAIRS 119	Overhead Duct Rough In	in progress
2025/07/25	INTERNAL AFFAIRS 119	Overhead Plumbing	complete
2025/07/25	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/07/25	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/07/25	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/07/25	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/07/25	INTERNAL AFFAIRS 120	Overhead Duct Insulation	complete
2025/07/25	INTERNAL AFFAIRS 120	Overhead Duct Rough In	complete
2025/07/25	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/07/25	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/07/25	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/07/25	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/07/25	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/07/25	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	

complete			
2025/07/25	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	no data
2025/07/25	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	complete
2025/07/25	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/07/25	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/07/25	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/07/25	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	no data
2025/07/25	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	complete
2025/07/25	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	in progress
2025/07/25	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	complete
2025/07/25	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/07/25	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	complete
2025/07/25	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	complete
2025/07/25	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	no data
2025/07/25	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	in progress
2025/07/25	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	no data
2025/07/25	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	in progress
2025/07/25	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/07/25	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/07/25	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	complete
2025/07/25	IT 115	In Wall Insulation	complete
2025/07/25	IT 115	Overhead Duct Insulation	no data
2025/07/25	IT 115	Overhead Duct Rough In	no data
2025/07/25	IT 115	Overhead Plumbing	no data
2025/07/25	IT 115	Wall Drywall	complete
2025/07/25	IT 115	Wall Drywall Finish	complete
2025/07/25	IT 115	Wall Prime Paint	complete
2025/07/25	IT 135	In Wall Insulation	complete
2025/07/25	IT 135	Overhead Duct Insulation	complete
2025/07/25	IT 135	Overhead Duct Rough In	in progress
2025/07/25	IT 135	Overhead Plumbing	complete
2025/07/25	IT 135	Wall Drywall	complete
2025/07/25	IT 135	Wall Drywall Finish	complete
2025/07/25	IT 135	Wall Prime Paint	complete
2025/07/25	IT MANAGER 136	In Wall Insulation	no data
2025/07/25	IT MANAGER 136	Overhead Duct Insulation	no data
2025/07/25	IT MANAGER 136	Overhead Duct Rough In	no data

2025/07/25	IT MANAGER 136	Overhead Plumbing	complete
2025/07/25	IT MANAGER 136	Wall Drywall	complete
2025/07/25	IT MANAGER 136	Wall Drywall Finish	complete
2025/07/25	IT MANAGER 136	Wall Prime Paint	complete
2025/07/25	IT MANAGER 137	In Wall Insulation	no data
2025/07/25	IT MANAGER 137	Overhead Duct Insulation	complete
2025/07/25	IT MANAGER 137	Overhead Duct Rough In	in progress
2025/07/25	IT MANAGER 137	Overhead Plumbing	complete
2025/07/25	IT MANAGER 137	Wall Drywall	complete
2025/07/25	IT MANAGER 137	Wall Drywall Finish	complete
2025/07/25	IT MANAGER 137	Wall Prime Paint	complete
2025/07/25	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/07/25	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data
2025/07/25	JUVENILE INTERVIEW 165	Overhead Duct Rough In	in progress
2025/07/25	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/07/25	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/07/25	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/07/25	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/07/25	JUVENILE INTERVIEWERS 166	In Wall Insulation	no data
2025/07/25	JUVENILE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/07/25	JUVENILE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/07/25	JUVENILE INTERVIEWERS 166	Overhead Plumbing	no data
2025/07/25	JUVENILE INTERVIEWERS 166	Wall Drywall	complete
2025/07/25	JUVENILE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/07/25	JUVENILE INTERVIEWERS 166	Wall Prime Paint	complete
2025/07/25	KEY ROOM 185	In Wall Insulation	complete
2025/07/25	KEY ROOM 185	Overhead Duct Insulation	in progress
2025/07/25	KEY ROOM 185	Overhead Duct Rough In	no data
2025/07/25	KEY ROOM 185	Overhead Plumbing	not started
2025/07/25	KEY ROOM 185	Wall Drywall	complete
2025/07/25	KEY ROOM 185	Wall Drywall Finish	complete
2025/07/25	KEY ROOM 185	Wall Prime Paint	complete
2025/07/25	LT 170	In Wall Insulation	complete
2025/07/25	LT 170	Overhead Duct Insulation	complete
2025/07/25	LT 170	Overhead Duct Rough In	complete
2025/07/25	LT 170	Overhead Plumbing	not started
2025/07/25	LT 170	Wall Drywall	complete
2025/07/25	LT 170	Wall Drywall Finish	complete
2025/07/25	LT 170	Wall Prime Paint	complete
2025/07/25	MACHINE ROOM 191	In Wall Insulation	no data
2025/07/25	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/07/25	MACHINE ROOM 191	Overhead Duct Rough In	no data
2025/07/25	MACHINE ROOM 191	Overhead Plumbing	no data
2025/07/25	MACHINE ROOM 191	Wall Drywall	complete
2025/07/25	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/07/25	MACHINE ROOM 191	Wall Prime Paint	complete



2025/07/25	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/07/25	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/07/25	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/07/25	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/07/25	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/07/25	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/07/25	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/07/25	MAIN JANITORIAL111	In Wall Insulation	no data
2025/07/25	MAIN JANITORIAL111	Overhead Duct Insulation	no data
2025/07/25	MAIN JANITORIAL111	Overhead Duct Rough In	complete
2025/07/25	MAIN JANITORIAL111	Overhead Plumbing	no data
2025/07/25	MAIN JANITORIAL111	Wall Drywall	complete
2025/07/25	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/07/25	MAIN JANITORIAL111	Wall Prime Paint	complete
2025/07/25	MARINE SERGEANT 142	In Wall Insulation	complete
2025/07/25	MARINE SERGEANT 142	Overhead Duct Insulation	in progress
2025/07/25	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/07/25	MARINE SERGEANT 142	Overhead Plumbing	in progress
2025/07/25	MARINE SERGEANT 142	Wall Drywall	complete
2025/07/25	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/07/25	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/07/25	MECHANICAL 192	In Wall Insulation	no data
2025/07/25	MECHANICAL 192	Overhead Duct Insulation	no data
2025/07/25	MECHANICAL 192	Overhead Duct Rough In	no data
2025/07/25	MECHANICAL 192	Overhead Plumbing	no data
2025/07/25	MECHANICAL 192	Wall Drywall	no data
2025/07/25	MECHANICAL 192	Wall Drywall Finish	no data
2025/07/25	MECHANICAL 192	Wall Prime Paint	no data
2025/07/25	MECHANICAL ROOM 122	In Wall Insulation	complete
2025/07/25	MECHANICAL ROOM 122	Overhead Duct Insulation	not started
2025/07/25	MECHANICAL ROOM 122	Overhead Duct Rough In	in progress
2025/07/25	MECHANICAL ROOM 122	Overhead Plumbing	complete
2025/07/25	MECHANICAL ROOM 122	Wall Drywall	complete
2025/07/25	MECHANICAL ROOM 122	Wall Drywall Finish	complete
2025/07/25	MECHANICAL ROOM 122	Wall Prime Paint	complete
2025/07/25	MENS RESTROOM 112	In Wall Insulation	complete
2025/07/25	MENS RESTROOM 112	Overhead Duct Insulation	complete
2025/07/25	MENS RESTROOM 112	Overhead Duct Rough In	complete
2025/07/25	MENS RESTROOM 112	Overhead Plumbing	complete
2025/07/25	MENS RESTROOM 112	Wall Drywall	complete
2025/07/25	MENS RESTROOM 112	Wall Drywall Finish	complete
2025/07/25	MENS RESTROOM 112	Wall Prime Paint	not started
2025/07/25	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
2025/07/25	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/07/25	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	in progress

progress

2025/07/25	MIS EQUIPMENT STORAGE 138   Overhead Plumbing   in progress
2025/07/25	MIS EQUIPMENT STORAGE 138   Wall Drywall   complete
2025/07/25	MIS EQUIPMENT STORAGE 138   Wall Drywall Finish   complete
2025/07/25	MIS EQUIPMENT STORAGE 138   Wall Prime Paint   complete
2025/07/25	MIS SHREDDING 117   In Wall Insulation   complete
2025/07/25	MIS SHREDDING 117   Overhead Duct Insulation   complete
2025/07/25	MIS SHREDDING 117   Overhead Duct Rough In   complete
2025/07/25	MIS SHREDDING 117   Overhead Plumbing   complete
2025/07/25	MIS SHREDDING 117   Wall Drywall   complete
2025/07/25	MIS SHREDDING 117   Wall Drywall Finish   complete
2025/07/25	MIS SHREDDING 117   Wall Prime Paint   complete
2025/07/25	OFFICE 128   In Wall Insulation   no data
2025/07/25	OFFICE 128   Overhead Duct Insulation   no data
2025/07/25	OFFICE 128   Overhead Duct Rough In   no data
2025/07/25	OFFICE 128   Overhead Plumbing   no data
2025/07/25	OFFICE 128   Wall Drywall   complete
2025/07/25	OFFICE 128   Wall Drywall Finish   complete
2025/07/25	OFFICE 128   Wall Prime Paint   complete
2025/07/25	OPERATIONS SUPPORT DIVISION 139   In Wall Insulation   no data
2025/07/25	OPERATIONS SUPPORT DIVISION 139   Overhead Duct Insulation   in progress
2025/07/25	OPERATIONS SUPPORT DIVISION 139   Overhead Duct Rough In   no data
2025/07/25	OPERATIONS SUPPORT DIVISION 139   Overhead Plumbing   no data
2025/07/25	OPERATIONS SUPPORT DIVISION 139   Wall Drywall   complete
2025/07/25	OPERATIONS SUPPORT DIVISION 139   Wall Drywall Finish   complete
2025/07/25	OPERATIONS SUPPORT DIVISION 139   Wall Prime Paint   complete
2025/07/25	PARTS STORAGE 189   In Wall Insulation   in progress
2025/07/25	PARTS STORAGE 189   Overhead Duct Insulation   no data
2025/07/25	PARTS STORAGE 189   Overhead Duct Rough In   no data
2025/07/25	PARTS STORAGE 189   Overhead Plumbing   no data
2025/07/25	PARTS STORAGE 189   Wall Drywall   complete
2025/07/25	PARTS STORAGE 189   Wall Drywall Finish   complete
2025/07/25	PARTS STORAGE 189   Wall Prime Paint   complete
2025/07/25	PUBLIC RESTROOM 106   In Wall Insulation   complete
2025/07/25	PUBLIC RESTROOM 106   Overhead Duct Insulation   complete
2025/07/25	PUBLIC RESTROOM 106   Overhead Duct Rough In   complete
2025/07/25	PUBLIC RESTROOM 106   Overhead Plumbing   complete
2025/07/25	PUBLIC RESTROOM 106   Wall Drywall   complete
2025/07/25	PUBLIC RESTROOM 106   Wall Drywall Finish   complete
2025/07/25	PUBLIC RESTROOM 106   Wall Prime Paint   in progress
2025/07/25	Polygraph 152   In Wall Insulation   complete
2025/07/25	Polygraph 152   Overhead Duct Insulation   in progress
2025/07/25	Polygraph 152   Overhead Duct Rough In   in progress
2025/07/25	Polygraph 152   Overhead Plumbing   not started

2025/07/25	Polygraph	152	Wall Drywall	complete
2025/07/25	Polygraph	152	Wall Drywall Finish	complete
2025/07/25	Polygraph	152	Wall Prime Paint	complete
2025/07/25	RECEPTION	101	In Wall Insulation	no data
2025/07/25	RECEPTION	101	Overhead Duct Insulation	no data
2025/07/25	RECEPTION	101	Overhead Duct Rough In	no data
2025/07/25	RECEPTION	101	Overhead Plumbing	no data
2025/07/25	RECEPTION	101	Wall Drywall	no data
2025/07/25	RECEPTION	101	Wall Drywall Finish	no data
2025/07/25	RECEPTION	101	Wall Prime Paint	no data
2025/07/25	RECEPTION	147	In Wall Insulation	complete
2025/07/25	RECEPTION	147	Overhead Duct Insulation	complete
2025/07/25	RECEPTION	147	Overhead Duct Rough In	in progress
2025/07/25	RECEPTION	147	Overhead Plumbing	complete
2025/07/25	RECEPTION	147	Wall Drywall	complete
2025/07/25	RECEPTION	147	Wall Drywall Finish	complete
2025/07/25	RECEPTION	147	Wall Prime Paint	complete
2025/07/25	RECEPTION	179	In Wall Insulation	complete
2025/07/25	RECEPTION	179	Overhead Duct Insulation	in progress
2025/07/25	RECEPTION	179	Overhead Duct Rough In	no data
2025/07/25	RECEPTION	179	Overhead Plumbing	not started
2025/07/25	RECEPTION	179	Wall Drywall	complete
2025/07/25	RECEPTION	179	Wall Drywall Finish	complete
2025/07/25	RECEPTION	179	Wall Prime Paint	complete
2025/07/25	RECORDS	130	In Wall Insulation	no data
2025/07/25	RECORDS	130	Overhead Duct Insulation	complete
2025/07/25	RECORDS	130	Overhead Duct Rough In	no data
2025/07/25	RECORDS	130	Overhead Plumbing	complete
2025/07/25	RECORDS	130	Wall Drywall	complete
2025/07/25	RECORDS	130	Wall Drywall Finish	complete
2025/07/25	RECORDS	130	Wall Prime Paint	complete
2025/07/25	RECORDS	STORAGE 133	In Wall Insulation	complete
2025/07/25	RECORDS	STORAGE 133	Overhead Duct Insulation	complete
2025/07/25	RECORDS	STORAGE 133	Overhead Duct Rough In	in progress
2025/07/25	RECORDS	STORAGE 133	Overhead Plumbing	complete
2025/07/25	RECORDS	STORAGE 133	Wall Drywall	complete
2025/07/25	RECORDS	STORAGE 133	Wall Drywall Finish	complete
2025/07/25	RECORDS	STORAGE 133	Wall Prime Paint	complete
2025/07/25	RECORDS	SUPERVISOR 131	In Wall Insulation	no data
2025/07/25	RECORDS	SUPERVISOR 131	Overhead Duct Insulation	complete
2025/07/25	RECORDS	SUPERVISOR 131	Overhead Duct Rough In	in progress
2025/07/25	RECORDS	SUPERVISOR 131	Overhead Plumbing	not started
2025/07/25	RECORDS	SUPERVISOR 131	Wall Drywall	complete
2025/07/25	RECORDS	SUPERVISOR 131	Wall Drywall Finish	complete
2025/07/25	RECORDS	SUPERVISOR 131	Wall Prime Paint	complete
2025/07/25	RECORDS	SUPERVISOR 132	In Wall Insulation	no data
2025/07/25	RECORDS	SUPERVISOR 132	Overhead Duct Insulation	complete
2025/07/25	RECORDS	SUPERVISOR 132	Overhead Duct Rough In	in

progress

2025/07/25	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/07/25	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/07/25	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/07/25	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/07/25	RESTROOM 183	In Wall Insulation	no data
2025/07/25	RESTROOM 183	Overhead Duct Insulation	no data
2025/07/25	RESTROOM 183	Overhead Duct Rough In	no data
2025/07/25	RESTROOM 183	Overhead Plumbing	no data
2025/07/25	RESTROOM 183	Wall Drywall	no data
2025/07/25	RESTROOM 183	Wall Drywall Finish	no data
2025/07/25	RESTROOM 183	Wall Prime Paint	no data
2025/07/25	Risk Management - 158	In Wall Insulation	complete
2025/07/25	Risk Management - 158	Overhead Duct Insulation	complete

2025/07/25	Risk Management - 158	Overhead Duct Rough In	in progress
------------	-----------------------	------------------------	-------------

2025/07/25	Risk Management - 158	Overhead Plumbing	complete
2025/07/25	Risk Management - 158	Wall Drywall	complete
2025/07/25	Risk Management - 158	Wall Drywall Finish	complete
2025/07/25	Risk Management - 158	Wall Prime Paint	complete
2025/07/25	SALLY PORT 105	In Wall Insulation	not started
2025/07/25	SALLY PORT 105	Overhead Duct Insulation	in progress
2025/07/25	SALLY PORT 105	Overhead Duct Rough In	no data
2025/07/25	SALLY PORT 105	Overhead Plumbing	no data
2025/07/25	SALLY PORT 105	Wall Drywall	not started
2025/07/25	SALLY PORT 105	Wall Drywall Finish	not started
2025/07/25	SALLY PORT 105	Wall Prime Paint	not started
2025/07/25	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/07/25	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/07/25	SANE EXAM ROOM 168	Overhead Duct Rough In	complete
2025/07/25	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/07/25	SANE EXAM ROOM 168	Wall Drywall	complete
2025/07/25	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/07/25	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/07/25	SGT 171	In Wall Insulation	no data
2025/07/25	SGT 171	Overhead Duct Insulation	complete
2025/07/25	SGT 171	Overhead Duct Rough In	in progress
2025/07/25	SGT 171	Overhead Plumbing	complete
2025/07/25	SGT 171	Wall Drywall	complete
2025/07/25	SGT 171	Wall Drywall Finish	complete
2025/07/25	SGT 171	Wall Prime Paint	complete
2025/07/25	SGT 172	In Wall Insulation	complete
2025/07/25	SGT 172	Overhead Duct Insulation	no data
2025/07/25	SGT 172	Overhead Duct Rough In	in progress
2025/07/25	SGT 172	Overhead Plumbing	complete
2025/07/25	SGT 172	Wall Drywall	complete
2025/07/25	SGT 172	Wall Drywall Finish	complete
2025/07/25	SGT 172	Wall Prime Paint	complete
2025/07/25	SHIPPING STORAGE 190	In Wall Insulation	complete
2025/07/25	SHIPPING STORAGE 190	Overhead Duct Insulation	in progress

progress

2025/07/25	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/07/25	SHIPPING STORAGE 190	Overhead Plumbing	no data

2025/07/25	SHIPPING STORAGE 190	Wall Drywall	complete
2025/07/25	SHIPPING STORAGE 190	Wall Drywall Finish	complete
2025/07/25	SHIPPING STORAGE 190	Wall Prime Paint	complete
2025/07/25	SHOP FORMAN 184	In Wall Insulation	complete
2025/07/25	SHOP FORMAN 184	Overhead Duct Insulation	in progress
2025/07/25	SHOP FORMAN 184	Overhead Duct Rough In	no data
2025/07/25	SHOP FORMAN 184	Overhead Plumbing	not started
2025/07/25	SHOP FORMAN 184	Wall Drywall	complete
2025/07/25	SHOP FORMAN 184	Wall Drywall Finish	complete
2025/07/25	SHOP FORMAN 184	Wall Prime Paint	complete
2025/07/25	SOFT INTERVIEW 161	In Wall Insulation	no data
2025/07/25	SOFT INTERVIEW 161	Overhead Duct Insulation	no data
2025/07/25	SOFT INTERVIEW 161	Overhead Duct Rough In	no data
2025/07/25	SOFT INTERVIEW 161	Overhead Plumbing	no data
2025/07/25	SOFT INTERVIEW 161	Wall Drywall	no data
2025/07/25	SOFT INTERVIEW 161	Wall Drywall Finish	no data
2025/07/25	SOFT INTERVIEW 161	Wall Prime Paint	no data
2025/07/25	SOFT INTERVIEW 162	In Wall Insulation	no data
2025/07/25	SOFT INTERVIEW 162	Overhead Duct Insulation	no data
2025/07/25	SOFT INTERVIEW 162	Overhead Duct Rough In	no data
2025/07/25	SOFT INTERVIEW 162	Overhead Plumbing	no data
2025/07/25	SOFT INTERVIEW 162	Wall Drywall	no data
2025/07/25	SOFT INTERVIEW 162	Wall Drywall Finish	no data
2025/07/25	SOFT INTERVIEW 162	Wall Prime Paint	no data
2025/07/25	SPECIAL OPERATION LT 143	In Wall Insulation	no data
2025/07/25	SPECIAL OPERATION LT 143	Overhead Duct Insulation	no data
2025/07/25	SPECIAL OPERATION LT 143	Overhead Duct Rough In	no data
2025/07/25	SPECIAL OPERATION LT 143	Overhead Plumbing	no data
2025/07/25	SPECIAL OPERATION LT 143	Wall Drywall	complete
2025/07/25	SPECIAL OPERATION LT 143	Wall Drywall Finish	complete
2025/07/25	SPECIAL OPERATION LT 143	Wall Prime Paint	complete
2025/07/25	STAIR A	In Wall Insulation	no data
2025/07/25	STAIR A	Overhead Duct Insulation	no data
2025/07/25	STAIR A	Overhead Duct Rough In	no data
2025/07/25	STAIR A	Overhead Plumbing	complete
2025/07/25	STAIR A	Wall Drywall	not started
2025/07/25	STAIR A	Wall Drywall Finish	not started
2025/07/25	STAIR A	Wall Prime Paint	in progress
2025/07/25	STORAGE 104	In Wall Insulation	no data
2025/07/25	STORAGE 104	Overhead Duct Insulation	in progress
2025/07/25	STORAGE 104	Overhead Duct Rough In	in progress
2025/07/25	STORAGE 104	Overhead Plumbing	not started
2025/07/25	STORAGE 104	Wall Drywall	complete
2025/07/25	STORAGE 104	Wall Drywall Finish	complete
2025/07/25	STORAGE 104	Wall Prime Paint	complete
2025/07/25	STORAGE 127	In Wall Insulation	no data
2025/07/25	STORAGE 127	Overhead Duct Insulation	in progress
2025/07/25	STORAGE 127	Overhead Duct Rough In	in progress
2025/07/25	STORAGE 127	Overhead Plumbing	not started
2025/07/25	STORAGE 127	Wall Drywall	complete

2025/07/25	STORAGE 127	Wall Drywall Finish	complete
2025/07/25	STORAGE 127	Wall Prime Paint	complete
2025/07/25	STUDIO 126	In Wall Insulation	complete
2025/07/25	STUDIO 126	Overhead Duct Insulation	complete
2025/07/25	STUDIO 126	Overhead Duct Rough In	complete
2025/07/25	STUDIO 126	Overhead Plumbing	complete
2025/07/25	STUDIO 126	Wall Drywall	complete
2025/07/25	STUDIO 126	Wall Drywall Finish	complete
2025/07/25	STUDIO 126	Wall Prime Paint	complete
2025/07/25	SUPERVISOR 129	In Wall Insulation	complete
2025/07/25	SUPERVISOR 129	Overhead Duct Insulation	complete
2025/07/25	SUPERVISOR 129	Overhead Duct Rough In	complete
2025/07/25	SUPERVISOR 129	Overhead Plumbing	not started
2025/07/25	SUPERVISOR 129	Wall Drywall	complete
2025/07/25	SUPERVISOR 129	Wall Drywall Finish	complete
2025/07/25	SUPERVISOR 129	Wall Prime Paint	complete
2025/07/25	Storage 164	In Wall Insulation	complete
2025/07/25	Storage 164	Overhead Duct Insulation	complete
2025/07/25	Storage 164	Overhead Duct Rough In	complete
2025/07/25	Storage 164	Overhead Plumbing	not started
2025/07/25	Storage 164	Wall Drywall	complete
2025/07/25	Storage 164	Wall Drywall Finish	complete
2025/07/25	Storage 164	Wall Prime Paint	complete
2025/07/25	Storage 177	In Wall Insulation	complete
2025/07/25	Storage 177	Overhead Duct Insulation	in progress
2025/07/25	Storage 177	Overhead Duct Rough In	in progress
2025/07/25	Storage 177	Overhead Plumbing	not started
2025/07/25	Storage 177	Wall Drywall	complete
2025/07/25	Storage 177	Wall Drywall Finish	complete
2025/07/25	Storage 177	Wall Prime Paint	complete
2025/07/25	TECHNICAL SURVEILLANCE 188	In Wall Insulation	complete
2025/07/25	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	in progress
2025/07/25	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	no data
2025/07/25	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	not started
2025/07/25	TECHNICAL SURVEILLANCE 188	Wall Drywall	complete
2025/07/25	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	complete
2025/07/25	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	complete
2025/07/25	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/07/25	TRAFFIC SERGEANT 141	Overhead Duct Insulation	in progress
2025/07/25	TRAFFIC SERGEANT 141	Overhead Duct Rough In	in progress
2025/07/25	TRAFFIC SERGEANT 141	Overhead Plumbing	in progress
2025/07/25	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/07/25	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/07/25	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/07/25	TRIAGE/RECEPTION 134	In Wall Insulation	no data
2025/07/25	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in

progress  
 2025/07/25 | TRIAGE/RECEPTION 134 | Overhead Duct Rough In | in  
 progress  
 2025/07/25 | TRIAGE/RECEPTION 134 | Overhead Plumbing | no data  
 2025/07/25 | TRIAGE/RECEPTION 134 | Wall Drywall | complete  
 2025/07/25 | TRIAGE/RECEPTION 134 | Wall Drywall Finish | complete  
 2025/07/25 | TRIAGE/RECEPTION 134 | Wall Prime Paint | complete  
 2025/07/25 | TST WORKSHOP 187 | In Wall Insulation | complete  
 2025/07/25 | TST WORKSHOP 187 | Overhead Duct Insulation | not  
 started  
 2025/07/25 | TST WORKSHOP 187 | Overhead Duct Rough In | no data  
 2025/07/25 | TST WORKSHOP 187 | Overhead Plumbing | no data  
 2025/07/25 | TST WORKSHOP 187 | Wall Drywall | complete  
 2025/07/25 | TST WORKSHOP 187 | Wall Drywall Finish | complete  
 2025/07/25 | TST WORKSHOP 187 | Wall Prime Paint | complete  
 2025/07/25 | UNISEX RESTROOM 169 | In Wall Insulation | no data  
 2025/07/25 | UNISEX RESTROOM 169 | Overhead Duct Insulation | no  
 data  
 2025/07/25 | UNISEX RESTROOM 169 | Overhead Duct Rough In | no data  
 2025/07/25 | UNISEX RESTROOM 169 | Overhead Plumbing | no data  
 2025/07/25 | UNISEX RESTROOM 169 | Wall Drywall | no data  
 2025/07/25 | UNISEX RESTROOM 169 | Wall Drywall Finish | no data  
 2025/07/25 | UNISEX RESTROOM 169 | Wall Prime Paint | no data  
 2025/07/25 | VEHICLE MAINTENANCE BAYS 186 | In Wall Insulation | in  
 progress  
 2025/07/25 | VEHICLE MAINTENANCE BAYS 186 | Overhead Duct Insulation  
 | not started  
 2025/07/25 | VEHICLE MAINTENANCE BAYS 186 | Overhead Duct Rough In |  
 no data  
 2025/07/25 | VEHICLE MAINTENANCE BAYS 186 | Overhead Plumbing |  
 complete  
 2025/07/25 | VEHICLE MAINTENANCE BAYS 186 | Wall Drywall | complete  
 2025/07/25 | VEHICLE MAINTENANCE BAYS 186 | Wall Drywall Finish |  
 complete  
 2025/07/25 | VEHICLE MAINTENANCE BAYS 186 | Wall Prime Paint |  
 complete  
 2025/07/25 | VOLUNTEER/LIGHT DUTY 140 | In Wall Insulation | no data  
 2025/07/25 | VOLUNTEER/LIGHT DUTY 140 | Overhead Duct Insulation |  
 complete  
 2025/07/25 | VOLUNTEER/LIGHT DUTY 140 | Overhead Duct Rough In |  
 complete  
 2025/07/25 | VOLUNTEER/LIGHT DUTY 140 | Overhead Plumbing | in  
 progress  
 2025/07/25 | VOLUNTEER/LIGHT DUTY 140 | Wall Drywall | complete  
 2025/07/25 | VOLUNTEER/LIGHT DUTY 140 | Wall Drywall Finish |  
 complete  
 2025/07/25 | VOLUNTEER/LIGHT DUTY 140 | Wall Prime Paint | complete  
 2025/07/25 | WAITING/LOBBY 100 | In Wall Insulation | not started  
 2025/07/25 | WAITING/LOBBY 100 | Overhead Duct Insulation | no data  
 2025/07/25 | WAITING/LOBBY 100 | Overhead Duct Rough In | no data  
 2025/07/25 | WAITING/LOBBY 100 | Overhead Plumbing | not started  
 2025/07/25 | WAITING/LOBBY 100 | Wall Drywall | not started  
 2025/07/25 | WAITING/LOBBY 100 | Wall Drywall Finish | not started  
 2025/07/25 | WAITING/LOBBY 100 | Wall Prime Paint | not started

2025/07/25	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/07/25	WOMENS RESTROOM 113	Overhead Duct Insulation	no data
2025/07/25	WOMENS RESTROOM 113	Overhead Duct Rough In	complete
2025/07/25	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/07/25	WOMENS RESTROOM 113	Wall Drywall	complete
2025/07/25	WOMENS RESTROOM 113	Wall Drywall Finish	complete
2025/07/25	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/08/01	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/08/01	ADMIN ASSISTANT 125	Overhead Duct Insulation	complete
2025/08/01	ADMIN ASSISTANT 125	Overhead Duct Rough In	in progress
2025/08/01	ADMIN ASSISTANT 125	Overhead Plumbing	not started
2025/08/01	ADMIN ASSISTANT 125	Wall Drywall	complete
2025/08/01	ADMIN ASSISTANT 125	Wall Drywall Finish	complete
2025/08/01	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/08/01	AV ROOM 103	In Wall Insulation	no data
2025/08/01	AV ROOM 103	Overhead Duct Insulation	complete
2025/08/01	AV ROOM 103	Overhead Duct Rough In	no data
2025/08/01	AV ROOM 103	Overhead Plumbing	not started
2025/08/01	AV ROOM 103	Wall Drywall	complete
2025/08/01	AV ROOM 103	Wall Drywall Finish	complete
2025/08/01	AV ROOM 103	Wall Prime Paint	complete
2025/08/01	BREAK ROOM CONFERENCE 182	In Wall Insulation	no data
2025/08/01	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	in progress
2025/08/01	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	no data
2025/08/01	BREAK ROOM CONFERENCE 182	Overhead Plumbing	complete
2025/08/01	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/08/01	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	complete
2025/08/01	BREAK ROOM CONFERENCE 182	Wall Prime Paint	complete
2025/08/01	Background-159	In Wall Insulation	complete
2025/08/01	Background-159	Overhead Duct Insulation	complete
2025/08/01	Background-159	Overhead Duct Rough In	complete
2025/08/01	Background-159	Overhead Plumbing	not started
2025/08/01	Background-159	Wall Drywall	complete
2025/08/01	Background-159	Wall Drywall Finish	complete
2025/08/01	Background-159	Wall Prime Paint	complete
2025/08/01	CENTRAL BREAKROOM 145	In Wall Insulation	complete
2025/08/01	CENTRAL BREAKROOM 145	Overhead Duct Insulation	complete
2025/08/01	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/08/01	CENTRAL BREAKROOM 145	Overhead Plumbing	complete
2025/08/01	CENTRAL BREAKROOM 145	Wall Drywall	complete
2025/08/01	CENTRAL BREAKROOM 145	Wall Drywall Finish	in progress
2025/08/01	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/08/01	COLD CASE 175	In Wall Insulation	no data



2025/08/01	COLD CASE 175	Overhead Duct Insulation	complete
2025/08/01	COLD CASE 175	Overhead Duct Rough In	in progress
2025/08/01	COLD CASE 175	Overhead Plumbing	complete
2025/08/01	COLD CASE 175	Wall Drywall	complete
2025/08/01	COLD CASE 175	Wall Drywall Finish	complete
2025/08/01	COLD CASE 175	Wall Prime Paint	complete
2025/08/01	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/08/01	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	complete
2025/08/01	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	no data
2025/08/01	COMMUNITY AFFAIRS 124	Overhead Plumbing	no data
2025/08/01	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/08/01	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/08/01	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/08/01	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/08/01	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	in progress
2025/08/01	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	no data
2025/08/01	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	not started
2025/08/01	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete
2025/08/01	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	complete
2025/08/01	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	complete
2025/08/01	CONFERENCE ROOM 153	In Wall Insulation	complete
2025/08/01	CONFERENCE ROOM 153	Overhead Duct Insulation	in progress
2025/08/01	CONFERENCE ROOM 153	Overhead Duct Rough In	in progress
2025/08/01	CONFERENCE ROOM 153	Overhead Plumbing	not started
2025/08/01	CONFERENCE ROOM 153	Wall Drywall	complete
2025/08/01	CONFERENCE ROOM 153	Wall Drywall Finish	complete
2025/08/01	CONFERENCE ROOM 153	Wall Prime Paint	complete
2025/08/01	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/08/01	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	complete
2025/08/01	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	in progress
2025/08/01	CONFERENCE/WAR ROOM 163	Overhead Plumbing	not started
2025/08/01	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/08/01	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete
2025/08/01	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/08/01	COPY 176	In Wall Insulation	complete
2025/08/01	COPY 176	Overhead Duct Insulation	complete
2025/08/01	COPY 176	Overhead Duct Rough In	complete
2025/08/01	COPY 176	Overhead Plumbing	not started
2025/08/01	COPY 176	Wall Drywall	complete
2025/08/01	COPY 176	Wall Drywall Finish	complete

2025/08/01	COPY 176	Wall Prime Paint	complete
2025/08/01	COPY/MAIL ROOM 114	In Wall Insulation	complete
2025/08/01	COPY/MAIL ROOM 114	Overhead Duct Insulation	complete
2025/08/01	COPY/MAIL ROOM 114	Overhead Duct Rough In	in progress
2025/08/01	COPY/MAIL ROOM 114	Overhead Plumbing	complete
2025/08/01	COPY/MAIL ROOM 114	Wall Drywall	complete
2025/08/01	COPY/MAIL ROOM 114	Wall Drywall Finish	complete
2025/08/01	COPY/MAIL ROOM 114	Wall Prime Paint	complete
2025/08/01	CORRIDOR 107	In Wall Insulation	complete
2025/08/01	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/08/01	CORRIDOR 107	Overhead Duct Rough In	in progress
2025/08/01	CORRIDOR 107	Overhead Plumbing	in progress
2025/08/01	CORRIDOR 107	Wall Drywall	complete
2025/08/01	CORRIDOR 107	Wall Drywall Finish	complete
2025/08/01	CORRIDOR 107	Wall Prime Paint	complete
2025/08/01	CORRIDOR 108	In Wall Insulation	complete
2025/08/01	CORRIDOR 108	In Wall Insulation	no data
2025/08/01	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/08/01	CORRIDOR 108	Overhead Duct Insulation	no data
2025/08/01	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/08/01	CORRIDOR 108	Overhead Duct Rough In	no data
2025/08/01	CORRIDOR 108	Overhead Plumbing	in progress
2025/08/01	CORRIDOR 108	Overhead Plumbing	no data
2025/08/01	CORRIDOR 108	Wall Drywall	complete
2025/08/01	CORRIDOR 108	Wall Drywall	complete
2025/08/01	CORRIDOR 108	Wall Drywall Finish	complete
2025/08/01	CORRIDOR 108	Wall Drywall Finish	complete
2025/08/01	CORRIDOR 108	Wall Prime Paint	complete
2025/08/01	CORRIDOR 108	Wall Prime Paint	complete
2025/08/01	CORRIDOR 109	In Wall Insulation	complete
2025/08/01	CORRIDOR 109	Overhead Duct Insulation	in progress
2025/08/01	CORRIDOR 109	Overhead Duct Rough In	in progress
2025/08/01	CORRIDOR 109	Overhead Plumbing	in progress
2025/08/01	CORRIDOR 109	Wall Drywall	complete
2025/08/01	CORRIDOR 109	Wall Drywall Finish	complete
2025/08/01	CORRIDOR 109	Wall Prime Paint	complete
2025/08/01	CORRIDOR 110	In Wall Insulation	no data
2025/08/01	CORRIDOR 110	In Wall Insulation	no data
2025/08/01	CORRIDOR 110	Overhead Duct Insulation	in progress
2025/08/01	CORRIDOR 110	Overhead Duct Insulation	no data
2025/08/01	CORRIDOR 110	Overhead Duct Rough In	in progress
2025/08/01	CORRIDOR 110	Overhead Duct Rough In	no data
2025/08/01	CORRIDOR 110	Overhead Plumbing	in progress
2025/08/01	CORRIDOR 110	Overhead Plumbing	in progress
2025/08/01	CORRIDOR 110	Wall Drywall	complete
2025/08/01	CORRIDOR 110	Wall Drywall	complete
2025/08/01	CORRIDOR 110	Wall Drywall Finish	complete
2025/08/01	CORRIDOR 110	Wall Drywall Finish	complete
2025/08/01	CORRIDOR 110	Wall Prime Paint	complete
2025/08/01	CORRIDOR 110	Wall Prime Paint	complete
2025/08/01	CORRIDOR 181	In Wall Insulation	complete
2025/08/01	CORRIDOR 181	Overhead Duct Insulation	in progress

2025/08/01	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/08/01	CORRIDOR 181	Overhead Plumbing	in progress
2025/08/01	CORRIDOR 181	Wall Drywall	complete
2025/08/01	CORRIDOR 181	Wall Drywall Finish	complete
2025/08/01	CORRIDOR 181	Wall Prime Paint	complete
2025/08/01	CORRIDOR144	In Wall Insulation	no data
2025/08/01	CORRIDOR144	Overhead Duct Insulation	in progress
2025/08/01	CORRIDOR144	Overhead Duct Rough In	no data
2025/08/01	CORRIDOR144	Overhead Plumbing	in progress
2025/08/01	CORRIDOR144	Wall Drywall	complete
2025/08/01	CORRIDOR144	Wall Drywall Finish	complete
2025/08/01	CORRIDOR144	Wall Prime Paint	complete
2025/08/01	CPL 173	In Wall Insulation	complete
2025/08/01	CPL 173	Overhead Duct Insulation	complete
2025/08/01	CPL 173	Overhead Duct Rough In	in progress
2025/08/01	CPL 173	Overhead Plumbing	complete
2025/08/01	CPL 173	Wall Drywall	complete
2025/08/01	CPL 173	Wall Drywall Finish	complete
2025/08/01	CPL 173	Wall Prime Paint	complete
2025/08/01	CPL 174	In Wall Insulation	complete
2025/08/01	CPL 174	Overhead Duct Insulation	no data
2025/08/01	CPL 174	Overhead Duct Rough In	no data
2025/08/01	CPL 174	Overhead Plumbing	no data
2025/08/01	CPL 174	Wall Drywall	complete
2025/08/01	CPL 174	Wall Drywall Finish	complete
2025/08/01	CPL 174	Wall Prime Paint	complete
2025/08/01	DRY STORAGE 146	In Wall Insulation	complete
2025/08/01	DRY STORAGE 146	Overhead Duct Insulation	complete
2025/08/01	DRY STORAGE 146	Overhead Duct Rough In	complete
2025/08/01	DRY STORAGE 146	Overhead Plumbing	not started
2025/08/01	DRY STORAGE 146	Wall Drywall	complete
2025/08/01	DRY STORAGE 146	Wall Drywall Finish	complete
2025/08/01	DRY STORAGE 146	Wall Prime Paint	in progress
2025/08/01	FIRE RISER 178	In Wall Insulation	no data
2025/08/01	FIRE RISER 178	Overhead Duct Insulation	no data
2025/08/01	FIRE RISER 178	Overhead Duct Rough In	no data
2025/08/01	FIRE RISER 178	Overhead Plumbing	no data
2025/08/01	FIRE RISER 178	Wall Drywall	no data
2025/08/01	FIRE RISER 178	Wall Drywall Finish	no data
2025/08/01	FIRE RISER 178	Wall Prime Paint	no data
2025/08/01	GREETING ROOM 106	In Wall Insulation	no data
2025/08/01	GREETING ROOM 106	Overhead Duct Insulation	complete
2025/08/01	GREETING ROOM 106	Overhead Duct Rough In	in progress
2025/08/01	GREETING ROOM 106	Overhead Plumbing	not started
2025/08/01	GREETING ROOM 106	Wall Drywall	complete
2025/08/01	GREETING ROOM 106	Wall Drywall Finish	complete
2025/08/01	GREETING ROOM 106	Wall Prime Paint	complete
2025/08/01	HR 149	In Wall Insulation	complete
2025/08/01	HR 149	Overhead Duct Insulation	complete
2025/08/01	HR 149	Overhead Duct Rough In	complete
2025/08/01	HR 149	Overhead Plumbing	not started
2025/08/01	HR 149	Wall Drywall	complete
2025/08/01	HR 149	Wall Drywall Finish	complete

2025/08/01	HR 149	Wall Prime Paint	complete
2025/08/01	HR 150	In Wall Insulation	complete
2025/08/01	HR 150	Overhead Duct Insulation	complete
2025/08/01	HR 150	Overhead Duct Rough In	complete
2025/08/01	HR 150	Overhead Plumbing	not started
2025/08/01	HR 150	Wall Drywall	complete
2025/08/01	HR 150	Wall Drywall Finish	complete
2025/08/01	HR 150	Wall Prime Paint	complete
2025/08/01	HR 151	In Wall Insulation	complete
2025/08/01	HR 151	Overhead Duct Insulation	complete
2025/08/01	HR 151	Overhead Duct Rough In	complete
2025/08/01	HR 151	Overhead Plumbing	complete
2025/08/01	HR 151	Wall Drywall	complete
2025/08/01	HR 151	Wall Drywall Finish	complete
2025/08/01	HR 151	Wall Prime Paint	complete
2025/08/01	HR 154	In Wall Insulation	complete
2025/08/01	HR 154	Overhead Duct Insulation	complete
2025/08/01	HR 154	Overhead Duct Rough In	complete
2025/08/01	HR 154	Overhead Plumbing	complete
2025/08/01	HR 154	Wall Drywall	complete
2025/08/01	HR 154	Wall Drywall Finish	complete
2025/08/01	HR 154	Wall Prime Paint	complete
2025/08/01	HR 155	In Wall Insulation	complete
2025/08/01	HR 155	Overhead Duct Insulation	complete
2025/08/01	HR 155	Overhead Duct Rough In	complete
2025/08/01	HR 155	Overhead Plumbing	no data
2025/08/01	HR 155	Wall Drywall	complete
2025/08/01	HR 155	Wall Drywall Finish	complete
2025/08/01	HR 155	Wall Prime Paint	complete
2025/08/01	HR 156	In Wall Insulation	complete
2025/08/01	HR 156	Overhead Duct Insulation	complete
2025/08/01	HR 156	Overhead Duct Rough In	complete
2025/08/01	HR 156	Overhead Plumbing	not started
2025/08/01	HR 156	Wall Drywall	complete
2025/08/01	HR 156	Wall Drywall Finish	complete
2025/08/01	HR 156	Wall Prime Paint	complete
2025/08/01	HR 157	In Wall Insulation	no data
2025/08/01	HR 157	Overhead Duct Insulation	no data
2025/08/01	HR 157	Overhead Duct Rough In	no data
2025/08/01	HR 157	Overhead Plumbing	no data
2025/08/01	HR 157	Wall Drywall	no data
2025/08/01	HR 157	Wall Drywall Finish	no data
2025/08/01	HR 157	Wall Prime Paint	no data
2025/08/01	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/08/01	HUMAN RESOURCES 148	Overhead Duct Insulation	in progress
2025/08/01	HUMAN RESOURCES 148	Overhead Duct Rough In	no data
2025/08/01	HUMAN RESOURCES 148	Overhead Plumbing	in progress
2025/08/01	HUMAN RESOURCES 148	Wall Drywall	complete
2025/08/01	HUMAN RESOURCES 148	Wall Drywall Finish	complete
2025/08/01	HUMAN RESOURCES 148	Wall Prime Paint	complete
2025/08/01	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/08/01	INTERNAL AFFAIRS 119	Overhead Duct Insulation	complete

2025/08/01	INTERNAL AFFAIRS 119	Overhead Duct Rough In	in progress
2025/08/01	INTERNAL AFFAIRS 119	Overhead Plumbing	complete
2025/08/01	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/08/01	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/08/01	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/08/01	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/08/01	INTERNAL AFFAIRS 120	Overhead Duct Insulation	complete
2025/08/01	INTERNAL AFFAIRS 120	Overhead Duct Rough In	complete
2025/08/01	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/08/01	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/08/01	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/08/01	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/08/01	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/08/01	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	complete
2025/08/01	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	complete
2025/08/01	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	complete
2025/08/01	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/08/01	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/08/01	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/08/01	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	no data
2025/08/01	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	complete
2025/08/01	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	in progress
2025/08/01	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	complete
2025/08/01	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/08/01	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	complete
2025/08/01	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	complete
2025/08/01	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	no data
2025/08/01	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	complete
2025/08/01	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	complete
2025/08/01	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	complete
2025/08/01	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/08/01	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/08/01	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	

complete

2025/08/01	IT 115	In Wall Insulation	complete
2025/08/01	IT 115	Overhead Duct Insulation	no data
2025/08/01	IT 115	Overhead Duct Rough In	no data
2025/08/01	IT 115	Overhead Plumbing	no data
2025/08/01	IT 115	Wall Drywall	complete
2025/08/01	IT 115	Wall Drywall Finish	complete
2025/08/01	IT 115	Wall Prime Paint	complete
2025/08/01	IT 135	In Wall Insulation	complete
2025/08/01	IT 135	Overhead Duct Insulation	complete
2025/08/01	IT 135	Overhead Duct Rough In	in progress
2025/08/01	IT 135	Overhead Plumbing	complete
2025/08/01	IT 135	Wall Drywall	complete
2025/08/01	IT 135	Wall Drywall Finish	complete
2025/08/01	IT 135	Wall Prime Paint	complete
2025/08/01	IT MANAGER 136	In Wall Insulation	no data
2025/08/01	IT MANAGER 136	Overhead Duct Insulation	in progress
2025/08/01	IT MANAGER 136	Overhead Duct Rough In	in progress
2025/08/01	IT MANAGER 136	Overhead Plumbing	complete
2025/08/01	IT MANAGER 136	Wall Drywall	complete
2025/08/01	IT MANAGER 136	Wall Drywall Finish	complete
2025/08/01	IT MANAGER 136	Wall Prime Paint	complete
2025/08/01	IT MANAGER 137	In Wall Insulation	no data
2025/08/01	IT MANAGER 137	Overhead Duct Insulation	complete
2025/08/01	IT MANAGER 137	Overhead Duct Rough In	no data
2025/08/01	IT MANAGER 137	Overhead Plumbing	complete
2025/08/01	IT MANAGER 137	Wall Drywall	complete
2025/08/01	IT MANAGER 137	Wall Drywall Finish	complete
2025/08/01	IT MANAGER 137	Wall Prime Paint	complete
2025/08/01	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/08/01	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data
2025/08/01	JUVENILE INTERVIEW 165	Overhead Duct Rough In	complete
2025/08/01	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/08/01	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/08/01	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/08/01	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/08/01	JUVENILE INTERVIEWERS 166	In Wall Insulation	no data
2025/08/01	JUVENILE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/08/01	JUVENILE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/08/01	JUVENILE INTERVIEWERS 166	Overhead Plumbing	no data
2025/08/01	JUVENILE INTERVIEWERS 166	Wall Drywall	complete
2025/08/01	JUVENILE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/08/01	JUVENILE INTERVIEWERS 166	Wall Prime Paint	complete
2025/08/01	KEY ROOM 185	In Wall Insulation	complete
2025/08/01	KEY ROOM 185	Overhead Duct Insulation	in progress
2025/08/01	KEY ROOM 185	Overhead Duct Rough In	no data

2025/08/01	KEY ROOM 185	Overhead Plumbing	not started
2025/08/01	KEY ROOM 185	Wall Drywall	complete
2025/08/01	KEY ROOM 185	Wall Drywall Finish	complete
2025/08/01	KEY ROOM 185	Wall Prime Paint	complete
2025/08/01	LT 170	In Wall Insulation	complete
2025/08/01	LT 170	Overhead Duct Insulation	complete
2025/08/01	LT 170	Overhead Duct Rough In	complete
2025/08/01	LT 170	Overhead Plumbing	not started
2025/08/01	LT 170	Wall Drywall	complete
2025/08/01	LT 170	Wall Drywall Finish	complete
2025/08/01	LT 170	Wall Prime Paint	complete
2025/08/01	MACHINE ROOM 191	In Wall Insulation	no data
2025/08/01	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/08/01	MACHINE ROOM 191	Overhead Duct Rough In	no data
2025/08/01	MACHINE ROOM 191	Overhead Plumbing	no data
2025/08/01	MACHINE ROOM 191	Wall Drywall	complete
2025/08/01	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/08/01	MACHINE ROOM 191	Wall Prime Paint	complete
2025/08/01	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/08/01	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/08/01	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/08/01	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/08/01	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/08/01	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/08/01	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/08/01	MAIN JANITORIAL111	In Wall Insulation	no data
2025/08/01	MAIN JANITORIAL111	Overhead Duct Insulation	no data
2025/08/01	MAIN JANITORIAL111	Overhead Duct Rough In	complete
2025/08/01	MAIN JANITORIAL111	Overhead Plumbing	no data
2025/08/01	MAIN JANITORIAL111	Wall Drywall	complete
2025/08/01	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/08/01	MAIN JANITORIAL111	Wall Prime Paint	complete
2025/08/01	MARINE SERGEANT 142	In Wall Insulation	complete
2025/08/01	MARINE SERGEANT 142	Overhead Duct Insulation	in progress
2025/08/01	MARINE SERGEANT 142	Overhead Duct Rough In	in progress
2025/08/01	MARINE SERGEANT 142	Overhead Plumbing	in progress
2025/08/01	MARINE SERGEANT 142	Wall Drywall	complete
2025/08/01	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/08/01	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/08/01	MECHANICAL 192	In Wall Insulation	no data
2025/08/01	MECHANICAL 192	Overhead Duct Insulation	no data
2025/08/01	MECHANICAL 192	Overhead Duct Rough In	no data
2025/08/01	MECHANICAL 192	Overhead Plumbing	no data
2025/08/01	MECHANICAL 192	Wall Drywall	no data
2025/08/01	MECHANICAL 192	Wall Drywall Finish	no data
2025/08/01	MECHANICAL 192	Wall Prime Paint	no data
2025/08/01	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/08/01	MECHANICAL ROOM 122	Overhead Duct Insulation	no data

2025/08/01	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/08/01	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/08/01	MECHANICAL ROOM 122	Wall Drywall	no data
2025/08/01	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/08/01	MECHANICAL ROOM 122	Wall Prime Paint	no data
2025/08/01	MENS RESTROOM 112	In Wall Insulation	complete
2025/08/01	MENS RESTROOM 112	Overhead Duct Insulation	complete
2025/08/01	MENS RESTROOM 112	Overhead Duct Rough In	complete
2025/08/01	MENS RESTROOM 112	Overhead Plumbing	complete
2025/08/01	MENS RESTROOM 112	Wall Drywall	complete
2025/08/01	MENS RESTROOM 112	Wall Drywall Finish	complete
2025/08/01	MENS RESTROOM 112	Wall Prime Paint	not started
2025/08/01	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
2025/08/01	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/08/01	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	in progress
2025/08/01	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	in progress
2025/08/01	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/08/01	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/08/01	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/08/01	MIS SHREDDING 117	In Wall Insulation	complete
2025/08/01	MIS SHREDDING 117	Overhead Duct Insulation	complete
2025/08/01	MIS SHREDDING 117	Overhead Duct Rough In	complete
2025/08/01	MIS SHREDDING 117	Overhead Plumbing	complete
2025/08/01	MIS SHREDDING 117	Wall Drywall	complete
2025/08/01	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/08/01	MIS SHREDDING 117	Wall Prime Paint	complete
2025/08/01	OFFICE 128	In Wall Insulation	no data
2025/08/01	OFFICE 128	Overhead Duct Insulation	no data
2025/08/01	OFFICE 128	Overhead Duct Rough In	no data
2025/08/01	OFFICE 128	Overhead Plumbing	no data
2025/08/01	OFFICE 128	Wall Drywall	complete
2025/08/01	OFFICE 128	Wall Drywall Finish	complete
2025/08/01	OFFICE 128	Wall Prime Paint	complete
2025/08/01	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	no data
2025/08/01	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	in progress
2025/08/01	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	no data
2025/08/01	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	in progress
2025/08/01	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/08/01	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/08/01	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	complete
2025/08/01	PARTS STORAGE 189	In Wall Insulation	no data
2025/08/01	PARTS STORAGE 189	Overhead Duct Insulation	no data



2025/08/01	PARTS STORAGE 189	Overhead Duct Rough In	no data
2025/08/01	PARTS STORAGE 189	Overhead Plumbing	no data
2025/08/01	PARTS STORAGE 189	Wall Drywall	complete
2025/08/01	PARTS STORAGE 189	Wall Drywall Finish	complete
2025/08/01	PARTS STORAGE 189	Wall Prime Paint	complete
2025/08/01	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/08/01	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/08/01	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/08/01	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/08/01	PUBLIC RESTROOM 106	Wall Drywall	no data
2025/08/01	PUBLIC RESTROOM 106	Wall Drywall Finish	no data
2025/08/01	PUBLIC RESTROOM 106	Wall Prime Paint	no data
2025/08/01	Polygraph 152	In Wall Insulation	complete
2025/08/01	Polygraph 152	Overhead Duct Insulation	in progress
2025/08/01	Polygraph 152	Overhead Duct Rough In	in progress
2025/08/01	Polygraph 152	Overhead Plumbing	not started
2025/08/01	Polygraph 152	Wall Drywall	complete
2025/08/01	Polygraph 152	Wall Drywall Finish	complete
2025/08/01	Polygraph 152	Wall Prime Paint	complete
2025/08/01	RECEPTION 101	In Wall Insulation	no data
2025/08/01	RECEPTION 101	Overhead Duct Insulation	no data
2025/08/01	RECEPTION 101	Overhead Duct Rough In	no data
2025/08/01	RECEPTION 101	Overhead Plumbing	no data
2025/08/01	RECEPTION 101	Wall Drywall	no data
2025/08/01	RECEPTION 101	Wall Drywall Finish	no data
2025/08/01	RECEPTION 101	Wall Prime Paint	no data
2025/08/01	RECEPTION 147	In Wall Insulation	complete
2025/08/01	RECEPTION 147	Overhead Duct Insulation	complete
2025/08/01	RECEPTION 147	Overhead Duct Rough In	in progress
2025/08/01	RECEPTION 147	Overhead Plumbing	complete
2025/08/01	RECEPTION 147	Wall Drywall	complete
2025/08/01	RECEPTION 147	Wall Drywall Finish	complete
2025/08/01	RECEPTION 147	Wall Prime Paint	complete
2025/08/01	RECEPTION 179	In Wall Insulation	complete
2025/08/01	RECEPTION 179	Overhead Duct Insulation	in progress
2025/08/01	RECEPTION 179	Overhead Duct Rough In	in progress
2025/08/01	RECEPTION 179	Overhead Plumbing	not started
2025/08/01	RECEPTION 179	Wall Drywall	complete
2025/08/01	RECEPTION 179	Wall Drywall Finish	complete
2025/08/01	RECEPTION 179	Wall Prime Paint	complete
2025/08/01	RECORDS 130	In Wall Insulation	no data
2025/08/01	RECORDS 130	Overhead Duct Insulation	complete
2025/08/01	RECORDS 130	Overhead Duct Rough In	in progress
2025/08/01	RECORDS 130	Overhead Plumbing	complete
2025/08/01	RECORDS 130	Wall Drywall	complete
2025/08/01	RECORDS 130	Wall Drywall Finish	complete
2025/08/01	RECORDS 130	Wall Prime Paint	complete
2025/08/01	RECORDS STORAGE 133	In Wall Insulation	complete
2025/08/01	RECORDS STORAGE 133	Overhead Duct Insulation	complete
2025/08/01	RECORDS STORAGE 133	Overhead Duct Rough In	in progress
2025/08/01	RECORDS STORAGE 133	Overhead Plumbing	complete

2025/08/01	RECORDS STORAGE 133	Wall Drywall	complete
2025/08/01	RECORDS STORAGE 133	Wall Drywall Finish	complete
2025/08/01	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/08/01	RECORDS SUPERVISOR 131	In Wall Insulation	no data
2025/08/01	RECORDS SUPERVISOR 131	Overhead Duct Insulation	complete
2025/08/01	RECORDS SUPERVISOR 131	Overhead Duct Rough In	no data
2025/08/01	RECORDS SUPERVISOR 131	Overhead Plumbing	not started
2025/08/01	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/08/01	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/08/01	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/08/01	RECORDS SUPERVISOR 132	In Wall Insulation	no data
2025/08/01	RECORDS SUPERVISOR 132	Overhead Duct Insulation	complete
2025/08/01	RECORDS SUPERVISOR 132	Overhead Duct Rough In	in progress
2025/08/01	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/08/01	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/08/01	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/08/01	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/08/01	RESTROOM 183	In Wall Insulation	complete
2025/08/01	RESTROOM 183	Overhead Duct Insulation	complete
2025/08/01	RESTROOM 183	Overhead Duct Rough In	complete
2025/08/01	RESTROOM 183	Overhead Plumbing	complete
2025/08/01	RESTROOM 183	Wall Drywall	complete
2025/08/01	RESTROOM 183	Wall Drywall Finish	in progress
2025/08/01	RESTROOM 183	Wall Prime Paint	not started
2025/08/01	Risk Management - 158	In Wall Insulation	complete
2025/08/01	Risk Management - 158	Overhead Duct Insulation	complete
2025/08/01	Risk Management - 158	Overhead Duct Rough In	in progress
2025/08/01	Risk Management - 158	Overhead Plumbing	complete
2025/08/01	Risk Management - 158	Wall Drywall	complete
2025/08/01	Risk Management - 158	Wall Drywall Finish	complete
2025/08/01	Risk Management - 158	Wall Prime Paint	complete
2025/08/01	SALLY PORT 105	In Wall Insulation	not started
2025/08/01	SALLY PORT 105	Overhead Duct Insulation	in progress
2025/08/01	SALLY PORT 105	Overhead Duct Rough In	no data
2025/08/01	SALLY PORT 105	Overhead Plumbing	no data
2025/08/01	SALLY PORT 105	Wall Drywall	not started
2025/08/01	SALLY PORT 105	Wall Drywall Finish	not started
2025/08/01	SALLY PORT 105	Wall Prime Paint	not started
2025/08/01	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/08/01	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/08/01	SANE EXAM ROOM 168	Overhead Duct Rough In	complete
2025/08/01	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/08/01	SANE EXAM ROOM 168	Wall Drywall	complete
2025/08/01	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/08/01	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/08/01	SGT 171	In Wall Insulation	no data
2025/08/01	SGT 171	Overhead Duct Insulation	complete

2025/08/01	SGT 171	Overhead Duct Rough In	in progress
2025/08/01	SGT 171	Overhead Plumbing	complete
2025/08/01	SGT 171	Wall Drywall	complete
2025/08/01	SGT 171	Wall Drywall Finish	complete
2025/08/01	SGT 171	Wall Prime Paint	complete
2025/08/01	SGT 172	In Wall Insulation	complete
2025/08/01	SGT 172	Overhead Duct Insulation	no data
2025/08/01	SGT 172	Overhead Duct Rough In	in progress
2025/08/01	SGT 172	Overhead Plumbing	complete
2025/08/01	SGT 172	Wall Drywall	complete
2025/08/01	SGT 172	Wall Drywall Finish	complete
2025/08/01	SGT 172	Wall Prime Paint	complete
2025/08/01	SHIPPING STORAGE 190	In Wall Insulation	complete
2025/08/01	SHIPPING STORAGE 190	Overhead Duct Insulation	in progress
2025/08/01	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/08/01	SHIPPING STORAGE 190	Overhead Plumbing	no data
2025/08/01	SHIPPING STORAGE 190	Wall Drywall	complete
2025/08/01	SHIPPING STORAGE 190	Wall Drywall Finish	complete
2025/08/01	SHIPPING STORAGE 190	Wall Prime Paint	complete
2025/08/01	SHOP FORMAN 184	In Wall Insulation	complete
2025/08/01	SHOP FORMAN 184	Overhead Duct Insulation	in progress
2025/08/01	SHOP FORMAN 184	Overhead Duct Rough In	no data
2025/08/01	SHOP FORMAN 184	Overhead Plumbing	not started
2025/08/01	SHOP FORMAN 184	Wall Drywall	complete
2025/08/01	SHOP FORMAN 184	Wall Drywall Finish	complete
2025/08/01	SHOP FORMAN 184	Wall Prime Paint	complete
2025/08/01	SOFT INTERVIEW 161	In Wall Insulation	no data
2025/08/01	SOFT INTERVIEW 161	Overhead Duct Insulation	no data
2025/08/01	SOFT INTERVIEW 161	Overhead Duct Rough In	no data
2025/08/01	SOFT INTERVIEW 161	Overhead Plumbing	no data
2025/08/01	SOFT INTERVIEW 161	Wall Drywall	no data
2025/08/01	SOFT INTERVIEW 161	Wall Drywall Finish	no data
2025/08/01	SOFT INTERVIEW 161	Wall Prime Paint	no data
2025/08/01	SOFT INTERVIEW 162	In Wall Insulation	no data
2025/08/01	SOFT INTERVIEW 162	Overhead Duct Insulation	no data
2025/08/01	SOFT INTERVIEW 162	Overhead Duct Rough In	no data
2025/08/01	SOFT INTERVIEW 162	Overhead Plumbing	no data
2025/08/01	SOFT INTERVIEW 162	Wall Drywall	no data
2025/08/01	SOFT INTERVIEW 162	Wall Drywall Finish	no data
2025/08/01	SOFT INTERVIEW 162	Wall Prime Paint	no data
2025/08/01	SPECIAL OPERATION LT 143	In Wall Insulation	no data
2025/08/01	SPECIAL OPERATION LT 143	Overhead Duct Insulation	no data
2025/08/01	SPECIAL OPERATION LT 143	Overhead Duct Rough In	no data
2025/08/01	SPECIAL OPERATION LT 143	Overhead Plumbing	no data
2025/08/01	SPECIAL OPERATION LT 143	Wall Drywall	complete
2025/08/01	SPECIAL OPERATION LT 143	Wall Drywall Finish	complete
2025/08/01	SPECIAL OPERATION LT 143	Wall Prime Paint	complete
2025/08/01	STAIR A	In Wall Insulation	no data
2025/08/01	STAIR A	Overhead Duct Insulation	no data

2025/08/01	STAIR A	Overhead Duct Rough In	no data
2025/08/01	STAIR A	Overhead Plumbing	complete
2025/08/01	STAIR A	Wall Drywall	not started
2025/08/01	STAIR A	Wall Drywall Finish	not started
2025/08/01	STAIR A	Wall Prime Paint	in progress
2025/08/01	STORAGE 104	In Wall Insulation	no data
2025/08/01	STORAGE 104	Overhead Duct Insulation	in progress
2025/08/01	STORAGE 104	Overhead Duct Rough In	in progress
2025/08/01	STORAGE 104	Overhead Plumbing	not started
2025/08/01	STORAGE 104	Wall Drywall	complete
2025/08/01	STORAGE 104	Wall Drywall Finish	complete
2025/08/01	STORAGE 104	Wall Prime Paint	complete
2025/08/01	STORAGE 127	In Wall Insulation	no data
2025/08/01	STORAGE 127	Overhead Duct Insulation	complete
2025/08/01	STORAGE 127	Overhead Duct Rough In	no data
2025/08/01	STORAGE 127	Overhead Plumbing	not started
2025/08/01	STORAGE 127	Wall Drywall	complete
2025/08/01	STORAGE 127	Wall Drywall Finish	complete
2025/08/01	STORAGE 127	Wall Prime Paint	complete
2025/08/01	STUDIO 126	In Wall Insulation	complete
2025/08/01	STUDIO 126	Overhead Duct Insulation	complete
2025/08/01	STUDIO 126	Overhead Duct Rough In	complete
2025/08/01	STUDIO 126	Overhead Plumbing	complete
2025/08/01	STUDIO 126	Wall Drywall	complete
2025/08/01	STUDIO 126	Wall Drywall Finish	complete
2025/08/01	STUDIO 126	Wall Prime Paint	complete
2025/08/01	SUPERVISOR 129	In Wall Insulation	complete
2025/08/01	SUPERVISOR 129	Overhead Duct Insulation	complete
2025/08/01	SUPERVISOR 129	Overhead Duct Rough In	complete
2025/08/01	SUPERVISOR 129	Overhead Plumbing	not started
2025/08/01	SUPERVISOR 129	Wall Drywall	complete
2025/08/01	SUPERVISOR 129	Wall Drywall Finish	complete
2025/08/01	SUPERVISOR 129	Wall Prime Paint	complete
2025/08/01	Storage 164	In Wall Insulation	complete
2025/08/01	Storage 164	Overhead Duct Insulation	complete
2025/08/01	Storage 164	Overhead Duct Rough In	complete
2025/08/01	Storage 164	Overhead Plumbing	not started
2025/08/01	Storage 164	Wall Drywall	complete
2025/08/01	Storage 164	Wall Drywall Finish	complete
2025/08/01	Storage 164	Wall Prime Paint	complete
2025/08/01	Storage 177	In Wall Insulation	complete
2025/08/01	Storage 177	Overhead Duct Insulation	complete
2025/08/01	Storage 177	Overhead Duct Rough In	complete
2025/08/01	Storage 177	Overhead Plumbing	not started
2025/08/01	Storage 177	Wall Drywall	complete
2025/08/01	Storage 177	Wall Drywall Finish	complete
2025/08/01	Storage 177	Wall Prime Paint	complete
2025/08/01	TECHNICAL SURVEILLANCE 188	In Wall Insulation	complete
2025/08/01	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	complete
2025/08/01	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	no data
2025/08/01	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	no

data

2025/08/01		TECHNICAL SURVEILLANCE 188		Wall Drywall		complete
2025/08/01		TECHNICAL SURVEILLANCE 188		Wall Drywall Finish		complete
2025/08/01		TECHNICAL SURVEILLANCE 188		Wall Prime Paint		complete
2025/08/01		TRAFFIC SERGEANT 141		In Wall Insulation		no data
2025/08/01		TRAFFIC SERGEANT 141		Overhead Duct Insulation		in progress
2025/08/01		TRAFFIC SERGEANT 141		Overhead Duct Rough In		in progress
2025/08/01		TRAFFIC SERGEANT 141		Overhead Plumbing		in progress
2025/08/01		TRAFFIC SERGEANT 141		Wall Drywall		complete
2025/08/01		TRAFFIC SERGEANT 141		Wall Drywall Finish		complete
2025/08/01		TRAFFIC SERGEANT 141		Wall Prime Paint		complete
2025/08/01		TRIAGE/RECEPTION 134		In Wall Insulation		no data
2025/08/01		TRIAGE/RECEPTION 134		Overhead Duct Insulation		no data
2025/08/01		TRIAGE/RECEPTION 134		Overhead Duct Rough In		no data
2025/08/01		TRIAGE/RECEPTION 134		Overhead Plumbing		no data
2025/08/01		TRIAGE/RECEPTION 134		Wall Drywall		complete
2025/08/01		TRIAGE/RECEPTION 134		Wall Drywall Finish		complete
2025/08/01		TRIAGE/RECEPTION 134		Wall Prime Paint		complete
2025/08/01		TST WORKSHOP 187		In Wall Insulation		complete
2025/08/01		TST WORKSHOP 187		Overhead Duct Insulation		not started
2025/08/01		TST WORKSHOP 187		Overhead Duct Rough In		no data
2025/08/01		TST WORKSHOP 187		Overhead Plumbing		no data
2025/08/01		TST WORKSHOP 187		Wall Drywall		complete
2025/08/01		TST WORKSHOP 187		Wall Drywall Finish		complete
2025/08/01		TST WORKSHOP 187		Wall Prime Paint		complete
2025/08/01		UNISEX RESTROOM 169		In Wall Insulation		no data
2025/08/01		UNISEX RESTROOM 169		Overhead Duct Insulation		no data
2025/08/01		UNISEX RESTROOM 169		Overhead Duct Rough In		no data
2025/08/01		UNISEX RESTROOM 169		Overhead Plumbing		no data
2025/08/01		UNISEX RESTROOM 169		Wall Drywall		no data
2025/08/01		UNISEX RESTROOM 169		Wall Drywall Finish		no data
2025/08/01		UNISEX RESTROOM 169		Wall Prime Paint		no data
2025/08/01		VEHICLE MAINTENANCE BAYS 186		In Wall Insulation		in progress
2025/08/01		VEHICLE MAINTENANCE BAYS 186		Overhead Duct Insulation		no data
2025/08/01		VEHICLE MAINTENANCE BAYS 186		Overhead Duct Rough In		no data
2025/08/01		VEHICLE MAINTENANCE BAYS 186		Overhead Plumbing		complete
2025/08/01		VEHICLE MAINTENANCE BAYS 186		Wall Drywall		complete
2025/08/01		VEHICLE MAINTENANCE BAYS 186		Wall Drywall Finish		complete
2025/08/01		VEHICLE MAINTENANCE BAYS 186		Wall Prime Paint		complete
2025/08/01		VOLUNTEER/LIGHT DUTY 140		In Wall Insulation		no data
2025/08/01		VOLUNTEER/LIGHT DUTY 140		Overhead Duct Insulation		

complete  
2025/08/01 | VOLUNTEER/LIGHT DUTY 140 | Overhead Duct Rough In | complete  
2025/08/01 | VOLUNTEER/LIGHT DUTY 140 | Overhead Plumbing | in progress  
2025/08/01 | VOLUNTEER/LIGHT DUTY 140 | Wall Drywall | complete  
2025/08/01 | VOLUNTEER/LIGHT DUTY 140 | Wall Drywall Finish | complete  
2025/08/01 | VOLUNTEER/LIGHT DUTY 140 | Wall Prime Paint | complete  
2025/08/01 | WAITING/LOBBY 100 | In Wall Insulation | no data  
2025/08/01 | WAITING/LOBBY 100 | Overhead Duct Insulation | no data  
2025/08/01 | WAITING/LOBBY 100 | Overhead Duct Rough In | no data  
2025/08/01 | WAITING/LOBBY 100 | Overhead Plumbing | no data  
2025/08/01 | WAITING/LOBBY 100 | Wall Drywall | not started  
2025/08/01 | WAITING/LOBBY 100 | Wall Drywall Finish | not started  
2025/08/01 | WAITING/LOBBY 100 | Wall Prime Paint | not started  
2025/08/01 | WOMENS RESTROOM 113 | In Wall Insulation | no data  
2025/08/01 | WOMENS RESTROOM 113 | Overhead Duct Insulation | no data  
2025/08/01 | WOMENS RESTROOM 113 | Overhead Duct Rough In | complete  
2025/08/01 | WOMENS RESTROOM 113 | Overhead Plumbing | no data  
2025/08/01 | WOMENS RESTROOM 113 | Wall Drywall | complete  
2025/08/01 | WOMENS RESTROOM 113 | Wall Drywall Finish | complete  
2025/08/01 | WOMENS RESTROOM 113 | Wall Prime Paint | not started  
2025/08/06 | ADMIN ASSISTANT 125 | In Wall Insulation | no data  
2025/08/06 | ADMIN ASSISTANT 125 | Overhead Duct Insulation | no data  
2025/08/06 | ADMIN ASSISTANT 125 | Overhead Duct Rough In | no data  
2025/08/06 | ADMIN ASSISTANT 125 | Overhead Plumbing | no data  
2025/08/06 | ADMIN ASSISTANT 125 | Wall Drywall | no data  
2025/08/06 | ADMIN ASSISTANT 125 | Wall Drywall Finish | no data  
2025/08/06 | ADMIN ASSISTANT 125 | Wall Prime Paint | complete  
2025/08/06 | AV ROOM 103 | In Wall Insulation | no data  
2025/08/06 | AV ROOM 103 | Overhead Duct Insulation | complete  
2025/08/06 | AV ROOM 103 | Overhead Duct Rough In | complete  
2025/08/06 | AV ROOM 103 | Overhead Plumbing | no data  
2025/08/06 | AV ROOM 103 | Wall Drywall | complete  
2025/08/06 | AV ROOM 103 | Wall Drywall Finish | complete  
2025/08/06 | AV ROOM 103 | Wall Prime Paint | complete  
2025/08/06 | BREAK ROOM CONFERENCE 182 | In Wall Insulation | no data  
2025/08/06 | BREAK ROOM CONFERENCE 182 | Overhead Duct Insulation | complete  
2025/08/06 | BREAK ROOM CONFERENCE 182 | Overhead Duct Rough In | no data  
2025/08/06 | BREAK ROOM CONFERENCE 182 | Overhead Plumbing | complete  
2025/08/06 | BREAK ROOM CONFERENCE 182 | Wall Drywall | complete  
2025/08/06 | BREAK ROOM CONFERENCE 182 | Wall Drywall Finish | complete  
2025/08/06 | BREAK ROOM CONFERENCE 182 | Wall Prime Paint | complete  
2025/08/06 | Background-159 | In Wall Insulation | complete  
2025/08/06 | Background-159 | Overhead Duct Insulation | complete  
2025/08/06 | Background-159 | Overhead Duct Rough In | complete

2025/08/06	Background-159	Overhead Plumbing	not started
2025/08/06	Background-159	Wall Drywall	complete
2025/08/06	Background-159	Wall Drywall Finish	complete
2025/08/06	Background-159	Wall Prime Paint	complete
2025/08/06	CENTRAL BREAKROOM 145	In Wall Insulation	complete
2025/08/06	CENTRAL BREAKROOM 145	Overhead Duct Insulation	complete
2025/08/06	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/08/06	CENTRAL BREAKROOM 145	Overhead Plumbing	complete
2025/08/06	CENTRAL BREAKROOM 145	Wall Drywall	complete
2025/08/06	CENTRAL BREAKROOM 145	Wall Drywall Finish	in progress
2025/08/06	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/08/06	COLD CASE 175	In Wall Insulation	no data
2025/08/06	COLD CASE 175	Overhead Duct Insulation	complete
2025/08/06	COLD CASE 175	Overhead Duct Rough In	complete
2025/08/06	COLD CASE 175	Overhead Plumbing	complete
2025/08/06	COLD CASE 175	Wall Drywall	complete
2025/08/06	COLD CASE 175	Wall Drywall Finish	complete
2025/08/06	COLD CASE 175	Wall Prime Paint	complete
2025/08/06	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/08/06	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	complete
2025/08/06	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	complete
2025/08/06	COMMUNITY AFFAIRS 124	Overhead Plumbing	no data
2025/08/06	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/08/06	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/08/06	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/08/06	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/08/06	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	in progress
2025/08/06	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	no data
2025/08/06	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	no data
2025/08/06	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete
2025/08/06	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	complete
2025/08/06	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	complete
2025/08/06	CONFERENCE ROOM 153	In Wall Insulation	no data
2025/08/06	CONFERENCE ROOM 153	Overhead Duct Insulation	no data
2025/08/06	CONFERENCE ROOM 153	Overhead Duct Rough In	no data
2025/08/06	CONFERENCE ROOM 153	Overhead Plumbing	no data
2025/08/06	CONFERENCE ROOM 153	Wall Drywall	no data
2025/08/06	CONFERENCE ROOM 153	Wall Drywall Finish	no data
2025/08/06	CONFERENCE ROOM 153	Wall Prime Paint	complete
2025/08/06	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/08/06	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	complete

2025/08/06		CONFERENCE/WAR ROOM 163		Overhead Duct Rough In		complete
2025/08/06		CONFERENCE/WAR ROOM 163		Overhead Plumbing		complete
2025/08/06		CONFERENCE/WAR ROOM 163		Wall Drywall		complete
2025/08/06		CONFERENCE/WAR ROOM 163		Wall Drywall Finish		complete
2025/08/06		CONFERENCE/WAR ROOM 163		Wall Prime Paint		complete
2025/08/06		COPY 176		In Wall Insulation		complete
2025/08/06		COPY 176		Overhead Duct Insulation		complete
2025/08/06		COPY 176		Overhead Duct Rough In		complete
2025/08/06		COPY 176		Overhead Plumbing		not started
2025/08/06		COPY 176		Wall Drywall		complete
2025/08/06		COPY 176		Wall Drywall Finish		complete
2025/08/06		COPY 176		Wall Prime Paint		complete
2025/08/06		COPY/MAIL ROOM 114		In Wall Insulation		complete
2025/08/06		COPY/MAIL ROOM 114		Overhead Duct Insulation		complete
2025/08/06		COPY/MAIL ROOM 114		Overhead Duct Rough In		complete
2025/08/06		COPY/MAIL ROOM 114		Overhead Plumbing		complete
2025/08/06		COPY/MAIL ROOM 114		Wall Drywall		complete
2025/08/06		COPY/MAIL ROOM 114		Wall Drywall Finish		complete
2025/08/06		COPY/MAIL ROOM 114		Wall Prime Paint		complete
2025/08/06		CORRIDOR 107		In Wall Insulation		complete
2025/08/06		CORRIDOR 107		Overhead Duct Insulation		in progress
2025/08/06		CORRIDOR 107		Overhead Duct Rough In		in progress
2025/08/06		CORRIDOR 107		Overhead Plumbing		in progress
2025/08/06		CORRIDOR 107		Wall Drywall		complete
2025/08/06		CORRIDOR 107		Wall Drywall Finish		complete
2025/08/06		CORRIDOR 107		Wall Prime Paint		complete
2025/08/06		CORRIDOR 108		In Wall Insulation		complete
2025/08/06		CORRIDOR 108		In Wall Insulation		no data
2025/08/06		CORRIDOR 108		Overhead Duct Insulation		in progress
2025/08/06		CORRIDOR 108		Overhead Duct Insulation		no data
2025/08/06		CORRIDOR 108		Overhead Duct Rough In		in progress
2025/08/06		CORRIDOR 108		Overhead Duct Rough In		no data
2025/08/06		CORRIDOR 108		Overhead Plumbing		in progress
2025/08/06		CORRIDOR 108		Overhead Plumbing		no data
2025/08/06		CORRIDOR 108		Wall Drywall		complete
2025/08/06		CORRIDOR 108		Wall Drywall		complete
2025/08/06		CORRIDOR 108		Wall Drywall Finish		complete
2025/08/06		CORRIDOR 108		Wall Drywall Finish		complete
2025/08/06		CORRIDOR 108		Wall Prime Paint		complete
2025/08/06		CORRIDOR 108		Wall Prime Paint		complete
2025/08/06		CORRIDOR 109		In Wall Insulation		complete
2025/08/06		CORRIDOR 109		Overhead Duct Insulation		in progress
2025/08/06		CORRIDOR 109		Overhead Duct Rough In		in progress
2025/08/06		CORRIDOR 109		Overhead Plumbing		in progress
2025/08/06		CORRIDOR 109		Wall Drywall		complete
2025/08/06		CORRIDOR 109		Wall Drywall Finish		complete
2025/08/06		CORRIDOR 109		Wall Prime Paint		complete
2025/08/06		CORRIDOR 110		In Wall Insulation		no data
2025/08/06		CORRIDOR 110		In Wall Insulation		no data
2025/08/06		CORRIDOR 110		Overhead Duct Insulation		no data
2025/08/06		CORRIDOR 110		Overhead Duct Insulation		no data



2025/08/06	CORRIDOR 110	Overhead Duct Rough In	no data
2025/08/06	CORRIDOR 110	Overhead Duct Rough In	no data
2025/08/06	CORRIDOR 110	Overhead Plumbing	no data
2025/08/06	CORRIDOR 110	Overhead Plumbing	in progress
2025/08/06	CORRIDOR 110	Wall Drywall	complete
2025/08/06	CORRIDOR 110	Wall Drywall	complete
2025/08/06	CORRIDOR 110	Wall Drywall Finish	complete
2025/08/06	CORRIDOR 110	Wall Drywall Finish	complete
2025/08/06	CORRIDOR 110	Wall Prime Paint	complete
2025/08/06	CORRIDOR 110	Wall Prime Paint	complete
2025/08/06	CORRIDOR 181	In Wall Insulation	complete
2025/08/06	CORRIDOR 181	Overhead Duct Insulation	in progress
2025/08/06	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/08/06	CORRIDOR 181	Overhead Plumbing	in progress
2025/08/06	CORRIDOR 181	Wall Drywall	complete
2025/08/06	CORRIDOR 181	Wall Drywall Finish	complete
2025/08/06	CORRIDOR 181	Wall Prime Paint	complete
2025/08/06	CORRIDOR144	In Wall Insulation	no data
2025/08/06	CORRIDOR144	Overhead Duct Insulation	no data
2025/08/06	CORRIDOR144	Overhead Duct Rough In	no data
2025/08/06	CORRIDOR144	Overhead Plumbing	no data
2025/08/06	CORRIDOR144	Wall Drywall	complete
2025/08/06	CORRIDOR144	Wall Drywall Finish	complete
2025/08/06	CORRIDOR144	Wall Prime Paint	complete
2025/08/06	CPL 173	In Wall Insulation	complete
2025/08/06	CPL 173	Overhead Duct Insulation	complete
2025/08/06	CPL 173	Overhead Duct Rough In	complete
2025/08/06	CPL 173	Overhead Plumbing	complete
2025/08/06	CPL 173	Wall Drywall	complete
2025/08/06	CPL 173	Wall Drywall Finish	complete
2025/08/06	CPL 173	Wall Prime Paint	complete
2025/08/06	CPL 174	In Wall Insulation	complete
2025/08/06	CPL 174	Overhead Duct Insulation	in progress
2025/08/06	CPL 174	Overhead Duct Rough In	in progress
2025/08/06	CPL 174	Overhead Plumbing	no data
2025/08/06	CPL 174	Wall Drywall	complete
2025/08/06	CPL 174	Wall Drywall Finish	complete
2025/08/06	CPL 174	Wall Prime Paint	complete
2025/08/06	DRY STORAGE 146	In Wall Insulation	complete
2025/08/06	DRY STORAGE 146	Overhead Duct Insulation	complete
2025/08/06	DRY STORAGE 146	Overhead Duct Rough In	complete
2025/08/06	DRY STORAGE 146	Overhead Plumbing	not started
2025/08/06	DRY STORAGE 146	Wall Drywall	complete
2025/08/06	DRY STORAGE 146	Wall Drywall Finish	complete
2025/08/06	DRY STORAGE 146	Wall Prime Paint	in progress
2025/08/06	FIRE RISER 178	In Wall Insulation	no data
2025/08/06	FIRE RISER 178	Overhead Duct Insulation	no data
2025/08/06	FIRE RISER 178	Overhead Duct Rough In	no data
2025/08/06	FIRE RISER 178	Overhead Plumbing	no data
2025/08/06	FIRE RISER 178	Wall Drywall	no data
2025/08/06	FIRE RISER 178	Wall Drywall Finish	no data
2025/08/06	FIRE RISER 178	Wall Prime Paint	no data
2025/08/06	GREETING ROOM 106	In Wall Insulation	no data
2025/08/06	GREETING ROOM 106	Overhead Duct Insulation	complete

2025/08/06		GREETING ROOM 106		Overhead Duct Rough In		complete
2025/08/06		GREETING ROOM 106		Overhead Plumbing		not started
2025/08/06		GREETING ROOM 106		Wall Drywall		complete
2025/08/06		GREETING ROOM 106		Wall Drywall Finish		complete
2025/08/06		GREETING ROOM 106		Wall Prime Paint		complete
2025/08/06		HR 149		In Wall Insulation		complete
2025/08/06		HR 149		Overhead Duct Insulation		complete
2025/08/06		HR 149		Overhead Duct Rough In		complete
2025/08/06		HR 149		Overhead Plumbing		not started
2025/08/06		HR 149		Wall Drywall		complete
2025/08/06		HR 149		Wall Drywall Finish		complete
2025/08/06		HR 149		Wall Prime Paint		complete
2025/08/06		HR 150		In Wall Insulation		complete
2025/08/06		HR 150		Overhead Duct Insulation		complete
2025/08/06		HR 150		Overhead Duct Rough In		complete
2025/08/06		HR 150		Overhead Plumbing		no data
2025/08/06		HR 150		Wall Drywall		complete
2025/08/06		HR 150		Wall Drywall Finish		complete
2025/08/06		HR 150		Wall Prime Paint		complete
2025/08/06		HR 151		In Wall Insulation		complete
2025/08/06		HR 151		Overhead Duct Insulation		complete
2025/08/06		HR 151		Overhead Duct Rough In		complete
2025/08/06		HR 151		Overhead Plumbing		complete
2025/08/06		HR 151		Wall Drywall		complete
2025/08/06		HR 151		Wall Drywall Finish		complete
2025/08/06		HR 151		Wall Prime Paint		complete
2025/08/06		HR 154		In Wall Insulation		complete
2025/08/06		HR 154		Overhead Duct Insulation		complete
2025/08/06		HR 154		Overhead Duct Rough In		complete
2025/08/06		HR 154		Overhead Plumbing		complete
2025/08/06		HR 154		Wall Drywall		complete
2025/08/06		HR 154		Wall Drywall Finish		complete
2025/08/06		HR 154		Wall Prime Paint		complete
2025/08/06		HR 155		In Wall Insulation		complete
2025/08/06		HR 155		Overhead Duct Insulation		complete
2025/08/06		HR 155		Overhead Duct Rough In		complete
2025/08/06		HR 155		Overhead Plumbing		complete
2025/08/06		HR 155		Wall Drywall		complete
2025/08/06		HR 155		Wall Drywall Finish		complete
2025/08/06		HR 155		Wall Prime Paint		complete
2025/08/06		HR 156		In Wall Insulation		complete
2025/08/06		HR 156		Overhead Duct Insulation		complete
2025/08/06		HR 156		Overhead Duct Rough In		complete
2025/08/06		HR 156		Overhead Plumbing		not started
2025/08/06		HR 156		Wall Drywall		complete
2025/08/06		HR 156		Wall Drywall Finish		complete
2025/08/06		HR 156		Wall Prime Paint		complete
2025/08/06		HR 157		In Wall Insulation		complete
2025/08/06		HR 157		Overhead Duct Insulation		complete
2025/08/06		HR 157		Overhead Duct Rough In		complete
2025/08/06		HR 157		Overhead Plumbing		complete
2025/08/06		HR 157		Wall Drywall		complete
2025/08/06		HR 157		Wall Drywall Finish		complete
2025/08/06		HR 157		Wall Prime Paint		complete

2025/08/06	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/08/06	HUMAN RESOURCES 148	Overhead Duct Insulation	in progress
2025/08/06	HUMAN RESOURCES 148	Overhead Duct Rough In	in progress
2025/08/06	HUMAN RESOURCES 148	Overhead Plumbing	in progress
2025/08/06	HUMAN RESOURCES 148	Wall Drywall	complete
2025/08/06	HUMAN RESOURCES 148	Wall Drywall Finish	complete
2025/08/06	HUMAN RESOURCES 148	Wall Prime Paint	complete
2025/08/06	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/08/06	INTERNAL AFFAIRS 119	Overhead Duct Insulation	complete
2025/08/06	INTERNAL AFFAIRS 119	Overhead Duct Rough In	complete
2025/08/06	INTERNAL AFFAIRS 119	Overhead Plumbing	complete
2025/08/06	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/08/06	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/08/06	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/08/06	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/08/06	INTERNAL AFFAIRS 120	Overhead Duct Insulation	complete
2025/08/06	INTERNAL AFFAIRS 120	Overhead Duct Rough In	complete
2025/08/06	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/08/06	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/08/06	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/08/06	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/08/06	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/08/06	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	complete
2025/08/06	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	complete
2025/08/06	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	complete
2025/08/06	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/08/06	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/08/06	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/08/06	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	no data
2025/08/06	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	complete
2025/08/06	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	complete
2025/08/06	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	complete
2025/08/06	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/08/06	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	complete
2025/08/06	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	complete
2025/08/06	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	

no data

2025/08/06	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	complete
2025/08/06	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	complete
2025/08/06	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	complete
2025/08/06	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/08/06	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/08/06	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	complete
2025/08/06	IT 115	In Wall Insulation	no data
2025/08/06	IT 115	Overhead Duct Insulation	no data
2025/08/06	IT 115	Overhead Duct Rough In	no data
2025/08/06	IT 115	Overhead Plumbing	no data
2025/08/06	IT 115	Wall Drywall	no data
2025/08/06	IT 115	Wall Drywall Finish	no data
2025/08/06	IT 115	Wall Prime Paint	no data
2025/08/06	IT 135	In Wall Insulation	complete
2025/08/06	IT 135	Overhead Duct Insulation	complete
2025/08/06	IT 135	Overhead Duct Rough In	complete
2025/08/06	IT 135	Overhead Plumbing	complete
2025/08/06	IT 135	Wall Drywall	complete
2025/08/06	IT 135	Wall Drywall Finish	complete
2025/08/06	IT 135	Wall Prime Paint	complete
2025/08/06	IT MANAGER 136	In Wall Insulation	complete
2025/08/06	IT MANAGER 136	Overhead Duct Insulation	in progress
2025/08/06	IT MANAGER 136	Overhead Duct Rough In	in progress
2025/08/06	IT MANAGER 136	Overhead Plumbing	complete
2025/08/06	IT MANAGER 136	Wall Drywall	complete
2025/08/06	IT MANAGER 136	Wall Drywall Finish	complete
2025/08/06	IT MANAGER 136	Wall Prime Paint	complete
2025/08/06	IT MANAGER 137	In Wall Insulation	no data
2025/08/06	IT MANAGER 137	Overhead Duct Insulation	complete
2025/08/06	IT MANAGER 137	Overhead Duct Rough In	complete
2025/08/06	IT MANAGER 137	Overhead Plumbing	complete
2025/08/06	IT MANAGER 137	Wall Drywall	complete
2025/08/06	IT MANAGER 137	Wall Drywall Finish	complete
2025/08/06	IT MANAGER 137	Wall Prime Paint	complete
2025/08/06	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/08/06	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data
2025/08/06	JUVENILE INTERVIEW 165	Overhead Duct Rough In	complete
2025/08/06	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/08/06	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/08/06	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/08/06	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/08/06	JUVENILE INTERVIEWERS 166	In Wall Insulation	no data
2025/08/06	JUVENILE INTERVIEWERS 166	Overhead Duct Insulation	in progress

2025/08/06		JUVENILE INTERVIEWERS 166		Overhead Duct Rough In		no data
2025/08/06		JUVENILE INTERVIEWERS 166		Overhead Plumbing		no data
2025/08/06		JUVENILE INTERVIEWERS 166		Wall Drywall		complete
2025/08/06		JUVENILE INTERVIEWERS 166		Wall Drywall Finish		complete
2025/08/06		JUVENILE INTERVIEWERS 166		Wall Prime Paint		complete
2025/08/06		KEY ROOM 185		In Wall Insulation		complete
2025/08/06		KEY ROOM 185		Overhead Duct Insulation		in progress
2025/08/06		KEY ROOM 185		Overhead Duct Rough In		no data
2025/08/06		KEY ROOM 185		Overhead Plumbing		no data
2025/08/06		KEY ROOM 185		Wall Drywall		complete
2025/08/06		KEY ROOM 185		Wall Drywall Finish		complete
2025/08/06		KEY ROOM 185		Wall Prime Paint		complete
2025/08/06		LT 170		In Wall Insulation		complete
2025/08/06		LT 170		Overhead Duct Insulation		complete
2025/08/06		LT 170		Overhead Duct Rough In		complete
2025/08/06		LT 170		Overhead Plumbing		not started
2025/08/06		LT 170		Wall Drywall		complete
2025/08/06		LT 170		Wall Drywall Finish		complete
2025/08/06		LT 170		Wall Prime Paint		complete
2025/08/06		MACHINE ROOM 191		In Wall Insulation		no data
2025/08/06		MACHINE ROOM 191		Overhead Duct Insulation		no data
2025/08/06		MACHINE ROOM 191		Overhead Duct Rough In		no data
2025/08/06		MACHINE ROOM 191		Overhead Plumbing		no data
2025/08/06		MACHINE ROOM 191		Wall Drywall		no data
2025/08/06		MACHINE ROOM 191		Wall Drywall Finish		no data
2025/08/06		MACHINE ROOM 191		Wall Prime Paint		no data
2025/08/06		MAIN ELECTRICAL ROOM 123		In Wall Insulation		no data
2025/08/06		MAIN ELECTRICAL ROOM 123		Overhead Duct Insulation		no data
2025/08/06		MAIN ELECTRICAL ROOM 123		Overhead Duct Rough In		no data
2025/08/06		MAIN ELECTRICAL ROOM 123		Overhead Plumbing		no data
2025/08/06		MAIN ELECTRICAL ROOM 123		Wall Drywall		no data
2025/08/06		MAIN ELECTRICAL ROOM 123		Wall Drywall Finish		no data
2025/08/06		MAIN ELECTRICAL ROOM 123		Wall Prime Paint		no data
2025/08/06		MAIN JANITORIAL111		In Wall Insulation		no data
2025/08/06		MAIN JANITORIAL111		Overhead Duct Insulation		complete
2025/08/06		MAIN JANITORIAL111		Overhead Duct Rough In		complete
2025/08/06		MAIN JANITORIAL111		Overhead Plumbing		complete
2025/08/06		MAIN JANITORIAL111		Wall Drywall		complete
2025/08/06		MAIN JANITORIAL111		Wall Drywall Finish		complete
2025/08/06		MAIN JANITORIAL111		Wall Prime Paint		complete
2025/08/06		MARINE SERGEANT 142		In Wall Insulation		complete
2025/08/06		MARINE SERGEANT 142		Overhead Duct Insulation		in progress
2025/08/06		MARINE SERGEANT 142		Overhead Duct Rough In		in progress
2025/08/06		MARINE SERGEANT 142		Overhead Plumbing		in progress

2025/08/06	MARINE SERGEANT 142	Wall Drywall	complete
2025/08/06	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/08/06	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/08/06	MECHANICAL 192	In Wall Insulation	no data
2025/08/06	MECHANICAL 192	Overhead Duct Insulation	no data
2025/08/06	MECHANICAL 192	Overhead Duct Rough In	no data
2025/08/06	MECHANICAL 192	Overhead Plumbing	no data
2025/08/06	MECHANICAL 192	Wall Drywall	no data
2025/08/06	MECHANICAL 192	Wall Drywall Finish	no data
2025/08/06	MECHANICAL 192	Wall Prime Paint	no data
2025/08/06	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/08/06	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
2025/08/06	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/08/06	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/08/06	MECHANICAL ROOM 122	Wall Drywall	no data
2025/08/06	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/08/06	MECHANICAL ROOM 122	Wall Prime Paint	no data
2025/08/06	MENS RESTROOM 112	In Wall Insulation	complete
2025/08/06	MENS RESTROOM 112	Overhead Duct Insulation	complete
2025/08/06	MENS RESTROOM 112	Overhead Duct Rough In	complete
2025/08/06	MENS RESTROOM 112	Overhead Plumbing	complete
2025/08/06	MENS RESTROOM 112	Wall Drywall	complete
2025/08/06	MENS RESTROOM 112	Wall Drywall Finish	complete
2025/08/06	MENS RESTROOM 112	Wall Prime Paint	not started
2025/08/06	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
2025/08/06	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	in progress
2025/08/06	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	no data
2025/08/06	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	in progress
2025/08/06	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/08/06	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/08/06	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/08/06	MIS SHREDDING 117	In Wall Insulation	complete
2025/08/06	MIS SHREDDING 117	Overhead Duct Insulation	complete
2025/08/06	MIS SHREDDING 117	Overhead Duct Rough In	complete
2025/08/06	MIS SHREDDING 117	Overhead Plumbing	complete
2025/08/06	MIS SHREDDING 117	Wall Drywall	complete
2025/08/06	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/08/06	MIS SHREDDING 117	Wall Prime Paint	complete
2025/08/06	OFFICE 128	In Wall Insulation	no data
2025/08/06	OFFICE 128	Overhead Duct Insulation	no data
2025/08/06	OFFICE 128	Overhead Duct Rough In	no data
2025/08/06	OFFICE 128	Overhead Plumbing	no data
2025/08/06	OFFICE 128	Wall Drywall	complete
2025/08/06	OFFICE 128	Wall Drywall Finish	complete
2025/08/06	OFFICE 128	Wall Prime Paint	complete
2025/08/06	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	no data
2025/08/06	OPERATIONS SUPPORT DIVISION 139	Overhead Duct	

Insulation		no data
2025/08/06		OPERATIONS SUPPORT DIVISION 139   Overhead Duct Rough In   no data
2025/08/06		OPERATIONS SUPPORT DIVISION 139   Overhead Plumbing   in progress
2025/08/06		OPERATIONS SUPPORT DIVISION 139   Wall Drywall   complete
2025/08/06		OPERATIONS SUPPORT DIVISION 139   Wall Drywall Finish   complete
2025/08/06		OPERATIONS SUPPORT DIVISION 139   Wall Prime Paint   complete
2025/08/06		PARTS STORAGE 189   In Wall Insulation   no data
2025/08/06		PARTS STORAGE 189   Overhead Duct Insulation   no data
2025/08/06		PARTS STORAGE 189   Overhead Duct Rough In   no data
2025/08/06		PARTS STORAGE 189   Overhead Plumbing   no data
2025/08/06		PARTS STORAGE 189   Wall Drywall   complete
2025/08/06		PARTS STORAGE 189   Wall Drywall Finish   complete
2025/08/06		PARTS STORAGE 189   Wall Prime Paint   complete
2025/08/06		PUBLIC RESTROOM 106   In Wall Insulation   no data
2025/08/06		PUBLIC RESTROOM 106   Overhead Duct Insulation   no data
2025/08/06		PUBLIC RESTROOM 106   Overhead Duct Rough In   no data
2025/08/06		PUBLIC RESTROOM 106   Overhead Plumbing   no data
2025/08/06		PUBLIC RESTROOM 106   Wall Drywall   no data
2025/08/06		PUBLIC RESTROOM 106   Wall Drywall Finish   no data
2025/08/06		PUBLIC RESTROOM 106   Wall Prime Paint   no data
2025/08/06		Polygraph 152   In Wall Insulation   complete
2025/08/06		Polygraph 152   Overhead Duct Insulation   complete
2025/08/06		Polygraph 152   Overhead Duct Rough In   complete
2025/08/06		Polygraph 152   Overhead Plumbing   not started
2025/08/06		Polygraph 152   Wall Drywall   complete
2025/08/06		Polygraph 152   Wall Drywall Finish   complete
2025/08/06		Polygraph 152   Wall Prime Paint   complete
2025/08/06		RECEPTION 101   In Wall Insulation   no data
2025/08/06		RECEPTION 101   Overhead Duct Insulation   no data
2025/08/06		RECEPTION 101   Overhead Duct Rough In   no data
2025/08/06		RECEPTION 101   Overhead Plumbing   no data
2025/08/06		RECEPTION 101   Wall Drywall   no data
2025/08/06		RECEPTION 101   Wall Drywall Finish   no data
2025/08/06		RECEPTION 101   Wall Prime Paint   no data
2025/08/06		RECEPTION 147   In Wall Insulation   complete
2025/08/06		RECEPTION 147   Overhead Duct Insulation   complete
2025/08/06		RECEPTION 147   Overhead Duct Rough In   complete
2025/08/06		RECEPTION 147   Overhead Plumbing   complete
2025/08/06		RECEPTION 147   Wall Drywall   complete
2025/08/06		RECEPTION 147   Wall Drywall Finish   complete
2025/08/06		RECEPTION 147   Wall Prime Paint   complete
2025/08/06		RECEPTION 179   In Wall Insulation   complete
2025/08/06		RECEPTION 179   Overhead Duct Insulation   complete
2025/08/06		RECEPTION 179   Overhead Duct Rough In   complete
2025/08/06		RECEPTION 179   Overhead Plumbing   no data
2025/08/06		RECEPTION 179   Wall Drywall   complete
2025/08/06		RECEPTION 179   Wall Drywall Finish   complete
2025/08/06		RECEPTION 179   Wall Prime Paint   complete

2025/08/06	RECORDS 130	In Wall Insulation	no data
2025/08/06	RECORDS 130	Overhead Duct Insulation	complete
2025/08/06	RECORDS 130	Overhead Duct Rough In	complete
2025/08/06	RECORDS 130	Overhead Plumbing	complete
2025/08/06	RECORDS 130	Wall Drywall	complete
2025/08/06	RECORDS 130	Wall Drywall Finish	complete
2025/08/06	RECORDS 130	Wall Prime Paint	complete
2025/08/06	RECORDS STORAGE 133	In Wall Insulation	complete
2025/08/06	RECORDS STORAGE 133	Overhead Duct Insulation	complete
2025/08/06	RECORDS STORAGE 133	Overhead Duct Rough In	complete
2025/08/06	RECORDS STORAGE 133	Overhead Plumbing	complete
2025/08/06	RECORDS STORAGE 133	Wall Drywall	complete
2025/08/06	RECORDS STORAGE 133	Wall Drywall Finish	complete
2025/08/06	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/08/06	RECORDS SUPERVISOR 131	In Wall Insulation	no data
2025/08/06	RECORDS SUPERVISOR 131	Overhead Duct Insulation	complete
2025/08/06	RECORDS SUPERVISOR 131	Overhead Duct Rough In	complete
2025/08/06	RECORDS SUPERVISOR 131	Overhead Plumbing	no data
2025/08/06	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/08/06	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/08/06	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/08/06	RECORDS SUPERVISOR 132	In Wall Insulation	no data
2025/08/06	RECORDS SUPERVISOR 132	Overhead Duct Insulation	complete
2025/08/06	RECORDS SUPERVISOR 132	Overhead Duct Rough In	complete
2025/08/06	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/08/06	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/08/06	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/08/06	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/08/06	RESTROOM 183	In Wall Insulation	no data
2025/08/06	RESTROOM 183	Overhead Duct Insulation	no data
2025/08/06	RESTROOM 183	Overhead Duct Rough In	no data
2025/08/06	RESTROOM 183	Overhead Plumbing	no data
2025/08/06	RESTROOM 183	Wall Drywall	no data
2025/08/06	RESTROOM 183	Wall Drywall Finish	no data
2025/08/06	RESTROOM 183	Wall Prime Paint	no data
2025/08/06	Risk Management - 158	In Wall Insulation	complete
2025/08/06	Risk Management - 158	Overhead Duct Insulation	complete
2025/08/06	Risk Management - 158	Overhead Duct Rough In	complete
2025/08/06	Risk Management - 158	Overhead Plumbing	complete
2025/08/06	Risk Management - 158	Wall Drywall	complete
2025/08/06	Risk Management - 158	Wall Drywall Finish	complete
2025/08/06	Risk Management - 158	Wall Prime Paint	complete
2025/08/06	SALLY PORT 105	In Wall Insulation	not started
2025/08/06	SALLY PORT 105	Overhead Duct Insulation	in progress
2025/08/06	SALLY PORT 105	Overhead Duct Rough In	in progress
2025/08/06	SALLY PORT 105	Overhead Plumbing	no data
2025/08/06	SALLY PORT 105	Wall Drywall	not started



2025/08/06		SALLY PORT 105		Wall Drywall Finish		not started
2025/08/06		SALLY PORT 105		Wall Prime Paint		not started
2025/08/06		SANE EXAM ROOM 168		In Wall Insulation		complete
2025/08/06		SANE EXAM ROOM 168		Overhead Duct Insulation		no data
2025/08/06		SANE EXAM ROOM 168		Overhead Duct Rough In		complete
2025/08/06		SANE EXAM ROOM 168		Overhead Plumbing		no data
2025/08/06		SANE EXAM ROOM 168		Wall Drywall		complete
2025/08/06		SANE EXAM ROOM 168		Wall Drywall Finish		complete
2025/08/06		SANE EXAM ROOM 168		Wall Prime Paint		complete
2025/08/06		SGT 171		In Wall Insulation		no data
2025/08/06		SGT 171		Overhead Duct Insulation		complete
2025/08/06		SGT 171		Overhead Duct Rough In		complete
2025/08/06		SGT 171		Overhead Plumbing		complete
2025/08/06		SGT 171		Wall Drywall		complete
2025/08/06		SGT 171		Wall Drywall Finish		complete
2025/08/06		SGT 171		Wall Prime Paint		complete
2025/08/06		SGT 172		In Wall Insulation		complete
2025/08/06		SGT 172		Overhead Duct Insulation		no data
2025/08/06		SGT 172		Overhead Duct Rough In		complete
2025/08/06		SGT 172		Overhead Plumbing		complete
2025/08/06		SGT 172		Wall Drywall		complete
2025/08/06		SGT 172		Wall Drywall Finish		complete
2025/08/06		SGT 172		Wall Prime Paint		complete
2025/08/06		SHIPPING STORAGE 190		In Wall Insulation		complete
2025/08/06		SHIPPING STORAGE 190		Overhead Duct Insulation		complete
2025/08/06		SHIPPING STORAGE 190		Overhead Duct Rough In		no data
2025/08/06		SHIPPING STORAGE 190		Overhead Plumbing		no data
2025/08/06		SHIPPING STORAGE 190		Wall Drywall		complete
2025/08/06		SHIPPING STORAGE 190		Wall Drywall Finish		complete
2025/08/06		SHIPPING STORAGE 190		Wall Prime Paint		complete
2025/08/06		SHOP FORMAN 184		In Wall Insulation		complete
2025/08/06		SHOP FORMAN 184		Overhead Duct Insulation		complete
2025/08/06		SHOP FORMAN 184		Overhead Duct Rough In		complete
2025/08/06		SHOP FORMAN 184		Overhead Plumbing		no data
2025/08/06		SHOP FORMAN 184		Wall Drywall		complete
2025/08/06		SHOP FORMAN 184		Wall Drywall Finish		complete
2025/08/06		SHOP FORMAN 184		Wall Prime Paint		complete
2025/08/06		SOFT INTERVIEW 161		In Wall Insulation		no data
2025/08/06		SOFT INTERVIEW 161		Overhead Duct Insulation		no data
2025/08/06		SOFT INTERVIEW 161		Overhead Duct Rough In		no data
2025/08/06		SOFT INTERVIEW 161		Overhead Plumbing		no data
2025/08/06		SOFT INTERVIEW 161		Wall Drywall		no data
2025/08/06		SOFT INTERVIEW 161		Wall Drywall Finish		no data
2025/08/06		SOFT INTERVIEW 161		Wall Prime Paint		no data
2025/08/06		SOFT INTERVIEW 162		In Wall Insulation		no data
2025/08/06		SOFT INTERVIEW 162		Overhead Duct Insulation		no data
2025/08/06		SOFT INTERVIEW 162		Overhead Duct Rough In		no data
2025/08/06		SOFT INTERVIEW 162		Overhead Plumbing		no data
2025/08/06		SOFT INTERVIEW 162		Wall Drywall		no data
2025/08/06		SOFT INTERVIEW 162		Wall Drywall Finish		no data
2025/08/06		SOFT INTERVIEW 162		Wall Prime Paint		no data
2025/08/06		SPECIAL OPERATION LT 143		In Wall Insulation		no data
2025/08/06		SPECIAL OPERATION LT 143		Overhead Duct Insulation		

no data			
2025/08/06	SPECIAL OPERATION LT 143	Overhead Duct Rough In	no data
2025/08/06	SPECIAL OPERATION LT 143	Overhead Plumbing	no data
2025/08/06	SPECIAL OPERATION LT 143	Wall Drywall	complete
2025/08/06	SPECIAL OPERATION LT 143	Wall Drywall Finish	complete
2025/08/06	SPECIAL OPERATION LT 143	Wall Prime Paint	complete
2025/08/06	STAIR A	In Wall Insulation	no data
2025/08/06	STAIR A	Overhead Duct Insulation	no data
2025/08/06	STAIR A	Overhead Duct Rough In	no data
2025/08/06	STAIR A	Overhead Plumbing	complete
2025/08/06	STAIR A	Wall Drywall	in progress
2025/08/06	STAIR A	Wall Drywall Finish	in progress
2025/08/06	STAIR A	Wall Prime Paint	in progress
2025/08/06	STORAGE 104	In Wall Insulation	no data
2025/08/06	STORAGE 104	Overhead Duct Insulation	no data
2025/08/06	STORAGE 104	Overhead Duct Rough In	no data
2025/08/06	STORAGE 104	Overhead Plumbing	not started
2025/08/06	STORAGE 104	Wall Drywall	complete
2025/08/06	STORAGE 104	Wall Drywall Finish	complete
2025/08/06	STORAGE 104	Wall Prime Paint	complete
2025/08/06	STORAGE 127	In Wall Insulation	no data
2025/08/06	STORAGE 127	Overhead Duct Insulation	complete
2025/08/06	STORAGE 127	Overhead Duct Rough In	complete
2025/08/06	STORAGE 127	Overhead Plumbing	not started
2025/08/06	STORAGE 127	Wall Drywall	complete
2025/08/06	STORAGE 127	Wall Drywall Finish	complete
2025/08/06	STORAGE 127	Wall Prime Paint	complete
2025/08/06	STUDIO 126	In Wall Insulation	complete
2025/08/06	STUDIO 126	Overhead Duct Insulation	complete
2025/08/06	STUDIO 126	Overhead Duct Rough In	complete
2025/08/06	STUDIO 126	Overhead Plumbing	complete
2025/08/06	STUDIO 126	Wall Drywall	complete
2025/08/06	STUDIO 126	Wall Drywall Finish	complete
2025/08/06	STUDIO 126	Wall Prime Paint	complete
2025/08/06	SUPERVISOR 129	In Wall Insulation	complete
2025/08/06	SUPERVISOR 129	Overhead Duct Insulation	complete
2025/08/06	SUPERVISOR 129	Overhead Duct Rough In	complete
2025/08/06	SUPERVISOR 129	Overhead Plumbing	not started
2025/08/06	SUPERVISOR 129	Wall Drywall	complete
2025/08/06	SUPERVISOR 129	Wall Drywall Finish	complete
2025/08/06	SUPERVISOR 129	Wall Prime Paint	complete
2025/08/06	Storage 164	In Wall Insulation	complete
2025/08/06	Storage 164	Overhead Duct Insulation	complete
2025/08/06	Storage 164	Overhead Duct Rough In	complete
2025/08/06	Storage 164	Overhead Plumbing	not started
2025/08/06	Storage 164	Wall Drywall	complete
2025/08/06	Storage 164	Wall Drywall Finish	complete
2025/08/06	Storage 164	Wall Prime Paint	complete
2025/08/06	Storage 177	In Wall Insulation	complete
2025/08/06	Storage 177	Overhead Duct Insulation	complete
2025/08/06	Storage 177	Overhead Duct Rough In	complete
2025/08/06	Storage 177	Overhead Plumbing	not started

2025/08/06	Storage 177	Wall Drywall	complete
2025/08/06	Storage 177	Wall Drywall Finish	complete
2025/08/06	Storage 177	Wall Prime Paint	complete
2025/08/06	TECHNICAL SURVEELLANCE 188	In Wall Insulation	complete
2025/08/06	TECHNICAL SURVEELLANCE 188	Overhead Duct Insulation	complete
2025/08/06	TECHNICAL SURVEELLANCE 188	Overhead Duct Rough In	no data
2025/08/06	TECHNICAL SURVEELLANCE 188	Overhead Plumbing	complete
2025/08/06	TECHNICAL SURVEELLANCE 188	Wall Drywall	complete
2025/08/06	TECHNICAL SURVEELLANCE 188	Wall Drywall Finish	complete
2025/08/06	TECHNICAL SURVEELLANCE 188	Wall Prime Paint	complete
2025/08/06	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/08/06	TRAFFIC SERGEANT 141	Overhead Duct Insulation	in progress
2025/08/06	TRAFFIC SERGEANT 141	Overhead Duct Rough In	in progress
2025/08/06	TRAFFIC SERGEANT 141	Overhead Plumbing	in progress
2025/08/06	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/08/06	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/08/06	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/08/06	TRIAGE/RECEPTION 134	In Wall Insulation	no data
2025/08/06	TRIAGE/RECEPTION 134	Overhead Duct Insulation	no data
2025/08/06	TRIAGE/RECEPTION 134	Overhead Duct Rough In	no data
2025/08/06	TRIAGE/RECEPTION 134	Overhead Plumbing	no data
2025/08/06	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/08/06	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/08/06	TRIAGE/RECEPTION 134	Wall Prime Paint	complete
2025/08/06	TST WORKSHOP 187	In Wall Insulation	complete
2025/08/06	TST WORKSHOP 187	Overhead Duct Insulation	no data
2025/08/06	TST WORKSHOP 187	Overhead Duct Rough In	no data
2025/08/06	TST WORKSHOP 187	Overhead Plumbing	no data
2025/08/06	TST WORKSHOP 187	Wall Drywall	complete
2025/08/06	TST WORKSHOP 187	Wall Drywall Finish	complete
2025/08/06	TST WORKSHOP 187	Wall Prime Paint	complete
2025/08/06	UNISEX RESTROOM 169	In Wall Insulation	no data
2025/08/06	UNISEX RESTROOM 169	Overhead Duct Insulation	no data
2025/08/06	UNISEX RESTROOM 169	Overhead Duct Rough In	no data
2025/08/06	UNISEX RESTROOM 169	Overhead Plumbing	no data
2025/08/06	UNISEX RESTROOM 169	Wall Drywall	no data
2025/08/06	UNISEX RESTROOM 169	Wall Drywall Finish	no data
2025/08/06	UNISEX RESTROOM 169	Wall Prime Paint	no data
2025/08/06	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	in progress
2025/08/06	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	no data
2025/08/06	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	no data

2025/08/06	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete
2025/08/06	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	complete
2025/08/06	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	complete
2025/08/06	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	complete
2025/08/06	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	no data
2025/08/06	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	complete
2025/08/06	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	complete
2025/08/06	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	in progress
2025/08/06	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/08/06	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/08/06	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/08/06	WAITING/LOBBY 100	In Wall Insulation	not started
2025/08/06	WAITING/LOBBY 100	Overhead Duct Insulation	no data
2025/08/06	WAITING/LOBBY 100	Overhead Duct Rough In	no data
2025/08/06	WAITING/LOBBY 100	Overhead Plumbing	not started
2025/08/06	WAITING/LOBBY 100	Wall Drywall	not started
2025/08/06	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/08/06	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/08/06	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/08/06	WOMENS RESTROOM 113	Overhead Duct Insulation	no data
2025/08/06	WOMENS RESTROOM 113	Overhead Duct Rough In	complete
2025/08/06	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/08/06	WOMENS RESTROOM 113	Wall Drywall	complete
2025/08/06	WOMENS RESTROOM 113	Wall Drywall Finish	complete
2025/08/06	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/08/08	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/08/08	ADMIN ASSISTANT 125	Overhead Duct Insulation	complete
2025/08/08	ADMIN ASSISTANT 125	Overhead Duct Rough In	complete
2025/08/08	ADMIN ASSISTANT 125	Overhead Plumbing	no data
2025/08/08	ADMIN ASSISTANT 125	Wall Drywall	complete
2025/08/08	ADMIN ASSISTANT 125	Wall Drywall Finish	complete
2025/08/08	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/08/08	AV ROOM 103	In Wall Insulation	no data
2025/08/08	AV ROOM 103	Overhead Duct Insulation	complete
2025/08/08	AV ROOM 103	Overhead Duct Rough In	complete
2025/08/08	AV ROOM 103	Overhead Plumbing	no data
2025/08/08	AV ROOM 103	Wall Drywall	complete
2025/08/08	AV ROOM 103	Wall Drywall Finish	complete
2025/08/08	AV ROOM 103	Wall Prime Paint	complete
2025/08/08	BREAK ROOM CONFERENCE 182	In Wall Insulation	no data
2025/08/08	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	complete
2025/08/08	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	no data

2025/08/08	BREAK ROOM CONFERENCE 182	Overhead Plumbing	complete
2025/08/08	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/08/08	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	complete
2025/08/08	BREAK ROOM CONFERENCE 182	Wall Prime Paint	complete
2025/08/08	Background-159	In Wall Insulation	complete
2025/08/08	Background-159	Overhead Duct Insulation	complete
2025/08/08	Background-159	Overhead Duct Rough In	complete
2025/08/08	Background-159	Overhead Plumbing	not started
2025/08/08	Background-159	Wall Drywall	complete
2025/08/08	Background-159	Wall Drywall Finish	complete
2025/08/08	Background-159	Wall Prime Paint	complete
2025/08/08	CENTRAL BREAKROOM 145	In Wall Insulation	complete
2025/08/08	CENTRAL BREAKROOM 145	Overhead Duct Insulation	complete
2025/08/08	CENTRAL BREAKROOM 145	Overhead Duct Rough In	no data
2025/08/08	CENTRAL BREAKROOM 145	Overhead Plumbing	complete
2025/08/08	CENTRAL BREAKROOM 145	Wall Drywall	complete
2025/08/08	CENTRAL BREAKROOM 145	Wall Drywall Finish	in progress
2025/08/08	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/08/08	COLD CASE 175	In Wall Insulation	no data
2025/08/08	COLD CASE 175	Overhead Duct Insulation	complete
2025/08/08	COLD CASE 175	Overhead Duct Rough In	complete
2025/08/08	COLD CASE 175	Overhead Plumbing	complete
2025/08/08	COLD CASE 175	Wall Drywall	complete
2025/08/08	COLD CASE 175	Wall Drywall Finish	complete
2025/08/08	COLD CASE 175	Wall Prime Paint	complete
2025/08/08	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/08/08	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	complete
2025/08/08	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	complete
2025/08/08	COMMUNITY AFFAIRS 124	Overhead Plumbing	no data
2025/08/08	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/08/08	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/08/08	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/08/08	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/08/08	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	no data
2025/08/08	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	no data
2025/08/08	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	no data
2025/08/08	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete
2025/08/08	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	complete
2025/08/08	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	complete
2025/08/08	CONFERENCE ROOM 153	In Wall Insulation	complete
2025/08/08	CONFERENCE ROOM 153	Overhead Duct Insulation	

complete			
2025/08/08	CONFERENCE ROOM 153	Overhead Duct Rough In	complete
2025/08/08	CONFERENCE ROOM 153	Overhead Plumbing	not started
2025/08/08	CONFERENCE ROOM 153	Wall Drywall	complete
2025/08/08	CONFERENCE ROOM 153	Wall Drywall Finish	complete
2025/08/08	CONFERENCE ROOM 153	Wall Prime Paint	complete
2025/08/08	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/08/08	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	complete
2025/08/08	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	complete
2025/08/08	CONFERENCE/WAR ROOM 163	Overhead Plumbing	complete
2025/08/08	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/08/08	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete
2025/08/08	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/08/08	COPY 176	In Wall Insulation	complete
2025/08/08	COPY 176	Overhead Duct Insulation	complete
2025/08/08	COPY 176	Overhead Duct Rough In	complete
2025/08/08	COPY 176	Overhead Plumbing	not started
2025/08/08	COPY 176	Wall Drywall	complete
2025/08/08	COPY 176	Wall Drywall Finish	complete
2025/08/08	COPY 176	Wall Prime Paint	complete
2025/08/08	COPY/MAIL ROOM 114	In Wall Insulation	complete
2025/08/08	COPY/MAIL ROOM 114	Overhead Duct Insulation	complete
2025/08/08	COPY/MAIL ROOM 114	Overhead Duct Rough In	complete
2025/08/08	COPY/MAIL ROOM 114	Overhead Plumbing	complete
2025/08/08	COPY/MAIL ROOM 114	Wall Drywall	complete
2025/08/08	COPY/MAIL ROOM 114	Wall Drywall Finish	complete
2025/08/08	COPY/MAIL ROOM 114	Wall Prime Paint	complete
2025/08/08	CORRIDOR 107	In Wall Insulation	complete
2025/08/08	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/08/08	CORRIDOR 107	Overhead Duct Rough In	in progress
2025/08/08	CORRIDOR 107	Overhead Plumbing	in progress
2025/08/08	CORRIDOR 107	Wall Drywall	complete
2025/08/08	CORRIDOR 107	Wall Drywall Finish	complete
2025/08/08	CORRIDOR 107	Wall Prime Paint	complete
2025/08/08	CORRIDOR 108	In Wall Insulation	complete
2025/08/08	CORRIDOR 108	In Wall Insulation	no data
2025/08/08	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/08/08	CORRIDOR 108	Overhead Duct Insulation	no data
2025/08/08	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/08/08	CORRIDOR 108	Overhead Duct Rough In	no data
2025/08/08	CORRIDOR 108	Overhead Plumbing	in progress
2025/08/08	CORRIDOR 108	Overhead Plumbing	no data
2025/08/08	CORRIDOR 108	Wall Drywall	complete
2025/08/08	CORRIDOR 108	Wall Drywall	complete
2025/08/08	CORRIDOR 108	Wall Drywall Finish	complete
2025/08/08	CORRIDOR 108	Wall Drywall Finish	complete
2025/08/08	CORRIDOR 108	Wall Prime Paint	complete
2025/08/08	CORRIDOR 108	Wall Prime Paint	complete
2025/08/08	CORRIDOR 109	In Wall Insulation	complete
2025/08/08	CORRIDOR 109	Overhead Duct Insulation	in progress

2025/08/08	CORRIDOR 109	Overhead Duct Rough In	in progress
2025/08/08	CORRIDOR 109	Overhead Plumbing	in progress
2025/08/08	CORRIDOR 109	Wall Drywall	complete
2025/08/08	CORRIDOR 109	Wall Drywall Finish	complete
2025/08/08	CORRIDOR 109	Wall Prime Paint	complete
2025/08/08	CORRIDOR 110	In Wall Insulation	no data
2025/08/08	CORRIDOR 110	In Wall Insulation	no data
2025/08/08	CORRIDOR 110	Overhead Duct Insulation	no data
2025/08/08	CORRIDOR 110	Overhead Duct Insulation	no data
2025/08/08	CORRIDOR 110	Overhead Duct Rough In	no data
2025/08/08	CORRIDOR 110	Overhead Duct Rough In	no data
2025/08/08	CORRIDOR 110	Overhead Plumbing	no data
2025/08/08	CORRIDOR 110	Overhead Plumbing	in progress
2025/08/08	CORRIDOR 110	Wall Drywall	complete
2025/08/08	CORRIDOR 110	Wall Drywall	complete
2025/08/08	CORRIDOR 110	Wall Drywall Finish	complete
2025/08/08	CORRIDOR 110	Wall Drywall Finish	complete
2025/08/08	CORRIDOR 110	Wall Prime Paint	complete
2025/08/08	CORRIDOR 110	Wall Prime Paint	complete
2025/08/08	CORRIDOR 181	In Wall Insulation	no data
2025/08/08	CORRIDOR 181	Overhead Duct Insulation	no data
2025/08/08	CORRIDOR 181	Overhead Duct Rough In	no data
2025/08/08	CORRIDOR 181	Overhead Plumbing	no data
2025/08/08	CORRIDOR 181	Wall Drywall	no data
2025/08/08	CORRIDOR 181	Wall Drywall Finish	no data
2025/08/08	CORRIDOR 181	Wall Prime Paint	no data
2025/08/08	CORRIDOR144	In Wall Insulation	no data
2025/08/08	CORRIDOR144	Overhead Duct Insulation	no data
2025/08/08	CORRIDOR144	Overhead Duct Rough In	no data
2025/08/08	CORRIDOR144	Overhead Plumbing	no data
2025/08/08	CORRIDOR144	Wall Drywall	complete
2025/08/08	CORRIDOR144	Wall Drywall Finish	complete
2025/08/08	CORRIDOR144	Wall Prime Paint	complete
2025/08/08	CPL 173	In Wall Insulation	complete
2025/08/08	CPL 173	Overhead Duct Insulation	complete
2025/08/08	CPL 173	Overhead Duct Rough In	complete
2025/08/08	CPL 173	Overhead Plumbing	complete
2025/08/08	CPL 173	Wall Drywall	complete
2025/08/08	CPL 173	Wall Drywall Finish	complete
2025/08/08	CPL 173	Wall Prime Paint	complete
2025/08/08	CPL 174	In Wall Insulation	complete
2025/08/08	CPL 174	Overhead Duct Insulation	no data
2025/08/08	CPL 174	Overhead Duct Rough In	complete
2025/08/08	CPL 174	Overhead Plumbing	no data
2025/08/08	CPL 174	Wall Drywall	complete
2025/08/08	CPL 174	Wall Drywall Finish	complete
2025/08/08	CPL 174	Wall Prime Paint	complete
2025/08/08	DRY STORAGE 146	In Wall Insulation	complete
2025/08/08	DRY STORAGE 146	Overhead Duct Insulation	complete
2025/08/08	DRY STORAGE 146	Overhead Duct Rough In	complete
2025/08/08	DRY STORAGE 146	Overhead Plumbing	not started
2025/08/08	DRY STORAGE 146	Wall Drywall	complete
2025/08/08	DRY STORAGE 146	Wall Drywall Finish	complete
2025/08/08	DRY STORAGE 146	Wall Prime Paint	in progress

2025/08/08	FIRE RISER 178	In Wall Insulation	no data
2025/08/08	FIRE RISER 178	Overhead Duct Insulation	no data
2025/08/08	FIRE RISER 178	Overhead Duct Rough In	no data
2025/08/08	FIRE RISER 178	Overhead Plumbing	no data
2025/08/08	FIRE RISER 178	Wall Drywall	no data
2025/08/08	FIRE RISER 178	Wall Drywall Finish	no data
2025/08/08	FIRE RISER 178	Wall Prime Paint	no data
2025/08/08	GREETING ROOM 106	In Wall Insulation	no data
2025/08/08	GREETING ROOM 106	Overhead Duct Insulation	complete
2025/08/08	GREETING ROOM 106	Overhead Duct Rough In	complete
2025/08/08	GREETING ROOM 106	Overhead Plumbing	not started
2025/08/08	GREETING ROOM 106	Wall Drywall	complete
2025/08/08	GREETING ROOM 106	Wall Drywall Finish	complete
2025/08/08	GREETING ROOM 106	Wall Prime Paint	complete
2025/08/08	HR 149	In Wall Insulation	complete
2025/08/08	HR 149	Overhead Duct Insulation	complete
2025/08/08	HR 149	Overhead Duct Rough In	complete
2025/08/08	HR 149	Overhead Plumbing	not started
2025/08/08	HR 149	Wall Drywall	complete
2025/08/08	HR 149	Wall Drywall Finish	complete
2025/08/08	HR 149	Wall Prime Paint	complete
2025/08/08	HR 150	In Wall Insulation	complete
2025/08/08	HR 150	Overhead Duct Insulation	complete
2025/08/08	HR 150	Overhead Duct Rough In	complete
2025/08/08	HR 150	Overhead Plumbing	no data
2025/08/08	HR 150	Wall Drywall	complete
2025/08/08	HR 150	Wall Drywall Finish	complete
2025/08/08	HR 150	Wall Prime Paint	complete
2025/08/08	HR 151	In Wall Insulation	complete
2025/08/08	HR 151	Overhead Duct Insulation	complete
2025/08/08	HR 151	Overhead Duct Rough In	complete
2025/08/08	HR 151	Overhead Plumbing	complete
2025/08/08	HR 151	Wall Drywall	complete
2025/08/08	HR 151	Wall Drywall Finish	complete
2025/08/08	HR 151	Wall Prime Paint	complete
2025/08/08	HR 154	In Wall Insulation	complete
2025/08/08	HR 154	Overhead Duct Insulation	complete
2025/08/08	HR 154	Overhead Duct Rough In	complete
2025/08/08	HR 154	Overhead Plumbing	complete
2025/08/08	HR 154	Wall Drywall	complete
2025/08/08	HR 154	Wall Drywall Finish	complete
2025/08/08	HR 154	Wall Prime Paint	complete
2025/08/08	HR 155	In Wall Insulation	complete
2025/08/08	HR 155	Overhead Duct Insulation	complete
2025/08/08	HR 155	Overhead Duct Rough In	complete
2025/08/08	HR 155	Overhead Plumbing	complete
2025/08/08	HR 155	Wall Drywall	complete
2025/08/08	HR 155	Wall Drywall Finish	complete
2025/08/08	HR 155	Wall Prime Paint	complete
2025/08/08	HR 156	In Wall Insulation	complete
2025/08/08	HR 156	Overhead Duct Insulation	complete
2025/08/08	HR 156	Overhead Duct Rough In	complete
2025/08/08	HR 156	Overhead Plumbing	not started
2025/08/08	HR 156	Wall Drywall	complete



2025/08/08	HR 156	Wall Drywall Finish	complete
2025/08/08	HR 156	Wall Prime Paint	complete
2025/08/08	HR 157	In Wall Insulation	complete
2025/08/08	HR 157	Overhead Duct Insulation	complete
2025/08/08	HR 157	Overhead Duct Rough In	complete
2025/08/08	HR 157	Overhead Plumbing	complete
2025/08/08	HR 157	Wall Drywall	complete
2025/08/08	HR 157	Wall Drywall Finish	complete
2025/08/08	HR 157	Wall Prime Paint	complete
2025/08/08	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/08/08	HUMAN RESOURCES 148	Overhead Duct Insulation	in progress
2025/08/08	HUMAN RESOURCES 148	Overhead Duct Rough In	no data
2025/08/08	HUMAN RESOURCES 148	Overhead Plumbing	in progress
2025/08/08	HUMAN RESOURCES 148	Wall Drywall	complete
2025/08/08	HUMAN RESOURCES 148	Wall Drywall Finish	complete
2025/08/08	HUMAN RESOURCES 148	Wall Prime Paint	complete
2025/08/08	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/08/08	INTERNAL AFFAIRS 119	Overhead Duct Insulation	complete
2025/08/08	INTERNAL AFFAIRS 119	Overhead Duct Rough In	complete
2025/08/08	INTERNAL AFFAIRS 119	Overhead Plumbing	complete
2025/08/08	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/08/08	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/08/08	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/08/08	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/08/08	INTERNAL AFFAIRS 120	Overhead Duct Insulation	complete
2025/08/08	INTERNAL AFFAIRS 120	Overhead Duct Rough In	complete
2025/08/08	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/08/08	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/08/08	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/08/08	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/08/08	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/08/08	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	complete
2025/08/08	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	complete
2025/08/08	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	complete
2025/08/08	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/08/08	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/08/08	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/08/08	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	no data
2025/08/08	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	complete
2025/08/08	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	complete

2025/08/08	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing   complete
2025/08/08	INTERVIEW/ REVIEW ROOM 121	Wall Drywall   complete
2025/08/08	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish   complete
2025/08/08	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint   complete
2025/08/08	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation   no data
2025/08/08	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation   complete
2025/08/08	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In   complete
2025/08/08	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing   complete
2025/08/08	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall   complete
2025/08/08	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish   complete
2025/08/08	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint   complete
2025/08/08	IT 115	In Wall Insulation   complete
2025/08/08	IT 115	Overhead Duct Insulation   no data
2025/08/08	IT 115	Overhead Duct Rough In   no data
2025/08/08	IT 115	Overhead Plumbing   no data
2025/08/08	IT 115	Wall Drywall   complete
2025/08/08	IT 115	Wall Drywall Finish   complete
2025/08/08	IT 115	Wall Prime Paint   complete
2025/08/08	IT 135	In Wall Insulation   complete
2025/08/08	IT 135	Overhead Duct Insulation   complete
2025/08/08	IT 135	Overhead Duct Rough In   complete
2025/08/08	IT 135	Overhead Plumbing   complete
2025/08/08	IT 135	Wall Drywall   complete
2025/08/08	IT 135	Wall Drywall Finish   complete
2025/08/08	IT 135	Wall Prime Paint   complete
2025/08/08	IT MANAGER 136	In Wall Insulation   no data
2025/08/08	IT MANAGER 136	Overhead Duct Insulation   complete
2025/08/08	IT MANAGER 136	Overhead Duct Rough In   complete
2025/08/08	IT MANAGER 136	Overhead Plumbing   complete
2025/08/08	IT MANAGER 136	Wall Drywall   complete
2025/08/08	IT MANAGER 136	Wall Drywall Finish   complete
2025/08/08	IT MANAGER 136	Wall Prime Paint   complete
2025/08/08	IT MANAGER 137	In Wall Insulation   no data
2025/08/08	IT MANAGER 137	Overhead Duct Insulation   complete
2025/08/08	IT MANAGER 137	Overhead Duct Rough In   complete
2025/08/08	IT MANAGER 137	Overhead Plumbing   complete
2025/08/08	IT MANAGER 137	Wall Drywall   complete
2025/08/08	IT MANAGER 137	Wall Drywall Finish   complete
2025/08/08	IT MANAGER 137	Wall Prime Paint   complete
2025/08/08	JUVENILE INTERVIEW 165	In Wall Insulation   complete
2025/08/08	JUVENILE INTERVIEW 165	Overhead Duct Insulation   no data
2025/08/08	JUVENILE INTERVIEW 165	Overhead Duct Rough In   complete

2025/08/08	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/08/08	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/08/08	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/08/08	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/08/08	JUVENILLE INTERVIEWERS 166	In Wall Insulation	complete
2025/08/08	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	in progress
2025/08/08	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	in progress
2025/08/08	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	not started
2025/08/08	JUVENILLE INTERVIEWERS 166	Wall Drywall	complete
2025/08/08	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/08/08	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/08/08	KEY ROOM 185	In Wall Insulation	no data
2025/08/08	KEY ROOM 185	Overhead Duct Insulation	in progress
2025/08/08	KEY ROOM 185	Overhead Duct Rough In	no data
2025/08/08	KEY ROOM 185	Overhead Plumbing	no data
2025/08/08	KEY ROOM 185	Wall Drywall	no data
2025/08/08	KEY ROOM 185	Wall Drywall Finish	no data
2025/08/08	KEY ROOM 185	Wall Prime Paint	no data
2025/08/08	LT 170	In Wall Insulation	complete
2025/08/08	LT 170	Overhead Duct Insulation	complete
2025/08/08	LT 170	Overhead Duct Rough In	complete
2025/08/08	LT 170	Overhead Plumbing	not started
2025/08/08	LT 170	Wall Drywall	complete
2025/08/08	LT 170	Wall Drywall Finish	complete
2025/08/08	LT 170	Wall Prime Paint	complete
2025/08/08	MACHINE ROOM 191	In Wall Insulation	no data
2025/08/08	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/08/08	MACHINE ROOM 191	Overhead Duct Rough In	no data
2025/08/08	MACHINE ROOM 191	Overhead Plumbing	no data
2025/08/08	MACHINE ROOM 191	Wall Drywall	no data
2025/08/08	MACHINE ROOM 191	Wall Drywall Finish	no data
2025/08/08	MACHINE ROOM 191	Wall Prime Paint	no data
2025/08/08	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/08/08	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/08/08	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/08/08	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/08/08	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/08/08	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/08/08	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/08/08	MAIN JANITORIAL111	In Wall Insulation	no data
2025/08/08	MAIN JANITORIAL111	Overhead Duct Insulation	no data
2025/08/08	MAIN JANITORIAL111	Overhead Duct Rough In	no data
2025/08/08	MAIN JANITORIAL111	Overhead Plumbing	no data
2025/08/08	MAIN JANITORIAL111	Wall Drywall	no data
2025/08/08	MAIN JANITORIAL111	Wall Drywall Finish	no data

2025/08/08	MAIN JANITORIAL111	Wall Prime Paint	no data
2025/08/08	MARINE SERGEANT 142	In Wall Insulation	complete
2025/08/08	MARINE SERGEANT 142	Overhead Duct Insulation	complete
2025/08/08	MARINE SERGEANT 142	Overhead Duct Rough In	complete
2025/08/08	MARINE SERGEANT 142	Overhead Plumbing	complete
2025/08/08	MARINE SERGEANT 142	Wall Drywall	complete
2025/08/08	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/08/08	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/08/08	MECHANICAL 192	In Wall Insulation	no data
2025/08/08	MECHANICAL 192	Overhead Duct Insulation	no data
2025/08/08	MECHANICAL 192	Overhead Duct Rough In	no data
2025/08/08	MECHANICAL 192	Overhead Plumbing	no data
2025/08/08	MECHANICAL 192	Wall Drywall	no data
2025/08/08	MECHANICAL 192	Wall Drywall Finish	no data
2025/08/08	MECHANICAL 192	Wall Prime Paint	no data
2025/08/08	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/08/08	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
2025/08/08	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/08/08	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/08/08	MECHANICAL ROOM 122	Wall Drywall	no data
2025/08/08	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/08/08	MECHANICAL ROOM 122	Wall Prime Paint	no data
2025/08/08	MENS RESTROOM 112	In Wall Insulation	no data
2025/08/08	MENS RESTROOM 112	Overhead Duct Insulation	no data
2025/08/08	MENS RESTROOM 112	Overhead Duct Rough In	no data
2025/08/08	MENS RESTROOM 112	Overhead Plumbing	no data
2025/08/08	MENS RESTROOM 112	Wall Drywall	no data
2025/08/08	MENS RESTROOM 112	Wall Drywall Finish	no data
2025/08/08	MENS RESTROOM 112	Wall Prime Paint	no data
2025/08/08	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
2025/08/08	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	complete
2025/08/08	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	complete
2025/08/08	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	complete
2025/08/08	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/08/08	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	complete
2025/08/08	MIS EQUIPMENT STORAGE 138	Wall Prime Paint	complete
2025/08/08	MIS SHREDDING 117	In Wall Insulation	complete
2025/08/08	MIS SHREDDING 117	Overhead Duct Insulation	complete
2025/08/08	MIS SHREDDING 117	Overhead Duct Rough In	complete
2025/08/08	MIS SHREDDING 117	Overhead Plumbing	complete
2025/08/08	MIS SHREDDING 117	Wall Drywall	complete
2025/08/08	MIS SHREDDING 117	Wall Drywall Finish	complete
2025/08/08	MIS SHREDDING 117	Wall Prime Paint	complete
2025/08/08	OFFICE 128	In Wall Insulation	no data
2025/08/08	OFFICE 128	Overhead Duct Insulation	complete
2025/08/08	OFFICE 128	Overhead Duct Rough In	in progress
2025/08/08	OFFICE 128	Overhead Plumbing	no data

2025/08/08	OFFICE 128	Wall Drywall	complete
2025/08/08	OFFICE 128	Wall Drywall Finish	complete
2025/08/08	OFFICE 128	Wall Prime Paint	complete
2025/08/08	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	no data
2025/08/08	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	complete
2025/08/08	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	complete
2025/08/08	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	in progress
2025/08/08	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/08/08	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/08/08	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	complete
2025/08/08	PARTS STORAGE 189	In Wall Insulation	no data
2025/08/08	PARTS STORAGE 189	Overhead Duct Insulation	no data
2025/08/08	PARTS STORAGE 189	Overhead Duct Rough In	no data
2025/08/08	PARTS STORAGE 189	Overhead Plumbing	no data
2025/08/08	PARTS STORAGE 189	Wall Drywall	complete
2025/08/08	PARTS STORAGE 189	Wall Drywall Finish	complete
2025/08/08	PARTS STORAGE 189	Wall Prime Paint	complete
2025/08/08	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/08/08	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/08/08	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/08/08	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/08/08	PUBLIC RESTROOM 106	Wall Drywall	no data
2025/08/08	PUBLIC RESTROOM 106	Wall Drywall Finish	no data
2025/08/08	PUBLIC RESTROOM 106	Wall Prime Paint	no data
2025/08/08	Polygraph 152	In Wall Insulation	complete
2025/08/08	Polygraph 152	Overhead Duct Insulation	complete
2025/08/08	Polygraph 152	Overhead Duct Rough In	complete
2025/08/08	Polygraph 152	Overhead Plumbing	not started
2025/08/08	Polygraph 152	Wall Drywall	complete
2025/08/08	Polygraph 152	Wall Drywall Finish	complete
2025/08/08	Polygraph 152	Wall Prime Paint	complete
2025/08/08	RECEPTION 101	In Wall Insulation	no data
2025/08/08	RECEPTION 101	Overhead Duct Insulation	no data
2025/08/08	RECEPTION 101	Overhead Duct Rough In	no data
2025/08/08	RECEPTION 101	Overhead Plumbing	no data
2025/08/08	RECEPTION 101	Wall Drywall	no data
2025/08/08	RECEPTION 101	Wall Drywall Finish	no data
2025/08/08	RECEPTION 101	Wall Prime Paint	no data
2025/08/08	RECEPTION 147	In Wall Insulation	complete
2025/08/08	RECEPTION 147	Overhead Duct Insulation	complete
2025/08/08	RECEPTION 147	Overhead Duct Rough In	complete
2025/08/08	RECEPTION 147	Overhead Plumbing	complete
2025/08/08	RECEPTION 147	Wall Drywall	complete
2025/08/08	RECEPTION 147	Wall Drywall Finish	complete
2025/08/08	RECEPTION 147	Wall Prime Paint	complete
2025/08/08	RECEPTION 179	In Wall Insulation	complete

2025/08/08	RECEPTION 179	Overhead Duct Insulation	complete
2025/08/08	RECEPTION 179	Overhead Duct Rough In	complete
2025/08/08	RECEPTION 179	Overhead Plumbing	no data
2025/08/08	RECEPTION 179	Wall Drywall	complete
2025/08/08	RECEPTION 179	Wall Drywall Finish	complete
2025/08/08	RECEPTION 179	Wall Prime Paint	complete
2025/08/08	RECORDS 130	In Wall Insulation	no data
2025/08/08	RECORDS 130	Overhead Duct Insulation	complete
2025/08/08	RECORDS 130	Overhead Duct Rough In	complete
2025/08/08	RECORDS 130	Overhead Plumbing	complete
2025/08/08	RECORDS 130	Wall Drywall	complete
2025/08/08	RECORDS 130	Wall Drywall Finish	complete
2025/08/08	RECORDS 130	Wall Prime Paint	complete
2025/08/08	RECORDS STORAGE 133	In Wall Insulation	complete
2025/08/08	RECORDS STORAGE 133	Overhead Duct Insulation	complete
2025/08/08	RECORDS STORAGE 133	Overhead Duct Rough In	complete
2025/08/08	RECORDS STORAGE 133	Overhead Plumbing	complete
2025/08/08	RECORDS STORAGE 133	Wall Drywall	complete
2025/08/08	RECORDS STORAGE 133	Wall Drywall Finish	complete
2025/08/08	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/08/08	RECORDS SUPERVISOR 131	In Wall Insulation	no data
2025/08/08	RECORDS SUPERVISOR 131	Overhead Duct Insulation	complete
2025/08/08	RECORDS SUPERVISOR 131	Overhead Duct Rough In	complete
2025/08/08	RECORDS SUPERVISOR 131	Overhead Plumbing	no data
2025/08/08	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/08/08	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/08/08	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/08/08	RECORDS SUPERVISOR 132	In Wall Insulation	no data
2025/08/08	RECORDS SUPERVISOR 132	Overhead Duct Insulation	complete
2025/08/08	RECORDS SUPERVISOR 132	Overhead Duct Rough In	complete
2025/08/08	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/08/08	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/08/08	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/08/08	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/08/08	RESTROOM 183	In Wall Insulation	no data
2025/08/08	RESTROOM 183	Overhead Duct Insulation	no data
2025/08/08	RESTROOM 183	Overhead Duct Rough In	no data
2025/08/08	RESTROOM 183	Overhead Plumbing	no data
2025/08/08	RESTROOM 183	Wall Drywall	no data
2025/08/08	RESTROOM 183	Wall Drywall Finish	no data
2025/08/08	RESTROOM 183	Wall Prime Paint	no data
2025/08/08	Risk Management - 158	In Wall Insulation	complete
2025/08/08	Risk Management - 158	Overhead Duct Insulation	complete
2025/08/08	Risk Management - 158	Overhead Duct Rough In	complete
2025/08/08	Risk Management - 158	Overhead Plumbing	complete
2025/08/08	Risk Management - 158	Wall Drywall	complete
2025/08/08	Risk Management - 158	Wall Drywall Finish	complete

2025/08/08	Risk Management – 158	Wall Prime Paint	complete
2025/08/08	SALLY PORT 105	In Wall Insulation	no data
2025/08/08	SALLY PORT 105	Overhead Duct Insulation	no data
2025/08/08	SALLY PORT 105	Overhead Duct Rough In	no data
2025/08/08	SALLY PORT 105	Overhead Plumbing	no data
2025/08/08	SALLY PORT 105	Wall Drywall	no data
2025/08/08	SALLY PORT 105	Wall Drywall Finish	no data
2025/08/08	SALLY PORT 105	Wall Prime Paint	no data
2025/08/08	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/08/08	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/08/08	SANE EXAM ROOM 168	Overhead Duct Rough In	complete
2025/08/08	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/08/08	SANE EXAM ROOM 168	Wall Drywall	complete
2025/08/08	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/08/08	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/08/08	SGT 171	In Wall Insulation	no data
2025/08/08	SGT 171	Overhead Duct Insulation	complete
2025/08/08	SGT 171	Overhead Duct Rough In	complete
2025/08/08	SGT 171	Overhead Plumbing	complete
2025/08/08	SGT 171	Wall Drywall	complete
2025/08/08	SGT 171	Wall Drywall Finish	complete
2025/08/08	SGT 171	Wall Prime Paint	complete
2025/08/08	SGT 172	In Wall Insulation	complete
2025/08/08	SGT 172	Overhead Duct Insulation	no data
2025/08/08	SGT 172	Overhead Duct Rough In	complete
2025/08/08	SGT 172	Overhead Plumbing	complete
2025/08/08	SGT 172	Wall Drywall	complete
2025/08/08	SGT 172	Wall Drywall Finish	complete
2025/08/08	SGT 172	Wall Prime Paint	complete
2025/08/08	SHIPPING STORAGE 190	In Wall Insulation	complete
2025/08/08	SHIPPING STORAGE 190	Overhead Duct Insulation	in progress
2025/08/08	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/08/08	SHIPPING STORAGE 190	Overhead Plumbing	no data
2025/08/08	SHIPPING STORAGE 190	Wall Drywall	complete
2025/08/08	SHIPPING STORAGE 190	Wall Drywall Finish	complete
2025/08/08	SHIPPING STORAGE 190	Wall Prime Paint	complete
2025/08/08	SHOP FORMAN 184	In Wall Insulation	no data
2025/08/08	SHOP FORMAN 184	Overhead Duct Insulation	no data
2025/08/08	SHOP FORMAN 184	Overhead Duct Rough In	no data
2025/08/08	SHOP FORMAN 184	Overhead Plumbing	no data
2025/08/08	SHOP FORMAN 184	Wall Drywall	no data
2025/08/08	SHOP FORMAN 184	Wall Drywall Finish	no data
2025/08/08	SHOP FORMAN 184	Wall Prime Paint	no data
2025/08/08	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/08/08	SOFT INTERVIEW 161	Overhead Duct Insulation	no data
2025/08/08	SOFT INTERVIEW 161	Overhead Duct Rough In	complete
2025/08/08	SOFT INTERVIEW 161	Overhead Plumbing	complete
2025/08/08	SOFT INTERVIEW 161	Wall Drywall	complete
2025/08/08	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/08/08	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/08/08	SOFT INTERVIEW 162	In Wall Insulation	no data
2025/08/08	SOFT INTERVIEW 162	Overhead Duct Insulation	no data
2025/08/08	SOFT INTERVIEW 162	Overhead Duct Rough In	no data

2025/08/08		SOFT INTERVIEW 162		Overhead Plumbing		no data
2025/08/08		SOFT INTERVIEW 162		Wall Drywall		no data
2025/08/08		SOFT INTERVIEW 162		Wall Drywall Finish		no data
2025/08/08		SOFT INTERVIEW 162		Wall Prime Paint		no data
2025/08/08		SPECIAL OPERATION LT 143		In Wall Insulation		no data
2025/08/08		SPECIAL OPERATION LT 143		Overhead Duct Insulation		in progress
2025/08/08		SPECIAL OPERATION LT 143		Overhead Duct Rough In		in progress
2025/08/08		SPECIAL OPERATION LT 143		Overhead Plumbing		in progress
2025/08/08		SPECIAL OPERATION LT 143		Wall Drywall		complete
2025/08/08		SPECIAL OPERATION LT 143		Wall Drywall Finish		complete
2025/08/08		SPECIAL OPERATION LT 143		Wall Prime Paint		complete
2025/08/08		STAIR A		In Wall Insulation		no data
2025/08/08		STAIR A		Overhead Duct Insulation		no data
2025/08/08		STAIR A		Overhead Duct Rough In		no data
2025/08/08		STAIR A		Overhead Plumbing		complete
2025/08/08		STAIR A		Wall Drywall		in progress
2025/08/08		STAIR A		Wall Drywall Finish		in progress
2025/08/08		STAIR A		Wall Prime Paint		in progress
2025/08/08		STORAGE 104		In Wall Insulation		no data
2025/08/08		STORAGE 104		Overhead Duct Insulation		no data
2025/08/08		STORAGE 104		Overhead Duct Rough In		no data
2025/08/08		STORAGE 104		Overhead Plumbing		not started
2025/08/08		STORAGE 104		Wall Drywall		complete
2025/08/08		STORAGE 104		Wall Drywall Finish		complete
2025/08/08		STORAGE 104		Wall Prime Paint		complete
2025/08/08		STORAGE 127		In Wall Insulation		no data
2025/08/08		STORAGE 127		Overhead Duct Insulation		complete
2025/08/08		STORAGE 127		Overhead Duct Rough In		complete
2025/08/08		STORAGE 127		Overhead Plumbing		no data
2025/08/08		STORAGE 127		Wall Drywall		complete
2025/08/08		STORAGE 127		Wall Drywall Finish		complete
2025/08/08		STORAGE 127		Wall Prime Paint		complete
2025/08/08		STUDIO 126		In Wall Insulation		complete
2025/08/08		STUDIO 126		Overhead Duct Insulation		complete
2025/08/08		STUDIO 126		Overhead Duct Rough In		complete
2025/08/08		STUDIO 126		Overhead Plumbing		complete
2025/08/08		STUDIO 126		Wall Drywall		complete
2025/08/08		STUDIO 126		Wall Drywall Finish		complete
2025/08/08		STUDIO 126		Wall Prime Paint		complete
2025/08/08		SUPERVISOR 129		In Wall Insulation		complete
2025/08/08		SUPERVISOR 129		Overhead Duct Insulation		complete
2025/08/08		SUPERVISOR 129		Overhead Duct Rough In		complete
2025/08/08		SUPERVISOR 129		Overhead Plumbing		not started
2025/08/08		SUPERVISOR 129		Wall Drywall		complete
2025/08/08		SUPERVISOR 129		Wall Drywall Finish		complete
2025/08/08		SUPERVISOR 129		Wall Prime Paint		complete
2025/08/08		Storage 164		In Wall Insulation		complete
2025/08/08		Storage 164		Overhead Duct Insulation		complete
2025/08/08		Storage 164		Overhead Duct Rough In		complete
2025/08/08		Storage 164		Overhead Plumbing		not started



2025/08/08	Storage 164	Wall Drywall	complete
2025/08/08	Storage 164	Wall Drywall Finish	complete
2025/08/08	Storage 164	Wall Prime Paint	complete
2025/08/08	Storage 177	In Wall Insulation	complete
2025/08/08	Storage 177	Overhead Duct Insulation	complete
2025/08/08	Storage 177	Overhead Duct Rough In	complete
2025/08/08	Storage 177	Overhead Plumbing	not started
2025/08/08	Storage 177	Wall Drywall	complete
2025/08/08	Storage 177	Wall Drywall Finish	complete
2025/08/08	Storage 177	Wall Prime Paint	complete
2025/08/08	TECHNICAL SURVEILLANCE 188	In Wall Insulation	complete
2025/08/08	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	complete
2025/08/08	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	no data
2025/08/08	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	complete
2025/08/08	TECHNICAL SURVEILLANCE 188	Wall Drywall	complete
2025/08/08	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	complete
2025/08/08	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	complete
2025/08/08	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/08/08	TRAFFIC SERGEANT 141	Overhead Duct Insulation	complete
2025/08/08	TRAFFIC SERGEANT 141	Overhead Duct Rough In	complete
2025/08/08	TRAFFIC SERGEANT 141	Overhead Plumbing	complete
2025/08/08	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/08/08	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/08/08	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/08/08	TRIAGE/RECEPTION 134	In Wall Insulation	no data
2025/08/08	TRIAGE/RECEPTION 134	Overhead Duct Insulation	in progress
2025/08/08	TRIAGE/RECEPTION 134	Overhead Duct Rough In	no data
2025/08/08	TRIAGE/RECEPTION 134	Overhead Plumbing	no data
2025/08/08	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/08/08	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/08/08	TRIAGE/RECEPTION 134	Wall Prime Paint	complete
2025/08/08	TST WORKSHOP 187	In Wall Insulation	complete
2025/08/08	TST WORKSHOP 187	Overhead Duct Insulation	no data
2025/08/08	TST WORKSHOP 187	Overhead Duct Rough In	no data
2025/08/08	TST WORKSHOP 187	Overhead Plumbing	no data
2025/08/08	TST WORKSHOP 187	Wall Drywall	complete
2025/08/08	TST WORKSHOP 187	Wall Drywall Finish	complete
2025/08/08	TST WORKSHOP 187	Wall Prime Paint	complete
2025/08/08	UNISEX RESTROOM 169	In Wall Insulation	no data
2025/08/08	UNISEX RESTROOM 169	Overhead Duct Insulation	no data
2025/08/08	UNISEX RESTROOM 169	Overhead Duct Rough In	no data
2025/08/08	UNISEX RESTROOM 169	Overhead Plumbing	no data
2025/08/08	UNISEX RESTROOM 169	Wall Drywall	no data
2025/08/08	UNISEX RESTROOM 169	Wall Drywall Finish	no data

2025/08/08	UNISEX RESTROOM 169	Wall Prime Paint	no data
2025/08/08	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	in progress
2025/08/08	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	not started
2025/08/08	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	no data
2025/08/08	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete
2025/08/08	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	complete
2025/08/08	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	complete
2025/08/08	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	complete
2025/08/08	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	no data
2025/08/08	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	complete
2025/08/08	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	complete
2025/08/08	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	complete
2025/08/08	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/08/08	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/08/08	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/08/08	WAITING/LOBBY 100	In Wall Insulation	no data
2025/08/08	WAITING/LOBBY 100	Overhead Duct Insulation	no data
2025/08/08	WAITING/LOBBY 100	Overhead Duct Rough In	no data
2025/08/08	WAITING/LOBBY 100	Overhead Plumbing	no data
2025/08/08	WAITING/LOBBY 100	Wall Drywall	no data
2025/08/08	WAITING/LOBBY 100	Wall Drywall Finish	no data
2025/08/08	WAITING/LOBBY 100	Wall Prime Paint	no data
2025/08/08	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/08/08	WOMENS RESTROOM 113	Overhead Duct Insulation	no data
2025/08/08	WOMENS RESTROOM 113	Overhead Duct Rough In	no data
2025/08/08	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/08/08	WOMENS RESTROOM 113	Wall Drywall	no data
2025/08/08	WOMENS RESTROOM 113	Wall Drywall Finish	no data
2025/08/08	WOMENS RESTROOM 113	Wall Prime Paint	no data
2025/08/12	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/08/12	ADMIN ASSISTANT 125	Overhead Duct Insulation	complete
2025/08/12	ADMIN ASSISTANT 125	Overhead Duct Rough In	complete
2025/08/12	ADMIN ASSISTANT 125	Overhead Plumbing	no data
2025/08/12	ADMIN ASSISTANT 125	Wall Drywall	complete
2025/08/12	ADMIN ASSISTANT 125	Wall Drywall Finish	complete
2025/08/12	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/08/12	AV ROOM 103	In Wall Insulation	no data
2025/08/12	AV ROOM 103	Overhead Duct Insulation	complete
2025/08/12	AV ROOM 103	Overhead Duct Rough In	complete
2025/08/12	AV ROOM 103	Overhead Plumbing	no data
2025/08/12	AV ROOM 103	Wall Drywall	complete
2025/08/12	AV ROOM 103	Wall Drywall Finish	complete
2025/08/12	AV ROOM 103	Wall Prime Paint	complete

2025/08/12	BREAK ROOM CONFERENCE 182	In Wall Insulation	no data
2025/08/12	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	complete
2025/08/12	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	no data
2025/08/12	BREAK ROOM CONFERENCE 182	Overhead Plumbing	complete
2025/08/12	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/08/12	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	complete
2025/08/12	BREAK ROOM CONFERENCE 182	Wall Prime Paint	complete
2025/08/12	Background-159	In Wall Insulation	complete
2025/08/12	Background-159	Overhead Duct Insulation	complete
2025/08/12	Background-159	Overhead Duct Rough In	complete
2025/08/12	Background-159	Overhead Plumbing	not started
2025/08/12	Background-159	Wall Drywall	complete
2025/08/12	Background-159	Wall Drywall Finish	complete
2025/08/12	Background-159	Wall Prime Paint	complete
2025/08/12	CENTRAL BREAKROOM 145	In Wall Insulation	complete
2025/08/12	CENTRAL BREAKROOM 145	Overhead Duct Insulation	complete
2025/08/12	CENTRAL BREAKROOM 145	Overhead Duct Rough In	complete
2025/08/12	CENTRAL BREAKROOM 145	Overhead Plumbing	complete
2025/08/12	CENTRAL BREAKROOM 145	Wall Drywall	complete
2025/08/12	CENTRAL BREAKROOM 145	Wall Drywall Finish	in progress
2025/08/12	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/08/12	COLD CASE 175	In Wall Insulation	no data
2025/08/12	COLD CASE 175	Overhead Duct Insulation	complete
2025/08/12	COLD CASE 175	Overhead Duct Rough In	complete
2025/08/12	COLD CASE 175	Overhead Plumbing	complete
2025/08/12	COLD CASE 175	Wall Drywall	complete
2025/08/12	COLD CASE 175	Wall Drywall Finish	complete
2025/08/12	COLD CASE 175	Wall Prime Paint	complete
2025/08/12	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/08/12	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	complete
2025/08/12	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	complete
2025/08/12	COMMUNITY AFFAIRS 124	Overhead Plumbing	no data
2025/08/12	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/08/12	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/08/12	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/08/12	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data
2025/08/12	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	no data
2025/08/12	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	no data
2025/08/12	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	no data
2025/08/12	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete

2025/08/12	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	complete
2025/08/12	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	complete
2025/08/12	CONFERENCE ROOM 153	In Wall Insulation	complete
2025/08/12	CONFERENCE ROOM 153	Overhead Duct Insulation	complete
2025/08/12	CONFERENCE ROOM 153	Overhead Duct Rough In	complete
2025/08/12	CONFERENCE ROOM 153	Overhead Plumbing	not started
2025/08/12	CONFERENCE ROOM 153	Wall Drywall	complete
2025/08/12	CONFERENCE ROOM 153	Wall Drywall Finish	complete
2025/08/12	CONFERENCE ROOM 153	Wall Prime Paint	complete
2025/08/12	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/08/12	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	complete
2025/08/12	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	complete
2025/08/12	CONFERENCE/WAR ROOM 163	Overhead Plumbing	complete
2025/08/12	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/08/12	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete
2025/08/12	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/08/12	COPY 176	In Wall Insulation	complete
2025/08/12	COPY 176	Overhead Duct Insulation	complete
2025/08/12	COPY 176	Overhead Duct Rough In	complete
2025/08/12	COPY 176	Overhead Plumbing	not started
2025/08/12	COPY 176	Wall Drywall	complete
2025/08/12	COPY 176	Wall Drywall Finish	complete
2025/08/12	COPY 176	Wall Prime Paint	complete
2025/08/12	COPY/MAIL ROOM 114	In Wall Insulation	no data
2025/08/12	COPY/MAIL ROOM 114	Overhead Duct Insulation	no data
2025/08/12	COPY/MAIL ROOM 114	Overhead Duct Rough In	no data
2025/08/12	COPY/MAIL ROOM 114	Overhead Plumbing	no data
2025/08/12	COPY/MAIL ROOM 114	Wall Drywall	no data
2025/08/12	COPY/MAIL ROOM 114	Wall Drywall Finish	no data
2025/08/12	COPY/MAIL ROOM 114	Wall Prime Paint	no data
2025/08/12	CORRIDOR 107	In Wall Insulation	complete
2025/08/12	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/08/12	CORRIDOR 107	Overhead Duct Rough In	in progress
2025/08/12	CORRIDOR 107	Overhead Plumbing	in progress
2025/08/12	CORRIDOR 107	Wall Drywall	complete
2025/08/12	CORRIDOR 107	Wall Drywall Finish	complete
2025/08/12	CORRIDOR 107	Wall Prime Paint	complete
2025/08/12	CORRIDOR 108	In Wall Insulation	complete
2025/08/12	CORRIDOR 108	In Wall Insulation	no data
2025/08/12	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/08/12	CORRIDOR 108	Overhead Duct Insulation	no data
2025/08/12	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/08/12	CORRIDOR 108	Overhead Duct Rough In	no data
2025/08/12	CORRIDOR 108	Overhead Plumbing	in progress
2025/08/12	CORRIDOR 108	Overhead Plumbing	no data
2025/08/12	CORRIDOR 108	Wall Drywall	complete
2025/08/12	CORRIDOR 108	Wall Drywall	complete
2025/08/12	CORRIDOR 108	Wall Drywall Finish	complete

2025/08/12	CORRIDOR 108	Wall Drywall Finish	complete
2025/08/12	CORRIDOR 108	Wall Prime Paint	complete
2025/08/12	CORRIDOR 108	Wall Prime Paint	complete
2025/08/12	CORRIDOR 109	In Wall Insulation	no data
2025/08/12	CORRIDOR 109	Overhead Duct Insulation	no data
2025/08/12	CORRIDOR 109	Overhead Duct Rough In	no data
2025/08/12	CORRIDOR 109	Overhead Plumbing	no data
2025/08/12	CORRIDOR 109	Wall Drywall	no data
2025/08/12	CORRIDOR 109	Wall Drywall Finish	no data
2025/08/12	CORRIDOR 109	Wall Prime Paint	no data
2025/08/12	CORRIDOR 110	In Wall Insulation	complete
2025/08/12	CORRIDOR 110	In Wall Insulation	no data
2025/08/12	CORRIDOR 110	Overhead Duct Insulation	no data
2025/08/12	CORRIDOR 110	Overhead Duct Insulation	no data
2025/08/12	CORRIDOR 110	Overhead Duct Rough In	no data
2025/08/12	CORRIDOR 110	Overhead Duct Rough In	no data
2025/08/12	CORRIDOR 110	Overhead Plumbing	no data
2025/08/12	CORRIDOR 110	Overhead Plumbing	in progress
2025/08/12	CORRIDOR 110	Wall Drywall	complete
2025/08/12	CORRIDOR 110	Wall Drywall	complete
2025/08/12	CORRIDOR 110	Wall Drywall Finish	complete
2025/08/12	CORRIDOR 110	Wall Drywall Finish	complete
2025/08/12	CORRIDOR 110	Wall Prime Paint	complete
2025/08/12	CORRIDOR 110	Wall Prime Paint	complete
2025/08/12	CORRIDOR 181	In Wall Insulation	complete
2025/08/12	CORRIDOR 181	Overhead Duct Insulation	in progress
2025/08/12	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/08/12	CORRIDOR 181	Overhead Plumbing	in progress
2025/08/12	CORRIDOR 181	Wall Drywall	complete
2025/08/12	CORRIDOR 181	Wall Drywall Finish	complete
2025/08/12	CORRIDOR 181	Wall Prime Paint	complete
2025/08/12	CORRIDOR144	In Wall Insulation	no data
2025/08/12	CORRIDOR144	Overhead Duct Insulation	complete
2025/08/12	CORRIDOR144	Overhead Duct Rough In	no data
2025/08/12	CORRIDOR144	Overhead Plumbing	no data
2025/08/12	CORRIDOR144	Wall Drywall	complete
2025/08/12	CORRIDOR144	Wall Drywall Finish	complete
2025/08/12	CORRIDOR144	Wall Prime Paint	complete
2025/08/12	CPL 173	In Wall Insulation	complete
2025/08/12	CPL 173	Overhead Duct Insulation	complete
2025/08/12	CPL 173	Overhead Duct Rough In	complete
2025/08/12	CPL 173	Overhead Plumbing	complete
2025/08/12	CPL 173	Wall Drywall	complete
2025/08/12	CPL 173	Wall Drywall Finish	complete
2025/08/12	CPL 173	Wall Prime Paint	complete
2025/08/12	CPL 174	In Wall Insulation	complete
2025/08/12	CPL 174	Overhead Duct Insulation	no data
2025/08/12	CPL 174	Overhead Duct Rough In	complete
2025/08/12	CPL 174	Overhead Plumbing	no data
2025/08/12	CPL 174	Wall Drywall	complete
2025/08/12	CPL 174	Wall Drywall Finish	complete
2025/08/12	CPL 174	Wall Prime Paint	complete
2025/08/12	DRY STORAGE 146	In Wall Insulation	complete
2025/08/12	DRY STORAGE 146	Overhead Duct Insulation	complete

2025/08/12	DRY STORAGE 146	Overhead Duct Rough In	complete
2025/08/12	DRY STORAGE 146	Overhead Plumbing	not started
2025/08/12	DRY STORAGE 146	Wall Drywall	complete
2025/08/12	DRY STORAGE 146	Wall Drywall Finish	complete
2025/08/12	DRY STORAGE 146	Wall Prime Paint	in progress
2025/08/12	FIRE RISER 178	In Wall Insulation	no data
2025/08/12	FIRE RISER 178	Overhead Duct Insulation	no data
2025/08/12	FIRE RISER 178	Overhead Duct Rough In	no data
2025/08/12	FIRE RISER 178	Overhead Plumbing	no data
2025/08/12	FIRE RISER 178	Wall Drywall	no data
2025/08/12	FIRE RISER 178	Wall Drywall Finish	no data
2025/08/12	FIRE RISER 178	Wall Prime Paint	no data
2025/08/12	GREETING ROOM 106	In Wall Insulation	no data
2025/08/12	GREETING ROOM 106	Overhead Duct Insulation	complete
2025/08/12	GREETING ROOM 106	Overhead Duct Rough In	complete
2025/08/12	GREETING ROOM 106	Overhead Plumbing	not started
2025/08/12	GREETING ROOM 106	Wall Drywall	complete
2025/08/12	GREETING ROOM 106	Wall Drywall Finish	complete
2025/08/12	GREETING ROOM 106	Wall Prime Paint	complete
2025/08/12	HR 149	In Wall Insulation	complete
2025/08/12	HR 149	Overhead Duct Insulation	complete
2025/08/12	HR 149	Overhead Duct Rough In	complete
2025/08/12	HR 149	Overhead Plumbing	not started
2025/08/12	HR 149	Wall Drywall	complete
2025/08/12	HR 149	Wall Drywall Finish	complete
2025/08/12	HR 149	Wall Prime Paint	complete
2025/08/12	HR 150	In Wall Insulation	complete
2025/08/12	HR 150	Overhead Duct Insulation	complete
2025/08/12	HR 150	Overhead Duct Rough In	complete
2025/08/12	HR 150	Overhead Plumbing	no data
2025/08/12	HR 150	Wall Drywall	complete
2025/08/12	HR 150	Wall Drywall Finish	complete
2025/08/12	HR 150	Wall Prime Paint	complete
2025/08/12	HR 151	In Wall Insulation	complete
2025/08/12	HR 151	Overhead Duct Insulation	complete
2025/08/12	HR 151	Overhead Duct Rough In	complete
2025/08/12	HR 151	Overhead Plumbing	complete
2025/08/12	HR 151	Wall Drywall	complete
2025/08/12	HR 151	Wall Drywall Finish	complete
2025/08/12	HR 151	Wall Prime Paint	complete
2025/08/12	HR 154	In Wall Insulation	complete
2025/08/12	HR 154	Overhead Duct Insulation	complete
2025/08/12	HR 154	Overhead Duct Rough In	complete
2025/08/12	HR 154	Overhead Plumbing	complete
2025/08/12	HR 154	Wall Drywall	complete
2025/08/12	HR 154	Wall Drywall Finish	complete
2025/08/12	HR 154	Wall Prime Paint	complete
2025/08/12	HR 155	In Wall Insulation	complete
2025/08/12	HR 155	Overhead Duct Insulation	complete
2025/08/12	HR 155	Overhead Duct Rough In	complete
2025/08/12	HR 155	Overhead Plumbing	complete
2025/08/12	HR 155	Wall Drywall	complete
2025/08/12	HR 155	Wall Drywall Finish	complete
2025/08/12	HR 155	Wall Prime Paint	complete

2025/08/12	HR 156	In Wall Insulation	complete
2025/08/12	HR 156	Overhead Duct Insulation	complete
2025/08/12	HR 156	Overhead Duct Rough In	complete
2025/08/12	HR 156	Overhead Plumbing	not started
2025/08/12	HR 156	Wall Drywall	complete
2025/08/12	HR 156	Wall Drywall Finish	complete
2025/08/12	HR 156	Wall Prime Paint	complete
2025/08/12	HR 157	In Wall Insulation	complete
2025/08/12	HR 157	Overhead Duct Insulation	complete
2025/08/12	HR 157	Overhead Duct Rough In	complete
2025/08/12	HR 157	Overhead Plumbing	complete
2025/08/12	HR 157	Wall Drywall	complete
2025/08/12	HR 157	Wall Drywall Finish	complete
2025/08/12	HR 157	Wall Prime Paint	complete
2025/08/12	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/08/12	HUMAN RESOURCES 148	Overhead Duct Insulation	complete
2025/08/12	HUMAN RESOURCES 148	Overhead Duct Rough In	no data
2025/08/12	HUMAN RESOURCES 148	Overhead Plumbing	complete
2025/08/12	HUMAN RESOURCES 148	Wall Drywall	complete
2025/08/12	HUMAN RESOURCES 148	Wall Drywall Finish	complete
2025/08/12	HUMAN RESOURCES 148	Wall Prime Paint	complete
2025/08/12	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/08/12	INTERNAL AFFAIRS 119	Overhead Duct Insulation	complete
2025/08/12	INTERNAL AFFAIRS 119	Overhead Duct Rough In	complete
2025/08/12	INTERNAL AFFAIRS 119	Overhead Plumbing	complete
2025/08/12	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/08/12	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/08/12	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/08/12	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/08/12	INTERNAL AFFAIRS 120	Overhead Duct Insulation	complete
2025/08/12	INTERNAL AFFAIRS 120	Overhead Duct Rough In	complete
2025/08/12	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/08/12	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/08/12	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/08/12	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/08/12	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/08/12	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	complete
2025/08/12	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	complete
2025/08/12	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	complete
2025/08/12	INTERVIEW / REVIEW ROOM 118	Wall Drywall	complete
2025/08/12	INTERVIEW / REVIEW ROOM 118	Wall Drywall Finish	complete
2025/08/12	INTERVIEW / REVIEW ROOM 118	Wall Prime Paint	complete
2025/08/12	INTERVIEW/ REVIEW ROOM 121	In Wall Insulation	no

data

2025/08/12	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Insulation	complete
2025/08/12	INTERVIEW/ REVIEW ROOM 121	Overhead Duct Rough In	complete
2025/08/12	INTERVIEW/ REVIEW ROOM 121	Overhead Plumbing	complete
2025/08/12	INTERVIEW/ REVIEW ROOM 121	Wall Drywall	complete
2025/08/12	INTERVIEW/ REVIEW ROOM 121	Wall Drywall Finish	complete
2025/08/12	INTERVIEW/ REVIEW ROOM 121	Wall Prime Paint	complete
2025/08/12	INVESTIGATIONS / MAJOR CASE 167	In Wall Insulation	no data
2025/08/12	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Insulation	complete
2025/08/12	INVESTIGATIONS / MAJOR CASE 167	Overhead Duct Rough In	complete
2025/08/12	INVESTIGATIONS / MAJOR CASE 167	Overhead Plumbing	complete
2025/08/12	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall	complete
2025/08/12	INVESTIGATIONS / MAJOR CASE 167	Wall Drywall Finish	complete
2025/08/12	INVESTIGATIONS / MAJOR CASE 167	Wall Prime Paint	complete
2025/08/12	IT 115	In Wall Insulation	no data
2025/08/12	IT 115	Overhead Duct Insulation	no data
2025/08/12	IT 115	Overhead Duct Rough In	no data
2025/08/12	IT 115	Overhead Plumbing	no data
2025/08/12	IT 115	Wall Drywall	complete
2025/08/12	IT 115	Wall Drywall Finish	complete
2025/08/12	IT 115	Wall Prime Paint	complete
2025/08/12	IT 135	In Wall Insulation	complete
2025/08/12	IT 135	Overhead Duct Insulation	complete
2025/08/12	IT 135	Overhead Duct Rough In	complete
2025/08/12	IT 135	Overhead Plumbing	complete
2025/08/12	IT 135	Wall Drywall	complete
2025/08/12	IT 135	Wall Drywall Finish	complete
2025/08/12	IT 135	Wall Prime Paint	complete
2025/08/12	IT MANAGER 136	In Wall Insulation	no data
2025/08/12	IT MANAGER 136	Overhead Duct Insulation	complete
2025/08/12	IT MANAGER 136	Overhead Duct Rough In	complete
2025/08/12	IT MANAGER 136	Overhead Plumbing	complete
2025/08/12	IT MANAGER 136	Wall Drywall	complete
2025/08/12	IT MANAGER 136	Wall Drywall Finish	complete
2025/08/12	IT MANAGER 136	Wall Prime Paint	complete
2025/08/12	IT MANAGER 137	In Wall Insulation	no data
2025/08/12	IT MANAGER 137	Overhead Duct Insulation	complete
2025/08/12	IT MANAGER 137	Overhead Duct Rough In	complete
2025/08/12	IT MANAGER 137	Overhead Plumbing	complete
2025/08/12	IT MANAGER 137	Wall Drywall	complete
2025/08/12	IT MANAGER 137	Wall Drywall Finish	complete
2025/08/12	IT MANAGER 137	Wall Prime Paint	complete



2025/08/12	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/08/12	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data
2025/08/12	JUVENILE INTERVIEW 165	Overhead Duct Rough In	complete
2025/08/12	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/08/12	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/08/12	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/08/12	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/08/12	JUVENILLE INTERVIEWERS 166	In Wall Insulation	no data
2025/08/12	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	complete
2025/08/12	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	no data
2025/08/12	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	no data
2025/08/12	JUVENILLE INTERVIEWERS 166	Wall Drywall	complete
2025/08/12	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	complete
2025/08/12	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/08/12	KEY ROOM 185	In Wall Insulation	complete
2025/08/12	KEY ROOM 185	Overhead Duct Insulation	in progress
2025/08/12	KEY ROOM 185	Overhead Duct Rough In	no data
2025/08/12	KEY ROOM 185	Overhead Plumbing	no data
2025/08/12	KEY ROOM 185	Wall Drywall	complete
2025/08/12	KEY ROOM 185	Wall Drywall Finish	complete
2025/08/12	KEY ROOM 185	Wall Prime Paint	complete
2025/08/12	LT 170	In Wall Insulation	complete
2025/08/12	LT 170	Overhead Duct Insulation	complete
2025/08/12	LT 170	Overhead Duct Rough In	complete
2025/08/12	LT 170	Overhead Plumbing	not started
2025/08/12	LT 170	Wall Drywall	complete
2025/08/12	LT 170	Wall Drywall Finish	complete
2025/08/12	LT 170	Wall Prime Paint	complete
2025/08/12	MACHINE ROOM 191	In Wall Insulation	no data
2025/08/12	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/08/12	MACHINE ROOM 191	Overhead Duct Rough In	no data
2025/08/12	MACHINE ROOM 191	Overhead Plumbing	no data
2025/08/12	MACHINE ROOM 191	Wall Drywall	no data
2025/08/12	MACHINE ROOM 191	Wall Drywall Finish	no data
2025/08/12	MACHINE ROOM 191	Wall Prime Paint	no data
2025/08/12	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/08/12	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/08/12	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no data
2025/08/12	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/08/12	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/08/12	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
2025/08/12	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/08/12	MAIN JANITORIAL111	In Wall Insulation	no data

2025/08/12	MAIN JANITORIAL111	Overhead Duct Insulation   complete
2025/08/12	MAIN JANITORIAL111	Overhead Duct Rough In   complete
2025/08/12	MAIN JANITORIAL111	Overhead Plumbing   complete
2025/08/12	MAIN JANITORIAL111	Wall Drywall   complete
2025/08/12	MAIN JANITORIAL111	Wall Drywall Finish   complete
2025/08/12	MAIN JANITORIAL111	Wall Prime Paint   complete
2025/08/12	MARINE SERGEANT 142	In Wall Insulation   complete
2025/08/12	MARINE SERGEANT 142	Overhead Duct Insulation   complete
2025/08/12	MARINE SERGEANT 142	Overhead Duct Rough In   complete
2025/08/12	MARINE SERGEANT 142	Overhead Plumbing   complete
2025/08/12	MARINE SERGEANT 142	Wall Drywall   complete
2025/08/12	MARINE SERGEANT 142	Wall Drywall Finish   complete
2025/08/12	MARINE SERGEANT 142	Wall Prime Paint   complete
2025/08/12	MECHANICAL 192	In Wall Insulation   no data
2025/08/12	MECHANICAL 192	Overhead Duct Insulation   no data
2025/08/12	MECHANICAL 192	Overhead Duct Rough In   no data
2025/08/12	MECHANICAL 192	Overhead Plumbing   no data
2025/08/12	MECHANICAL 192	Wall Drywall   no data
2025/08/12	MECHANICAL 192	Wall Drywall Finish   no data
2025/08/12	MECHANICAL 192	Wall Prime Paint   no data
2025/08/12	MECHANICAL ROOM 122	In Wall Insulation   no data
2025/08/12	MECHANICAL ROOM 122	Overhead Duct Insulation   no data
2025/08/12	MECHANICAL ROOM 122	Overhead Duct Rough In   no data
2025/08/12	MECHANICAL ROOM 122	Overhead Plumbing   no data
2025/08/12	MECHANICAL ROOM 122	Wall Drywall   no data
2025/08/12	MECHANICAL ROOM 122	Wall Drywall Finish   no data
2025/08/12	MECHANICAL ROOM 122	Wall Prime Paint   no data
2025/08/12	MENS RESTROOM 112	In Wall Insulation   no data
2025/08/12	MENS RESTROOM 112	Overhead Duct Insulation   no data
2025/08/12	MENS RESTROOM 112	Overhead Duct Rough In   no data
2025/08/12	MENS RESTROOM 112	Overhead Plumbing   no data
2025/08/12	MENS RESTROOM 112	Wall Drywall   no data
2025/08/12	MENS RESTROOM 112	Wall Drywall Finish   no data
2025/08/12	MENS RESTROOM 112	Wall Prime Paint   no data
2025/08/12	MIS EQUIPMENT STORAGE 138	In Wall Insulation   no data
2025/08/12	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation   complete
2025/08/12	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In   complete
2025/08/12	MIS EQUIPMENT STORAGE 138	Overhead Plumbing   complete
2025/08/12	MIS EQUIPMENT STORAGE 138	Wall Drywall   complete
2025/08/12	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish   complete
2025/08/12	MIS EQUIPMENT STORAGE 138	Wall Prime Paint   complete
2025/08/12	MIS SHREDDING 117	In Wall Insulation   no data
2025/08/12	MIS SHREDDING 117	Overhead Duct Insulation   no data
2025/08/12	MIS SHREDDING 117	Overhead Duct Rough In   no data
2025/08/12	MIS SHREDDING 117	Overhead Plumbing   no data
2025/08/12	MIS SHREDDING 117	Wall Drywall   no data

2025/08/12	MIS SHREDDING 117	Wall Drywall Finish	no data
2025/08/12	MIS SHREDDING 117	Wall Prime Paint	no data
2025/08/12	OFFICE 128	In Wall Insulation	no data
2025/08/12	OFFICE 128	Overhead Duct Insulation	complete
2025/08/12	OFFICE 128	Overhead Duct Rough In	complete
2025/08/12	OFFICE 128	Overhead Plumbing	no data
2025/08/12	OFFICE 128	Wall Drywall	complete
2025/08/12	OFFICE 128	Wall Drywall Finish	complete
2025/08/12	OFFICE 128	Wall Prime Paint	complete
2025/08/12	OPERATIONS SUPPORT DIVISION 139	In Wall Insulation	no data
2025/08/12	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Insulation	complete
2025/08/12	OPERATIONS SUPPORT DIVISION 139	Overhead Duct Rough In	complete
2025/08/12	OPERATIONS SUPPORT DIVISION 139	Overhead Plumbing	no data
2025/08/12	OPERATIONS SUPPORT DIVISION 139	Wall Drywall	complete
2025/08/12	OPERATIONS SUPPORT DIVISION 139	Wall Drywall Finish	complete
2025/08/12	OPERATIONS SUPPORT DIVISION 139	Wall Prime Paint	complete
2025/08/12	PARTS STORAGE 189	In Wall Insulation	no data
2025/08/12	PARTS STORAGE 189	Overhead Duct Insulation	no data
2025/08/12	PARTS STORAGE 189	Overhead Duct Rough In	no data
2025/08/12	PARTS STORAGE 189	Overhead Plumbing	no data
2025/08/12	PARTS STORAGE 189	Wall Drywall	complete
2025/08/12	PARTS STORAGE 189	Wall Drywall Finish	complete
2025/08/12	PARTS STORAGE 189	Wall Prime Paint	complete
2025/08/12	PUBLIC RESTROOM 106	In Wall Insulation	no data
2025/08/12	PUBLIC RESTROOM 106	Overhead Duct Insulation	no data
2025/08/12	PUBLIC RESTROOM 106	Overhead Duct Rough In	no data
2025/08/12	PUBLIC RESTROOM 106	Overhead Plumbing	no data
2025/08/12	PUBLIC RESTROOM 106	Wall Drywall	no data
2025/08/12	PUBLIC RESTROOM 106	Wall Drywall Finish	no data
2025/08/12	PUBLIC RESTROOM 106	Wall Prime Paint	no data
2025/08/12	Polygraph 152	In Wall Insulation	complete
2025/08/12	Polygraph 152	Overhead Duct Insulation	complete
2025/08/12	Polygraph 152	Overhead Duct Rough In	complete
2025/08/12	Polygraph 152	Overhead Plumbing	not started
2025/08/12	Polygraph 152	Wall Drywall	complete
2025/08/12	Polygraph 152	Wall Drywall Finish	complete
2025/08/12	Polygraph 152	Wall Prime Paint	complete
2025/08/12	RECEPTION 101	In Wall Insulation	no data
2025/08/12	RECEPTION 101	Overhead Duct Insulation	no data
2025/08/12	RECEPTION 101	Overhead Duct Rough In	no data
2025/08/12	RECEPTION 101	Overhead Plumbing	no data
2025/08/12	RECEPTION 101	Wall Drywall	no data
2025/08/12	RECEPTION 101	Wall Drywall Finish	no data
2025/08/12	RECEPTION 101	Wall Prime Paint	no data
2025/08/12	RECEPTION 147	In Wall Insulation	complete
2025/08/12	RECEPTION 147	Overhead Duct Insulation	complete

2025/08/12	RECEPTION 147	Overhead Duct Rough In	complete
2025/08/12	RECEPTION 147	Overhead Plumbing	complete
2025/08/12	RECEPTION 147	Wall Drywall	complete
2025/08/12	RECEPTION 147	Wall Drywall Finish	complete
2025/08/12	RECEPTION 147	Wall Prime Paint	complete
2025/08/12	RECEPTION 179	In Wall Insulation	complete
2025/08/12	RECEPTION 179	Overhead Duct Insulation	complete
2025/08/12	RECEPTION 179	Overhead Duct Rough In	complete
2025/08/12	RECEPTION 179	Overhead Plumbing	no data
2025/08/12	RECEPTION 179	Wall Drywall	complete
2025/08/12	RECEPTION 179	Wall Drywall Finish	complete
2025/08/12	RECEPTION 179	Wall Prime Paint	complete
2025/08/12	RECORDS 130	In Wall Insulation	no data
2025/08/12	RECORDS 130	Overhead Duct Insulation	complete
2025/08/12	RECORDS 130	Overhead Duct Rough In	complete
2025/08/12	RECORDS 130	Overhead Plumbing	complete
2025/08/12	RECORDS 130	Wall Drywall	complete
2025/08/12	RECORDS 130	Wall Drywall Finish	complete
2025/08/12	RECORDS 130	Wall Prime Paint	complete
2025/08/12	RECORDS STORAGE 133	In Wall Insulation	complete
2025/08/12	RECORDS STORAGE 133	Overhead Duct Insulation	complete
2025/08/12	RECORDS STORAGE 133	Overhead Duct Rough In	complete
2025/08/12	RECORDS STORAGE 133	Overhead Plumbing	complete
2025/08/12	RECORDS STORAGE 133	Wall Drywall	complete
2025/08/12	RECORDS STORAGE 133	Wall Drywall Finish	complete
2025/08/12	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/08/12	RECORDS SUPERVISOR 131	In Wall Insulation	no data
2025/08/12	RECORDS SUPERVISOR 131	Overhead Duct Insulation	complete
2025/08/12	RECORDS SUPERVISOR 131	Overhead Duct Rough In	complete
2025/08/12	RECORDS SUPERVISOR 131	Overhead Plumbing	no data
2025/08/12	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/08/12	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/08/12	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/08/12	RECORDS SUPERVISOR 132	In Wall Insulation	no data
2025/08/12	RECORDS SUPERVISOR 132	Overhead Duct Insulation	complete
2025/08/12	RECORDS SUPERVISOR 132	Overhead Duct Rough In	complete
2025/08/12	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/08/12	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/08/12	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/08/12	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/08/12	RESTROOM 183	In Wall Insulation	no data
2025/08/12	RESTROOM 183	Overhead Duct Insulation	no data
2025/08/12	RESTROOM 183	Overhead Duct Rough In	no data
2025/08/12	RESTROOM 183	Overhead Plumbing	no data
2025/08/12	RESTROOM 183	Wall Drywall	no data
2025/08/12	RESTROOM 183	Wall Drywall Finish	no data
2025/08/12	RESTROOM 183	Wall Prime Paint	no data
2025/08/12	Risk Management - 158	In Wall Insulation	complete
2025/08/12	Risk Management - 158	Overhead Duct Insulation	

complete			
2025/08/12	Risk Management - 158	Overhead Duct Rough In	
complete			
2025/08/12	Risk Management - 158	Overhead Plumbing	complete
2025/08/12	Risk Management - 158	Wall Drywall	complete
2025/08/12	Risk Management - 158	Wall Drywall Finish	complete
2025/08/12	Risk Management - 158	Wall Prime Paint	complete
2025/08/12	SALLY PORT 105	In Wall Insulation	not started
2025/08/12	SALLY PORT 105	Overhead Duct Insulation	in progress
2025/08/12	SALLY PORT 105	Overhead Duct Rough In	no data
2025/08/12	SALLY PORT 105	Overhead Plumbing	no data
2025/08/12	SALLY PORT 105	Wall Drywall	not started
2025/08/12	SALLY PORT 105	Wall Drywall Finish	not started
2025/08/12	SALLY PORT 105	Wall Prime Paint	not started
2025/08/12	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/08/12	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/08/12	SANE EXAM ROOM 168	Overhead Duct Rough In	complete
2025/08/12	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/08/12	SANE EXAM ROOM 168	Wall Drywall	complete
2025/08/12	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/08/12	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/08/12	SGT 171	In Wall Insulation	no data
2025/08/12	SGT 171	Overhead Duct Insulation	complete
2025/08/12	SGT 171	Overhead Duct Rough In	complete
2025/08/12	SGT 171	Overhead Plumbing	complete
2025/08/12	SGT 171	Wall Drywall	complete
2025/08/12	SGT 171	Wall Drywall Finish	complete
2025/08/12	SGT 171	Wall Prime Paint	complete
2025/08/12	SGT 172	In Wall Insulation	complete
2025/08/12	SGT 172	Overhead Duct Insulation	no data
2025/08/12	SGT 172	Overhead Duct Rough In	complete
2025/08/12	SGT 172	Overhead Plumbing	complete
2025/08/12	SGT 172	Wall Drywall	complete
2025/08/12	SGT 172	Wall Drywall Finish	complete
2025/08/12	SGT 172	Wall Prime Paint	complete
2025/08/12	SHIPPING STORAGE 190	In Wall Insulation	no data
2025/08/12	SHIPPING STORAGE 190	Overhead Duct Insulation	no data
2025/08/12	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/08/12	SHIPPING STORAGE 190	Overhead Plumbing	not started
2025/08/12	SHIPPING STORAGE 190	Wall Drywall	no data
2025/08/12	SHIPPING STORAGE 190	Wall Drywall Finish	no data
2025/08/12	SHIPPING STORAGE 190	Wall Prime Paint	no data
2025/08/12	SHOP FORMAN 184	In Wall Insulation	complete
2025/08/12	SHOP FORMAN 184	Overhead Duct Insulation	complete
2025/08/12	SHOP FORMAN 184	Overhead Duct Rough In	complete
2025/08/12	SHOP FORMAN 184	Overhead Plumbing	no data
2025/08/12	SHOP FORMAN 184	Wall Drywall	complete
2025/08/12	SHOP FORMAN 184	Wall Drywall Finish	complete
2025/08/12	SHOP FORMAN 184	Wall Prime Paint	complete
2025/08/12	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/08/12	SOFT INTERVIEW 161	Overhead Duct Insulation	no data
2025/08/12	SOFT INTERVIEW 161	Overhead Duct Rough In	complete
2025/08/12	SOFT INTERVIEW 161	Overhead Plumbing	complete

2025/08/12		SOFT INTERVIEW 161		Wall Drywall		complete
2025/08/12		SOFT INTERVIEW 161		Wall Drywall Finish		complete
2025/08/12		SOFT INTERVIEW 161		Wall Prime Paint		complete
2025/08/12		SOFT INTERVIEW 162		In Wall Insulation		complete
2025/08/12		SOFT INTERVIEW 162		Overhead Duct Insulation		no data
2025/08/12		SOFT INTERVIEW 162		Overhead Duct Rough In		complete
2025/08/12		SOFT INTERVIEW 162		Overhead Plumbing		complete
2025/08/12		SOFT INTERVIEW 162		Wall Drywall		complete
2025/08/12		SOFT INTERVIEW 162		Wall Drywall Finish		complete
2025/08/12		SOFT INTERVIEW 162		Wall Prime Paint		complete
2025/08/12		SPECIAL OPERATION LT 143		In Wall Insulation		no data
2025/08/12		SPECIAL OPERATION LT 143		Overhead Duct Insulation		no data
2025/08/12		SPECIAL OPERATION LT 143		Overhead Duct Rough In		no data
2025/08/12		SPECIAL OPERATION LT 143		Overhead Plumbing		no data
2025/08/12		SPECIAL OPERATION LT 143		Wall Drywall		complete
2025/08/12		SPECIAL OPERATION LT 143		Wall Drywall Finish		complete
2025/08/12		SPECIAL OPERATION LT 143		Wall Prime Paint		complete
2025/08/12		STAIR A		In Wall Insulation		no data
2025/08/12		STAIR A		Overhead Duct Insulation		no data
2025/08/12		STAIR A		Overhead Duct Rough In		no data
2025/08/12		STAIR A		Overhead Plumbing		complete
2025/08/12		STAIR A		Wall Drywall		in progress
2025/08/12		STAIR A		Wall Drywall Finish		in progress
2025/08/12		STAIR A		Wall Prime Paint		in progress
2025/08/12		STORAGE 104		In Wall Insulation		no data
2025/08/12		STORAGE 104		Overhead Duct Insulation		no data
2025/08/12		STORAGE 104		Overhead Duct Rough In		no data
2025/08/12		STORAGE 104		Overhead Plumbing		not started
2025/08/12		STORAGE 104		Wall Drywall		complete
2025/08/12		STORAGE 104		Wall Drywall Finish		complete
2025/08/12		STORAGE 104		Wall Prime Paint		complete
2025/08/12		STORAGE 127		In Wall Insulation		no data
2025/08/12		STORAGE 127		Overhead Duct Insulation		complete
2025/08/12		STORAGE 127		Overhead Duct Rough In		complete
2025/08/12		STORAGE 127		Overhead Plumbing		no data
2025/08/12		STORAGE 127		Wall Drywall		complete
2025/08/12		STORAGE 127		Wall Drywall Finish		complete
2025/08/12		STORAGE 127		Wall Prime Paint		complete
2025/08/12		STUDIO 126		In Wall Insulation		complete
2025/08/12		STUDIO 126		Overhead Duct Insulation		complete
2025/08/12		STUDIO 126		Overhead Duct Rough In		complete
2025/08/12		STUDIO 126		Overhead Plumbing		complete
2025/08/12		STUDIO 126		Wall Drywall		complete
2025/08/12		STUDIO 126		Wall Drywall Finish		complete
2025/08/12		STUDIO 126		Wall Prime Paint		complete
2025/08/12		SUPERVISOR 129		In Wall Insulation		complete
2025/08/12		SUPERVISOR 129		Overhead Duct Insulation		complete
2025/08/12		SUPERVISOR 129		Overhead Duct Rough In		complete
2025/08/12		SUPERVISOR 129		Overhead Plumbing		not started
2025/08/12		SUPERVISOR 129		Wall Drywall		complete
2025/08/12		SUPERVISOR 129		Wall Drywall Finish		complete

2025/08/12	SUPERVISOR 129	Wall Prime Paint	complete
2025/08/12	Storage 164	In Wall Insulation	complete
2025/08/12	Storage 164	Overhead Duct Insulation	complete
2025/08/12	Storage 164	Overhead Duct Rough In	complete
2025/08/12	Storage 164	Overhead Plumbing	not started
2025/08/12	Storage 164	Wall Drywall	complete
2025/08/12	Storage 164	Wall Drywall Finish	complete
2025/08/12	Storage 164	Wall Prime Paint	complete
2025/08/12	Storage 177	In Wall Insulation	complete
2025/08/12	Storage 177	Overhead Duct Insulation	complete
2025/08/12	Storage 177	Overhead Duct Rough In	complete
2025/08/12	Storage 177	Overhead Plumbing	not started
2025/08/12	Storage 177	Wall Drywall	complete
2025/08/12	Storage 177	Wall Drywall Finish	complete
2025/08/12	Storage 177	Wall Prime Paint	complete
2025/08/12	TECHNICAL SURVEILLANCE 188	In Wall Insulation	complete
2025/08/12	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	complete
2025/08/12	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	complete
2025/08/12	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	complete
2025/08/12	TECHNICAL SURVEILLANCE 188	Wall Drywall	complete
2025/08/12	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	complete
2025/08/12	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	complete
2025/08/12	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/08/12	TRAFFIC SERGEANT 141	Overhead Duct Insulation	complete
2025/08/12	TRAFFIC SERGEANT 141	Overhead Duct Rough In	complete
2025/08/12	TRAFFIC SERGEANT 141	Overhead Plumbing	complete
2025/08/12	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/08/12	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/08/12	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/08/12	TRIAGE/RECEPTION 134	In Wall Insulation	complete
2025/08/12	TRIAGE/RECEPTION 134	Overhead Duct Insulation	complete
2025/08/12	TRIAGE/RECEPTION 134	Overhead Duct Rough In	no data
2025/08/12	TRIAGE/RECEPTION 134	Overhead Plumbing	no data
2025/08/12	TRIAGE/RECEPTION 134	Wall Drywall	complete
2025/08/12	TRIAGE/RECEPTION 134	Wall Drywall Finish	complete
2025/08/12	TRIAGE/RECEPTION 134	Wall Prime Paint	complete
2025/08/12	TST WORKSHOP 187	In Wall Insulation	complete
2025/08/12	TST WORKSHOP 187	Overhead Duct Insulation	not started
2025/08/12	TST WORKSHOP 187	Overhead Duct Rough In	complete
2025/08/12	TST WORKSHOP 187	Overhead Plumbing	no data
2025/08/12	TST WORKSHOP 187	Wall Drywall	complete
2025/08/12	TST WORKSHOP 187	Wall Drywall Finish	complete
2025/08/12	TST WORKSHOP 187	Wall Prime Paint	complete
2025/08/12	UNISEX RESTROOM 169	In Wall Insulation	no data

2025/08/12	UNISEX RESTROOM 169	Overhead Duct Insulation	no data
2025/08/12	UNISEX RESTROOM 169	Overhead Duct Rough In	no data
2025/08/12	UNISEX RESTROOM 169	Overhead Plumbing	no data
2025/08/12	UNISEX RESTROOM 169	Wall Drywall	no data
2025/08/12	UNISEX RESTROOM 169	Wall Drywall Finish	no data
2025/08/12	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/08/12	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	no data
2025/08/12	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	no data
2025/08/12	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	no data
2025/08/12	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	no data
2025/08/12	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	complete
2025/08/12	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	complete
2025/08/12	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	complete
2025/08/12	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	no data
2025/08/12	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	complete
2025/08/12	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	complete
2025/08/12	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	complete
2025/08/12	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/08/12	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/08/12	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/08/12	WAITING/LOBBY 100	In Wall Insulation	not started
2025/08/12	WAITING/LOBBY 100	Overhead Duct Insulation	not started
2025/08/12	WAITING/LOBBY 100	Overhead Duct Rough In	in progress
2025/08/12	WAITING/LOBBY 100	Overhead Plumbing	no data
2025/08/12	WAITING/LOBBY 100	Wall Drywall	not started
2025/08/12	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/08/12	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/08/12	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/08/12	WOMENS RESTROOM 113	Overhead Duct Insulation	no data
2025/08/12	WOMENS RESTROOM 113	Overhead Duct Rough In	complete
2025/08/12	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/08/12	WOMENS RESTROOM 113	Wall Drywall	complete
2025/08/12	WOMENS RESTROOM 113	Wall Drywall Finish	complete
2025/08/12	WOMENS RESTROOM 113	Wall Prime Paint	not started
2025/08/22	ADMIN ASSISTANT 125	In Wall Insulation	no data
2025/08/22	ADMIN ASSISTANT 125	Overhead Duct Insulation	complete
2025/08/22	ADMIN ASSISTANT 125	Overhead Duct Rough In	complete
2025/08/22	ADMIN ASSISTANT 125	Overhead Plumbing	in progress
2025/08/22	ADMIN ASSISTANT 125	Wall Drywall	no data
2025/08/22	ADMIN ASSISTANT 125	Wall Drywall Finish	no data



2025/08/22	ADMIN ASSISTANT 125	Wall Prime Paint	complete
2025/08/22	AV ROOM 103	In Wall Insulation	no data
2025/08/22	AV ROOM 103	Overhead Duct Insulation	complete
2025/08/22	AV ROOM 103	Overhead Duct Rough In	complete
2025/08/22	AV ROOM 103	Overhead Plumbing	no data
2025/08/22	AV ROOM 103	Wall Drywall	complete
2025/08/22	AV ROOM 103	Wall Drywall Finish	complete
2025/08/22	AV ROOM 103	Wall Prime Paint	complete
2025/08/22	BREAK ROOM CONFERENCE 182	In Wall Insulation	no data
2025/08/22	BREAK ROOM CONFERENCE 182	Overhead Duct Insulation	complete
2025/08/22	BREAK ROOM CONFERENCE 182	Overhead Duct Rough In	in progress
2025/08/22	BREAK ROOM CONFERENCE 182	Overhead Plumbing	complete
2025/08/22	BREAK ROOM CONFERENCE 182	Wall Drywall	complete
2025/08/22	BREAK ROOM CONFERENCE 182	Wall Drywall Finish	complete
2025/08/22	BREAK ROOM CONFERENCE 182	Wall Prime Paint	complete
2025/08/22	Background-159	In Wall Insulation	complete
2025/08/22	Background-159	Overhead Duct Insulation	complete
2025/08/22	Background-159	Overhead Duct Rough In	complete
2025/08/22	Background-159	Overhead Plumbing	not started
2025/08/22	Background-159	Wall Drywall	complete
2025/08/22	Background-159	Wall Drywall Finish	complete
2025/08/22	Background-159	Wall Prime Paint	complete
2025/08/22	CENTRAL BREAKROOM 145	In Wall Insulation	complete
2025/08/22	CENTRAL BREAKROOM 145	Overhead Duct Insulation	complete
2025/08/22	CENTRAL BREAKROOM 145	Overhead Duct Rough In	complete
2025/08/22	CENTRAL BREAKROOM 145	Overhead Plumbing	complete
2025/08/22	CENTRAL BREAKROOM 145	Wall Drywall	no data
2025/08/22	CENTRAL BREAKROOM 145	Wall Drywall Finish	no data
2025/08/22	CENTRAL BREAKROOM 145	Wall Prime Paint	not started
2025/08/22	COLD CASE 175	In Wall Insulation	no data
2025/08/22	COLD CASE 175	Overhead Duct Insulation	complete
2025/08/22	COLD CASE 175	Overhead Duct Rough In	complete
2025/08/22	COLD CASE 175	Overhead Plumbing	complete
2025/08/22	COLD CASE 175	Wall Drywall	complete
2025/08/22	COLD CASE 175	Wall Drywall Finish	complete
2025/08/22	COLD CASE 175	Wall Prime Paint	complete
2025/08/22	COMMUNITY AFFAIRS 124	In Wall Insulation	no data
2025/08/22	COMMUNITY AFFAIRS 124	Overhead Duct Insulation	complete
2025/08/22	COMMUNITY AFFAIRS 124	Overhead Duct Rough In	complete
2025/08/22	COMMUNITY AFFAIRS 124	Overhead Plumbing	not started
2025/08/22	COMMUNITY AFFAIRS 124	Wall Drywall	complete
2025/08/22	COMMUNITY AFFAIRS 124	Wall Drywall Finish	complete
2025/08/22	COMMUNITY AFFAIRS 124	Wall Prime Paint	complete
2025/08/22	COMMUNITY ROOM 247 PPL 102	In Wall Insulation	no data

2025/08/22	COMMUNITY ROOM 247 PPL 102	Overhead Duct Insulation	no data
2025/08/22	COMMUNITY ROOM 247 PPL 102	Overhead Duct Rough In	in progress
2025/08/22	COMMUNITY ROOM 247 PPL 102	Overhead Plumbing	no data
2025/08/22	COMMUNITY ROOM 247 PPL 102	Wall Drywall	complete
2025/08/22	COMMUNITY ROOM 247 PPL 102	Wall Drywall Finish	complete
2025/08/22	COMMUNITY ROOM 247 PPL 102	Wall Prime Paint	complete
2025/08/22	CONFERENCE ROOM 153	In Wall Insulation	complete
2025/08/22	CONFERENCE ROOM 153	Overhead Duct Insulation	complete
2025/08/22	CONFERENCE ROOM 153	Overhead Duct Rough In	complete
2025/08/22	CONFERENCE ROOM 153	Overhead Plumbing	in progress
2025/08/22	CONFERENCE ROOM 153	Wall Drywall	complete
2025/08/22	CONFERENCE ROOM 153	Wall Drywall Finish	complete
2025/08/22	CONFERENCE ROOM 153	Wall Prime Paint	complete
2025/08/22	CONFERENCE/WAR ROOM 163	In Wall Insulation	no data
2025/08/22	CONFERENCE/WAR ROOM 163	Overhead Duct Insulation	complete
2025/08/22	CONFERENCE/WAR ROOM 163	Overhead Duct Rough In	complete
2025/08/22	CONFERENCE/WAR ROOM 163	Overhead Plumbing	complete
2025/08/22	CONFERENCE/WAR ROOM 163	Wall Drywall	complete
2025/08/22	CONFERENCE/WAR ROOM 163	Wall Drywall Finish	complete
2025/08/22	CONFERENCE/WAR ROOM 163	Wall Prime Paint	complete
2025/08/22	COPY 176	In Wall Insulation	complete
2025/08/22	COPY 176	Overhead Duct Insulation	complete
2025/08/22	COPY 176	Overhead Duct Rough In	complete
2025/08/22	COPY 176	Overhead Plumbing	not started
2025/08/22	COPY 176	Wall Drywall	complete
2025/08/22	COPY 176	Wall Drywall Finish	complete
2025/08/22	COPY 176	Wall Prime Paint	complete
2025/08/22	COPY/MAIL ROOM 114	In Wall Insulation	complete
2025/08/22	COPY/MAIL ROOM 114	Overhead Duct Insulation	no data
2025/08/22	COPY/MAIL ROOM 114	Overhead Duct Rough In	complete
2025/08/22	COPY/MAIL ROOM 114	Overhead Plumbing	no data
2025/08/22	COPY/MAIL ROOM 114	Wall Drywall	complete
2025/08/22	COPY/MAIL ROOM 114	Wall Drywall Finish	complete
2025/08/22	COPY/MAIL ROOM 114	Wall Prime Paint	complete
2025/08/22	CORRIDOR 107	In Wall Insulation	complete
2025/08/22	CORRIDOR 107	Overhead Duct Insulation	in progress
2025/08/22	CORRIDOR 107	Overhead Duct Rough In	in progress
2025/08/22	CORRIDOR 107	Overhead Plumbing	in progress
2025/08/22	CORRIDOR 107	Wall Drywall	complete
2025/08/22	CORRIDOR 107	Wall Drywall Finish	complete
2025/08/22	CORRIDOR 107	Wall Prime Paint	complete
2025/08/22	CORRIDOR 108	In Wall Insulation	complete
2025/08/22	CORRIDOR 108	In Wall Insulation	no data
2025/08/22	CORRIDOR 108	Overhead Duct Insulation	in progress
2025/08/22	CORRIDOR 108	Overhead Duct Insulation	no data

2025/08/22	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/08/22	CORRIDOR 108	Overhead Duct Rough In	in progress
2025/08/22	CORRIDOR 108	Overhead Plumbing	in progress
2025/08/22	CORRIDOR 108	Overhead Plumbing	no data
2025/08/22	CORRIDOR 108	Wall Drywall	complete
2025/08/22	CORRIDOR 108	Wall Drywall	complete
2025/08/22	CORRIDOR 108	Wall Drywall Finish	complete
2025/08/22	CORRIDOR 108	Wall Drywall Finish	complete
2025/08/22	CORRIDOR 108	Wall Prime Paint	complete
2025/08/22	CORRIDOR 108	Wall Prime Paint	complete
2025/08/22	CORRIDOR 109	In Wall Insulation	complete
2025/08/22	CORRIDOR 109	Overhead Duct Insulation	in progress
2025/08/22	CORRIDOR 109	Overhead Duct Rough In	in progress
2025/08/22	CORRIDOR 109	Overhead Plumbing	in progress
2025/08/22	CORRIDOR 109	Wall Drywall	complete
2025/08/22	CORRIDOR 109	Wall Drywall Finish	complete
2025/08/22	CORRIDOR 109	Wall Prime Paint	complete
2025/08/22	CORRIDOR 110	In Wall Insulation	no data
2025/08/22	CORRIDOR 110	In Wall Insulation	no data
2025/08/22	CORRIDOR 110	Overhead Duct Insulation	no data
2025/08/22	CORRIDOR 110	Overhead Duct Insulation	no data
2025/08/22	CORRIDOR 110	Overhead Duct Rough In	in progress
2025/08/22	CORRIDOR 110	Overhead Duct Rough In	no data
2025/08/22	CORRIDOR 110	Overhead Plumbing	in progress
2025/08/22	CORRIDOR 110	Overhead Plumbing	no data
2025/08/22	CORRIDOR 110	Wall Drywall	complete
2025/08/22	CORRIDOR 110	Wall Drywall	no data
2025/08/22	CORRIDOR 110	Wall Drywall Finish	complete
2025/08/22	CORRIDOR 110	Wall Drywall Finish	no data
2025/08/22	CORRIDOR 110	Wall Prime Paint	complete
2025/08/22	CORRIDOR 110	Wall Prime Paint	complete
2025/08/22	CORRIDOR 181	In Wall Insulation	complete
2025/08/22	CORRIDOR 181	Overhead Duct Insulation	in progress
2025/08/22	CORRIDOR 181	Overhead Duct Rough In	in progress
2025/08/22	CORRIDOR 181	Overhead Plumbing	in progress
2025/08/22	CORRIDOR 181	Wall Drywall	complete
2025/08/22	CORRIDOR 181	Wall Drywall Finish	complete
2025/08/22	CORRIDOR 181	Wall Prime Paint	complete
2025/08/22	CORRIDOR144	In Wall Insulation	no data
2025/08/22	CORRIDOR144	Overhead Duct Insulation	complete
2025/08/22	CORRIDOR144	Overhead Duct Rough In	no data
2025/08/22	CORRIDOR144	Overhead Plumbing	no data
2025/08/22	CORRIDOR144	Wall Drywall	no data
2025/08/22	CORRIDOR144	Wall Drywall Finish	no data
2025/08/22	CORRIDOR144	Wall Prime Paint	complete
2025/08/22	CPL 173	In Wall Insulation	complete
2025/08/22	CPL 173	Overhead Duct Insulation	complete
2025/08/22	CPL 173	Overhead Duct Rough In	complete
2025/08/22	CPL 173	Overhead Plumbing	complete
2025/08/22	CPL 173	Wall Drywall	complete
2025/08/22	CPL 173	Wall Drywall Finish	complete
2025/08/22	CPL 173	Wall Prime Paint	complete
2025/08/22	CPL 174	In Wall Insulation	complete
2025/08/22	CPL 174	Overhead Duct Insulation	no data

2025/08/22	CPL 174	Overhead Duct Rough In	complete
2025/08/22	CPL 174	Overhead Plumbing	no data
2025/08/22	CPL 174	Wall Drywall	complete
2025/08/22	CPL 174	Wall Drywall Finish	complete
2025/08/22	CPL 174	Wall Prime Paint	complete
2025/08/22	DRY STORAGE 146	In Wall Insulation	complete
2025/08/22	DRY STORAGE 146	Overhead Duct Insulation	complete
2025/08/22	DRY STORAGE 146	Overhead Duct Rough In	complete
2025/08/22	DRY STORAGE 146	Overhead Plumbing	not started
2025/08/22	DRY STORAGE 146	Wall Drywall	complete
2025/08/22	DRY STORAGE 146	Wall Drywall Finish	complete
2025/08/22	DRY STORAGE 146	Wall Prime Paint	in progress
2025/08/22	FIRE RISER 178	In Wall Insulation	no data
2025/08/22	FIRE RISER 178	Overhead Duct Insulation	no data
2025/08/22	FIRE RISER 178	Overhead Duct Rough In	no data
2025/08/22	FIRE RISER 178	Overhead Plumbing	no data
2025/08/22	FIRE RISER 178	Wall Drywall	no data
2025/08/22	FIRE RISER 178	Wall Drywall Finish	no data
2025/08/22	FIRE RISER 178	Wall Prime Paint	no data
2025/08/22	GREETING ROOM 106	In Wall Insulation	no data
2025/08/22	GREETING ROOM 106	Overhead Duct Insulation	complete
2025/08/22	GREETING ROOM 106	Overhead Duct Rough In	complete
2025/08/22	GREETING ROOM 106	Overhead Plumbing	not started
2025/08/22	GREETING ROOM 106	Wall Drywall	complete
2025/08/22	GREETING ROOM 106	Wall Drywall Finish	complete
2025/08/22	GREETING ROOM 106	Wall Prime Paint	complete
2025/08/22	HR 149	In Wall Insulation	complete
2025/08/22	HR 149	Overhead Duct Insulation	complete
2025/08/22	HR 149	Overhead Duct Rough In	complete
2025/08/22	HR 149	Overhead Plumbing	not started
2025/08/22	HR 149	Wall Drywall	complete
2025/08/22	HR 149	Wall Drywall Finish	complete
2025/08/22	HR 149	Wall Prime Paint	complete
2025/08/22	HR 150	In Wall Insulation	complete
2025/08/22	HR 150	Overhead Duct Insulation	complete
2025/08/22	HR 150	Overhead Duct Rough In	complete
2025/08/22	HR 150	Overhead Plumbing	no data
2025/08/22	HR 150	Wall Drywall	complete
2025/08/22	HR 150	Wall Drywall Finish	complete
2025/08/22	HR 150	Wall Prime Paint	complete
2025/08/22	HR 151	In Wall Insulation	complete
2025/08/22	HR 151	Overhead Duct Insulation	complete
2025/08/22	HR 151	Overhead Duct Rough In	complete
2025/08/22	HR 151	Overhead Plumbing	complete
2025/08/22	HR 151	Wall Drywall	complete
2025/08/22	HR 151	Wall Drywall Finish	complete
2025/08/22	HR 151	Wall Prime Paint	complete
2025/08/22	HR 154	In Wall Insulation	complete
2025/08/22	HR 154	Overhead Duct Insulation	complete
2025/08/22	HR 154	Overhead Duct Rough In	complete
2025/08/22	HR 154	Overhead Plumbing	complete
2025/08/22	HR 154	Wall Drywall	complete
2025/08/22	HR 154	Wall Drywall Finish	complete
2025/08/22	HR 154	Wall Prime Paint	complete

2025/08/22	HR 155	In Wall Insulation	complete
2025/08/22	HR 155	Overhead Duct Insulation	complete
2025/08/22	HR 155	Overhead Duct Rough In	complete
2025/08/22	HR 155	Overhead Plumbing	complete
2025/08/22	HR 155	Wall Drywall	complete
2025/08/22	HR 155	Wall Drywall Finish	complete
2025/08/22	HR 155	Wall Prime Paint	complete
2025/08/22	HR 156	In Wall Insulation	complete
2025/08/22	HR 156	Overhead Duct Insulation	complete
2025/08/22	HR 156	Overhead Duct Rough In	complete
2025/08/22	HR 156	Overhead Plumbing	not started
2025/08/22	HR 156	Wall Drywall	complete
2025/08/22	HR 156	Wall Drywall Finish	complete
2025/08/22	HR 156	Wall Prime Paint	complete
2025/08/22	HR 157	In Wall Insulation	complete
2025/08/22	HR 157	Overhead Duct Insulation	complete
2025/08/22	HR 157	Overhead Duct Rough In	complete
2025/08/22	HR 157	Overhead Plumbing	complete
2025/08/22	HR 157	Wall Drywall	complete
2025/08/22	HR 157	Wall Drywall Finish	complete
2025/08/22	HR 157	Wall Prime Paint	complete
2025/08/22	HUMAN RESOURCES 148	In Wall Insulation	complete
2025/08/22	HUMAN RESOURCES 148	Overhead Duct Insulation	complete
2025/08/22	HUMAN RESOURCES 148	Overhead Duct Rough In	no data
2025/08/22	HUMAN RESOURCES 148	Overhead Plumbing	complete
2025/08/22	HUMAN RESOURCES 148	Wall Drywall	no data
2025/08/22	HUMAN RESOURCES 148	Wall Drywall Finish	no data
2025/08/22	HUMAN RESOURCES 148	Wall Prime Paint	complete
2025/08/22	INTERNAL AFFAIRS 119	In Wall Insulation	complete
2025/08/22	INTERNAL AFFAIRS 119	Overhead Duct Insulation	complete
2025/08/22	INTERNAL AFFAIRS 119	Overhead Duct Rough In	complete
2025/08/22	INTERNAL AFFAIRS 119	Overhead Plumbing	complete
2025/08/22	INTERNAL AFFAIRS 119	Wall Drywall	complete
2025/08/22	INTERNAL AFFAIRS 119	Wall Drywall Finish	complete
2025/08/22	INTERNAL AFFAIRS 119	Wall Prime Paint	complete
2025/08/22	INTERNAL AFFAIRS 120	In Wall Insulation	complete
2025/08/22	INTERNAL AFFAIRS 120	Overhead Duct Insulation	complete
2025/08/22	INTERNAL AFFAIRS 120	Overhead Duct Rough In	complete
2025/08/22	INTERNAL AFFAIRS 120	Overhead Plumbing	not started
2025/08/22	INTERNAL AFFAIRS 120	Wall Drywall	complete
2025/08/22	INTERNAL AFFAIRS 120	Wall Drywall Finish	complete
2025/08/22	INTERNAL AFFAIRS 120	Wall Prime Paint	complete
2025/08/22	INTERVIEW / REVIEW ROOM 118	In Wall Insulation	no data
2025/08/22	INTERVIEW / REVIEW ROOM 118	Overhead Duct Insulation	complete
2025/08/22	INTERVIEW / REVIEW ROOM 118	Overhead Duct Rough In	complete
2025/08/22	INTERVIEW / REVIEW ROOM 118	Overhead Plumbing	

complete  
2025/08/22 | INTERVIEW / REVIEW ROOM 118 | Wall Drywall | complete  
2025/08/22 | INTERVIEW / REVIEW ROOM 118 | Wall Drywall Finish | complete  
2025/08/22 | INTERVIEW / REVIEW ROOM 118 | Wall Prime Paint | complete  
2025/08/22 | INTERVIEW/ REVIEW ROOM 121 | In Wall Insulation | no data  
2025/08/22 | INTERVIEW/ REVIEW ROOM 121 | Overhead Duct Insulation | complete  
2025/08/22 | INTERVIEW/ REVIEW ROOM 121 | Overhead Duct Rough In | complete  
2025/08/22 | INTERVIEW/ REVIEW ROOM 121 | Overhead Plumbing | complete  
2025/08/22 | INTERVIEW/ REVIEW ROOM 121 | Wall Drywall | complete  
2025/08/22 | INTERVIEW/ REVIEW ROOM 121 | Wall Drywall Finish | complete  
2025/08/22 | INTERVIEW/ REVIEW ROOM 121 | Wall Prime Paint | complete  
2025/08/22 | INVESTIGATIONS / MAJOR CASE 167 | In Wall Insulation | no data  
2025/08/22 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Insulation | complete  
2025/08/22 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Duct Rough In | complete  
2025/08/22 | INVESTIGATIONS / MAJOR CASE 167 | Overhead Plumbing | complete  
2025/08/22 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall | no data  
2025/08/22 | INVESTIGATIONS / MAJOR CASE 167 | Wall Drywall Finish | no data  
2025/08/22 | INVESTIGATIONS / MAJOR CASE 167 | Wall Prime Paint | complete  
2025/08/22 | IT 115 | In Wall Insulation | no data  
2025/08/22 | IT 115 | Overhead Duct Insulation | no data  
2025/08/22 | IT 115 | Overhead Duct Rough In | no data  
2025/08/22 | IT 115 | Overhead Plumbing | no data  
2025/08/22 | IT 115 | Wall Drywall | no data  
2025/08/22 | IT 115 | Wall Drywall Finish | no data  
2025/08/22 | IT 115 | Wall Prime Paint | complete  
2025/08/22 | IT 135 | In Wall Insulation | complete  
2025/08/22 | IT 135 | Overhead Duct Insulation | complete  
2025/08/22 | IT 135 | Overhead Duct Rough In | complete  
2025/08/22 | IT 135 | Overhead Plumbing | complete  
2025/08/22 | IT 135 | Wall Drywall | complete  
2025/08/22 | IT 135 | Wall Drywall Finish | complete  
2025/08/22 | IT 135 | Wall Prime Paint | complete  
2025/08/22 | IT MANAGER 136 | In Wall Insulation | no data  
2025/08/22 | IT MANAGER 136 | Overhead Duct Insulation | complete  
2025/08/22 | IT MANAGER 136 | Overhead Duct Rough In | complete  
2025/08/22 | IT MANAGER 136 | Overhead Plumbing | complete  
2025/08/22 | IT MANAGER 136 | Wall Drywall | complete  
2025/08/22 | IT MANAGER 136 | Wall Drywall Finish | complete  
2025/08/22 | IT MANAGER 136 | Wall Prime Paint | complete

2025/08/22	IT MANAGER 137	In Wall Insulation	no data
2025/08/22	IT MANAGER 137	Overhead Duct Insulation	complete
2025/08/22	IT MANAGER 137	Overhead Duct Rough In	complete
2025/08/22	IT MANAGER 137	Overhead Plumbing	complete
2025/08/22	IT MANAGER 137	Wall Drywall	complete
2025/08/22	IT MANAGER 137	Wall Drywall Finish	complete
2025/08/22	IT MANAGER 137	Wall Prime Paint	complete
2025/08/22	JUVENILE INTERVIEW 165	In Wall Insulation	complete
2025/08/22	JUVENILE INTERVIEW 165	Overhead Duct Insulation	no data
2025/08/22	JUVENILE INTERVIEW 165	Overhead Duct Rough In	complete
2025/08/22	JUVENILE INTERVIEW 165	Overhead Plumbing	no data
2025/08/22	JUVENILE INTERVIEW 165	Wall Drywall	complete
2025/08/22	JUVENILE INTERVIEW 165	Wall Drywall Finish	complete
2025/08/22	JUVENILE INTERVIEW 165	Wall Prime Paint	complete
2025/08/22	JUVENILLE INTERVIEWERS 166	In Wall Insulation	no data
2025/08/22	JUVENILLE INTERVIEWERS 166	Overhead Duct Insulation	complete
2025/08/22	JUVENILLE INTERVIEWERS 166	Overhead Duct Rough In	no data
2025/08/22	JUVENILLE INTERVIEWERS 166	Overhead Plumbing	no data
2025/08/22	JUVENILLE INTERVIEWERS 166	Wall Drywall	no data
2025/08/22	JUVENILLE INTERVIEWERS 166	Wall Drywall Finish	no data
2025/08/22	JUVENILLE INTERVIEWERS 166	Wall Prime Paint	complete
2025/08/22	KEY ROOM 185	In Wall Insulation	complete
2025/08/22	KEY ROOM 185	Overhead Duct Insulation	in progress
2025/08/22	KEY ROOM 185	Overhead Duct Rough In	in progress
2025/08/22	KEY ROOM 185	Overhead Plumbing	no data
2025/08/22	KEY ROOM 185	Wall Drywall	complete
2025/08/22	KEY ROOM 185	Wall Drywall Finish	complete
2025/08/22	KEY ROOM 185	Wall Prime Paint	complete
2025/08/22	LT 170	In Wall Insulation	complete
2025/08/22	LT 170	Overhead Duct Insulation	complete
2025/08/22	LT 170	Overhead Duct Rough In	complete
2025/08/22	LT 170	Overhead Plumbing	not started
2025/08/22	LT 170	Wall Drywall	complete
2025/08/22	LT 170	Wall Drywall Finish	complete
2025/08/22	LT 170	Wall Prime Paint	complete
2025/08/22	MACHINE ROOM 191	In Wall Insulation	no data
2025/08/22	MACHINE ROOM 191	Overhead Duct Insulation	no data
2025/08/22	MACHINE ROOM 191	Overhead Duct Rough In	complete
2025/08/22	MACHINE ROOM 191	Overhead Plumbing	no data
2025/08/22	MACHINE ROOM 191	Wall Drywall	complete
2025/08/22	MACHINE ROOM 191	Wall Drywall Finish	complete
2025/08/22	MACHINE ROOM 191	Wall Prime Paint	complete
2025/08/22	MAIN ELECTRICAL ROOM 123	In Wall Insulation	no data
2025/08/22	MAIN ELECTRICAL ROOM 123	Overhead Duct Insulation	no data
2025/08/22	MAIN ELECTRICAL ROOM 123	Overhead Duct Rough In	no

data			
2025/08/22	MAIN ELECTRICAL ROOM 123	Overhead Plumbing	no data
2025/08/22	MAIN ELECTRICAL ROOM 123	Wall Drywall	no data
2025/08/22	MAIN ELECTRICAL ROOM 123	Wall Drywall Finish	no data
data			
2025/08/22	MAIN ELECTRICAL ROOM 123	Wall Prime Paint	no data
2025/08/22	MAIN JANITORIAL111	In Wall Insulation	no data
2025/08/22	MAIN JANITORIAL111	Overhead Duct Insulation	complete
2025/08/22	MAIN JANITORIAL111	Overhead Duct Rough In	complete
2025/08/22	MAIN JANITORIAL111	Overhead Plumbing	complete
2025/08/22	MAIN JANITORIAL111	Wall Drywall	complete
2025/08/22	MAIN JANITORIAL111	Wall Drywall Finish	complete
2025/08/22	MAIN JANITORIAL111	Wall Prime Paint	complete
2025/08/22	MARINE SERGEANT 142	In Wall Insulation	complete
2025/08/22	MARINE SERGEANT 142	Overhead Duct Insulation	complete
2025/08/22	MARINE SERGEANT 142	Overhead Duct Rough In	complete
2025/08/22	MARINE SERGEANT 142	Overhead Plumbing	complete
2025/08/22	MARINE SERGEANT 142	Wall Drywall	complete
2025/08/22	MARINE SERGEANT 142	Wall Drywall Finish	complete
2025/08/22	MARINE SERGEANT 142	Wall Prime Paint	complete
2025/08/22	MECHANICAL 192	In Wall Insulation	no data
2025/08/22	MECHANICAL 192	Overhead Duct Insulation	no data
2025/08/22	MECHANICAL 192	Overhead Duct Rough In	no data
2025/08/22	MECHANICAL 192	Overhead Plumbing	no data
2025/08/22	MECHANICAL 192	Wall Drywall	no data
2025/08/22	MECHANICAL 192	Wall Drywall Finish	no data
2025/08/22	MECHANICAL 192	Wall Prime Paint	no data
2025/08/22	MECHANICAL ROOM 122	In Wall Insulation	no data
2025/08/22	MECHANICAL ROOM 122	Overhead Duct Insulation	no data
data			
2025/08/22	MECHANICAL ROOM 122	Overhead Duct Rough In	no data
2025/08/22	MECHANICAL ROOM 122	Overhead Plumbing	no data
2025/08/22	MECHANICAL ROOM 122	Wall Drywall	no data
2025/08/22	MECHANICAL ROOM 122	Wall Drywall Finish	no data
2025/08/22	MECHANICAL ROOM 122	Wall Prime Paint	no data
2025/08/22	MENS RESTROOM 112	In Wall Insulation	no data
2025/08/22	MENS RESTROOM 112	Overhead Duct Insulation	no data
2025/08/22	MENS RESTROOM 112	Overhead Duct Rough In	complete
2025/08/22	MENS RESTROOM 112	Overhead Plumbing	complete
2025/08/22	MENS RESTROOM 112	Wall Drywall	complete
2025/08/22	MENS RESTROOM 112	Wall Drywall Finish	complete
2025/08/22	MENS RESTROOM 112	Wall Prime Paint	not started
2025/08/22	MIS EQUIPMENT STORAGE 138	In Wall Insulation	no data
data			
2025/08/22	MIS EQUIPMENT STORAGE 138	Overhead Duct Insulation	complete
2025/08/22	MIS EQUIPMENT STORAGE 138	Overhead Duct Rough In	complete
2025/08/22	MIS EQUIPMENT STORAGE 138	Overhead Plumbing	complete
2025/08/22	MIS EQUIPMENT STORAGE 138	Wall Drywall	complete
2025/08/22	MIS EQUIPMENT STORAGE 138	Wall Drywall Finish	



complete

2025/08/22		MIS EQUIPMENT STORAGE 138		Wall Prime Paint		complete
2025/08/22		MIS SHREDDING 117		In Wall Insulation		complete
2025/08/22		MIS SHREDDING 117		Overhead Duct Insulation		complete
2025/08/22		MIS SHREDDING 117		Overhead Duct Rough In		complete
2025/08/22		MIS SHREDDING 117		Overhead Plumbing		complete
2025/08/22		MIS SHREDDING 117		Wall Drywall		complete
2025/08/22		MIS SHREDDING 117		Wall Drywall Finish		complete
2025/08/22		MIS SHREDDING 117		Wall Prime Paint		complete
2025/08/22		OFFICE 128		In Wall Insulation		no data
2025/08/22		OFFICE 128		Overhead Duct Insulation		complete
2025/08/22		OFFICE 128		Overhead Duct Rough In		complete
2025/08/22		OFFICE 128		Overhead Plumbing		no data
2025/08/22		OFFICE 128		Wall Drywall		complete
2025/08/22		OFFICE 128		Wall Drywall Finish		complete
2025/08/22		OFFICE 128		Wall Prime Paint		complete
2025/08/22		OPERATIONS SUPPORT DIVISION 139		In Wall Insulation		no data
2025/08/22		OPERATIONS SUPPORT DIVISION 139		Overhead Duct Insulation		complete
2025/08/22		OPERATIONS SUPPORT DIVISION 139		Overhead Duct Rough In		complete
2025/08/22		OPERATIONS SUPPORT DIVISION 139		Overhead Plumbing		no data
2025/08/22		OPERATIONS SUPPORT DIVISION 139		Wall Drywall		complete
2025/08/22		OPERATIONS SUPPORT DIVISION 139		Wall Drywall Finish		complete
2025/08/22		OPERATIONS SUPPORT DIVISION 139		Wall Prime Paint		complete
2025/08/22		PARTS STORAGE 189		In Wall Insulation		no data
2025/08/22		PARTS STORAGE 189		Overhead Duct Insulation		no data
2025/08/22		PARTS STORAGE 189		Overhead Duct Rough In		no data
2025/08/22		PARTS STORAGE 189		Overhead Plumbing		no data
2025/08/22		PARTS STORAGE 189		Wall Drywall		no data
2025/08/22		PARTS STORAGE 189		Wall Drywall Finish		no data
2025/08/22		PARTS STORAGE 189		Wall Prime Paint		complete
2025/08/22		PUBLIC RESTROOM 106		In Wall Insulation		complete
2025/08/22		PUBLIC RESTROOM 106		Overhead Duct Insulation		complete
2025/08/22		PUBLIC RESTROOM 106		Overhead Duct Rough In		complete
2025/08/22		PUBLIC RESTROOM 106		Overhead Plumbing		complete
2025/08/22		PUBLIC RESTROOM 106		Wall Drywall		complete
2025/08/22		PUBLIC RESTROOM 106		Wall Drywall Finish		complete
2025/08/22		PUBLIC RESTROOM 106		Wall Prime Paint		in progress
2025/08/22		Polygraph 152		In Wall Insulation		complete
2025/08/22		Polygraph 152		Overhead Duct Insulation		complete
2025/08/22		Polygraph 152		Overhead Duct Rough In		complete
2025/08/22		Polygraph 152		Overhead Plumbing		not started
2025/08/22		Polygraph 152		Wall Drywall		complete
2025/08/22		Polygraph 152		Wall Drywall Finish		complete
2025/08/22		Polygraph 152		Wall Prime Paint		complete
2025/08/22		RECEPTION 101		In Wall Insulation		no data
2025/08/22		RECEPTION 101		Overhead Duct Insulation		no data

2025/08/22	RECEPTION 101	Overhead Duct Rough In	no data
2025/08/22	RECEPTION 101	Overhead Plumbing	no data
2025/08/22	RECEPTION 101	Wall Drywall	no data
2025/08/22	RECEPTION 101	Wall Drywall Finish	no data
2025/08/22	RECEPTION 101	Wall Prime Paint	no data
2025/08/22	RECEPTION 147	In Wall Insulation	complete
2025/08/22	RECEPTION 147	Overhead Duct Insulation	complete
2025/08/22	RECEPTION 147	Overhead Duct Rough In	complete
2025/08/22	RECEPTION 147	Overhead Plumbing	complete
2025/08/22	RECEPTION 147	Wall Drywall	complete
2025/08/22	RECEPTION 147	Wall Drywall Finish	complete
2025/08/22	RECEPTION 147	Wall Prime Paint	complete
2025/08/22	RECEPTION 179	In Wall Insulation	complete
2025/08/22	RECEPTION 179	Overhead Duct Insulation	complete
2025/08/22	RECEPTION 179	Overhead Duct Rough In	complete
2025/08/22	RECEPTION 179	Overhead Plumbing	no data
2025/08/22	RECEPTION 179	Wall Drywall	complete
2025/08/22	RECEPTION 179	Wall Drywall Finish	complete
2025/08/22	RECEPTION 179	Wall Prime Paint	complete
2025/08/22	RECORDS 130	In Wall Insulation	no data
2025/08/22	RECORDS 130	Overhead Duct Insulation	complete
2025/08/22	RECORDS 130	Overhead Duct Rough In	complete
2025/08/22	RECORDS 130	Overhead Plumbing	complete
2025/08/22	RECORDS 130	Wall Drywall	complete
2025/08/22	RECORDS 130	Wall Drywall Finish	complete
2025/08/22	RECORDS 130	Wall Prime Paint	complete
2025/08/22	RECORDS STORAGE 133	In Wall Insulation	complete
2025/08/22	RECORDS STORAGE 133	Overhead Duct Insulation	complete
2025/08/22	RECORDS STORAGE 133	Overhead Duct Rough In	complete
2025/08/22	RECORDS STORAGE 133	Overhead Plumbing	complete
2025/08/22	RECORDS STORAGE 133	Wall Drywall	complete
2025/08/22	RECORDS STORAGE 133	Wall Drywall Finish	complete
2025/08/22	RECORDS STORAGE 133	Wall Prime Paint	complete
2025/08/22	RECORDS SUPERVISOR 131	In Wall Insulation	no data
2025/08/22	RECORDS SUPERVISOR 131	Overhead Duct Insulation	complete
2025/08/22	RECORDS SUPERVISOR 131	Overhead Duct Rough In	complete
2025/08/22	RECORDS SUPERVISOR 131	Overhead Plumbing	not started
2025/08/22	RECORDS SUPERVISOR 131	Wall Drywall	complete
2025/08/22	RECORDS SUPERVISOR 131	Wall Drywall Finish	complete
2025/08/22	RECORDS SUPERVISOR 131	Wall Prime Paint	complete
2025/08/22	RECORDS SUPERVISOR 132	In Wall Insulation	no data
2025/08/22	RECORDS SUPERVISOR 132	Overhead Duct Insulation	complete
2025/08/22	RECORDS SUPERVISOR 132	Overhead Duct Rough In	complete
2025/08/22	RECORDS SUPERVISOR 132	Overhead Plumbing	no data
2025/08/22	RECORDS SUPERVISOR 132	Wall Drywall	complete
2025/08/22	RECORDS SUPERVISOR 132	Wall Drywall Finish	complete
2025/08/22	RECORDS SUPERVISOR 132	Wall Prime Paint	complete
2025/08/22	RESTROOM 183	In Wall Insulation	complete

2025/08/22	RESTROOM 183	Overhead Duct Insulation	complete
2025/08/22	RESTROOM 183	Overhead Duct Rough In	complete
2025/08/22	RESTROOM 183	Overhead Plumbing	complete
2025/08/22	RESTROOM 183	Wall Drywall	complete
2025/08/22	RESTROOM 183	Wall Drywall Finish	in progress
2025/08/22	RESTROOM 183	Wall Prime Paint	not started
2025/08/22	Risk Management - 158	In Wall Insulation	complete
2025/08/22	Risk Management - 158	Overhead Duct Insulation	complete
2025/08/22	Risk Management - 158	Overhead Duct Rough In	complete
2025/08/22	Risk Management - 158	Overhead Plumbing	complete
2025/08/22	Risk Management - 158	Wall Drywall	complete
2025/08/22	Risk Management - 158	Wall Drywall Finish	complete
2025/08/22	Risk Management - 158	Wall Prime Paint	complete
2025/08/22	SALLY PORT 105	In Wall Insulation	not started
2025/08/22	SALLY PORT 105	Overhead Duct Insulation	in progress
2025/08/22	SALLY PORT 105	Overhead Duct Rough In	in progress
2025/08/22	SALLY PORT 105	Overhead Plumbing	no data
2025/08/22	SALLY PORT 105	Wall Drywall	no data
2025/08/22	SALLY PORT 105	Wall Drywall Finish	not started
2025/08/22	SALLY PORT 105	Wall Prime Paint	not started
2025/08/22	SANE EXAM ROOM 168	In Wall Insulation	complete
2025/08/22	SANE EXAM ROOM 168	Overhead Duct Insulation	no data
2025/08/22	SANE EXAM ROOM 168	Overhead Duct Rough In	complete
2025/08/22	SANE EXAM ROOM 168	Overhead Plumbing	no data
2025/08/22	SANE EXAM ROOM 168	Wall Drywall	complete
2025/08/22	SANE EXAM ROOM 168	Wall Drywall Finish	complete
2025/08/22	SANE EXAM ROOM 168	Wall Prime Paint	complete
2025/08/22	SGT 171	In Wall Insulation	no data
2025/08/22	SGT 171	Overhead Duct Insulation	complete
2025/08/22	SGT 171	Overhead Duct Rough In	complete
2025/08/22	SGT 171	Overhead Plumbing	complete
2025/08/22	SGT 171	Wall Drywall	complete
2025/08/22	SGT 171	Wall Drywall Finish	complete
2025/08/22	SGT 171	Wall Prime Paint	complete
2025/08/22	SGT 172	In Wall Insulation	complete
2025/08/22	SGT 172	Overhead Duct Insulation	no data
2025/08/22	SGT 172	Overhead Duct Rough In	complete
2025/08/22	SGT 172	Overhead Plumbing	complete
2025/08/22	SGT 172	Wall Drywall	complete
2025/08/22	SGT 172	Wall Drywall Finish	complete
2025/08/22	SGT 172	Wall Prime Paint	complete
2025/08/22	SHIPPING STORAGE 190	In Wall Insulation	complete
2025/08/22	SHIPPING STORAGE 190	Overhead Duct Insulation	complete
2025/08/22	SHIPPING STORAGE 190	Overhead Duct Rough In	no data
2025/08/22	SHIPPING STORAGE 190	Overhead Plumbing	no data
2025/08/22	SHIPPING STORAGE 190	Wall Drywall	no data
2025/08/22	SHIPPING STORAGE 190	Wall Drywall Finish	no data
2025/08/22	SHIPPING STORAGE 190	Wall Prime Paint	complete
2025/08/22	SHOP FORMAN 184	In Wall Insulation	complete
2025/08/22	SHOP FORMAN 184	Overhead Duct Insulation	complete
2025/08/22	SHOP FORMAN 184	Overhead Duct Rough In	complete

2025/08/22	SHOP FORMAN 184	Overhead Plumbing	no data
2025/08/22	SHOP FORMAN 184	Wall Drywall	complete
2025/08/22	SHOP FORMAN 184	Wall Drywall Finish	complete
2025/08/22	SHOP FORMAN 184	Wall Prime Paint	complete
2025/08/22	SOFT INTERVIEW 161	In Wall Insulation	complete
2025/08/22	SOFT INTERVIEW 161	Overhead Duct Insulation	no data
2025/08/22	SOFT INTERVIEW 161	Overhead Duct Rough In	complete
2025/08/22	SOFT INTERVIEW 161	Overhead Plumbing	complete
2025/08/22	SOFT INTERVIEW 161	Wall Drywall	complete
2025/08/22	SOFT INTERVIEW 161	Wall Drywall Finish	complete
2025/08/22	SOFT INTERVIEW 161	Wall Prime Paint	complete
2025/08/22	SOFT INTERVIEW 162	In Wall Insulation	complete
2025/08/22	SOFT INTERVIEW 162	Overhead Duct Insulation	no data
2025/08/22	SOFT INTERVIEW 162	Overhead Duct Rough In	complete
2025/08/22	SOFT INTERVIEW 162	Overhead Plumbing	complete
2025/08/22	SOFT INTERVIEW 162	Wall Drywall	no data
2025/08/22	SOFT INTERVIEW 162	Wall Drywall Finish	no data
2025/08/22	SOFT INTERVIEW 162	Wall Prime Paint	complete
2025/08/22	SPECIAL OPERATION LT 143	In Wall Insulation	no data
2025/08/22	SPECIAL OPERATION LT 143	Overhead Duct Insulation	no data
2025/08/22	SPECIAL OPERATION LT 143	Overhead Duct Rough In	in progress
2025/08/22	SPECIAL OPERATION LT 143	Overhead Plumbing	in progress
2025/08/22	SPECIAL OPERATION LT 143	Wall Drywall	complete
2025/08/22	SPECIAL OPERATION LT 143	Wall Drywall Finish	complete
2025/08/22	SPECIAL OPERATION LT 143	Wall Prime Paint	complete
2025/08/22	STAIR A	In Wall Insulation	no data
2025/08/22	STAIR A	Overhead Duct Insulation	no data
2025/08/22	STAIR A	Overhead Duct Rough In	no data
2025/08/22	STAIR A	Overhead Plumbing	complete
2025/08/22	STAIR A	Wall Drywall	in progress
2025/08/22	STAIR A	Wall Drywall Finish	in progress
2025/08/22	STAIR A	Wall Prime Paint	in progress
2025/08/22	STORAGE 104	In Wall Insulation	no data
2025/08/22	STORAGE 104	Overhead Duct Insulation	no data
2025/08/22	STORAGE 104	Overhead Duct Rough In	in progress
2025/08/22	STORAGE 104	Overhead Plumbing	not started
2025/08/22	STORAGE 104	Wall Drywall	complete
2025/08/22	STORAGE 104	Wall Drywall Finish	complete
2025/08/22	STORAGE 104	Wall Prime Paint	complete
2025/08/22	STORAGE 127	In Wall Insulation	no data
2025/08/22	STORAGE 127	Overhead Duct Insulation	complete
2025/08/22	STORAGE 127	Overhead Duct Rough In	complete
2025/08/22	STORAGE 127	Overhead Plumbing	no data
2025/08/22	STORAGE 127	Wall Drywall	complete
2025/08/22	STORAGE 127	Wall Drywall Finish	complete
2025/08/22	STORAGE 127	Wall Prime Paint	complete
2025/08/22	STUDIO 126	In Wall Insulation	complete
2025/08/22	STUDIO 126	Overhead Duct Insulation	complete
2025/08/22	STUDIO 126	Overhead Duct Rough In	complete
2025/08/22	STUDIO 126	Overhead Plumbing	complete

2025/08/22	STUDIO 126	Wall Drywall	no data
2025/08/22	STUDIO 126	Wall Drywall Finish	no data
2025/08/22	STUDIO 126	Wall Prime Paint	complete
2025/08/22	SUPERVISOR 129	In Wall Insulation	complete
2025/08/22	SUPERVISOR 129	Overhead Duct Insulation	complete
2025/08/22	SUPERVISOR 129	Overhead Duct Rough In	complete
2025/08/22	SUPERVISOR 129	Overhead Plumbing	not started
2025/08/22	SUPERVISOR 129	Wall Drywall	complete
2025/08/22	SUPERVISOR 129	Wall Drywall Finish	complete
2025/08/22	SUPERVISOR 129	Wall Prime Paint	complete
2025/08/22	Storage 164	In Wall Insulation	complete
2025/08/22	Storage 164	Overhead Duct Insulation	complete
2025/08/22	Storage 164	Overhead Duct Rough In	complete
2025/08/22	Storage 164	Overhead Plumbing	not started
2025/08/22	Storage 164	Wall Drywall	complete
2025/08/22	Storage 164	Wall Drywall Finish	complete
2025/08/22	Storage 164	Wall Prime Paint	complete
2025/08/22	Storage 177	In Wall Insulation	complete
2025/08/22	Storage 177	Overhead Duct Insulation	complete
2025/08/22	Storage 177	Overhead Duct Rough In	complete
2025/08/22	Storage 177	Overhead Plumbing	not started
2025/08/22	Storage 177	Wall Drywall	complete
2025/08/22	Storage 177	Wall Drywall Finish	complete
2025/08/22	Storage 177	Wall Prime Paint	complete
2025/08/22	TECHNICAL SURVEILLANCE 188	In Wall Insulation	complete
2025/08/22	TECHNICAL SURVEILLANCE 188	Overhead Duct Insulation	complete
2025/08/22	TECHNICAL SURVEILLANCE 188	Overhead Duct Rough In	complete
2025/08/22	TECHNICAL SURVEILLANCE 188	Overhead Plumbing	complete
2025/08/22	TECHNICAL SURVEILLANCE 188	Wall Drywall	no data
2025/08/22	TECHNICAL SURVEILLANCE 188	Wall Drywall Finish	no data
2025/08/22	TECHNICAL SURVEILLANCE 188	Wall Prime Paint	complete
2025/08/22	TRAFFIC SERGEANT 141	In Wall Insulation	no data
2025/08/22	TRAFFIC SERGEANT 141	Overhead Duct Insulation	complete
2025/08/22	TRAFFIC SERGEANT 141	Overhead Duct Rough In	complete
2025/08/22	TRAFFIC SERGEANT 141	Overhead Plumbing	complete
2025/08/22	TRAFFIC SERGEANT 141	Wall Drywall	complete
2025/08/22	TRAFFIC SERGEANT 141	Wall Drywall Finish	complete
2025/08/22	TRAFFIC SERGEANT 141	Wall Prime Paint	complete
2025/08/22	TRIAGE/RECEPTION 134	In Wall Insulation	no data
2025/08/22	TRIAGE/RECEPTION 134	Overhead Duct Insulation	complete
2025/08/22	TRIAGE/RECEPTION 134	Overhead Duct Rough In	no data
2025/08/22	TRIAGE/RECEPTION 134	Overhead Plumbing	no data
2025/08/22	TRIAGE/RECEPTION 134	Wall Drywall	no data
2025/08/22	TRIAGE/RECEPTION 134	Wall Drywall Finish	no data
2025/08/22	TRIAGE/RECEPTION 134	Wall Prime Paint	complete

2025/08/22	TST WORKSHOP 187	In Wall Insulation	complete
2025/08/22	TST WORKSHOP 187	Overhead Duct Insulation	not started
2025/08/22	TST WORKSHOP 187	Overhead Duct Rough In	complete
2025/08/22	TST WORKSHOP 187	Overhead Plumbing	no data
2025/08/22	TST WORKSHOP 187	Wall Drywall	no data
2025/08/22	TST WORKSHOP 187	Wall Drywall Finish	no data
2025/08/22	TST WORKSHOP 187	Wall Prime Paint	complete
2025/08/22	UNISEX RESTROOM 169	In Wall Insulation	complete
2025/08/22	UNISEX RESTROOM 169	Overhead Duct Insulation	no data
2025/08/22	UNISEX RESTROOM 169	Overhead Duct Rough In	complete
2025/08/22	UNISEX RESTROOM 169	Overhead Plumbing	no data
2025/08/22	UNISEX RESTROOM 169	Wall Drywall	complete
2025/08/22	UNISEX RESTROOM 169	Wall Drywall Finish	in progress
2025/08/22	UNISEX RESTROOM 169	Wall Prime Paint	not started
2025/08/22	VEHICLE MAINTENANCE BAYS 186	In Wall Insulation	no data
2025/08/22	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Insulation	no data
2025/08/22	VEHICLE MAINTENANCE BAYS 186	Overhead Duct Rough In	no data
2025/08/22	VEHICLE MAINTENANCE BAYS 186	Overhead Plumbing	complete
2025/08/22	VEHICLE MAINTENANCE BAYS 186	Wall Drywall	no data
2025/08/22	VEHICLE MAINTENANCE BAYS 186	Wall Drywall Finish	no data
2025/08/22	VEHICLE MAINTENANCE BAYS 186	Wall Prime Paint	complete
2025/08/22	VOLUNTEER/LIGHT DUTY 140	In Wall Insulation	no data
2025/08/22	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Insulation	complete
2025/08/22	VOLUNTEER/LIGHT DUTY 140	Overhead Duct Rough In	complete
2025/08/22	VOLUNTEER/LIGHT DUTY 140	Overhead Plumbing	complete
2025/08/22	VOLUNTEER/LIGHT DUTY 140	Wall Drywall	complete
2025/08/22	VOLUNTEER/LIGHT DUTY 140	Wall Drywall Finish	complete
2025/08/22	VOLUNTEER/LIGHT DUTY 140	Wall Prime Paint	complete
2025/08/22	WAITING/LOBBY 100	In Wall Insulation	no data
2025/08/22	WAITING/LOBBY 100	Overhead Duct Insulation	no data
2025/08/22	WAITING/LOBBY 100	Overhead Duct Rough In	in progress
2025/08/22	WAITING/LOBBY 100	Overhead Plumbing	in progress
2025/08/22	WAITING/LOBBY 100	Wall Drywall	in progress
2025/08/22	WAITING/LOBBY 100	Wall Drywall Finish	not started
2025/08/22	WAITING/LOBBY 100	Wall Prime Paint	not started
2025/08/22	WOMENS RESTROOM 113	In Wall Insulation	no data
2025/08/22	WOMENS RESTROOM 113	Overhead Duct Insulation	no data
2025/08/22	WOMENS RESTROOM 113	Overhead Duct Rough In	complete
2025/08/22	WOMENS RESTROOM 113	Overhead Plumbing	no data
2025/08/22	WOMENS RESTROOM 113	Wall Drywall	complete
2025/08/22	WOMENS RESTROOM 113	Wall Drywall Finish	complete

2025/08/22 | WOMENS RESTROOM 113 | Wall Prime Paint | not started