

# Fault code: 405003 Arm sensor detection timeout

## Type

Error Code

## Solution

Check whether there is a paper stick inserted into the arm, and if so, enter "Device Test" and click "Arm Insertion Sensor" to detect "None", then replace the arm insertion sensor. If "Yes" is displayed, restart the device, and try again. See Figure below for the position of the arm insertion rod sensor.

Created by

 Jason Lopez



