



Overview: Part of spill impact on 4" Santa Barbara Well 11T flowline right of way at Ikegimakiri. Picture was taken during Joint Investigation of 27<sup>th</sup> September 2012.



Close up: Failed weld on 4" Santa Barbara Well 11T flowline at Ikegimakiri. Picture was taken during Joint Investigation of 27<sup>th</sup> September 2012.