



Overview: Part of the spill impact on Imoriver2 Well28L flowline at Umuedeokware.
Picture taken during Joint Investigation of 1st July, 2011



Close-up: Spill due to cut pipe on Imoriver2 Well28L flowline at Umuedeokware. Picture taken during Joint Investigation of 1st July, 2011