



Overview: Extent of the spill incident impact on Adibawa North-East Well 4L pipeline route at Biseni. Insert shows pit with large volume of oil, 12m from spill point.



Close-up: Spill due to tampering with clamp nuts and bolts on Adibawa North-East Well 4L pipeline route at Biseni. Pictures taken during JIV of 11th April, 2011.