



Overview: Part of spill impact on Oguta Well6S flowline at Umuashichi. Picture was taken during Joint Investigation of 4th April 2013.



Close up: Spill due to corrosion on Oguta Well6S flowline at Umuashichi. Picture was taken during Joint Investigation of 4th April 2013.