



Overview: Part of spill impact on 36" Rumuekpe-Nkpoku pipeline at Aluu. Picture taken during Joint Investigation of 20<sup>th</sup> June, 2011



Close-up: Illegally welded fittings on 36" Rumuekpe-Nkpoku pipeline at Aluu. Picture taken during Joint Investigation of 19<sup>th</sup> June, 2011