



Overview: Part of spill impact on Cawthorne Channel Well 21L flowline at Mbiama.
Picture taken during Joint Investigation of 3rd August, 2011



Close-up: Failed clamp on Cawthorne Channel Well 21L flowline at Mbiama. Picture
taken during Joint Investigation of 3rd August, 2011