



Overview: Part of spill impact on 4" Adibawa North East Well10S flowline at Edagberi/Betterland. Picture was taken during Joint Investigation of 2<sup>nd</sup> October 2013.



Close up: Hacksaw cut on 4" Adibawa North East Well10S flowline at Edagberi/Betterland. Picture was taken during Joint Investigation of 2<sup>nd</sup> October 2013.



Close up: Hacksaw cut on 4" Adibawa North East Well10S flowline at Edagberi/Betterland. Picture was taken during Joint Investigation of 2<sup>nd</sup> October 2013.