



Overview: Part of spill impact on 4" Adibawa North East Well11L flowline right of way at Biseni. Picture was taken during Joint Investigation of 18th September 2013.



Close up: Tampered clamp on 4" Adibawa North East Well11L flowline at Biseni. Picture was taken during Joint Investigation of 18th September 2013.