



Overview: Part of spill impact on 12" ImoRiver2 pipeline at Owaza. Picture taken during Joint Investigation of 16th June, 2011



Close-up: Spill from hose used for illegal transport of crude on 12" ImoRiver2 pipeline at Owaza. Picture taken during Joint Investigation of 16th June, 2011



Close-up: Illegally welded fitting at 12 o'clock position on 12" ImoRiver2 pipeline at Owaza.
Picture taken during Joint Investigation of 16th June, 2011