



Overview: Part of spill impact on Opukushi Well 25 at Agbediamma. Picture was taken during Joint Investigation of 13<sup>th</sup> Sept. 2012.



Close-up: Internal corrosion on Opukushi Well 25 at Agbediamma. Picture was taken during Joint Investigation of 13<sup>th</sup> Sept. 2012