



Overview: Part of spill impact on Well 56S flow line right of way (RoW) at Etitioha. Picture was taken during Joint Investigation of 26th August 2012.



Close-up: Missing flowline on Well 56S flow line right of way (RoW) at Etitioha. Picture was taken during Joint Investigation of 26th August 2012.