



Overview: Part of extent of the spill incident impact on 12" Imo River 1 pipeline route in Owaza. Picture taken during Joint Investigation of 9<sup>th</sup> June, 2011



Close-up: Illegally welded fitting on 12" Imo River 1 pipeline in Owaza. Picture taken during Joint Investigation of 9<sup>th</sup> June, 2011.