



Close up: Spill point due to corrosion on 10" Ekulama2 pipeline at Luckyland. Picture was taken during Joint Investigation of 11<sup>th</sup> April 2012.