



Overview: Part of the spill impact on Obigbo Well 28LS flowline at Imea. Picture taken during Joint Investigation of 10<sup>th</sup> June, 2011



Close-up: Hacksaw cut on Obigbo Well 28LS flowline at Imea. Picture taken during Joint Investigation of 10<sup>th</sup> June, 2011