



Overview: Part of spill impact on Adibawa Well 10S flowline route at Edagberi. Picture was taken during Joint Investigation of 15th September, 2011.



Close-up: Spill point on Adibawa Well 10S flowline at Edagberi. Picture was taken during Joint Investigation of 15th September, 2011.



Overview: Initial hacksaw cut previously clamped on Adibawa Well 10S flowline at Edagberi.
Picture was taken during Joint Investigation of 15th September, 2011.