



Overview: Spill incident site at low tide at Akaso Well 3L Flowline route. Picture was taken during JIV of 15th April, 2011



Close-up: Hacksaw cut on Akaso Well 3L Flowline route in Akaso. Picture was taken during JIV of 15th April, 2011