



Overview: Part of spill impact on 12" ImoRiver2-Ebubu pipeline right of way at Odagwa. Picture was taken during Joint Investigation of 23<sup>rd</sup> November, 2011.



Close-up: Illegal fitting on 12" ImoRiver2-Ebubu pipeline at Odagwa. Picture was taken during Joint Investigation of 23<sup>rd</sup> November, 2011.