



Overview: Part of spill incident impact on NunRiver Well 15 Flowline route at Onyonma. Picture was taken during Joint Investigation of 14th September, 2011.



Close-up: Spill due to drilled hole on NunRiver Well 15 Flowline at Onyonma. Stick was inserted into the pipe to show the position of the drilled hole. Picture was taken during Joint Investigation of 14th September, 2011.