



Close-up: Spill due to pinhole and slight tear close to previous weld on Kanbo Well 5L flowline at Egbemo Angalabiri. Picture taken during Joint Investigation of 25<sup>th</sup> November 2011.