



Overview: Part of spill impact on Obigbo Flowline Gathering Manifold route at Umuwalia. Picture was taken during Joint Investigation of 29th August 2012.



Close-up: Corrosion on Obigbo well 33S flowline at Obigbo Flowline Gathering Manifold at Umuwalia. Picture was taken during Joint Investigation of 29th August 2012.