



Overview: Spill point within cofferdam on 30" Nembe Creek pipeline right of way at Krakama. Picture was taken during Joint Investigation of 24<sup>th</sup> September 2013.



Close up: Failed clamp on 30" Nembe Creek pipeline at Krakama. Picture was taken during Joint Investigation of 24<sup>th</sup> September 2013.