



Overview: Bubbles with slight oil sheen along Bonny-Oloma Well 12S flowline Right of Way at Oloma with passing fisherman's canoe in the background.



Close-up: Spill due to hacksaw cut on Bonny-Oloma Well 12S flowline at Oloma.
Picture taken during Joint Investigation of 15th June, 2011.