



Overview: Extent of the spill incident impact on Imo River well 37L flow line at Owaza. Picture taken during Joint Investigation of 14th February, 2011



Close-up: Spill due to illegally drilled hole on Imo River well 37L flow line at Owaza. Picture taken during Joint Investigation of 14th February, 2011.