



Overview: Yokri Well 114S flowline at Yokri/Sokebolou being raised for inspection.
Picture taken during Joint Investigation of 15th August, 2011



Close-up: Spill due to corrosion on Yokri Well 114S flowline at Yokri/Sokebolou.
Picture taken during Joint Investigation of 15th August, 2011