



Close up: Spill due to corrosion on Opukushi Well24T flowline at Egbemo-Angalebiri.
Picture was taken during Joint Investigation of 10th July 2012.