



Overview: Extent of the spill incident impact on 6" Well 59T flow line at Imo River.
Pictures taken during Joint Investigation of 30th March, 2011



Close-up: Picture showing illegally welded point on 6" Well 59T flow line at Imo River.
Picture taken during Joint Investigation of 30th March, 2011.