



Overview: Part of area burnt by fire on Well56L flowline at Isietitioha. Picture taken during Joint Investigation of 17<sup>th</sup> June, 2011



Close-up: Illegally welded fitting on Well56L flowline at Isietitioha. Picture taken during Joint Investigation of 17<sup>th</sup> June, 2011