



Close-up: Spill due to corrosion on Otumara Well22L flowline at Ugborodo, Deghele & Ugboegbungun. Picture taken during Joint Investigation of 18th July, 2011