



Overview: Hacksaw cuts visible on Well 13L flowline at Akaso. Picture was taken during JIV of 4th May, 2011