



Overview: Part of spill impact on 4" ImoRiver1 Well30S flowline right of way at Igiriukwu. Picture taken during Joint Investigation of 6th October, 2011.



Close-up: Spill due hacksaw cut on 4" ImoRiver1 Well30S flowline at Igiriukwu. Picture taken during Joint Investigation of 6th October, 2011.