



Overview: Part of spill impact on Opukushi Well33L flowline at Egbema-Angalabiri.
Picture was taken during Joint Investigation of 19th January 2012.



Close-up: Point of internal corrosion on Opukushi Well33L flowline at Egbema-Angalabiri.
Picture was taken during Joint Investigation of 27th January 2012.