



Overview: Part of spill impact on Well15 flowline right of way at Peremabiri. Picture was taken during Joint Investigation of 15th February 2012.



Close-up: Tampered clamp on Well15 flowline at Peremabiri. Picture was taken during Joint Investigation of 15th February 2012.